

REC. BY: Adrian King

REF:

CC3 / ALH1801373 / Arbzn

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. 17000 49849

Claims No. 85 91390075 SG

Sum Insured:

Excess:

\$660.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

120K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 88%

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLS1847A

Yr Regn:

2017 Sept

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A3 Sedan

c.c. 999

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading:

20277

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAUZZZ8VSJ1008931

Gen. Cond:

Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

205/55R16

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

19/07/18

Survey held at

Premium

Des. of Damages

☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD ALG.

SLS1847A - CC6/ALH18012638/UH63

DLA: 10072018

Confirm with Mr Boo \$2751.40 @ 3 days
Red: \$5792.60, 68%

RECEIVED 12 NOV 2018

Date/Time, File Pass to?

☐

: Preli. Report

1) typed

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

~

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

200
10

210

Report Format :

00

Lump Sum / I.B.I. (\$

2751.40

Janice Lee (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Monday, September 10, 2018 4:11 PM
To: Adrian Ling (LKKAUTO); Janice Lee (LKKAUTO); SUR; Carrine Leong; jiajee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: FINAL REVISION - SLS1847A - OD AIG - SURVEYED 19 JULY 18
Attachments: PA08032018 - SLS 1847 A - A3 1.0 TFSI QU - (AIG).xls

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$2751.40 @ 3 days .

Photos sent to you on 6 Aug 18

Your early closure is well appreciated.

Best regards - jb

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licensed Member: **S8574448H**

XIN PENGWEI

Birth Date: **14 Sep 1985**
Issue Date: **05 Mar 2013**

002157690E




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8574448H

XIN PENGWEI

辛 鵬 威

Race: **CHINESE**
Date of birth: **14-09-1985**
Country of birth: **CHINA**

Sex: **F**

S8574448H




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg **29 Oct 2007**

NP 428A



4860454



NRIC No. S8574448H



Date of issue: **11-04-2013**

APT BLK 321 TAMPINES STREET 33 #07-124
SINGAPORE 520321

NRIC No: S8574448H Date: **14/12/2014**



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : XIN PENGWEI
 Period of Insurance : 12 Sep 2017 To 11 Sep 2018
 Engine No. : CHZ521068
 Chassis No. : WAUZZZ8V5J1008931

Vehicle No. : SLS1847A
 Policy No. : 1700049849
 Endorsement No. :
 Issued Date : 23 Sep 2017

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
 Engine Capacity/Tonnage : 999.00 CC
 Driver Restriction : NA
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2017
 Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
 You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

XIN PENGWEI - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125251

PREMIUM LEASING -LES

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manik

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Chong Qian Yee

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondence from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within 3 working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Premium Automobiles Pte. Ltd.

Activation Hotline: 64741223

55 Ubi Road 1 Singapore 408699

Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 1pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

REPUBLIC OF SINGAPORE DRIVING LICENCE

XIN PENGWEI

14 Sep 1985

05 May 2013

002157630E

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8574448H

XIN PENGWEI

辛 鵬 威

Race
CHINESE

Date of birth
14-09-1985

Country of birth
CHINA

Sex
F

S8574448H

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 29 Oct 2007

NP 428A

Licence No: S8574448H

4960454

NRIC No: S8574448H

Date of issue
11-04-2013

APT BLK 321 TAMPINES STREET 33 #07-124
SINGAPORE 520321

NRIC No: S8574448H Date: 14/12/2014

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0803/2018/PH
Date	:	13-Jul-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Xin PengWei
Address	:	Blk 321 Tampines Street 33 #07-124
Telephone	:	HP 81396049
Type of Claim	:	Own Damage Claim
Policy No.	:	
Vehicle No	:	SLS 1837 S
Model Code	:	Audi A3 1.0 TFSI
Model / Year	:	Sep-17
Engine No	:	CHZ 521068
Chassis No	:	WAUZZZ8V5J1008931
Mileage	:	-
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	10-Jul-18
Place of Accident	:	AT PIE NEAR JLN EUNOS EXIT

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 1837 S.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy.	S/N \$ 360.00	✓ /
2	To dismantle and renew front bumper. Re-organise front crash management components. Reinstall all parts removed.	\$ 900.00	500 /
3	To respray front bumper and bonnet.	\$ 1,500.00	550 /
4	To carry out diagnostic check	S/N \$ 192.00	✓ /
TOTAL LABOUR CHARGES		: \$ 2,952.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No SLS 1847 A.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Reqs</i>	\$ 1,739.00	X
2	1 SET OF FIXING PARTS FOR BUMPER <i>new</i>	\$ 161.00	X
4	GUIDE SECTION LH / RH <i>new</i>	\$ 66.00	X
5	FRONT BUMPER CENTER GRILLE <i>new</i>	\$ 140.00	X
6	FRONT BUMPER UNDERCARRIAGE COVER CENTRE <i>new</i>	\$ 460.00	X
7	FRONT BUMPER CLOSING ELEMENT LH / RH <i>new</i>	2 \$ 508.00	X
8	FRONT BUMPER COVER TRIM LH / RH <i>new</i>	2 \$ 280.00	X
9	WHEEL HOUSING LINER LH / RH	2 \$ 64.00	X
10	RADIATOR GRILLE <i>Grille & Damaged.</i>	\$ 1,239.00	✓ 991.20
11	RADIATOR GRILLE END PLATE	\$ 167.00	? 133.20
12	AIR GUIDE GRILLE LH <i>new</i>	\$ 164.00	X
13	FOAM FILLER PIECE <i>new</i>	\$ 162.00	X
14	FRONT BUMPER TOP COVER <i>new</i>	\$ 105.00	X
15	SIGN "CAUTION" STICKER <i>new</i>	\$ 12.00	X
16	CAR PLATE NO <i>Dented</i>	\$ 25.00	✓ 25.00
17	SUNDRIES <i>new</i>	\$ 300.00	? X
TOTAL SPARE PARTS		\$ 5,592.00	
TOTAL LABOUR CHARGES		\$ 2,952.00	
GRAND TOTAL		\$ 8,544.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 19/07/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Authorised Repairs, 03 Days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0803/2018/GW
Date	:	13-Jul-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

3 days - ok - jb - 10 Sep 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Xin PengWei
Address	:	Blk 321 Tampines Street 33 #07-124 Singapore 520321
Telephone	:	HP 81396049
Type of Claim	:	Own Damage Claim
Policy No.	:	
Vehicle No	:	SLS 1847 A
Model Code	:	Audi Sedan 1.0 TFSI
Model / Year	:	Sep-17
Engine No	:	CHZ 521068
Chassis No	:	WAUZZZ8V5J1008931
Mileage	:	-
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	10-Jul-18
Place of Accident	:	At PIE Near JLN Eunus Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 1847 A .

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy.	S/N \$ 360.00	\$ 360.00
2	To dismantle and renew front bumper. Re-organise front crash management components. Reinstall all parts removed.	\$ 900.00	\$ 500.00
3	To respray front bumper and bonnet.	\$ 1,500.00	\$ 550.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 2,952.00	\$ 1,602.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No SLS 1847 A.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,739.00	
2	1 SET OF FIXING PARTS FOR BUMPER	\$ 161.00	
4	GUIDE SECTION - LH/RH	\$ 66.00	
5	FRONT BUMPER CENTER GRILLE	\$ 140.00	
6	FRONT BUMPER UNDERCARRIAGE COVER CENTRE	\$ 460.00	
7	FRONT BUMPER CLOSING ELEMENT-LH/RH	2 \$ 508.00	
8	FRONT BUMPER COVER TRIM LH/RH	2 \$ 280.00	
9	FRONT WHEEL HOUSING LINER-LH/RH	2 \$ 64.00	
10	RADIATOR GRILLE	\$ 1,239.00	\$ 991.20
11	RADIATOR GRILLE END PLATE	\$ 167.00	\$ 133.20
12	AIR GUIDE GRILLE-LH	\$ 164.00	
13	FOAM FILLER PIECE	\$ 162.00	
14	FRONT BUMPER TOP COVER	\$ 105.00	
15	SIGN ' CAUTION'	\$ 12.00	
16	CAR PLATE NO.	S/N \$ 25.00	\$ 25.00
17	SUNDRIES	\$ 300.00	
	TOTAL SPARE PARTS	\$ 5,592.00	\$ 1,149.40
	TOTAL LABOUR CHARGES	\$ 2,952.00	\$ 1,602.00
	GRAND TOTAL	\$ 8,544.00	\$ 2,751.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLS 1847 A

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0803/2018/MAS

10 Nov 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLS 1847 A, Audi A3 Sedan 1.0 TFSI

With reference to the above-mentioned vehicle, no **SLS 1847 A**, claimant,
Ms. Xin PengWei, please find the related document per attached.

1. A copy of the Original invoice no. 85013111 – S\$2,302.00
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLS 1847 A

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



















...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jul 2018 Edit Reg		19 Jul 2018 00:00 Edit Adj Rpt	S\$2,751.40 Edit Estimates	S\$2,751.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:		XIN PENGWEI, ID: S8574448H, Tel: +6581396049							
Vehicle Reg. No.:		SLS1847A	Date of Loss: 10/07/2018 19:00 - :59 [9 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:		OD / 8591390075SG	Policy/Cover Note No.: 1700049849 (Comprehensive) Excess: S\$600.00						
Repairer:		Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911							
Handling Insurer:		AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 30/07/2018]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (20/07/2018): SLS1847A / OD / 10/07/2018 / Coverage & Excess update									
<input type="checkbox"/> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS1847A (8591390075SG)
 OD
 Jul 10 2018 7:00PM
 [XIN PENGWEI]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View Use Viewer		
Photos/Images															3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	20/07/18 11:02	General View												 Load JPG	<input checked="" type="checkbox"/>		
2	20/07/18 11:02	General View												 Load JPG	<input checked="" type="checkbox"/>		
3	20/07/18 11:02	General View												 Load JPG	<input checked="" type="checkbox"/>		
4	20/07/18 11:02	General View												 Load JPG	<input checked="" type="checkbox"/>		
5	20/07/18 11:02	General View												 Load JPG	<input checked="" type="checkbox"/>		
6	20/07/18 11:02	General View												 Load JPG	<input checked="" type="checkbox"/>		
7	20/07/18 11:02	General View												 Load JPG	<input checked="" type="checkbox"/>		
8	20/07/18 11:02	General View												 Load JPG	<input checked="" type="checkbox"/>		
9	20/07/18 11:02	General View												 Load JPG	<input checked="" type="checkbox"/>		
10	20/07/18 11:02	General View												 Load JPG	<input checked="" type="checkbox"/>		
11	20/07/18 11:02	General View												 Load JPG	<input checked="" type="checkbox"/>		
Documentation															1 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	20/07/18 11:02	SLS 1847A ESTIMATE												 Load PDF			
2	20/07/18 11:02	SLS 1847A NRIC & DL												 Load PDF			
3	20/07/18 11:02	Certificate of Insurance												 Load PDF			
4	20/07/18 11:02	Singapore Accident Statement												 Load PDF			
5	20/07/18 13:37	SLS 1847A GIA AMEND												 Load PDF			
6	13/11/18 09:28	WORKSHOP INVOICE												 Load PDF			
7	13/11/18 09:28	DISCHARGE VOUCHER												 Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18013173/ARBN2

Date: 13/11/2018

REFERENCE

Insured/Claimant:	XIN PENGWEI	Policy No:	1700049849	
Date of Loss:	10/07/2018	Nature of Claim:	OD	Claim No: 8591390075SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS1847A	Engine No:	CHZ521068
Make & Model:	AUDI A3, 999cc TFSI (A)	Chassis No:	WAUZZZ8V5J1008931
Reg. Date:	12/09/2017 (Man. Year: 2017)	Odometer:	20277 km
Colour:	White		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,592.00	1,149.40	4,442.60	79.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,952.00	1,602.00	1,350.00	45.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,544.00	2,751.40	5,792.60	67.80
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	7,944.00	2,151.40	5,792.60	72.92
+ GST 7.00/7.00% (S\$)	556.08	150.60	405.48	72.92
Nett Amount (S\$)	8,500.08	2,302.00	6,198.08	72.92

INSPECTION

Date of Assignment: 19/07/2018

Date Inspected: 19/07/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Repair	1,739.00 FS	*- FS
2	1	*SET OF FIXING PARTS FOR BUMPER	Not Necessary	161.00 FS	*- FS
3	2	*GUIDE SECTION LH/RH	Not Necessary	66.00 FS	*- FS
4	1	*FRONT BUMPER CENTRE GRILLE	Not Necessary	140.00 FS	*- FS
5	1	*FRONT BUMPER UNDERCARRIAGE COVER CENTRE	Not Necessary	460.00 FS	*- FS
6	2	*FRONT BUMPER CLOSING ELEMENT LH/RH	Not Necessary	508.00 FS	*- FS
7	2	*FRONT BUMPER COVER TRIM LH/RH	Not Necessary	280.00 FS	*- FS
8	2	*WHEEL HOUSING LINER LH/RH	Not Necessary	64.00 FS	*- FS
9	1	*RADIATOR GRILLE	Cracked	1,239.00 FS	*991.20 FS
10	1	*RADIATOR GRILLE END PLATE	Damaged	167.00 FS	*133.20 FS
11	1	*AIR GUIDE GRILLE LH	Not Necessary	164.00 FS	*- FS
12	1	*FOAM FILLER PIECE	Not Necessary	162.00 FS	*- FS
13	1	*FRONT BUMPER TOP COVER	Not Necessary	105.00 FS	*- FS
14	1	*SIGN CAUTION STICKER	Not Necessary	12.00 FS	*- FS
15	1	*CAR PLATE NO	Dented	25.00 FS	*25.00 FS
16	1	*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	5,592.00	1,149.40
--------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	900.00	500.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	1,500.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,952.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >