	Monica Churg	of	MSIG	Date/Time	19/7/18/8 4.26pm
Estimated Co			Bill to		1
To Inspect V		SHB 8949	E	Insured: GBD	4908K
at Workshop	m/s P	remier Tax	zi'S	Tel: 65-	14 6676
of	23 Changi soi	Ith Are 2=	# 0 4-03		
	28638098Mk	CC .	Claim No:	564764	
Sum Insured			Excess:		
Make of Veh (Client's Recon				D.O.A.	8/07/2018
	/ REP. / REV 24 HRS	lup		8106/F0/0G	
Date/Time:	1 10 - Alalalia	Person Contacted:	Vincent	H.O.D. End Vehicle(IN)	
Date/Time	Action/Instruction (- Estimate	2		
		- NA MSG/8			DOA: 18/07/201
	GBD 4908 K	- NA MSG181	013158/24		8104 F0/81 : A

8/11/13)	955		
zineur: Kalvin	REF:		
4.2	ASS	SIGNMENT	
rom;	Date:	Veh No: SHB 8949E Yr Regn: 25 Apr 20	1%
rom:stimatedCost:	Date,	Type: M.Car / M.Cycle / Bus / Van / Lorry / Toi / Prime Mover /	
DITP WS ITP RES I OD RES	/ FVA / INV / MV	Truck / Trailer or	
	•	Make: KIA optima c.c /683	5
Inspect Vehicle No:		Make: KIA optima c.c 1682 Colour Silver A/C: Insurgal Std / NI /	NA
Workshop m/s		Sp.Reading 509192 T/Radio: Insuded / Std / NI /	
aund:		Eng/No:	
		C/No: KNAhm414ME 54 62596	
olicy No.		Gen. Cond: Good / Fair / Poor / Burnt	
laims No.		Steering: Inor 1 Jammed / Leaked / Burnt or	
um Insured:	Excess:	Brake: Inorder / Jammed / Leaked / Burnt or	
(Client's Record)		Modi: Nil / S/Rim / STD ARim or	
Make of Veh:			
		Tyre Size: F: 205/65 (16	
(Policy Condition)	ed its N/S 0/S	TO SEE THE PROPERTY OF THE PRO	- I
Remark: The veh had commend repair at the time of in	Journal Tolling	1/4//	
repair at the time of m	ареспол.		
Bal. or Market Value:		Front Rear R/Bal. 7	mm ,
DAC Accident Rport:	Consistent? : Yes or No	Toda. 7 min	mm .
GIA / PR Seen:	Consistent? : Yes or No	1 1 10	mm -
Est. Repairs:da	ays Res.: Yes or No	D.O.A. 18/7/18 D.O.I. 20/7/18	-
Lum Sum: %	3 Val.: Yes or No	Survey held at Fremier	-
CA / REV / REP. / 24 H	IRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or	
	Vehicle: IN / O	01	Mision
	Contacted:	The U/C / Chassis frame / Body Structure affected due to co	illision.
Date / Time Action / Instru		Red 1033.39 1990 MJZ	
3/8/18 Ladred C	(15 \$2500/4B)	New 1055.51 - 112	
		1 1	
	DECEIVED of 0	AUG 2018	
100	W = 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	PSSW-EBBU	
100	RECEIVED 0 3	8 0 B	
1000	RECEIVED U.S.	6 v 14	
17.00	RECEIVED U.S.		
110.00	RECEIVED 0 3		
	;	Davis Of Popular	
Date/Time, File Pass to?	: Preli. Report	Days Of Repair:	0
1)	;	Resurvey No. of Trip: Survey Fee: 15	0
	: Preli. Report : Final Report	Resurvey No. of Trip: Survey Fee: Its	0
1)	: Preli. Report	Resurvey No. of Trip: Survey Fee: Transportation: Survey Fee: It propries (\$)S+RS,SI	
1) Date/Time, File Return to? 2) 38- typist	: Preli. Report : Final Report Add I	Resurvey No. of Trip: Survey Fee: It Transportation: Transportation: Fee: : Site Insp (\$)	
1) Date/Time, File Return to? 2) 38 - typist	: Preli. Report : Final Report	Resurvey No. of Trip: Survey Fee: Transportation: Survey Fee: It propries (\$)S+RS,SI	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

SM.		Affiliated to Federation Internation	onale Des Experts En Autom	obile		
MSI	G INSURANCE (S	INGAPORE) PTE LTD	Ref : CS/MSG18013	178/K1vd3		
	RAFFLES QUAY -01 HONG LEONG	BLDG SINGAPORE 048581	Date: 19-07-2018 Code: MSG			
1.		Policy Particulars	:- THIRD PARTY CLAI	M		
	Insured Veh.	GBD 4908K	Veh. Inspected	SHB 8949E		
	Policy No.	28638098MKC	Coverage (\$)	0.00		
	Claim No.	564764	Excess (\$)	0.00		
	Assign From	MERIMEN (MONICA CHUNG)	Assign Date	19/07/2018		
2.		Vehicle Parti	culars & Condition			
	Make & Model		c.c	0		
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	SI.	Steering			
	Brakes		Modification			
	General					
3.		Condit	ons of Tyres			
		Size	Make	Balance		
	R/H Front Tyre			mm		
	L/H Front Tyre			mm		
	R/H Rear Tyre			mm		
	L/H Rear Tyre			mm		
4.		Descripti	on of Damages			
5.		Genera	I Information			
	Accident Date		Inspection Date			
	Survey held at	PREMIER AUTOMOTIVE SERV				
	land at	23 CHANGI SOUTH AVENUE 2		443		
5a.			emarks			
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W				

ALL ASSOCIATED TASKS

Due Date

No results.

Priority Type

Task Group

Subject

Handler

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adi Assigned	Adi Rot	Adi Sul	new little of	Ins Auth'ed	Status	
Main	18 Jul 2018	Est Submitted	19 Jul 2018 16:26 Assign	мај крс	Aujsa	omiced	This Auth ea	New	Assignment el Case
	Main	Re	ference		Claim Details		Docume	nts	Show All
CLAIM SU	BFOLDER DI	ETAILS				[Creat	ed by insurer]		
Insured:	Natrad F	ood Private Limit	ed, Co. Reg. N	0.: 1979003	348G	-			
Main Claimant:	PREMIER	TAXIS PTE LTD,	Co. Reg. No.:	200304975	н				
Vehicle Reg No.:	SHB8949E		Date of Loss:	18/07/2018 10:00 - :59 [50 Months and 23 Days From LTA Reg Date (Man Yr)]					
Claim Type	TP / 564	TP / 564764			Policy/Cover Note No.:		98MKC (Comprehe ge: 20/11/2017 - :		8
Vehicle Reg No. (Insured):	GBD4908	К			Policy No. (Claimant):				
					Excess:				
Repairer:	Premier 1	Premier Taxis Pte Ltd (HQ) 23 Changi South Avenue 2, #04-03, 486443 Changi - Tel:							
Handling Insurer:	MSIG Ins	urance (Singapo	re) Pte. Ltd. (H	Q) - Tel: +	65 6827 7888	. [Handled	by Monica Chun	g Pei Zhe	en - 6594 2552]
Adjuster:	LKK Auto	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Imm.Advice due 20/07/2018]							
Adj Asg. Remarks:		SJE Agree Please appoint LKK and contact 65446676 / 65446689 Liability (Non-reporting)							
ASSOCIAT	ED MAIL RE	CEIVED						View All	Compose Case Ma
There are n	o mail for this	case.						11017741	Compose Case Me

Assigned By

Complete

Done?

Search Tasks | Create New Task

Created On

Completed On

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Monica Chung Pei Zhen

Date: 23 Jul 2018

Preliminary Advice

Insured Vehicle

: GBD4908K

No

TP Vehicle No : SHB8949E Accident Date

: 18/07/2018

Make

: KIA OPTIMA

Assignment Date

: 19/07/2018

Date of Inspection: 20/07/2018

Est. Duration of Repair : 4.00

Inspection At

: PREMIER TAXIS PTE LTD (HQ)

23 CHANGI SOUTH AVENUE 2, #04-03

SINGAPORE 486443

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,533.39
Revised Amount	:S\$	3,164.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,164.40

:S\$

Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

The vehicle is economical/not economical for repair.

(X)

The above survey was conducted on a 'without prejudice' basis.

Text size +

Enquire Transaction History

Transaction History Details

Log Date/Time:

25 Apr 2014 / 09:14:02

Receipt No .:

AACCK001-AX239-140425-000003

Asset Type:

Vehicle

Transaction Amount:

\$72,769.00

Asset ID:

SHB8949E

Channel:

AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type:

Business Transaction

01.02 Register New Vehicle (AA)

Reference No.:

20140425091402502499

Vehicle No.:

SHB8949E

Vehicle Type:

H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1:

Vehicle Attachment 2:

Vehicle Attachment 3:

Vehicle Scheme:

Taxi (Company)

Air-Con (Taxi)

First Registration Date: 25 Apr 2014

Original Registration

25 Apr 2014

Date: Vehicle Make:

KIA

Vehicle Model:

OPTIMA 1.7(A) DIESEL

Chassis No.:

KNAGM414ME5462596

Engine No.:

D4FDDH309682

Motor No.:

Trailer Chassis No.: Propellant:

Diesel

Passenger Capacity:

4

Engine Capacity:

1685

Power Rating: Unladen Weight:

1584

Maximum Laden

2050

Weight:

Silver

Primary Color:

Secondary Color: Manufacturing Year:

Open Market Value:

\$20,184.00

Minimum PARF Benefit:

\$7,654.00 Y

2013

PARF Eligibility:

No. of Transfer:

Effective Ownership

25 Apr 2014 09:14:02

Date/Time: COE No .:

2014042501000977K

COE Expiry Date:

24 Apr 2022

COE Bid Category:

Actual QP/PQP Paid Amount:

\$59,871.00

Lifespan Expiry Date:

24 Apr 2022

Owner ID Type:

Company

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

alolesalu.	
	ACCIDENT STATEMENT
Date Of Report	18/07/2018 10:49
Date Of Accident	18/07/2018 10:15
Exact Location Of Accident	MARINE PARADE ROAD AFTER STILL ROAD SOUTH
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHB8949E
Insured/Policyholder	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880
Vehicle Particulars	
Manufacturer	KIA
Model	OPTIMA-1.7 D (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5095103893
Cover Note Number	
Driver	
Name of Driver	ABDUL GAFFOOR MOHAMED SALIM
NRIC No	S0158657B
Date Of Birth	04/03/1951
Occupation	OUTDOOR
Date Of Driving Pass	21/01/1978
Driving Experience	40 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96155154
Fax Number	
Contact Number	

NOEMAIL

Address

8 #02-03 SIGLAP ROAD

Postcode

455839

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - MAJOR/MINOR RD

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

VEH. A - NO PAX VEH. B - UNKNOWN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

Vehicle Registration Number

GBD4908K

Vehicle Make/Model/Colour

TOYOTA GOODS VAN

DETAILS OF OTHER VEHICLE PROPERTY 1

Details Of Properties

VEH. B

Vehicle Category

GOODS VEHICLE

Name of Driver

SHASHI KUMAL A/L POOBALAN

NRIC/Passport Number

G8163668R

Contact Number

82905408

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Taxis of Live

× JAH

18 JUL 2018

P


Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

X 0188687-B

× 848 8749-E

Sketch Plan Pg. 2



Describe Circumstance of the Accident.

ON 18/07/2018 @ 1015HRS, I STOPPED MY TAXI (SHB 8949 E) ALONG MARINE PARADE ROAD – TWDS PARKWAY PARADE, AT THE TRAFFIC LIGHT JUNCTION OF STILL ROAD SOUTH, IN THE MIDDLE LANE (ARROW ON ROAD SURFACE SHOWS STRAIGHT AHEAD ONLY) – AS TRAFFIC LIGHT WAS RED.


WHEN TRAFFIC LIGHT TURNED GREEN ON MY ROUTE FAVOUR, I PROCEED STRAIGHT AHEAD BUT SUDDENLY VEHICLE B (GBD 4908 K - GOODS VAN) WHICH WAS EXITING FROM THE SLIP ROAD OF STILL ROAD SOUTH, FAILED TO KEEP FOR PROPER LOOK OUT FOR CLEARANCE FROM MY ROUTE - HAD MOVED OFF AHEAD & ENCROACHED ONTO MY PATH ON MY LEFT ABRUPTLY.

AS SUCH, THE FRONT RIGHT PORTION OF VEHICLE B COLLIDED ONTO THE LEFT PORTION OF MY TAXI.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE LEFT PORTION AND VEHICLE B HAD DAMAGES ON THE FRONT RIGHT PORTION.

NO INJURY INVOLVED. UNKNOWN PASSENGERS ONBOARD VEHICLE B.

*VIDEO FOOTAGE CAPTURED.



PREMIER AUTOMOTIVE SERVICES PTE LTD

23 Changi South Ave 2 #01-02, Singapore 486443

Assessment Number: MSIG0025

Assessor Report Printed: 20/07/2018 Version: PREMIERA/1

Summary Information

Claim

Claim Reference:

SHB8949E

Insured:

Policy Number: Date of Decision:

20/07/2018

Third Party:

Repairer:

Able to Authorise Repairs: TBA TBA

Estimated Repair Time (Working Days):

0.0

Repairs Authorised?

Insured's Liability

Excess:

TBA

Customer Contribution:

\$0.00 (excl GST)

Vehicle Details

Vehicle

Registration:

SHB8949E

VIN/Chassis Number:

Manufacturer:

KIA

Model:

Optima

Registration Month: Odometer:

April Not Known Registration Year: Colour:

2014

Build Date:

Model Specs

FROM 01/2014

WHEEL COVER 16 INCH PREPARE OFF VEHICLE

BASECOAT CLEAR

Vehicle Condition

Vehicle Status

Date of Incident: 18/07/2018

Pre-Accident Condition:

Pre-Accident Damage: Steering Rim Ply:

Brake Pedal Travel: Vehicle Status: Damage Severity:

Market Value:

Salvage Value: Date of Inspection: Unknown Unknown 20/07/2018

Place of Inspection:

Tyres Condition:

Tread Depth LHF: Tread Depth LHR: Tread Depth RHF: Tread Depth RHR:

Repair Information

LABOUR Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HRPrice/Dent = \$50.00/HR

Repair / WU **Guide Number Repair Details** Cost Price (\$) RENEW L/R DOOR 90.00 77000R00 18.0 INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY 15.00 87755R00 R + R L/SILL TRIM 3.0 5.00 NO NUMBER R + R L/R BUMPER REFLECTOR 1.0 REAR SCREEN R + R 22.0 110.00 87111R00

> INCLUDES: REAR SEAT BACKREST AND ALL REQUIRED TRIMS REMOVE AND REFIT

PREMIER AUTOMOTIVE SERVICES PTE LTD 23 Changi South Ave 2

#01-02, Singapore 486443

Assessment Number: MSIG0025

Assessor Report Printed: 20/07/2018 Version: PREMIERA/1

	Total Labour	28.0HRS	\$1,400.00
	Paint Labour	11.3HRS	\$565.00
	Sub Total	16.7HRS	\$835.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Corrosion Protection External Labour	0.0HRS	0.00
	Total Work Units	167.0	
	BOUR COST		
2583	REPAIR REAR BUMPER	20.0*	100.00
1481	REPAIR LEFT FRONT DOOR	20.0*	100.00
68869R0B)	R + R L/- AND R/BOOT TRIM (ADD)	2.0	10.00
85710R00	R + R BOOT CARPET	2.0	10.00
68869R00)	R + R L/LOAD COMPARTMENT TRIM	1.0	5.00
85875R00)	R + R L/R SILL MOULDING	1.0	5.00
NO NUMBÉR	RENEW L/R SIDE PANEL	72.0	360.00
59200R00)	R + R BOOTLID	5.0	25.00

PAINT W	ORK Time Basis 10) WU = 1 HR. Price =	\$50.00/HR
Guide Nu	mber Description	WU	Cost Price (\$)
	 PREPARE OFF VEHICLE 		
	- BASECOAT CLEAR		
1781	L/R DOOR NEW PART PAINTING	15.0	
3485	L/R OUTER SIDE PANELNEW PART PAINTING	31.0	
1481	LEFT FRONT DOOR REPAIR PAINTING <50%	17.0	
2583	REAR BUMPER REPAIR PAINT PLASTIC	17.0	
	LABOUR COST - PAINT		
	TIME(PAINT)	80.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	113.0	
	Total Paintwork Labour	11.3HRS	\$565.00
	MATERIAL COST - PAINT		Cost Price
	New Part Painting		\$84.28
	Material-Constant Main Work Metal		\$28.60
	Repair Painting		\$28.10
	Repair Painting Plastic		\$57.92
	Material-Const Main Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$211.60
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$211.60

PARTS Price Valid: 01/06/2015 Guide No.Qty Description Part Number Supplier Bet. Price (\$) 0% 29.00* 2617 L/R BUMPER BRACKET 866132T501 X 1 0% and 1781 L/R DOOR 770032T000 / 791.00* 0% 1985 1 L/R DOOR FRM UP TRIM 831342T000 X 2.44U 1987 1 L/R DOOR FRT MLDG 863812T000 0% 9.80U 831352T000 0% 17.04U 1983 1 L/R DR FRM FRT TRIM 0% 1,205.00* 3485 1 L/R OUTER SIDE PANEL 715032TC00

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 Changi South Ave 2 #01-02, Singapore 486443

Assessment Number: MSIG0025

Assessor Report Version: PREMIERA/1 Printed: 20/07/2018

3413	1	L/R REFLECTOR		924052T500	X	su	0,0	% 46.00
1991	1	L/R UPP DOOR MLDG	838502T00		×	su	0.0	% 63.80
9559	1	L/R WHEEL COVER	529602T10		-	horal	00	% 116.00
4201	1	L/R WHEELHOUSE CO			×	ser		% 120.00
3169	1	LWR REAR WINDOW	MLDG	871302T000	×	44	0.0	% 87.00
3160	1	REAR SCREEN BOND	KIT	ZK20063001/		× 11	0.0	% 80.8:
3163	1	REAR SCREEN FIX SI	ΞT	USE SINGLE	PARTS	× **	0.0	% 0.00
3173	2	REAR SCREEN SPACE	ER	871143K000		× "	0.0	% 7.20
3171	10	REAR SCREEN SUPPO	ORTS	861143D000		× m	0.0	% 15.30
f: OEM P	arts			Sub To	otal	F		\$2,590.4
g: Origin	al			Deduc	tion fro	m RRP	(35 %)	-\$906.6
h: Secon	dhand			Total	Parts			\$1,683.79
p: Paralle	el							
x: Excha	nge							
				NT CONTAINS				
		NB - COLOUR (CODED IT	EMS/TRIM - P	ART NL	JMBERS	MAY DIFFER	
Extras		120 020						
		Description			Better	ment		Price
		N/S DOOR STICKER		RASSES IN	0%		AME	\$100.00
		REAR FENDER	SPECIAL	IST			NL	\$60.00
		STICKER						
		RR FENDER COVER	SPECIAL	IST	0%	×	44	\$28.00
		CLIP	CDECIAL	107		- 1	4.	#F0.00
		SEALANT	SPECIAL			×	77	\$50.00
10		12.5			Total I	extras		\$238.00
Final C		lation						
Total Pa	irts							\$1,683.79
Labour	Take	J. Danal (Maahaalaa)					±025 00	855
		al Panel/Mechanical					\$835.00	
Totalia		al Paintwork					\$565.00	\$1,400.00
Total La								\$1,400.00
Addition			-1				¢0.00	
Corr Prot Materials External						\$0.00		
Corr Prot Materials Internal			11				\$0.00	
Total of		t of Specialist cional Costs					\$238.00	\$238.00
		laterial Costs						\$211.60
							3553.39	
Grand I		xcludes GST					1333	\$3,533.39 \$247.34
Grand T		ncludes GST						\$3,780.73
Granu I	otal I	includes GST						\$3,700.73

Assessment Notes

Kalvi ((lley

1/20/7/18 0945L

4/8, Repir ploto

Audatex System Using Manufacturer Times

408933

Claim Reference: SHB8949E Assessment Number: MSIG0025

Version: LKKAUTOC/2

Date Calculated: 23/07/2018 07:02

Full Report - V1

Registration: SHB8949E

Printed: 23/07/2018 14:02

SGD

TBA

18/07/2018

Summary Information

Claim

Location:

Printed by:

Work Provider:

Authorisation Status:

Claim Reference:

Policy Number: Other Reference:

Third Party: Insured Amount: Under Warranty: Warranty Expired: Singapore (SG) LKK AUTO

Interim MSIG Insurance

(Singapore) Pte

KIA

Optima

2836 01 SHB8949E

Not Known

April

2014

BASE MODEL

SHB8949E

LKK

Estimated Repair Time: **Quote Due Date:**

Date of Incident:

Repairs Authorised:

Able to Authorise Repairs: TBA

Currency:

Actual Repair Days: Parts Ordered Date: Hire Car Start: Hire Car End: Vehicle Collected:

Vehicle Details

Vehicle Manufacturer:

Model:

Sub Model: Model Sheet Number:

Registration:

Registration Month:

Registration Year:

VIN Number:

Odometer:

Colour:

Engine Number:

Fuel Level:

%

Model Specs

FROM 01/2014

PREPARE OFF VEHICLE

WHEEL COVER 16 INCH BASECOAT CLEAR

Vehicle Condition

Vehicle Status

Pre-Accident Condition: Steering:

Place of Inspection: Pre-Accident Damage:

Brakes Pedal Travel:

Tyres Condition:

Tread Depth LHF: Tread Depth LHR:

Damage Areas:

Severity of Impact:

Vehicle Status on Inspection:

Date of Inspection:

20/07/2018

Tread Depth RHF: Tread Depth RHR:

Direction of Impact:

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore Full Report - V1

Claim Reference: SHB8949E


Assessment Number: MSIG0025


Version: LKKAUTOC/2

Date Calculated: 23/07/2018 07:02

Registration: SHB8949E

Printed: 23/07/2018 14:02





Addresses

Total Labour	\$1,420.00
Total Paint/Material	\$211.60
Total Parts	\$1,372.80
Total of Additional Costs	\$160.00
Excess:	TBA
Grand Total Exc GST:	\$3,164.40
	\$221.51
Grand Total Inc GST:	\$3,385.91
	Total Paint/Material Total Parts Total of Additional Costs Excess: Grand Total Exc GST: 7 % GST:

Repair	Information
LABOUR	

LABOUR	Time Basis 10 WU =		= \$50.00/HR = \$50.00/HR
Repair /		14/11	Cost Price (\$)
	Repair Details	WU 18.0	90.00
77000R00	RENEW L/R DOOR	18.0	90.00
	INCLUDES: R + R DOOR AND ALL NECESSARY		
	ATTACHED PARTS, RENEW IF NECESSARY	2.0	15.00
87755R00	R + R L/SILL TRIM	3.0	25.00
86520R00 ZAX	R + R REAR BUMPER	5.0	25.00
	INCLUDES: BOTH OUTER REAR LAMPS		
	REMOVE AND REFIT		440.00
87111R00	REAR SCREEN R + R	22.0	110.00
	INCLUDES: REAR SEAT BACKREST AND ALL		
	REQUIRED TRIMS REMOVE AND REFIT		
69200R00)	R + R BOOTLID	5.0	25.00
NO NUMBER	RENEW L/R SIDE PANEL	72.0	360.00
85875R00)	R + R L/R SILL MOULDING	1.0	5.00
68869R00)	R + R L/LOAD COMPARTMENT TRIM	1.0	5.00
85710R00	R + R BOOT CARPET	2.0	10.00
68869R0B)	R + R L/- AND R/BOOT TRIM (ADD)	2.0	10.00
1481	REPAIR LEFT FRONT DOOR	20.0*	100.00
2583	REPAIR REAR BUMPER	20.0*	100.00
LAB	OUR COST		
	Total Work Units	171.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	17.1HRS	\$855.00
	Paint Labour	11.3HRS	\$565.00
	Total Labour	28.4HRS	\$1,420.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Claim Reference: SHB8949E Full Report - V1
Assessment Number: MSIG0025 Registration: SHB8949E

Version: LKKAUTOC/2 Printed: 23/07/2018 14:02

Date Calculated: 23/07/2018 07:02

Guide N	lumbei	r Description - PREPARE OFF V - BASECOAT CLE		w	U	Cost Price (\$)
1781		L/R DOOR NEW PART PAIN		15.	.0	
3485		L/R OUTER SIDE PANELNEY		31.		
1481		LEFT FRONT DOOR REPAIR		17.		
2583		REAR BUMPER REPAIR PAIN		17.		
2000	IΔB	OUR COST - PAINT	11.12.10.12			
	LAD	TIME(PAINT)		80.	.0	
		Preparation Main Work F	Plastic	8.	53	
		Preparation Main Work		25.		
		Preparation Work Multi I		0.		
		Total Work Units (10WU		113.		
		Total Paintwork Labour	,,	100	3HRS	\$565.00
	мат	ERIAL COST - PAINT			51110	Cost Price
	PIA	New Part Painting				\$84.28
		Material-Constant Main	Nork Metal			\$28.60
		Repair Painting	WOIK MELAI			\$28.10
		Repair Painting Plastic				\$57.92
		Material-Const Main Wor	k Plastic		\$12.70	
						\$211.60
	Total Excluding Pearlescent Uplift Pearlescent Uplift @ 0.0%					\$0.00
		Total Paint Material Cost				\$211.60
PARTS		101411 41111 11111 1111 1111				
					Price V	alid: 01/06/2015
Guide N	lo.Qty	Description	Part Number	Supplier	Bet.	
1781	1	L/R DOOR	770032T000		0%	791.00*
1985	1	L/R DOOR FRM UP TRIM	831342T000		0%	0.00F
1987	1	L/R DOOR FRT MLDG	863812T000		0%	0.00F
4000		LID DO FOM FOT TOTAL	0242527000		00/-	0.005

PARIS					Price Val	id: 01/06/2015
Guide N	o.Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1781	1	L/R DOOR	770032T000		0%	791.00*
1985	1	L/R DOOR FRM UP TRIM	831342T000		0%	0.00F
1987	1	L/R DOOR FRT MLDG	863812T000		0%	0.00F
1983	1	L/R DR FRM FRT TRIM	831352T000		0%	0.00F
3485	1	L/R OUTER SIDE PANEL	715032TC00		0%	1,205.00*
1991	1	L/R UPP DOOR MLDG	838502T000		0%	0.00F
9559	1	L/R WHEEL COVER	529602T100		0%	116.00*
3160	1	REAR SCREEN BOND KIT	ZK20063001A		0%	0.00F
3163	1	REAR SCREEN FIX SET	USE SINGLE PARTS		0%	0.00
3173	2	REAR SCREEN SPACER	871143K000		0%	0.00F
3171	10	REAR SCREEN SUPPORTS	861143D000		0%	0.00F
f: OEM P	arts		Saving			\$196.45
g: Origin	nal		Sub Total			\$2,112.00
h: Secor			Deduction fro	om RRP	(35 %)	-\$739.20
p: Parall	el		Total Parts			\$1,372.80
x: Excha						

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extra	

Description		Betterment	Price
N/S DOOR STICKER	SPECIALIST	0%	\$100.00
REAR FENDER STICKER	SPECIALIST		\$60.00
RR FENDER COVER	SPECIALIST	0%	\$0.00
SEALANT	SPECIALIST		\$0.00

Claim Reference: SHB8949E

Full Report - V1

Assessment Number: MSIG0025

Registration: SHB8949E

Version: LKKAUTOC/2

Printed: 23/07/2018 14:02

Date Calculated: 23/07/2018 07:02

	Total Extras	\$160.00
Final Calculation		
Total Parts		\$1,372.80
Labour		
Total Panel/Mechanical	\$855.00	
Total Paintwork	\$565.00	
Total Labour		\$1,420.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$160.00	
Total of Additional Costs		\$160.00
Total Paint/Material Costs		\$211.60
Grand Total Excludes GST		\$3,164.40
GST @ 7 %		\$221.51
Grand Total Includes GST		\$3,385.91

Finalisad

SGD

TBA

18/07/2018

WHEEL COVER 16 INCH

BASECOAT CLEAR

408933

Claim Reference: SHB8949E Assessment Number: MSIG0025

Version: LKKAUTOC/4

Date Calculated: 03/08/2018 02:08

Full Report - V1 Registration: SHB8949E

Printed: 03/08/2018 09:08

Summary Information

Claim

Location:

Printed by:

Authorisation Status: Work Provider:

Claim Reference:

Policy Number: Other Reference:

Third Party:

Insured Amount: Under Warranty: Warranty Expired: Singapore (SG)

LKK AUTO Interim

MSIG Insurance

(Singapore) Pte

SHB8949E

LKK

KIA

April

2014

Optima

2836 01 SHB8949E

Not Known

BASE MODEL

Estimated Repair Time: Ouote Due Date:

Repairs Authorised:

Date of Incident:

Able to Authorise Repairs: TBA

Currency:

Actual Repair Days: Parts Ordered Date: Hire Car Start: Hire Car End: Vehicle Collected:

PREPARE OFF VEHICLE

Model Specs

FROM 01/2014

Vehicle Details

Vehicle

Manufacturer: Model:

Sub Model: Model Sheet Number:

Registration:

Registration Month:

Registration Year:

VIN Number:

Odometer:

Colour: Engine Number:

Fuel Level:

%

Vehicle Condition **Vehicle Status**

Pre-Accident Condition:

Steering:

Brakes Pedal Travel:

Place of Inspection: Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF: Tread Depth LHR:

Damage Areas:

Severity of Impact:

Vehicle Status on Inspection:

Date of Inspection:

20/07/2018

Tread Depth RHF: Tread Depth RHR:

Direction of Impact:

Claim Reference: SHB8949E


Full Report - V1 Registration: SHB8949E Printed: 03/08/2018 09:08

Assessment Number: MSIG0025

Version: LKKAUTOC/4

Date Calculated: 03/08/2018 02:08





Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR

Addresses

LABOUR

Cost Summary		
	Total Labour	\$1,420.00
	Total Paint/Material	\$211.60
	Total Parts	\$1,372.80
	Total of Additional Costs	\$160.00
	Excess:	TBA
	Grand Total Exc GST:	\$3,164.40
	7 % GST:	\$221.51
	Grand Total Inc GST:	\$3,385.91

Repair	· Informati	on
--------	-------------	----

LABOUR		Price/Dent	= \$50.00/HR
Repair /	- Bonair Details	wu	Cost Price (\$)
	r Repair Details RENEW L/R DOOR	18.0	90.00
77000R00	INCLUDES: R + R DOOR AND ALL NECESSARY		
	ATTACHED PARTS, RENEW IF NECESSARY		
07755000	R + R L/SILL TRIM	3.0	15.00
87755R00 86520R00 ZAX	•	5.0	25.00
8652UKUU ZAX	INCLUDES: BOTH OUTER REAR LAMPS		
	REMOVE AND REFIT		
87111R00	REAR SCREEN R + R	22.0	110.00
6/111KUU	INCLUDES: REAR SEAT BACKREST AND ALL		
	REQUIRED TRIMS REMOVE AND REFIT		
69200R00)	R + R BOOTLID	5.0	25.00
NO NUMBER	RENEW L/R SIDE PANEL	72.0	360.00
85875R00)	R + R L/R SILL MOULDING	1.0	5.00
68869R00)	R + R L/LOAD COMPARTMENT TRIM	1.0	5.00
85710R00	R + R BOOT CARPET	2.0	10.00
68869R0B)	R + R L/- AND R/BOOT TRIM (ADD)	2.0	10.00
1481	REPAIR LEFT FRONT DOOR	20.0*	100.00
2583	REPAIR REAR BUMPER	20.0*	100.00
	OUR COST		
	Total Work Units	171.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	17.1HRS	\$855.00
	Paint Labour	11.3HRS	\$565.00
	Total Labour	28.4HRS _	\$1,420.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Claim Reference: SHB8949E Full Report - V1
Assessment Number: MSIG0025 Registration: SHB8949E

Version: LKKAUTOC/4 Printed: 03/08/2018 09:08

Date Calculated: 03/08/2018 02:08

Guide I	Numbe	r Description - PREPARE OFF V - BASECOAT CLE		w	U	Cost Price (\$)
1781		L/R DOOR NEW PART PAIN	TING	15.	.0	
3485		L/R OUTER SIDE PANELNEY	V PART PAINTING	31.	.0	
1481		LEFT FRONT DOOR REPAIR	PAINTING <50%	17.	.0	
2583	583 REAR BUMPER REPAIR PAINT PLASTIC			17.	.0	
	LAB	OUR COST - PAINT				
		TIME(PAINT)		80.		
Preparation Main Work Plastic			8.			
		Preparation Main Work		25.		
		Preparation Work Multi I		0.		
	Total Work Units (10WU/HR) Total Paintwork Labour			113.0 11.3HRS		+505.00
						\$565.00
	MAT	ERIAL COST - PAINT				Cost Price
		New Part Painting				\$84.28
		Material-Constant Main	Work Metal			\$28.60
		Repair Painting			\$28.10	
		Repair Painting Plastic	1. ml			\$57.92
		Material-Const Main Wor				\$12.70
		Total Excluding Pearlesc				\$211.60 \$0.00
		Pearlescent Uplift @ 0.00				
		Total Paint Material Cost				\$211.60
PARTS					Price Va	alid: 01/06/2015
Guide N	No.Otv	Description	Part Number	Supplier	Bet.	
1781	1	L/R DOOR	770032T000	* *	0%	791.00*
1985	1	L/R DOOR FRM UP TRIM	831342T000		0%	0.00F
1987	1	L/R DOOR FRT MLDG	863812T000		0%	0.00 G
1983	1	L/R DR FRM FRT TRIM	831352T000		0%	0.00F
Tarbonia berrata						

					Price	e Valid	: 01/06/2015
Guide N	lo.Otv	Description	Part Number S	Supplier	В	et.	Price (\$)
1781	1	L/R DOOR	770032T000		0	%	791.00*
1985	1	L/R DOOR FRM UP TRIM	831342T000		0	%	0.00F
1987	1	L/R DOOR FRT MLDG	863812T000		0	%	0.00 G
1983	1	L/R DR FRM FRT TRIM	831352T000		0	%	0.00F
3485	1	L/R OUTER SIDE PANEL	715032TC00		0	%	1,205.00*
1991	1	L/R UPP DOOR MLDG	838502T000		0	%	0.00F
9559	1	L/R WHEEL COVER	529602T100		0	%	116.00*
3160	1	REAR SCREEN BOND KIT	ZK20063001A		0	%	0.00 G
3163	1	REAR SCREEN FIX SET	USE SINGLE PARTS		0	%	0.00
3173	2	REAR SCREEN SPACER	871143K000		0	%	0.00F
3171	10	REAR SCREEN SUPPORTS	861143D000		0	%	0.00F
f: OEM F	Parts		Saving				\$196.45
g: Origin			Sub Total				\$2,112.00
h: Secor			Deduction from	m RRP	(35%)		-\$739.20
p: Parall			Total Parts				\$1,372.80
x: Excha	ange						

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras	Description N/S DOOR STICKER REAR FENDER STICKER	SPECIALIST SPECIALIST	Betterment 0%	Price \$100.00 \$60.00
	RR FENDER COVER	SPECIALIST	0%	\$0.00
	SEALANT	SPECIALIST		\$0.00

Claim Reference: SHB8949E

Full Report - V1

Assessment Number: MSIG0025

Registration: SHB8949E

Version: LKKAUTOC/4

Printed: 03/08/2018 09:08

Date Calculated: 03/08/2018 02:08

	Total Extras	\$160.00
Final Calculation		
Total Parts		\$1,372.80
Labour		
Total Panel/Mechanical	\$855.00	
Total Paintwork	\$565.00	
Total Labour		\$1,420.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$160.00	
Total of Additional Costs		\$160.00
Total Paint/Material Costs		\$211.60
Grand Total Excludes GST		\$3,164.40
GST @ 7 %		\$221.51
Grand Total Includes GST		\$3,385.91

Assessment Notes

Merimen e-Claims

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRA	-					1			
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj S	Submitted	Ins Auth'ed	Statu		
Main	18 Jul 2018		19 Jul 2018 16:26 Edit Adj Rpt	S\$2,500.00 Edit Estimates	1	,500.00 ew Rpt		Repo	ling for S ort icel Case	urvey
	Main	R	eference	Claim	Details		Documen	its	1_	Show All
CLAIM SU	BFOLDER D	ETAILS				[Created	by insurer]			
Insured:	Natrad F	Natrad Food Private Limited, Co. Reg. No.: 197900348G								
Main Claimant:	PREMIER	TAXIS PTE LTD,	Co. Reg. No.: 20	0304975H						
Vehicle Reg No.:	SHB894	19E		Date	of Loss:		8 10:00 - :59 s and 23 Days F	rom LTA Re	eg Date (Man Yr)]
Claim Type	TP / 564	1764		Policy Note	/Cover No.:		MKC (Compreher 20/11/2017 - 1			
Vehicle Reg No. (Insured):	GBD4908	к		Policy (Clair	No. mant):					
				Exce	ss:					
Repairer:	Premier '	Taxis Pte Ltd (HC	2) 23 Changi South	Avenue 2, #04-0	3, 48644	3 Changi - T	el:			
Handling Insurer:		8 2 8	re) Pte. Ltd. (HQ							552]
Adjuster:	18/08/2	Consultants Pte 018]	Ltd (HQ) - Tel: 62	256-3561 [Hand	lled by K	ALVIN AND	G WEI KUN]	[Final R	pt due	
Adj Asg. Remarks:	SJE Agree	Please appoint LK	K and contact 6544	6676 / 65446689	Liability	(Non-report	ing)			
ASSOCIAT	TED MAIL RE	CEIVED					V	/iew All	Compose	Case Mail
There are r	no mail for this	case.								
ALL ASSO	CIATED TAS	sks⊟				View All	Search Tasks	Create Nev	v Task	Complete
Due Dat		Type Task	Group Subject	ct Handler	Assign	ned By	Completed Or	n Cre	ated On	Done

Claim Documents

*SHB8949E (564764) [GBD4908K] TP PREMIER TAXIS PTE LTD Jul 18 2018 10:00AM [Natrad Food Private Limited] **Premier Taxis Pte Ltd**

Let	ters/Corresponder	nces	1 per page		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbna	il Print	
1	19/07/18 10:30	Non Reporting Letter to OI	1 Load HTM	1	
Ass	essment Reports		1 per page		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	il Print	
1	23/07/18 14:12	Adjuster Immediate Advice	■ Load HTN	1	
Pho	otos/Images		3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna		
1	23/07/18 08:12	Front View	■ Load JPG	-	
2	23/07/18 08:12	Front View	■ Load JPG	_	
3	23/07/18 08:12	Front View	♠ Load JPG	-	
4	23/07/18 08:12	Front View	■ Load JPG	-	
5	23/07/18 08:12	Front View	1 Load JPG	1 -	
6	23/07/18 08:12	Front View	1 Load JPG	-	
7	23/07/18 08:12	Front View	Load JPG	V	
8	23/07/18 08:12	Front View	Load JPG	-	
9	23/07/18 08:12	Front View	1 Load JPG	V	
10	23/07/18 08:12	Front View	1 Load JPG	~	
11	23/07/18 08:12	Front View	1 Load JPG	-	
12	23/07/18 08:12	Front View	1 Load JPG		
13	23/07/18 08:12	Front View	Load JPG	V	
14	23/07/18 08:12	Front View	■ Load JPG	V	
15	23/07/18 08:12	Front View	1 Load JPG	V	
16	23/07/18 08:12	Front View	■ Load JPG	~	
17	23/07/18 08:12	Front View	■ Load JPG	~	
18	23/07/18 08:12	Front View	1 Load JPG	V	
19	23/07/18 08:12	Front View	1 Load JPG	~	
20	23/07/18 08:12	Front View	1 Load JPG	V	
21	23/07/18 08:12	Front View	■ Load JPG	V	
22	23/07/18 08:12	Front View	Load JPG	~	
23	23/07/18 08:12	Front View	1 Load JPG	V	
24	23/07/18 08:12	Front View	Load JPG	~	
25	23/07/18 08:12	Front View	Load JPG	V	
26	23/07/18 08:12	Front View	Load JPG	V	
27	23/07/18 08:12	Front View	Load JPG	V	
28	23/07/18 08:12	Front View	Load JPG	V	
29	23/07/18 08:12	Front View	1 Load JPG	V	
30	23/07/18 08:12	Front View	■ Load JPG	V	

Merimen e-Claims

Let	ters/Corresponde	ences	1 per	1 per page 🔻	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	The state of the s	Thumbnail	Print
31	23/07/18 08:12	Front View	0	Load JPG	~
32	23/07/18 08:12	Front View	0	Load JPG	✓
33	23/07/18 08:12	Front View	0	Load JPG	V
34	03/08/18 08:32	Reinspection Photo	O	Load JPG	✓
35	03/08/18 08:32	Reinspection Photo	0	Load JPG	V
36	03/08/18 08:32	Reinspection Photo	0	Load JPG	~
37	03/08/18 08:32	Reinspection Photo	0	Load JPG	V
Doc	umentation		1 per	page 🔻	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	19/07/18 10:39	PRI & THIRD PARTY ACCIDENT REPORT	0	Load PDF	
2	19/07/18 15:07	SJE AGREE - LKK	0	Load PDF	
3	27/07/18 13:09	SHB8949E	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG18013178/K1VD3E2

Date:

16/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

28638098MKC Policy No:

Claimant Vehicle SHB8949E No:

Insured Vehicle No:

GBD4908K

Date of Loss:

18/07/2018

Nature of Claim:

TP

Claim No: 564764

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHB8949E

Make & Model:

KIA OPTIMA, 1.7 D (A)

Engine No:

D4FDDH309682

Reg. Date: Colour:

25/04/2014 (Man. Year: 2013)

Chassis No: Odometer:

KNAGM414ME5462596 509992 km

Engine Capacity:

Silver 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size:

205/65 R16

Rear Tyre Size:

205/65 R16

Front Left Side: Front Right Side: Achilles 7 mm

Rear Left Side: Rear Right Side: Achilles 7 mm Achilles 7 mm

Achilles 7 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,921.79	1,532.80	388.99	20.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,631.60	1,631.60	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,553.39	3,164.40	388.99	10.95
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	3,553.39	2,500.00	1,053.39	29.64
+ GST 7.00/7.00% (S\$)	248.74	175.00	73.74	29.65
Nett Amount (S\$)	3,802.13	2,675.00	1,127.13	29.64

INSPECTION

Date of Assignment:

19/07/2018

Date Inspected:

20/07/2018 Inspected At:

Premier Taxis Pte Ltd (HQ)

23 Changi South Avenue 2, #04-03

Singapore 486443

Estimated Period of Repair:

4.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Aug 2018)

Parts: 143 KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB8949E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*L/R BUMPER BRACKET	Serviceable	29.00 FL	*-FL
2	1		*L/R DOOR	Dented	791.00 FL	*791.00 FL
3	1		*L/R DOOR FRM UP TRIM	Serviceable	2.44 FL	*-FL
4	1		*L/R DOOR FRT MLDG	Serviceable	9.80 FL	*-FL
5	1		*L/R DR FRM FRT TRIM	Serviceable	17.04 FL	*-FL
6	1		*L/R OUTER SIDE PANEL	Dented	1,205.00 FL	*1,205.00 FL
7	1		*L/R REFLECTOR	Serviceable	46.00 FL	*-FL
8	1		*L/R WHEEL COVER	Grazed	116.00 FL	*116.00 FL
9	1		*L/R WHEELHOUSE COVER	Serviceable	120.00 FL	*-FL
10	1		*LWR REAR WINDOW MLDG	Not Necessary	87.00 FL	*-FL
11	1		*REAR SCREEN BOND KIT	Not Necessary	80.81 FL	*-FL
12	1		*SET REAR SCREEN FIX (NPA)	Not Necessary	0.00 FL	*-FL
13	2		*REAR SCREEN SPACER	Not Necessary	7.20 FL	*-FL
14	10		*REAR SCREEN SUPPORTS	Not Necessary	15.30 FL	*-FL
15	1		*N/S DOOR STICKER	Necessary	100.00 FS	*100.00 FS
16	1		*REAR FENDER STICKER	Necessary	60.00 FS	*60.00 FS
17	1		*RR FENDER COVER CLIP	Not Necessary	28.00 FS	*-FS
18	1		*SEALANT	Not Necessary	50.00 FS	*-FS
19	1		*L/R UPP DOOR MLDG	Serviceable	63.86 FL	*-FL
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.	·-		
				Sub Total (S\$)	2,828.45	2,272.00
			- List Item Discount on L	. Items 35.00/35.00% (S\$)_	906.66	739.20
				Total Parts (S\$)	1,921.79	1,532.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TOTAL PANEL / MECHANICAL	New	855.00	855.00
2	TOTAL PAINTWORK	New	565.00	565.00
3	TOTAL PAINT / MATERIAL COSTS	New	211.60	211.60
		Gross Labour Cost (S\$)	1,631.60	1,631.60
	Report wa	as unsubmitted during this print-out.		

< END OF ESTIMATES >