

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0399/18
DATE : 14-JUN-2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BLDG
S(079120)
TEL : 64191891
FAX : 68357416
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : YEO AQUARIUM ENTERPRISES
ADDRESS : 210B PONGGOL SEVENTEENTH AVENUE

REG:7 LIM CHU KANG LANE 60 S(719764) S(829690)
TELEPHONE NO : 97719238

yeo-bh@hotmail.com

TYPE OF CLAIM : OO OR OO RECOVERY CLAIM
POLICY NO : 2100390889-03
VEHICLE NO : G804782E
MODEL CODE : SWS2RBFF24MRV-AA-A
MODEL/YEAR : CABSTAR 3.0 SMT ABS AIRBAG EU5
ENGINE NO : ZD30342526K
CHASSIS NO : JN1SC2F24Z0856574
MILEAGE : 1 KM
DATE IN : 14/06/2018
LIABILITY : 0.00
EXCESS/CLAUSE : 0.00
ESTIMATE BY : HAMZAH
ACCIDENT DATE : 14/06/2018

- Miss Yeo - 93703657
63866404

Spoken to Miss Yeo
on 4/7/2018 @ 9.15 am

Spoken to Miss Yeo
on 9/7/2018 @ 3.25 pm

13/7/2018 @ 3.05 pm -
update Miss Yeo

- driver cant speak english
its her dad

- 96450079

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO 8804782E

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOUR CHARGES TO CAB REAR PORTION, LH SIDE PILLAR LH WHEEL ARC, LH FRT DOOR AND LH SIDE CARRIER.	800.00	570
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME.	1200.00	720
3 ZZ/003	RENEW FRONT W/SCREEN GLASS.	150.00	
4 ZZ/004	RENEW REAR W/SCREEN GLASS.	150.00	✓
5 ZZ/005	RENEW ENGINE WIRING HARNESS.	240.00	✓
6 ZZ/006	RENEW DASHBOARD WIRING HARNESS.	240.00	Done
7 ZZ/007	RENEW ENGINE TURBO.	180.00	✓
8 ZZ/008	REMOVE AND INSTALL EXHAUST.	120.00	✓
9 ZZ/009	REMOVE AND INSTALL ENGINE ASSY TO RENEW CYLINDER HEAD AND GRIND VALVE.	610.00	✓
10 ZZ/011	TOWING CHARGES BY ENG BEE RECOVERY W/O 200 208236	120.00	
11 ZZ/10	REMOVE AND INSTALL DASHBOARD.	240.00	Done
TOTAL LABOUR CHARGES		4050.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBO4782E

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	SUNRISER	APN		200.00 50
2	OIL COOLER	21305-LC30C		998.40
3	FRT CAB LOWER HEAT INSULATOR	74280-M021A	291.30	
4	REAR W/SCREEN W/STRIP	79710-0T000	✓ 84.40	
5	REAR W/SCREEN GLASS	79712-5T000	✓ 124.00	
6	INSULATOR FLOOR	05930-B9904	✓ 126.10	
7	HEAT INSULATOR FLOOR	74750-M020A	✓ 118.70	
8	INSULATOR TILT BRACKET LH	95520-MA00A	✓ 70.40	
9	BRACKET-LH FRT CAB TILT	95121-MA70B	✓ 434.80	
10	BUMPER RUBBER SIDE CARRIER	93315-TB101	✓ 8.90	
11	COVER RETRACTOR	87840-MA000	✓ 19.30	
12	LH MUD FLAP LH FRONT	63115-MA00A	58.90	
13	LH MUD FLAP GARNISH FRONT	63101-MA000	187.90	
14	LH MUD FLAP BRKT SEAL	63820-MA00A	✓ 15.50	
15	LH MUD FLAP BRACKET LH	16581-MA00A	✓ 32.00	
16	AIR CLEANER SUPPORT FRONT	16573-MA000		✓ 18.40
17	AIR CLEANER SUPPORT BRKT	16574-MA000		✓ 81.00
18	DUCT AIR CLEANER	16567-MA000		✓ 205.80
19	BATTERY TERMINAL CONNECTOR	24340-JA74A		✓ 20.10
20	CABLE BATTERY-EARTH	24080-MA001	✓ 81.70	
21	HARNESS WIRE AIR CLEANER TO TAIL	24015-MA000	✓ 285.10	
22	BRACKET-FUSE	24135-MA00A		✓ 19.30
23	BRACKET-RELAY	24383-51E00		✓ 21.50
24	DASHBOARD WIRE HARNESS	24013-MC900	2642.90 Chale	
25	ENGINE-CHASSIS WIRE HARNESS	24014-MC90C	✓ 2636.50	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBD4782E

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
26	AIR-FUEL RATIO SENSOR	226A3-VZ20B		✓ 693.00
27	EXHAUST GAS TEMP SENSOR	22640-LC30B		✓ 365.00
28	ENGINE CONTROL MODULE	23710-MQ21E		1451.20 Chale
29	GLOW PLUG RELAY	25230-80A0A		✓ 276.00
30	ROCKER COVER OIL SEAL @ \$17.20 EACH	13276-D8000		✓ 68.80
31	GLOW PLUG @ \$89.40 EACH	11065-LC30A		✓ 357.60
32	OIL COOLER O RING	21304-2W200		✓ 20.60
33	WATER HOSE	14056-MA70B	✓ 19.50	
34	HEATER PIPE	21022-MQ20A		✓ 116.80
35	WATER HOSE	21047-MA70A	✓ 19.50	
36	HEATER PIPE	21022-MA70C		✓ 70.10
37	INJECTION PUMP GASKET	16701-MA71A		✓ 14.20
38	FUEL INJECTION PUMP	16700-LC30B		3784.10
39	HOSE ASSY-FUEL	17520-LC30C	✓ 39.60	
40	TUBE-INJECTION	16684-LC30A	✓ 98.40	
41	TUBE-INJECTION	16681-LC30A	✓ 61.10	
42	TUBE-INJECTION	16680-LC30A	✓ 61.10	
43	TUBE-INJECTION	16683-LC30A	✓ 61.10	
44	FUEL RAIL TEMPERATURE SENSOR	22630-LC30A		✓ 65.20
45	HOSE-FUEL	A6440-N7686	✓ 151.40	
46	CLAMP-HOSE NOZZLE @ \$4.70 EACH	16439-16E0A		✓ 18.80
47	NOZZLE & HOLDER	A6600-MQ20A		1330.10 Chale
48	TUBE-FUEL SPILL	16672-LC30A	✓ 56.30	
49	TUBE ASSY-FUEL RAIL	17520-LC30A	✓ 1370.30	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO 8804782E

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
50	HOSE AIR DUCT-AIR CLEANER	16578-M020A	✓ 498.50		
51	AIR CLEANER ASSY	16500-MA71B	✓ 831.10		
52	DIESEL STRAINER	16400-M020A		✓ 142.50	
53	GASKET-THROTTLE CHAMBER	16175-MA70A		✓ 11.40	
54	ADAPTOR	16576-MA70A		444.70	Chale
55	GASKET-EGR TUBE	14722-V540A		✓ 19.90	
56	VALVE ASSY-EGR	14710-MA70A		672.70	Chale
57	GASKET-EGR PIPE	14719-43G02		✓ 5.70	
58	GASKET-EGR TUBE	14722-EC00A		✓ 19.90	
59	COOLER ASSY-EGR	14735-V290A		439.20	Chale
60	EGR TUBE ASSY	14725-M020A	✓ 89.20		
61	GASKET-TUBE OUTLET	13050-LC30A		✓ 2.00	
62	TUBE ASSY-WATER OUTLET	14498-LC30A	✓ 84.40		
63	HOSE-WATER	14056-MA72A	✓ 38.90		
64	TURBO CHARGER OIL OUTLET	15197-MA70A		✓ 83.00	
65	HOSE-SUCT AIR	14468-M020A	✓ 240.00		
66	TUBE ASSY-INLET	14460-LC20A		✓ 144.00	
67	CLAMP-HOSE	14464-BN303		✓ 24.30	
68	HOSE-AIR INLET	14463-M020A		✓ 106.20	
69	BRKT-AIR INLET	14467-MA70A		✓ 61.60	
70	HOSE-AIR INLET	14463-MA71B		✓ 106.20	
71	TURBO CHARGER INLET TUBE	14465-MA70A		✓ 8.60	
72	TUBE TURBO CHARGER OIL FEED	15192-MA70A	✓ 79.50		
73	OUTLET-EXHAUST TURBO	14440-MA73A		✓ 389.40	
74	TURBO CHARGER	14411-LC30B		✓ 3074.90	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO G804782E

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
75 TUBE ASSY-SUCTION	14469-MA73A	✓ 156.80		
76 ACTUATOR-POWER VALVE	14517-MA70A		✓ 146.90	
77 GASKET-MANIFOLD INTAKE	14035-MA70A		✓ 91.10	
78 EXHAUST MANIFOLD GASKET	14036-VE300		✓ 91.10	
79 HOSE-AIR INLET GAS	11821-LC20B	✓ 35.90		
80 BELT-FAN	11720-MA70B		111.00	
81 BRACKET ENGINE MNTH LH	11233-VK100		69.20 Chale	
82 BRACKET ENGINE MNTH RH	11232-MC000		11.30 Chale	
83 INSULATOR ENGINE-MYNG FRT	11220-MC00B		✓ 87.90	
84 ENGINE OVERHAUL GASKET	ADA01-MA70A		✓ 418.40	
85 ROCKER COVER GASKET	13270-MA70A		✓ 59.90	
86 CYLINDER HEAD GASKET	11044-MA70A		✓ 134.50	
87 CYLINDER HEAD	11039-LC30B	2019.30 Chale		
88 ROCKER COVER OIL REFILL CAP	15255-21B00		18.60	
89 ENGINE ROCKER COVER	13264-LC30A		✓ 258.60	
SUB TOTAL		15903.00	19.30	17466.70
LESS DISCOUNT (NETT-30.00%, LIST-45.00%, S/NETT-10.00%)		4770.90	8.68	1746.67
GRAND TOTAL		11132.10	10.62	16720.03
OVERALL TOTAL		26862.75		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO G8D47B2E

TOTAL LABOUR CHARGES	4050.00
TOTAL SPARE PARTS CHARGES	26862.75

GRAND TOTAL	30912.75 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:	KAR CHENG - ALG
SURVEYED DATE	:	28/06/18 @ 1528hrs
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	5.00
LIABILITY	:	0.00
REMARKS	:	\$ 800/ T&A

AS per
Not Authorized Repair
18 days repair

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

FIRE INVESTIGATION INTERVIEW

- Where and what time did the fire occur?

About 3 to 3.30 pm at PIE near Lornie Road.

- Where were you from and where were you going?

From Lim Chu Kang to Bedok.

- Were you alone in the vehicle?

Yes.

- Which side of the vehicle did the smoke and fire come from?

Left side.

- Where exactly was the fire? Which part of the vehicle was on fire?

Just behind the front wheel.

- What did you do after you saw the fire?

I stopped vehicle at the side and quickly pour some water on the fire. The water put out some fire. I also use cloth to beat fire out.

- Did you put out the fire yourself or did you call the SCDF?

I put out the fire myself. The SCDF came and also did some spraying after that.

- Did anybody else help you?

A passer-by.

- Were there any police at the location?

Police came later.

- If you called the SCDF, what time did the SCDF arrive?

About 20-30 minutes later.

- How long did the fire fighters take to put out the fire?

The fire was already put out before that.

- What did you do after the fire was put out?

Was waiting for help.

- Did you call your insurance and make towing arrangements?

Yes. Towing vehicle came at that time.

- What time did the tow truck come?

Just after fire was put out.

- Where was the vehicle towed to?

Towed to a carpark at Aljunied.

- Did you make a police report?

We wanted to make report but the police came said there was no need.

- Did you take pictures of the fire and after the fire was put out?

No.

- Did you buy this vehicle new or second hand?

New.

- Are you the only driver for this vehicle?

Yes.

- Does anybody follow you when you do deliveries?

No.

- How often do you service this vehicle?

Regularly service, about once in 3-4 months.

- When was the last servicing for this vehicle?

2 month ago

- Do you keep the servicing records?

No record upkeep.

- Has the vehicle been giving any problems?

No.

- Was there anything wrong with the vehicle on the day of incident?

Nothing.

- Were there any warning lights or overheating lights displayed on the speedometer?

No.