



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLP2337P
Make & Model : HYUNDAI, ELANTRA AD 136 GLS
AT, KMHD841CMJU464798
Year of Manufacture : 2017

Estimation No. : E18070024
DOA : 17/07/2018

No	Description	Qty	U/P	Amt
21	Rear door inner trim board clips (LH) X NN	1.00	50.00	50.00

Amt S\$ 50.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 50.00

Section: Labour Items

22	To R&R accident affected areas	1.00	600.00	600.00 400
23	To putty & respray accident affected areas	1.00	600.00	600.00 400
24	To rust proof accident affected areas	1.00	60.00	60.00 X NN
25	To R&R front door mechanism	1.00	80.00	80.00 60
26	To R&R rear door mechanism	1.00	80.00	80.00 60
27	To check for water seepage	1.00	60.00	60.00 X NN

Amt S\$ 1,480.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 1,480.00 920

4 Days.

Insurance Rep
part by part.

After paint photos.

Quo Q: 4 - 82880282
26/7/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

List Items Subtotal S\$ 0.00
Special Nett Items Subtotal S\$ 50.00
Labour Items Subtotal S\$ 1,480.00
Total S\$ 1,530.00

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLP2337P
Make & Model : HYUNDAI, ELANTRA AD 136 GLS
AT, KMHD841CMJU464798
Year of Manufacture : 2017

Estimation No. : E18070024
DOA : 17/07/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Front door (LH) <i>X Repair</i>	1.00	0.00	0.00
2	Front door lock (LH) <i>X</i>	1.00	0.00	0.00
3	Front door handle (LH) <i>X</i>	1.00	0.00	0.00
4	Front door weather strip (LH) <i>X</i>	1.00	0.00	0.00
5	Front door window garnish - black (LH) <i>X</i>	1.00	0.00	0.00
6	Front door window moulding (LH) <i>X</i>	1.00	0.00	0.00
7	Front door window chrome strip (LH) <i>X</i>	1.00	0.00	0.00
8	Rear door (LH) <i>X Repair</i>	1.00	0.00	0.00
9	Rear door hinge-up (LH) <i>X</i>	1.00	0.00	0.00
10	Rear door hinge-down (LH) <i>X</i>	1.00	0.00	0.00
11	Rear door checker (LH) <i>X</i>	1.00	0.00	0.00
12	Rear door weather strip (LH) <i>X</i>	1.00	0.00	0.00
13	Rear door lock (LH) <i>X</i>	1.00	0.00	0.00
14	Rear door window garnish - black (LH) <i>X</i>	1.00	0.00	0.00
15	Rear door window chrome strip (LH) <i>X</i>	1.00	0.00	0.00
16	Rear door window moulding (LH) <i>X</i>	1.00	0.00	0.00
17	Rear door power window motor (LH) <i>X</i>	1.00	0.00	0.00
18	Rear door power window gear (LH) <i>X</i>	1.00	0.00	0.00
19	Rear door inner trim board (LH) <i>X</i>	1.00	0.00	0.00
20	Side skirt / rocker panel (LH) - repair	1.00	0.00	0.00
				Amt S\$ 0.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 0.00

Section: Special Nett Items

Continue on next page...