

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 2575J

DATE 19/7/2018 9:46

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Sonata Plate ✕			\$ 43.60	
	Boot Lid Hyundai Plate ✕			\$ 24.20	
	Boot Lid 'H' Emblem ✕			\$ 26.10	
	Boot Lid CRDI Plate ✕			\$ 22.70	
	Rear Bumper ✓			\$ 578.40	
	Rear Bumper Reinforcement ?			\$ 483.30	
	Rear Bumper Clip ✓			\$ 22.00	
	Rear Bumper Sponge ?			\$ 137.40	
	Rear Bumper Under Cover ?			\$ 185.80	
	Rear Bumper Protector (RH) ✕ <i>14.2</i>			\$ 38.00	
	Tail Lamp (RH) ✓			\$ 344.00	
	Rear Fender (RH) ✕ <i>14.2</i>			\$ 1,935.90	
	Rear Fender Inner Lining (RH) ✕			\$ 74.10	
	Rear Windscreen Moulding ✕			\$ 60.00	
	SUB TOTAL			\$ 3,975.50	
	LESS 20%			\$ 795.10	
	DISCOUNTED TOTAL			\$ 3,180.40	
	Boot Lid Comfort Logo & Tel No. Sticker ✕			\$ 30.00	Nett
	Boot Lid Advertisement Logo ✕			\$ 100.00	Nett
	Rear Bumper Reverse Sensor ✓			\$ 135.70	Nett
	Rear Bumper Advertisement Logo ✓			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00	Nett
	Rear Fender Comfort Sticker (RH) ✓			\$ 30.00	Nett
	Rear Windscreen Sealant ✕			\$ 46.00	Nett
				\$ 591.70	
	Labour Charge				
	Panel Beating			\$ 850.00	
	Spray Painting Charge-Bootlid/Bumper/Fender			\$ 750.00	400
	Wiring Charge			\$ 50.00	20
	Tuff Kote			\$ 50.00	20
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	50
	Remove/Refix Rear Windscreen Glass			\$ 120.00	X
	Remove/Refix Reverse Sensor			\$ 120.00	20
	TOTAL LABOUR			\$ 2,090.00	
	ESTIMATE TOTAL			\$ 5,862.10	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Signature: _____ Date: _____					