



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lion City Rentals Pte Ltd.	Cust No/Name /Lion City Rentals Pte Ltd
60 Anson Road	Reg No/Reg Date SLF2481H / 19/08/201
#11-01 Mapletree Anson	Date In/Mileage / 0
Singapore 079914	Chassis No MMBSTA13AHH002434
Contact No Mobile: 67420984	Engine No 3A92UDJ8783
	Make/Model MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	19/07/2018/ 16:52		465 / Tay Jian Ye	28584		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							100 1650.00
TO RENEW FRT BUMPER , FRT LH FENDER,							✓ 840.00
E PNT98000							30 50.00
PAINT WORK SPRAY FRT BUMPER , FRT LH FENDER							✓ 200.00
A 54900099							40 50.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							X 80.00
A 10028901							btv 50.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							✓ 150.00
USING HI-SCAN PRO TEST							20 50.00
M SUNDRY							de 696.00
TO APPLY ANTI COROSSION							at 126.00
M SUNDRY							X 62.00
TO APPLY BODY SEALANT							nel 13.00
M SUNDRY							nel 30.00
TO SUPPLY FRT NUMBER PLATE WITH FRAME							? 136.00
M SUNDRY							cin 654.00
ACCIDENT TOWING							ht 458.00
M SUNDRY							de 97.00
SUNDRIES							
M	FACE,FR BUMPER		1.00	696.00	00.00		
M	GARNISH,FR BUMPER,LH		1.00	126.00	00.00		
M	COVER,HEADLAMP SUPT PANEL		1.00	62.00	00.00		
M	BRACKET,FR BUMPER,LH		1.00	13.00	00.00		
M	CLIP,FR BUMPER		10.00	3.00	00.00		
M	REINFORCEMENT,FR BUMPER		1.00	136.00	00.00		
M	HEADLAMP ASSY,LH		1.00	654.00	00.00		
M	FENDER,FR LH		1.00	458.00	00.00		
M	SHIELD,FR WHEELHOUSE,LH		1.00	97.00	00.00		

Estimate

SURVEYOR NAME: Tan Jiah 97445749

SURVEYOR SIGNATURE: [Signature]

DATE: 23/7/18 @ 1400

REMARKS: Money before paint
sur @ [unclear] com
4 days

100 1650.00

✓ 840.00

30 50.00

✓ 200.00

40 50.00

X 80.00

btv 50.00

✓ 150.00

20 50.00

de 696.00

at 126.00

X 62.00

nel 13.00

nel 30.00

? 136.00

cin 654.00

ht 458.00

de 97.00

Estimate

SURVEYOR NAME: Tanjiluh 97453749SURVEYOR SIGNATURE: [Signature]DATE: 23/7/18 @ 1400REMARKS: Resurvey before paintsw & Inkantocom4 days

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

7% GST on **Nett** 5,392.00 377.44

Total Payable 5,769.44

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.