



EUROKARS HABITAT PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
ESTIMATE COST OF REPAIRS



AXA INSURANCE PTE LTD		NAME : Ms Ying Shun Shi Jaslyn	WIP : 20472
8 SHENTON WAY		ADDRESS : 76 Jalan Greja	EXCESS :
#24-01 AXA TOWER		Singapore 488939	DATE: 19-Jul-18
SINGAPORE 068811			
ATTN. :	MOTOR CLAIM DEPT	TEL : 81136232	(98582814 Mrs. Amy)
FAX :	68804838 / 68804739		

VEH NO :	SKT8926R	DATE IN :		CONTACT PERSON :	JOBI THOMAS 6360 2446
CHASSIS NO :	WMWXS520502B40617	MILEAGE :		TYPE OF CLAIM :	TP AGAINST XE2114G
MODEL :	F55 COOPER	DATE REG.:	25.06.2015	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description			REVISED	PRICES
	QTY				
1	BONNET	1	M41.00.7.374.519	PA ✓	\$ 1,234.94
2	BONNET ADJUSTER	1	B51.76.7.183.752	NA ✓	\$ 7.69
3	BONNET TWIST PROTECTOR	2	M51.23.7.300.579	NA ✓	\$ 17.50
4	BONNET INSULATOR CLIP	15	B51.48.9.119.216	NA ✓	\$ 15.00
5	TRIM RING LH	1	M51.13.7.300.631	NA ✓	\$ 68.94
6	TRIM RING RH	1	M51.13.7.300.632	NA ✓	\$ 68.94
7	TRIM RING CLIP	12	M51.13.2.752.145	NA ✓	\$ 44.28
8	BONNET / FENDER TRIM	1	M51.13.7.424.554	NA ✓	\$ 258.00
9	FRONT DOOR OUTER TRIM	1	M51.33.7.322.514	cut ✓	\$ 90.00
10	REAR DOOR OUTER TRIM	1	M51.35.7.322.526	X	\$ 90.00
11	MINI EMBLEM	1	M51.14.7.316.703	NA ✓	\$ 73.88
12	WING MIRROR HOUSING RH	1	M51.16.7.401.096	SEA ✓	\$ 680.56
13	FRONT FENDER RH	1	M41.00.7.374.522	PA ✓	\$ 492.63
14	FRONT FENDER BRACKET	1	M41.00.7.374.528	REC ✓	\$ 34.06
15	FRONT FENDER BRACKET	1	M41.00.7.389.468	NA ✓	\$ 33.50
16	FRONT FENDER BRACKET	1	M41.00.7.389.472	NA ✓	\$ 33.50
17	FRONT FENDER BRACKET	1	M41.00.7.389.466	NA ✓	\$ 33.50
18	FRONT FENDER BRACKET	1	M41.00.7.389.489	NA ✓	\$ 33.50
19	WING MIRROR COVER RH	1	M51.16.7.401.232	SEA ✓	\$ 93.44
20	WING MIRROR GROMMET	2	M51.16.9.905.223	NA ✓	\$ 5.50
21	WING MIRROR CLIP	1	M51.16.2.755.643	NA ✓	\$ 3.81
22	FRONT DOOR RH	1	M41.00.7.327.446	PA ✓	\$ 1,136.19
23	FRONT DOOR CHECKER RH	1	M51.21.7.328.595	?	\$ 84.19
24	FRONT DOOR BOLT	4	B07.14.7.248.303	NA ✓	\$ 13.00
25	FRONT DOOR SCREW	4	B51.22.6.976.687	NA ✓	\$ 8.76
26	DOOR SOUND INSULATOR	1	M51.48.8.165.271	NA ✓	\$ 128.69
27	FRONT WHEEL ARCH RH	1	M51.77.7.300.820	SEA ✓	\$ 169.63
28	WHEEL ARCH CLIP	1	B07.14.9.126.886	NA ✓	\$ 2.19
29	FRONT FENDER INNER SHIELD RH	1	M51.71.7.290.790	DB ✓	\$ 143.75
30	INNER SHIELD EXPANDING NUT	8	B07.14.7.201.307	NA ✓	\$ 13.52
31	INNER SHIELD EXPANDING RIVET	2	B07.14.7.136.172	NA ✓	\$ 1.88
32	FRONT DOOR HANDLE RH	1	M51.21.7.434.538	SEA ✓	\$ 167.63
33	FRONT DOOR HANDLE COVER CAP RH	1	M51.21.7.431.945	X	\$ 67.00
34	DOOR HANDLE SEAL	2	M51.21.7.405.768	NA ✓	\$ 26.00

35	DOOR HANDLE GASKET	2	M51.21.7.317.426	neu /	\$ 37.12
36	DOOR CARRIER	2	M51.21.7.296.458	?	\$ 227.56
37	FRONT DOOR CARRIER BRACKET	1	M51.21.7.316.360	?	\$ 23.38
38	DOOR LOCK CABLE	2	M51.21.7.331.286	X	\$ 85.62
39	DOOR LOCK CABLE CIRCLIP	2	M51.22.1.817.032	RM /	\$ 8.38
40	FRONT DOOR RUBBER GUIDE	1	M51.33.7.322.516	X	\$ 109.31
41	FRONT DOOR CHANNEL SEAL	1	M51.35.7.322.530	X	\$ 61.19
42	FRONT DOOR FOAM RUBBER	1	M51.35.7.410.482	X	\$ 17.94
43	FRONT DOOR COVER PANEL	1	M51.33.7.338.842	X	\$ 20.88
44	FRONT DOOR SEAL A PILLAR	1	M51.76.7.322.456	neu /	\$ 59.13
45	FRONT DOOR WEATHERSTRIP RH	1	M51.72.7.322.511	X	\$ 173.75
46	FRONT DOOR LOWER RUBBER SEAL	1	M51.76.7.322.508	?	\$ 34.75
47	FRONT DOOR WEATHERSTRIP RH	1	M51.33.7.409.358	?	\$ 333.69
48	FRONT DOOR WINDOW MOTOR	1	M67.62.7.405.702	?	\$ 312.06
49	FRONT DOOR MOUNTING KIT	1	M51.33.7.388.688	?	\$ 24.88
50	FRONT DOOR T-HEAD BOLT	2	B51.33.7.184.604	neu /	\$ 27.26
51	FRONT DOOR CLIP	2	M51.21.7.040.545	neu /	\$ 11.12
52	REAR DOOR RH	1	M41.00.7.327.450	RA /	\$ 1,136.19
53	REAR DOOR CHECKER RH	1	M51.22.7.322.423	?	\$ 84.19
54	REAR DOOR HANDLE RH	1	M51.21.7.317.636	neu /	\$ 134.13
55	REAR DOOR HANDLE CABLE	1	M51.22.7.331.287	X	\$ 42.81
56	REAR DOOR GUIDE RUBBER	1	M51.35.7.322.444	at /	\$ 128.06
57	REAR DOOR SEAL	1	M51.33.7.337.034	X	\$ 23.19
58	REAR DOOR CLIP	2	M51.33.7.162.282	neu /	\$ 2.00
59	REAR DOOR INNER WEATHERSTRIP	1	M51.35.7.322.532	neu /	\$ 61.19
60	REAR DOOR SEAL B PILLAR	1	M51.76.7.322.458	at /	\$ 64.31
61	REAR DOOR SEAL CLIP	5	M51.76.7.412.895	neu /	\$ 8.45
62	REAR DOOR LOWER RUBBER SEAL	1	M51.76.7.327.314	?	\$ 34.75
63	REAR DOOR WEATHERSTRIP RH	1	M51.72.7.322.523	X	\$ 173.75
64	REAR DOOR SEAL END COVER	1	M51.35.7.338.844	X	\$ 28.88
65	REAR FENDER ARCH RH	1	M51.77.7.318.830	neu /	\$ 101.81
66	REAR DOOR ARCH RH	1	M51.77.7.329.032	neu /	\$ 86.88
67	REAR FENDER INNER SHIELD RH	1	M51.71.7.290.768	neu /	\$ 143.75
68	FRONT DOOR QUARTER GARNISH RH	1	M51.47.7.322.510	neu /	\$ 30.38
69	FRONT COLUMN COVER RH	1	M51.13.7.329.050	X	\$ 85.44
70	B PILLAR COLUMN COVER RH	1	M51.35.7.322.518	neu /	\$ 91.75
71	REAR DOOR QUARTER GARNISH RH	1	M51.35.7.322.446	neu /	\$ 54.75
72	COLUMN COVER CLIP	6	M07.13.1.504.184	neu /	\$ 6.00
73	REAR FENDER COLUMN COVER RH	1	M51.13.7.328.874	X	\$ 81.38
74	SPORT RIM	2	M36.11.6.855.103	neu /	\$ 1,474.38
75	ENGINE MOUNT RH	1	B22.11.6.885.934	?	\$ 248.19
76	ASA-BOLT	3	B22.11.6.858.061	?	\$ 24.93
77	TORX SCREW,	3	M07.12.9.908.650	?	\$ 19.50
78	ENGINE MOUNT LH	1	M22.11.6.885.778	?	\$ 112.25
79	ASA-BOLT	1	B31.10.6.868.038	?	\$ 11.38
80	ENGINE MOUNT REAR	1	B22.31.6.853.453	?	\$ 248.19
81	HEXAGON SCRE	1	B07.12.9.908.653	?	\$ 5.75
82	ASA-BOLT	3	B22.31.6.858.990	?	\$ 27.57
83	ASA-BOLT	4	B22.31.6.864.386	?	\$ 23.24
84	SIGNAL LAMP RH	1	M63.13.7.298.348	CRA /	\$ 91.31
85	BULB	1	M63.21.7.381.759	short /	\$ 23.94

86	FRONT FENDER RUBBER	1	M51.76.7.300.564	X	\$	31.44
87	FRONT FENDER SEAL	1	M51.76.7.297.242	ME /	\$	20.00
88	FRONT FENDER SEAL CLIP	3	M51.71.8.153.561	NE /	\$	12.93
89	DOOR TRIM CLIP	6	M51.25.2.753.575	NE /	\$	11.64
90	DOOR TRIM EXPANDING NUT	4	B07.14.7.265.039	NE /	\$	11.76
91	DOOR TRIM RIVET	6	M65.13.8.387.414	NE /	\$	7.50
TOTAL PARTS					\$	11,953.56
					\$	-
TOTAL PARTS COST					\$	11,953.56
Labour Description						
1	TO REMOVE / REPLACE BONNET, FRT FENDER RH, RH FRT / REAR DOOR		5.5 (840)	4620	\$	5,040.00
	RH WING MIRROR ASSY & TO REPAIR REAR FENDER RH AREAS AFFECTED BY THE ACCIDENT.					
2	TO RESPRAY BONNET, RH FRT FENDER, RH FRT / REAR DOOR & RH REAR FENDER.		(800) 5	4000	\$	4200.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.			150	\$	250.00
4	TO REMOVE / REPLACE THE ENGINE MOUNTING.			NETT 840?	\$	1,000.00
5	TO REPLACE 1 PC TYRE 195/55 R16			NETT 80% WAT / 384	\$	480.00
6	TO MOUNT 2 PC SPORT RIM AND CONDUCT WHEEL BALANCING.			NETT 200	\$	240.00
7	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.			NETT	\$	560.00
8	TO TRANSFER THE RH FRT / REAR DOOR MECHANISM.			840	\$	1000.00
9	TO INSTALL THE BONNET STICKER.			NETT	\$	350.00
10	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			150	\$	250.00
11	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			250	\$	350.00
12	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.			NETT	\$	200.00
13	SUNDRIES.			NETT	\$ 50	100.00
TOTAL LABOUR				\$	-	\$ 14,020.00
TOTAL PARTS				\$	-	\$ 11,953.56
TOTAL				\$	-	\$ 25,973.56
LESS EXCESS				\$	-	\$ -
TOTAL AFTER EXCESS				\$	-	
GST 7%				\$	-	\$ -
GRAND TOTAL				\$	-	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL

BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A
QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED
IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul

Hp 90010068

15 days

20/07/18 @ 1545

Resury b & paint