

REPAIR ESTIMATE*

VEHICLE NO : SHC3917A

DATE 19. Jul. 2018

MAKE : HYUNDAI

MODEL : i40

DOA: 18. Jul. 2018

EQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT FENDER – RH <i>x mpr</i>			\$619.00
1	FRONT DOOR – RH ✓			\$1,403.00
1	REAR DOOR – RH <i>x mpr</i>			\$1,351.10
SUB TOTAL				\$3,373.10
LESS 20%				\$674.62
DISCOUNTED TOTAL				\$2,698.48
1	Front Fender Advertisement Logo – RH ✓			\$100.00
1	Front Door Advertisement – RH ✓			\$100.00
1	Rear Door Advertisement – RH ✓			\$100.00
1	Rear Fender Advertisement – RH ✓			\$100.00
				Nett
				\$400.00
Labour Charge				
1	Panel Beating			\$800.00 <i>400</i>
1	Spray Painting Charge			\$1,000.00 <i>600</i>
1	Wiring Charge			\$100.00 <i>x</i>
1	Tuff Kote			\$100.00 <i>20</i>
1	Transfer of Door			\$300.00 <i>50</i>
TOTAL LABOUR				\$2,300.00
ESTIMATE TOTAL				\$5,398.48
<i>Kahn LKK</i> <i>19/7/18 1020 L</i> <i>2 Pys</i> <i>4/5</i> <i>After Repair ph</i> LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from insurance company Acknowledged by Repairer Signature: _____ This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor surveyor appointed by the insurance company.				