

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHC2449R

DATE: 19. Jul. 2018

MAKE : HYUNDAI

MODEL : SONATA

DOA: 17. Jul. 2018

EQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper <i>X repair</i>			\$578.40
1	Rear Bumper Protector – RH <i>X repair</i>			\$38.00
10	Rear Bumper Clips <i>X</i>		\$2.20	\$22.00
SUB TOTAL				\$638.40
LESS 20%				\$127.68
DISCOUNTED TOTAL				\$510.72
1	Advertisement – Rear Bumper <i>✓</i>			\$50.00
2	Advertisement – Rear Fender – RH/LH <i>✓</i>		\$100.00	\$200.00
				\$250.00
Labour Charge				<i>100</i>
Panel Beating				<del>\$250.00</del>
Spray Painting Charge				<del>\$250.00</del>
				<i>200</i>
TOTAL LABOUR				\$500.00
ESTIMATE TOTAL				\$1,260.72
<i>Kahin 100%</i> <i>19/7/18 1100h.</i> <i>2 Days</i> <i>4/5</i> <i>After Repair photo</i>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Larry Ng

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

 Signature:  
 Date: