

To Survey by U.K.K.I

LONPAC

Page 1 of 3

SHC 267L

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>BT</i>			\$ 1,349.50	✓
	Boot Lid Rubber <i>deformed</i>			\$ 110.90	✓
	Boot Lid Lock Upper <i>BT</i>			\$ 132.10	✓
	Boot Lid Lock Lower <i>ray</i>			\$ 30.30	X
	Boot Lid Key Lock <i>HH</i>			\$ 78.20	X
	Boot Lid Sonata Plate <i>HLC</i>			\$ 43.60	✓
	Boot Lid Hyundai Plate <i>HLC</i>			\$ 24.20	✓
	Boot Lid 'H' Emblem <i>HLC</i>			\$ 26.10	✓
	Boot Lid CRDI Plate <i>HLC</i>			\$ 22.70	✓
	Boot Lid Lamp (LH/RH) <i>crack</i>		\$ 230.20	\$ 460.40	✓
	Boot Lid Trimboard <i>torn</i>			\$ 165.40	✓
	Boot Lid Trimboard Clips (11pcs) <i>HLC</i>			\$ 11.00	✓
	Rear Bumper <i>Dented</i>			\$ 578.40	✓
	Rear Bumper Reinforcement <i>broken</i>			\$ 483.30	✓
	Rear Bumper Clip <i>HLC</i>			\$ 22.00	✓
	Rear Bumper Bracket <i>HH</i>			\$ 49.00	X
	Rear Bumper Sponge <i>torn</i>			\$ 137.40	✓
	Rear Bumper Under Cover <i>crack</i>			\$ 185.80	✓
	Rear Bumper Protector (LH/RH) <i>BT</i>		\$ 38.00	\$ 76.00	✓
	Tail Lamp (LH/RH) <i>crack</i>		\$ 344.00	\$ 688.00	✓
	Tail Lamp Quarter Panel (LH/RH) <i>ray</i>		\$ 93.80	\$ 187.60	X
	Rear Panel <i>Dented</i>			\$ 391.80	✓
	Rear Panel Garnish <i>deformed</i>			\$ 95.80	✓
	Spare Tyre Holder <i>HHL</i>			\$ 27.60	X
	Tail Lamp Panel Top (RH) <i>ray</i>			\$ 217.40	X
	Spare Tyre Panel <i>Dented</i>			\$ 863.00	✓
	Spare Tyre Panel Cushion <i>SVC</i>			\$ 200.30	X
	Rear Towing Hook <i>HHL</i>			\$ 135.30	X
	Member Assy- Rear Floor Centre <i>HHL</i>			\$ 163.60	X
	Exhaust Pipe Insulator <i>HH</i>			\$ 56.10	X
	Exhaust Silencer <i>BT</i>			\$ 723.00	✓
	Exhaust Pipe Hanger <i>HH</i>			\$ 56.10	X
	Rear Fender (LH/RH) <i>o/s Dented H/S HHL</i>		\$ 1,935.90	\$ 3,871.80	✓
	Rear Fender Inner Lining (LH/RH) <i>HHL</i>		\$ 74.10	\$ 148.20	X
	Rear Fender Trim Board (LH/RH) <i>o/s torn H/S HHL</i>		\$ 180.90	\$ 361.80	✓
	Rear Windscreen Moulding <i>HLC</i>			\$ 60.00	✓
	SUB TOTAL			\$ 12,233.70	
	LESS 20%			\$ 2,446.74	
	DISCOUNTED TOTAL			\$ 9,786.96	
	Boot Lid City Cab Logo & Tel No Sticker <i>HLC</i>			\$ 30.00	Nett ✓
	Boot Lid Advertisement Logo <i>HLC</i>			\$ 100.00	Nett ✓
	Rear No.Plac <i>HHL</i>			\$ 25.00	Nett X
	Rear Bumper Reverse Sensor <i>Dent</i>			\$ 135.70	Nett ✓
	Rear Bumper Advertisement Logo <i>HLC</i>			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>HLC</i>		\$ 100.00	\$ 200.00	Nett ✓
	Rear Windscreen Sealant <i>HLC</i>			\$ 46.00	Nett ✓
				\$ 586.70	

SHC 267L

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,400.00 800/-
	Spray Painting Charge			\$ 1,000.00 700/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 80.00 40/-
	Remove/Refix Cushion & Upholstery Rear			\$ 80.00 60/-
	Remove/Refix Rear Windscreen Glass			\$ 100.00 80/-
	TOTAL LABOUR			\$ 2,710.00
	ESTIMATE TOTAL			\$ 26,885.94
20/7/2018 @ 1130m Not Author L/Smm Ryan 9 days. LKK Auto				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				