

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9812Z**AAD1807-171***Not Authorised
L1 Lmp 853001*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9812Z

VF1ABL15AUC277381

RENAULT

LATITUDE

17.7.2018

AIG**PART****LIST**

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMEPBR BRACKET SIDE RH REAR
- 5 1 BUMEPBR RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMEPBR BRACKET SIDE LH REAR
- 8 1 BUMEPBR RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 BOOT REAR
- 14 1 BOOT FINISHER
- 15 1 BOOT WHEATERSTRIP
- 16 1 BOOT REFLECTOR LAMP LH
- 17 1 BOOT REFLECTOR LAMP RH
- 18 1 BOOT BADGE 'RENAULT'
- 19 1 BOOT BADGE
- 20 1 BOOT STRUT LH
- 21 1 BOOT STRUT RH
- 22 1 BOOT HINGE LH
- 23 1 BOOT HINGE RH
- 24 1 BOOT INNER TRIM
- 25 1 BOOT SWITCH
- 26 1 BOOT LOCK
- 27 1 BOOT LOCK CATCH
- 28 2 LICENCE PLATE LAMP
- 29 2 BOOT RUBBER PLUG

- | | | | |
|----|---------------|----------|----------|
| \$ | <i>Bu</i> | 1,108.46 | <i>✓</i> |
| \$ | <i>Del/Bu</i> | 768.84 | <i>✓</i> |
| \$ | <i>Sm</i> | 113.47 | <i>X</i> |
| \$ | <i>Sm</i> | 135.97 | <i>X</i> |
| \$ | <i>Sm</i> | 44.99 | <i>X</i> |
| \$ | <i>CM</i> | 43.61 | <i>✓</i> |
| \$ | <i>Sm</i> | 135.97 | <i>X</i> |
| \$ | <i>Sm</i> | 44.99 | <i>X</i> |
| \$ | <i>Sm</i> | 43.61 | <i>X</i> |
| \$ | <i>Bu</i> | 777.52 | <i>✓</i> |
| \$ | <i>R</i> | 225.95 | <i>X</i> |
| \$ | <i>D.V</i> | 225.95 | <i>✓</i> |
| \$ | <i>R</i> | 2,872.68 | <i>X</i> |
| \$ | <i>Sm</i> | 470.06 | <i>X</i> |
| \$ | <i>Sm</i> | 323.05 | <i>X</i> |
| \$ | <i>Sm</i> | 493.35 | <i>X</i> |
| \$ | <i>Sm</i> | 493.35 | <i>X</i> |
| \$ | <i>Me</i> | 225.36 | <i>✓</i> |
| \$ | <i>Me</i> | 225.36 | <i>✓</i> |
| \$ | <i>Sm</i> | 276.08 | <i>X</i> |
| \$ | <i>Sm</i> | 276.08 | |
| \$ | <i>R</i> | 367.84 | |
| \$ | <i>R</i> | 367.84 | |
| \$ | <i>Sm</i> | 586.45 | |
| \$ | <i>Sm</i> | 168.13 | |
| \$ | <i>R</i> | 202.67 | |
| \$ | <i>R</i> | 74.40 | |
| \$ | <i>Sm</i> | 50.52 | |
| \$ | <i>Sm</i> | 221.81 | |

Trans-cab Auto Services Pte Ltd**AAD1807-171**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9812Z

30	1 DOOR PANEL REAR LH	\$	R	2,844.66	}	X
31	1 FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45		
32	1 FENDER PANEL REAR LH	\$	R	3,299.13		
33	1 WHEELARCH REAR LH	\$	R	543.47		
34	1 FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45		
35	1 FENDER PANEL REAR RH	\$	R	3,299.13		
36	1 WHEELARCH REAR RH	\$	Sn	543.47		
37	1 TAILLAMP RH	\$	Sn	552.55		
38	1 TAILLAMP PANEL RH	\$	R	986.70		
39	1 TAILLAMP LH	\$	Sn	552.55		
40	1 TAILLAMP PANEL LH	\$	R	986.70		
41	1 OUTER PANEL REAR (End Panel)	\$	B	1,471.77	}	X
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sn	404.56		
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88		
44	1 SPARE WHEEL PANEL TRIM	\$	Sn	612.21		
45	1 EXHAUST REAR	\$	R	7,489.05		
46	1 EXHAUST CAP REAR	\$	R	230.49		
47	1 FUEL FLAP L70Y	\$	Sn	343.57		
48	1 CHASSIS PANEL REAR LH	\$	R	3,766.43		
49	1 WHEEL HOUSING PANEL REAR LH	\$	R	4,682.09		
TOTAL		\$		47,505.69		
10%		\$		4,750.57		
		\$		42,755.12		

Specical Nett

1	1SET PARKING AID	\$	<i>Shan</i>	700.00	<i>600.00</i>
2	1SET REAR BUMPER CLIP	\$	<i>na</i>	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i>	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	<i>na</i>	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	<i>na</i>	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i>	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	—
10	1 EXHAUST MOUNTING REAR	\$	<i>Sn</i>	17.82	X
11	1SET BOOT FINISHER CLIP	\$	<i>na</i>	24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	<i>na</i>	30.00	—

Trans-cab Auto Services Pte Ltd**AAD1807-171**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9812Z

13	1 BOOT STICKER "6555-3333"	\$	<i>nn</i> 30.00 ✓
14	1 BOOT INNER TRIM CLIP	\$	<i>nn</i> 45.00
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	<i>nn</i> 35.00
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	<i>nn</i> 35.00
17	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00
18	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00
19	1 TAILLAMP CLIP RH	\$	<i>nn</i> 5.00
20	1 TAILLAMP CLIP LH	\$	<i>nn</i> 5.00
21	2 REAR WINDSCREEN SELANT	\$	<i>nn</i> 80.00
22	1 WINDSCREEN MOULDING	\$	<i>nn</i> 100.00
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>nn</i> 385.00
25	1 SPARE TYRE	\$	<i>nn</i> 330.00

TOTAL \$ 2,225.02**TOTAL PARTS \$ 44,980.14****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 <i>6601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>601</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>6-301</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1807-171

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9812Z

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X

TOTAL \$ 12,540.00**Over All Total \$ 57,520.14****(LUMP SUM)****Repair Days**~~20 DAYS~~*5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: