

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)Synergy@kb 25 Kaki Bukit Road 4 #01-60/61
Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : AXA INSURANCE SINGAPORE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTKB/TP/1807/012
Policy No:	5069537001-03	Date of Loss:	17/07/2018
Vehicle Reg. No.:	SJY2137B	Driveable?	yes
Driver Age:	03/03/1978	Third Party Vehicle No.:	SHB7564M
Any Injuries?	no	Contact No:	91454374
Insured/Claimant:	MUHAMMAD DZHAFIR BIN NAHRAWI	Driver:	MUHAMMAD DZHAFIR BIN NAHRAWI

Make/Model:	Suzuki, VITARA 2.0 - JSAJTE54V00	Vehicle Reg. Date:	12/08/2010
Vehicle Colour:		Engine Number:	
Chassis No:	JSAJTE54V00601447	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

	Amount
Parts	3,173.50
Miscellaneous Items	250.00
Labour	990.00
Paintwork Labour	675.00
Towing	0.00
Gross Total(S\$):	5,088.50
GST 7.00%(S\$):	356.19
Nett Amount(S\$):	5,444.69

This claim is handled by: Shaun Toh L M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized
LAL
n/s
H. Loo.
Shaun Toh L M
20/7/18
Tel: 62563561

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER <i>DIS ✓</i>	500.00	500.00	+10.00	550.00
2	1	REAR SPARE TYRE COVER OUTER <i>cre ✓</i>	490.00	490.00	+10.00	539.00
3	1	REAR SPARE TYRE COVER INNER <i>cre ✓</i>	350.00	350.00	+10.00	385.00
4	1	REAR BUMPER REFLECTOR LH <i>cre ✓</i>	15.00	15.00	+10.00	16.50
5	1	REAR TAILGATE <i>DD/Bent ✓</i>	650.00	650.00	+10.00	715.00
6	1	REAR BUMPER SIDE RETAINER LH <i>but ✓</i>	18.00	18.00	+10.00	19.80
7	1	REAR BUMPER SIDE RETAINER RH <i>rx ✓</i>	18.00	18.00	+10.00	19.80
8	1	REAR BUMPER BRACKET LH <i>but ✓</i>	25.00	25.00	+10.00	27.50
9	1	REAR BUMPER BRACKET RH <i>rx ✓</i>	25.00	25.00	+10.00	27.50
10	1	REAR TAILGATE SUZUKI EMBLEM <i>me ✓</i>	28.00	28.00	+10.00	30.80
11	1	REAR TAILGATE GRAND VITRA EMBLEM <i>me ✓</i>	36.00	36.00	+10.00	39.60
12	1	REAR END PANEL <i>DD ✓</i>	230.00	230.00	+10.00	253.00
13	1	REAR NUMBER PLATE LAMP <i>rx ✓</i>	50.00	50.00	+10.00	55.00
14	1	REAR EXHAUST PIPE <i>rx ✓</i>	450.00	450.00	+10.00	495.00

Total Parts (S\$) 3,173.50

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIP <i>me ✓</i>	20.00	20.00	0.00	20.00 ✓
2	1	REAR NUMBER PLATE <i>but ✓</i>	30.00	30.00	0.00	30.00 ✓
3	1	REAR REVERSE SENSOR <i>cre ✓</i>	200.00	200.00	0.00	200.00 ✓

Sub Total (S\$) 250.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	180.00	0.00	180.00 60
2	1	To Transfer Rear Tailgate.	80.00	80.00	0.00	80.00 60
3	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	100.00	0.00	100.00 ✓
4	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 20
5	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	600.00	600.00	0.00	600.00 500

Gross Labour Cost (S\$) 990.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	30.00	30.00	0.00	30.00 ✓
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00 <i>me</i>	45.00 40
3	1	To Spray painting on the Replaced and Repair	600.00	600.00	0.00	600.00 580

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
		Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.				

Gross Labour Cost (S\$)	675.00
-------------------------	--------

< END OF ESTIMATES >