

22/03/2002

ASS. REC. BY:

REF:

CS/CTI18013245/Aqd301

Special Instruction:

Survivor:
Minimen

Adrian

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

2017/2018 4:54pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFP 886E

Insured:

YN 8881B

at Workshop m/s

Kai Motor

Tel:

G747 4006 / 9655 9667

of

Bik 3007, Ubi Rd 1 # 01-440

Policy No:

DMCVSN 3075961700

Claim No:

SNM18 D03565C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/07/2018

CA / REV / REP. / REV 24 HRS

lwp)

23/07/2018

H.O.D. Endorsement:

Date/Time:

5:43pm @ 20/7/18

Person Contacted:

Ms. Kym

Vehicle

IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SFP 8896E-X
	YN 8881B-X
	US \$9900, 9 days (red \$11514.94, 54%)



Accident Photo



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18013245/Aqd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 20-07-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 8881B	Veh. Inspected	SFP 8896E
Policy No.	DMCVSN3075961700	Coverage (\$)	0.00
Claim No.	SNM18D03565C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	20/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/07/2018	Inspection Date	23/07/2018
Survey held at	KAI MOTOR TRADING BLK 3007 UBI ROAD 1 #01-434 SINGAPORE 408701		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jul 2018		20 Jul 2018 16:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIAN KOK HENG ENTERPRISE PTE LTD, Co. Reg. No.: -		
Main Claimant:	BOK SANG KUAN, ID: S1511460F		
Vehicle Reg. No.:	SFP8896E	Date of Loss:	18/07/2018 11:00 - :59
Claim Type:	TP / SNM18D03565C02	Policy/Cover Note No.:	DMCVSN3075961700 (Comprehensive)
Vehicle Reg. No. (Insured):	YN8881B	Policy No. (Claimant):	GA076160
		Excess:	S\$0.00
Repairer:	KAI MOTOR TRADING (HQ) BLK 3007 UBI ROAD 1, #01-440, 408701 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/07/2018]		
Driver/Custodian (Insured):	SIVAPERUMAN VELU (38 / Male), NRIC: g7680177r, Tel: +6583009529		
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 2 November 2018 10:31 AM
To: Kai Motor
Subject: FINALISE OF VEHICLE SFP 886E (DOA: 18/07/2018)

Dear Ms Kym,

WITHOUT PREJUDICE

As spoken with you.

Please be informed that the repair cost should be Lump Sum \$11,100.00 instead of \$9,900.00 due to our surveyor calculation error.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SUMMARY REPORT

ENTRY DATE FROM 28/03/2005 TO 28/03/2005

28/03/2005

Reference	Vehicle No.	Entry Date	Accident Date	Closed Date
AIC/002050/05YX	YJ 9222T	28/03/2005	26/03/2005	
AIG/002054/05SX	SFA 9863R	28/03/2005	26/03/2005	
AIG/002075/05PMX	GX 9207C	28/03/2005	28/03/2005	
AXA/002067/05FR	SDD 188Z	28/03/2005	28/03/2005	
CAI/002053/05YR	SDL 9960J	28/03/2005	27/03/2005	
CAI/M002049/05SS	SFE 4093H	28/03/2005	27/03/2005	
INC/002046/05ZE	SDM 3638A	28/03/2005	27/03/2005	
INC/002047/05ZE	SFH 8589C	28/03/2005	27/03/2005	
INC/002055/05WX	SFH 6352G	28/03/2005	27/03/2005	
INC/002056/05YQ	SDT 9040Y	28/03/2005	27/03/2005	
INC/002057/05ZT	SH 2511L	28/03/2005	27/03/2005	
INC/002060/05PMS	SFL 9000G	28/03/2005	24/03/2005	
INC/002061/05FQ	SFK 5927P	28/03/2005	27/03/2005	
INC/002063/05ZR	SDU 8347P	28/03/2005	28/03/2005	
INC/002065/05FS	SDU 1588G	28/03/2005	28/03/2005	
INC/002066/05YX	EU 861L	28/03/2005	28/03/2005	
INC/002068/05PMX	YL 6205C	28/03/2005	27/03/2005	
INC/002069/05ZX	YH 4693K	28/03/2005	27/03/2005	
INC/002071/05YQ	FY 4989T	28/03/2005	26/03/2005	
INC/002072/05PMQ	GW 8221Y	28/03/2005	28/03/2005	
INC/002073/05FA	SDP 6608B	28/03/2005	26/03/2005	
INC/002074/05FA	SDG 3390U	28/03/2005	28/03/2005	
INC/002076/05PMA	SCV 2623M	28/03/2005	21/09/2004	
INC/002077/05FA	SFE 5176X	28/03/2005	28/03/2005	
INC/P002052/05SS	GN 9532R	28/03/2005		
INC/P002064/05S	SBV 1852L	28/03/2005		
MGA/002048/05YX	GT 8696B	28/03/2005	09/01/2005	
MSI/002058/05FQ	SDA 4665C	28/03/2005	27/03/2005	
MSI/002062/05PM	FP 4403P	28/03/2005	28/03/2005	
NIC/002070/05FQ	EL 8388G	28/03/2005	28/03/2005	
OAC/002051/05ZX	XB 7905Z	28/03/2005	27/03/2005	
TIC/002059/05PMQ	GW 4142T	28/03/2005	27/03/2005	

Total Reports: 32

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1460F
Vehicle Details	
Vehicle No.:	SFP886E
Vehicle to be Exported:	Yes
Intended De-registration Date:	23 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS ES250 AUTO
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	2ARE746673
Chassis No.:	JTHBJ1GG202034832
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$35,305.00
Original Registration Date:	22 Nov 2013
First Registration Date:	22 Nov 2013
Transfer Count:	0
Actual ARF Paid:	\$41,427.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Nov 2023
PARF Rebate Amount:	\$31,070.00
Intended COE Rebate Details	
COE Expiry Date:	21 Nov 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$93,889.00
COE Rebate Amount:	\$49,833.00
Total Rebate Amount:	\$80,903.00

The information contained herein is correct as at 23 Jul 2018

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)





Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [i Ways of Selling](#)

New 5 Years Coe Renewal Toyota Wish 1.8A



\$2800 Downpayment Monthly
From \$688 Onwards. Lowest
3.68%P.A@Gv Cars Financing
GV Credit Pte Ltd StarAd





**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

HOTLINE: 6741 9997 [view our cars](#)

Browse by Category  Save Search  Print Sort by Date Posted 20 results/page

2 vehicles | Search [Advanced Search](#) [Search](#) [View All](#)

Search Selection	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
es250	Any	Any	Any	Any	Any	Any	Any	Any	Available



☐ **Lexus ES250 Luxury** **\$104,800** **\$15,210 /yr** **15-Nov-2013** **2,494 cc** **71,000 km** **Luxury** **Available**

Priced Reduced To Sell! Luxury Model, Carefully Driven By Single Owner, Full Agent Service History, Warranty Valid Till Nov'2018, Drive Home With Safe Peace Of Mind, 100% Accident Free, Monthly At \$12...

Horizon Motoring

 Posted: 23-Jul-2018 Tags: 2013 Lexus ES250, Lexus ES250, Lexus, ES250, Used Lexus



☐ **Lexus ES250 Luxury** **\$99,800** **\$14,340 /yr** **05-Nov-2013** **2,494 cc** **82,000 km** **Luxury** **Available**

Interest Rate At 1.99%! Beautiful Is A Understatement. Spotless Perfection. Road Tax 4/11/2018. Quiet Engine With A Gearbox As Smooth As Silk, 100% Accident Free. Various Loan Schemes Available. Call ...

Auto Zoom Enterprise Pte Ltd

 Posted: 21-Jul-2018 Tags: 2013 Lexus ES250, Lexus ES250, Lexus, ES250, Used Lexus

Save this search criteria, to get email alerts whenever a match is found.  Save Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads 20 results/page

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/07/2018 14:50
Date Of Accident	18/07/2018 11:45
Exact Location Of Accident	TOA PAYOH LOR 2 TOWARDS PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFP886E
Insured/Policyholder	
Name Of Registered Owner	BOK SANG KUAN
NRIC No	S1511460F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96783045
Alternative Phone No	OTHERS-96783045

Vehicle Particulars

Manufacturer	LEXUS
Model	ES250-2.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA076160
Cover Note Number	

Driver

Name of Driver	BOK SANG KUAN
NRIC No	S1511460F
Date Of Birth	13/09/1961
Occupation	INDOOR
Date Of Driving Pass	26/06/1985
Driving Experience	33 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96783045
Fax Number	
Contact Number	OTHERS-96783045
Email Address	NOEMAIL

Address	BLK 230 CHOA CHU KANG CENTRAL #07-161 SINGAPORE
Postcode	680230
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 6741 5336


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN8881B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SIVAPERUMAN YELU
NRIC/Passport Number	
Contact Number	
Address	LTA
Postcode	EA
Insurance Company Name	china
Nature Of Damage	laiping
No. Of Passenger (Including Driver)	

Sketch Plan #2



Vehicle No
A - SFP 886 E
B - YN 8881 B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18/07/2018 around 11:45 AM, I was driving along Toa Payoh Lor 2 towards PIE ~~town~~, and I was at giving way, Suddenly the vehicle B (YN 8881 B) behind me hit the rear of my vehicle. Because of that my vehicle rear portion has accident damaged serious.

DECLARATION

I/We declare the foregoing particulars are true in every respect. Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated time frame from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature
Date & Time: 18/7/18 2:15 PM

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: [Signature]
NRIC/FIN No:

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

2:15pm
18/7/18

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRC/FIN No.:

DAWEN



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

JTH BJ1 G6 202034832

Date : 20/07/2018

Attn: The Motor Claims Department
China Taiping Insurance (S) Pte Ltd
3 Anson oad
#16-00
Spring Leaf Tower
Singapore 079909

Xiao Chen

LKK
Adrian
9689 3735

Dear Sir / Madam

Estimate Cost repair Bill To Lexus SFP 88 6 E & YN 8881 B on 18072018

To Supply:-

1pc	Rear boot cover	<i>Distorted</i>	\$	985.10	✓
1pc	Rear boot cover inner lock	<i>Damaged</i>	\$	478.40	✓
1pc	Rear boot cover logo	<i>New</i>	\$	95.70	✓
1pc	Rear boot cover rubber	<i>cut</i>	\$	256.70	✓
1pc	Rear boot cover "LEXUS" emblem	<i>Free</i>	\$	131.10	✓
1pc	Rear boot cover "ES 2500" emblem		\$	148.60	✓
1pc	Rear boot cover lamp	<i>at</i>	\$	460.35	✓
1pc	Rear boot cover moulding	<i>could</i>	\$	151.00	✓
1pc	Rear boot cover insulator	<i>Del d</i>	\$	498.60	✓
8pcs	Rear boot cover insulator clips	<i>in</i>	\$	50.00	30
1pc	Rear boot cover hinge	<i>Best</i>	\$	139.60	✓
1pc	Rear antenna ele	<i>Damage</i>	\$	480.00	✓
1pc	Rear lamp RH	<i>could</i>	\$	751.60	✓
1pc	Rear fender RH	<i>Repair</i>	\$	1,155.10	✓
1pc	Rear lamp panel RH	<i>painted</i>	\$	138.10	✓
1pc	Rear panel	<i>Distorted</i>	\$	801.60	✓
1pc	Rear panel inner garnish	<i>Del d</i>	\$	248.10	✓
1pc	Rear bumper	<i>Distorted</i>	\$	899.70	✓
2pcs	Rear bumper side retainer	<i>in</i>	\$	303.20	✓
1pc	Rear bumper center spong gr	<i>could</i>	\$	215.60	✓
2pcs	Rear bumper reinforcement	<i>Best</i>	\$	623.40	✓
8pcs	Rear bumper clips	<i>New</i>	\$	50.00	30
1pc	Rear spare tyre box	<i>2 new</i>	\$	496.80	✓
1pc	Rear spare panel cover	<i>Del d</i>	\$	455.60	✓
			\$	9,862.35	

10013 95



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 20/07/2018

Attn: The Motor Claims Department
China Taiping Insurance (S) Pte Ltd
3 Anson oad
#16-00
Spring Leaf Tower
Singapore 079909

Dear Sir / Madam

Page .2

Estimate Cost repair Bill To Lexus SFP 88 6 E & YN 8881 B on 18072018

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Date:

To Supply:-

			\$ 9,862.35	
1set	Reverse sensor	Damaged	\$ 492.40	
			less	10%
				\$ 196.96
				\$ 1,772.64
1pc	Rear boot cover reverse cam	Damaged	\$ 680.00	S/nett 380
1pc	Rear windscreen glass seal	Not run	\$ 150.00	S/nett 75
1pc	Rear number plate	Best	\$ 65.00	S/nett 32.5
To dismantl & replace damage parts, panel beat where necessary.			\$ 1,500.00	? ? 1400
To putty, apply primer & spray paint on the affected portion.			\$ 1,680.00	1300
labour charge to remove & refix windscreen			\$ 150.00	275
To remove spary tuff cost.			\$ 200.00	50
To computer wheel alignment.			\$ 120.00	x
To check wiring functions.			\$ 100.00	30
To remove reverse sensor.			\$ 150.00	60
To remove & refit car caushion.			\$ 120.00	60

Adrian King

L/s 23/07/18.

No of Days 09

9.5K

\$ 16,549.99
Supplementary 2026.77
Total: 12378.87.
L/s: 8.9K.
21414.94
15700.20



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y



專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 25/07/2018

Attn: The Motor Claims Department

China Taiping Insurance (S) Pte Ltd

3 Anson oad

#16-00

SFP886E (CTI: SNM18D03565C02)

Spring Leaf Tower

Singapore 079909

6389 6171

Dear Sir / Madam

Supplementary Cost repair Bill To Lexus SFP 886 E & YN 8881 B on 18072018

To Supply:-

1pc	Rear lamp LH <i>ut</i>	\$ 751.60	✓
1pc	Rear boot cover lamp (add one more pc) <i>ut</i>	\$ 460.35	✓
1pc	Rear boot inn/fl luggage mat <i>the new</i>	\$ 423.50	X
1pc	Rear boot cover hinge (add one more pc) <i>Bent</i>	\$ 139.60	✓
1pc	Rear spare wheel tray cover <i>Replaced</i>	\$ 408.60	X
1pc	Rear floor sp/wh panel <i>Buckled</i>	\$ 765.80	✓
1pc	Rear ex pipe <i>Repair</i>	\$ 598.50	X
1pc	Rear ex pipe top muff/insulater <i>newer</i> <i>2829.75</i>	\$ 215.30	X
1pc	Rear fender inner trim <i>changed</i> <i>2546.77</i>	\$ 683.50 <i>494.20</i>	
1pc	Rear sp/wh side tool board RH <i>del d</i>	\$ 218.20	✓
		\$ 4,664.95	

Less

To remove exhaust pipe.

\$ ~~200.00~~ *80*

Supplementary: *2626.77*

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Jul 2018		20 Jul 2018 16:54 Edit Adj Rpt	S\$9,900.00 Edit Estimates	S\$9,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LIAN KOK HENG ENTERPRISE PTE LTD , Co. Reg. No.: -									
Main Claimant: BOK SANG KUAN , ID: S1511460F									
Vehicle Reg. No.: SFP886E		Date of Loss: 18/07/2018 11:00 - :59 [55 Months and 26 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D03565C02		Policy/Cover Note No.: DMCVSN3075961700 (Comprehensive)							
Vehicle Reg. No. (Insured): YN8881B		Policy No. (Claimant): GA076160							
		Excess: S\$0.00							
Repairer: KAI MOTOR TRADING (HQ) BLK 3007 UBI ROAD 1, #01-440, 408701 Ubi - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 31/07/2018]									
Driver/Custodian (Insured): SIVAPERUMAN VELU (38 / Male), NRIC: G7680177R, Tel: +6583009529									
Adj Asg. Remarks: NO EST, ASSIGN ADRIAN LING AS SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFP886E (SNM18D03565C02)
[YN8881B]
TP
BOK SANG KUAN
Jul 18 2018 11:00AM
[LIAN KOK HENG ENTERPRISE PTE LTD]
KAI MOTOR TRADING

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports							1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print			
1	18/07/18 15:04	Accident Statement			Load HTM			
Photos/Images							3 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print			
1	18/07/18 15:01	Accident Photo [Linked Accident Report Documents]			Load JPG		☒	
2	18/07/18 15:01	Accident Photo [Linked Accident Report Documents]			Load JPG		☒	
3	18/07/18 15:01	Accident Photo [Linked Accident Report Documents]			Load JPG		☒	
4	18/07/18 15:01	Accident Photo [Linked Accident Report Documents]			Load JPG		☒	
5	18/07/18 15:01	Accident Photo [Linked Accident Report Documents]			Load JPG		☒	
6	18/07/18 15:01	Accident Photo [Linked Accident Report Documents]			Load JPG		☒	
7	18/07/18 15:01	Accident Photo [Linked Accident Report Documents]			Load JPG		☒	
8	18/07/18 15:01	Accident Photo [Linked Accident Report Documents]			Load JPG		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	23/10/18 11:14	General View			Load JPG		☒	
2	23/10/18 11:14	Chassis Number			Load JPG		☒	
3	23/10/18 11:14	General View			Load JPG		☒	
4	23/10/18 11:14	General View			Load JPG		☒	
5	23/10/18 11:14	General View			Load JPG		☒	
6	23/10/18 11:14	General View			Load JPG		☒	
7	23/10/18 11:14	General View			Load JPG		☒	
8	23/10/18 11:14	General View			Load JPG		☒	
9	23/10/18 11:14	General View			Load JPG		☒	
10	23/10/18 11:14	General View			Load JPG		☒	
11	23/10/18 11:14	General View			Load JPG		☒	
12	23/10/18 11:14	General View			Load JPG		☒	
13	23/10/18 11:14	General View			Load JPG		☒	
14	23/10/18 11:14	General View			Load JPG		☒	
15	23/10/18 11:14	General View			Load JPG		☒	
16	23/10/18 11:14	General View			Load JPG		☒	
17	23/10/18 11:14	General View			Load JPG		☒	
18	23/10/18 11:14	General View			Load JPG		☒	
19	23/10/18 11:14	General View			Load JPG		☒	
20	23/10/18 11:14	General View			Load JPG		☒	
21	23/10/18 11:14	General View			Load JPG		☒	
22	23/10/18 11:14	General View			Load JPG		☒	

Assessment Reports			1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
23	23/10/18 11:14	General View	 Load JPG	☒
24	23/10/18 11:14	General View	 Load JPG	☒
25	23/10/18 11:14	General View	 Load JPG	☒
26	23/10/18 11:14	General View	 Load JPG	☒
27	23/10/18 11:14	General View	 Load JPG	☒
28	23/10/18 11:14	General View	 Load JPG	☒
29	23/10/18 11:14	General View	 Load JPG	☒
30	23/10/18 11:14	General View	 Load JPG	☒
31	23/10/18 11:14	General View	 Load JPG	☒
32	23/10/18 11:14	General View	 Load JPG	☒
33	23/10/18 11:14	General View	 Load JPG	☒
34	23/10/18 11:14	General View	 Load JPG	☒
35	23/10/18 11:14	General View	 Load JPG	☒
36	23/10/18 11:14	General View	 Load JPG	☒
37	23/10/18 11:14	General View	 Load JPG	☒
38	23/10/18 11:14	General View	 Load JPG	☒
39	23/10/18 11:14	General View	 Load JPG	☒
40	23/10/18 11:14	General View	 Load JPG	☒
41	23/10/18 11:14	General View	 Load JPG	☒
42	23/10/18 11:14	General View	 Load JPG	☒
43	23/10/18 11:14	General View	 Load JPG	☒
44	23/10/18 11:14	General View	 Load JPG	☒
45	23/10/18 11:14	General View	 Load JPG	☒
46	23/10/18 11:14	General View	 Load JPG	☒
47	23/10/18 11:14	General View	 Load JPG	☒
48	23/10/18 11:14	General View	 Load JPG	☒
49	23/10/18 11:14	General View	 Load JPG	☒
50	23/10/18 11:14	General View	 Load JPG	☒
51	23/10/18 11:14	General View	 Load JPG	☒
52	23/10/18 11:14	General View	 Load JPG	☒
53	23/10/18 11:14	General View	 Load JPG	☒
54	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
55	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
56	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
57	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
58	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
59	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
60	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
61	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
62	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
63	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
64	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
65	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
66	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
67	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
68	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
69	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
70	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
71	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
72	23/10/18 11:14	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
73	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
74	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
75	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
76	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
77	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
78	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
79	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
80	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
81	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
82	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
83	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
84	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
85	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
86	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
87	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
88	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
89	23/10/18 11:14	Reinspection Photo	 Load JPG	☒
90	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
91	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
92	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
93	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
94	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
95	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
96	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
97	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
98	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
99	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
100	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
101	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
102	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
103	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
104	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
105	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
106	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
107	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
108	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
109	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
110	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
111	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
112	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
113	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
114	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
115	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
116	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
117	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
118	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
119	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
120	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
121	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
122	23/10/18 11:15	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
123	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
124	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
125	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
126	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
127	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
128	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
129	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
130	23/10/18 11:15	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	18/07/18 15:02	Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	18/07/18 15:02	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	☒
3	18/07/18 15:03	Common Statement [Linked Accident Report Documents]	 Load JPG	☒
4	18/07/18 15:03	Individual Statement [Linked Accident Report Documents]	 Load JPG	☒
5	18/07/18 15:03	DRIVER NRIC & LICENSE [Linked Accident Report Documents]	 Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/07/18 16:53	PRS	 Load PDF	
2	20/07/18 16:54	OI GIA	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/11/18 14:04	Supplementary	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	18/07/18 15:04	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	18/07/18 15:01	Accident Photo	 Load JPG	☒
2	18/07/18 15:01	Accident Photo	 Load JPG	☒
3	18/07/18 15:01	Accident Photo	 Load JPG	☒
4	18/07/18 15:01	Accident Photo	 Load JPG	☒
5	18/07/18 15:01	Accident Photo	 Load JPG	☒
6	18/07/18 15:01	Accident Photo	 Load JPG	☒
7	18/07/18 15:01	Accident Photo	 Load JPG	☒
8	18/07/18 15:01	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	18/07/18 15:02	Sketch Plan	 Load JPG	☒
2	18/07/18 15:02	Sketch Plan #2	 Load JPG	☒
3	18/07/18 15:03	Common Statement	 Load JPG	☒
4	18/07/18 15:03	Individual Statement	 Load JPG	☒
5	18/07/18 15:03	DRIVER NRIC & LICENSE	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18013245/AQD3E2

Date: 05/11/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3075961700

Claimant Vehicle
No : SFP886EInsured Vehicle
No : YN8881B

Date of Loss: 18/07/2018

Nature of Claim: TP

Claim
No: SNM18D03565C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFP886E

Make & Model: LEXUS ES250, 2.5 (A)

Engine No: 2ARE746673

Reg. Date: 22/11/2013 (Man. Year: 2013)

Chassis No: JTHBJ1GG202034832

Colour: White

Odometer: 120840 km

Engine Capacity: 2494 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,878.65	10,985.62	4,893.03	30.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,220.00	2,980.00	1,240.00	29.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,098.65	13,965.62	6,133.03	30.51
Approved Total (Overridden) (S\$)		9,900.00		
(S\$)	20,098.65	9,900.00	10,198.65	50.74
+ GST 7.00/7.00% (S\$)	1,406.91	693.00	713.91	50.74
Nett Amount (S\$)	21,505.56	10,593.00	10,912.56	50.74

INSPECTION

Date of Assignment: 20/07/2018

Date Inspected: 23/07/2018 Inspected At:

KAI MOTOR TRADING (HQ)
BLK 3007 UBI ROAD 1, #01-440
Singapore 408701

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Nov 2018)
Parts: 143	LEXUS ES250 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SFP886E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Distorted	985.10 FL	*985.10 FL
2	1		*REAR BOOT COVER INNER LOCK	Damaged	478.40 FL	*478.40 FL
3	1		*REAR BOOT COVER LOGO	Necessary	95.70 FL	*95.70 FL
4	1		*REAR BOOT COVER RUBBER	Cut	256.70 FL	*256.70 FL
5	1		*REAR BOOT COVER LEXUS EMBLEM	Necessary	131.10 FL	*131.10 FL
6	1		*REAR BOOT COVER ES 2500 EMBLEM	Necessary	148.60 FL	*148.60 FL
7	1		*REAR BOOT COVER LAMP	Cut	460.35 FL	*460.35 FL
8	1		*REAR BOOT COVER MOULDING	Cracked	151.00 FL	*151.00 FL
9	1		*REAR BOOT COVER INSULATOR	Deformed	498.60 FL	*498.60 FL
10	8		*REAR BOOT COVER INSULATOR CLIPS	Necessary	50.00 FL	*30.00 FL
11	1		*REAR BOOT COVER HINGE	Bent	139.60 FL	*139.60 FL
12	1		*REAR ANTENNA ELE	Damaged	480.00 FL	*480.00 FL
13	1		*REAR LAMP RH	Cracked	751.60 FL	*751.60 FL
14	1		*REAR FENDER RH	Repair	1,155.10 FL	*- FL
15	1		*REAR LAMP PANEL RH	Dented	138.10 FL	*138.10 FL
16	1		*REAR PANEL	Distorted	801.60 FL	*801.60 FL
17	1		*REAR PANEL INNER GARNISH	Deformed	248.10 FL	*248.10 FL
18	1		*REAR BUMPER	Distorted	899.70 FL	*899.70 FL
19	2		*REAR BUMPER SIDE RETAINER	Necessary	303.20 FL	*303.20 FL
20	1		*REAR BUMPER CENTER SPONG GR	Cracked	215.60 FL	*215.60 FL
21	2		*REAR BUMPER REINFORCEMENT	Bent	623.40 FL	*623.40 FL
22	8		*REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
23	1		*REAR SPARE TYRE BOX	Not Necessary	496.80 FL	*- FL
24	1		*REAR SPARE PANEL COVER	Deformed	455.60 FL	*455.60 FL
25	1		*SET REVERSE SENSOR	Damaged	1,969.60 FL	*560.00 FL
26	1		*REAR BOOT COVER REVERSE CAM	Damaged	680.00 FS	*380.00 FS
27	1		*REAR WINDSCREEN GLASS SEAL	Not Necessary	150.00 FS	*- FS
28	1		*REAR NUMBER PLATE	Bent	65.00 FS	*65.00 FS
29	1		*REAR LAMP LH	Cut	751.60 FL	*751.60 FL
30	1		*REAR BOOT COVER LAMP	Cut	460.35 FL	*460.35 FL
31	1		*REAR BOOT INN/FL LUGGAGE MAT	Not Necessary	423.50 FL	*- FL
32	1		*REAR BOOT COVER HINGE	Bent	139.60 FL	*139.60 FL
33	1		*REAR SPARE WHEEL TRAY COVER	Repeated	408.60 FL	*- FL
34	1		*REAR FLOOR SP/WH PANEL	Buckled	765.80 FL	*765.80 FL
35	1		*REAR EX PIPE	Repair	598.50 FL	*- FL
36	1		*REAR EX PIPE TOP MUFF / INSULATOR	Not Necessary	215.30 FL	*- FL
37	1		*REAR FENDER INNER TRIM	Crumpled	683.50 FL	*494.20 FL
38	1		*REAR SP/WH SIDE TOOL BOARD RH	Deformed	218.20 FL	*218.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	17,543.50	12,156.80
				- List Item Discount on L Items 10.00/10.00% (S\$)	1,664.85	1,171.18
				Total Parts (S\$)	15,878.65	10,985.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGE PARTS, PANEL BEAT WHERE NECESSARY	New	1,500.00	1,400.00
2	TO PUTTY, APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	1,680.00	1,300.00
3	LABOUR CHARGE TO REMOVE & REFIX WINDSCREEN	New	150.00	0.00
4	TO REMOVE SPARY TUFF COST	New	200.00	50.00
5	TO COMPUTER WHEEL ALIGNMENT	New	120.00	0.00
6	TO CHECK WIRING FUNCTIONS	New	100.00	30.00
7	TO REMOVE REVERSE SENSOR	New	150.00	60.00
8	TO REMOVE & REFIT CAR CAUSHION	New	120.00	60.00
9	TO REMOVE EXHAUST PIPE	New	200.00	80.00
Gross Labour Cost (S\$)			4,220.00	2,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >