

ASS. REC. BY:

REF: CS/LPC18013252/Ked322

Special Instruction:

Surveyor's
Maimin

Kenneth

ASSIGNMENT (Office)

From (Person):

Gerald Poh

of

LPC

Date/Time:

20/7/18 @ 2:19pm

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

3KT8261S

Insured:

at Workshop n/s:

Cheng Hwe Motor

Tel:

67556142

of

3IK 1019 #01-374/382

Policy No:

Z1/7/VPOS/015456

Claim No:

17/18/18/VPOS/020761

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A.

17/07/2018

CA / (REV)

/ REP. / REV 24 HRS

H.O.D. Enforcement:

Date/Time:

3:55pm @ 20/7/18

Person Contacted:

June

Vehicle

☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	wesp has yet to upload estimates. 3KT8261S-CC4/LPC18013153/wb3 DOA: 17/7/2018
24/7/18	Alert the mainin
27/7/18	According Kenneth change mv: to 36k & repair on L/s. base on Gerald.
30/7/18	Approve mandate, call and inform June to proceed to repair.

ASS. REC. BY:

REF: LPC /Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 875k 76k

IDAC Accident Rpt: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: 14 days

Res.: Yes or No

Lum Sum: 1.1B1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SXT 82645Yr Regn: 06, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mazda 5c.c. 1900Colour: M.D. Blue

A/C: Insured / Std / NI / NA

Sp. Reading: _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6CW1071F0121815Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 17/7/18D.O.I. 20/7/18

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/7 File pass to Catherine18/12 D.K. / 1 Lp. 814, 750 (Red. 4512.70, 23%). Confirmed with Edeeda.

RECEIVED 16 DEC 2018

Date/Time, File Pass to?

☐

Prell. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 14Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

Fees:

Others:

TOTAL

9x19=171120+135=305305 + 20% = 3663665050+5037563+10563Report Format: ODLump Sum / L.B.I. (\$ 14,750)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS/LPC18013252/Krd3

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 20-07-2018



Code : LPC2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKT 8264S
Policy No.	Z/17/VP05/015486	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020761	Excess (\$)	500.00
Assign From	MERIMEN (GERALD POH)	Assign Date	20/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	17/07/2018	Inspection Date	20/07/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jul 2018 Sendback Est	20 Jul 2018 14:11 S\$3,165.00	20 Jul 2018 14:19 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	WONG FOCK HONG(HUANG FU XIONG), ID: S74117891		
Vehicle Reg. No.:	SKT8264S	Date of Loss:	17/07/2018 15:00 - :59 [36 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 17/18/18/VP05/020761	Policy/Cover Note No.:	Z/17/VP05/015486 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/07/2018]		
Driver/Custodian:	WONG FOCK HONG(HUANG FU XIONG) (), NRIC: S74117891		
Adj Asg. Remarks:	SURVEY & REVERT. WORKSHOP HAS YET TO UPLOAD ESTIMATES.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Monday, July 30, 2018 4:58 PM
To: Cheng Hoe Motor Pte Ltd (Yishun-June)
Cc: SUR
Subject: SKT 8264S LPC OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKT 8264S (excess \$500/-)**. Please note the **vehicle repair at repair cost not more than L/S \$14,750.00**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

SKT8264S (17/18/18/VP05/020761)

OD

Jul 17 2018 3:00PM

[WONG FOCK HONG(HUANG FU XIONG)]

Cheng Hoe Motor Pte Ltd

From Lonpac Insurance Bhd (HQ) (LONPAC_HQ), sent on 30/07/2018 15:05 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$14750.00) - SKT8264S - Claim Handler: Gerald Poh

Approved:14750.00.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gerald Poh

Date: 27 Jul 2018

Preliminary Advice

Vehicle No	: SKT8264S	Accident Date	: 17/07/2018
Make	: MAZDA 5	Policy No.	: Z/17/VP05/015486
Assignment Date	: 20/07/2018	Excess	: S\$500.00
Date of Inspection	: 20/07/2018	Est. Duration of Repair	: 0.00
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,796.95
Revised Amount	:S\$	15,271.05
Check Items (Estimated)	:S\$	3,134.90
Total	:S\$	18,405.95
 Lump Sum Repair	 :S\$	 14,750.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	76,000.00
COE / PARF Rebate	:S\$	61,143.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,857.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Repair will be done on lump sum basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gerald Poh

Date: 24 Jul 2018

Preliminary Advice

Vehicle No	: SKT8264S	Accident Date	: 17/07/2018
Make	: MAZDA 5	Policy No.	: Z/17/VP05/015486
Assignment Date	: 20/07/2018	Excess	: S\$500.00
Date of Inspection	: 20/07/2018	Est. Duration of Repair	: 0.00
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,796.95
Revised Amount	:S\$	15,271.05
Check Items (Estimated)	:S\$	3,134.90
Total	:S\$	18,405.95

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	75,000.00
COE / PARF Rebate	:S\$	61,143.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,857.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1789I
Vehicle Details	
Vehicle No.:	SKT82645
Vehicle to be Exported:	No
Intended De-registration Date:	17 Jul 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 5-DOOR WAGON 2.0L SP.6EAT SUNROOF
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	PE10229258
Chassis No.:	JM6CW1071F0121815
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$17,191.00
Original Registration Date:	24 Jun 2015
First Registration Date:	24 Jun 2015
Transfer Count:	1
Actual ARF Paid:	\$12,191.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jun 2025
PARF Rebate Amount:	\$9,143.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jun 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$75,000.00
COE Rebate Amount:	\$52,000.00
Total Rebate Amount:	\$61,143.00

The information contained herein is correct as at 17 Jul 2018

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

- Exercising and losing weight
- Change in SMRT CEO (Apr 2018), Management & Other...
- Stop-Start Systems

MAZDA 5 Price Range Depreciation 2015 Vehicle Type Submit

Home > Used Cars > The Car Enthusiast Pte Ltd > Mazda 5 2.0A

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Rental

For Private &
Commercial Vehicles
Rental From
\$50/Day


Mazda 5 2.0A

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$75,800	
Depreciation	\$10,030 /yr View models with similar depreciation	
Reg Date	16-Jun-2015 (6yrs 10mths 28days COE left)	
Manufactured	2015	
Mileage	60,801 km (19.7k /yr)	
Transmission	Auto	
Engine Cap	1,998 cc	
Road Tax	\$1,210 /yr	
Power	111.0 kW (148 bhp) View specs of the Mazda 5 (2012-2018)	
Curb Weight	1,535 kg	
Features	2.0L 4 Cylinders Inline DOHC SkyActiv 6 Engine, 6 Speed Auto, Smart Key, Multi Function Steering.	
Accessories	Multi Function Steering Wheel, Auto Headlights, Rain Sensing Wipers, Retractable Side Mirrors, Reverse Camera, Twin Power Sliding Doors, Sunroof.	
Description	1 Owner Only! Well Maintained, Excellent Condition! Minimum Down Payment With Bank Or In House Loan Available. Call For More Enquiries!	
COE	\$75,002	
OMV	\$17,889	
ARF	\$12,889	
Dereg Value	\$61,531 as of today (change)	
No. of Owners	1	
Type of Veh	MPV	
Category	MPV Car	
Availability	Available	

Add to Shortlist

Add to Compare

Add a Note

Posted on: 11-Jul-2018 | Last Updated on: 17-Jul-2018

Tags: Mazda 5, 2015 Mazda 5, Mazda, Mazda 5, Used Mazda

Upfront Payment

> more Financial info



Seller Information

Company	The Car Enthusiast • dealer's pricelist • 22 vehs sold 22 veh
Address	1 Bukit Batok Crescent Search cars nearby this
Location	WCEGA Plaza
Office No	66848470
Contact Person(s)	Pan Sebastian Ng

Useful Services



Afraid of lemons? Request to
this car evaluated profession
Vehicle Evaluation



Find out the market value fo
Get a free Car Valuation.
Free Valuation

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/07/2018 17:07
Date Of Accident	17/07/2018 15:55
Exact Location Of Accident	ALONG YISHUN AVE 7
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT8264S
Insured/Policyholder	
Name Of Registered Owner	WONG FOCK HONG(HUANG FUXIONG)
NRIC No	S7411789I
Email Address	JEFWONG@ROCKETMAIL.COM
Mobile Phone No	(LOCAL) +65-96335545
Alternative Phone No	OTHERS-96335545

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA5 5-DOOR WAGON 2.0L SP.6EAT
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z/17/VP05/015486
Cover Note Number	02/10/17 - 23/12/18

Driver

Name of Driver	WONG FOCK HONG(HUANG FUXIONG)
NRIC No	S7411789I
Date Of Birth	16/04/1974
Occupation	INDOOR
Date Of Driving Pass	08/12/1992
Driving Experience	25 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96335545
Fax Number	
Contact Number	
EEmail Address	JEFWONG@ROCKETMAIL.COM

Address	BLK 115C CANBERRA WALK #11-157
Postcode	753115
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Traffic was moderate and smooth. I was travelling on the extreme right when I noticed front vehicles jammed brake. I immediately applied e-brake but unable to avoid and collided onto vehicle B. Upon alighted to check, I then realised I was involved in a chain collision of total 4 vehicles including mine. The impact had caused my car 2 air bags activated and was towed to the workshop. No one was injured.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB657X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHINESE MALE
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLA9687L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHINESE MALE
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	GBC1532L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHINESE MALE
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

<p>Vishnu Ave 7</p>	<p>A: SKT82645</p>
	<p>B: GBB657X</p> <p>Chinese Male</p>
	<p>C: SLA9687L</p> <p>Chinese Male</p>
	<p>D: GBC1532L</p> <p>Chinese Male</p>

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Traffic was moderate and smooth. I was travelling on the extreme right when I noticed front vehicles jammed brake. I immediately applied e-brake but unable to avoid and collided onto vehicle B. Upon alighted to check, I then realized I was involved in a chain collision of total 4 vehicles including mine. The impact had caused my car 2 air bags activated and was towed to the workshop. No one was injured.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

<p></p> <p>Policyholder's Signature</p>	<p></p> <p>Driver's Signature (If driver is not the policyholder)</p>	<p></p> <p>Reporting Centre Personnel's Signature</p>
<p>Date & Time:</p>	<p>Date & Time:</p>	<p>Name: (YS)</p>
<p>GIARMC SketchPlanForm_V3</p>		
<p>(<input checked="" type="checkbox"/>) Claim Own Policy () Claim Third Party () Reporting Only</p>		
<p>() Claim OD/TP at other workshop ()</p>		

SKETCH PLAN

VEHICLE NO.: SKT 82645
 INSURER : Longpac
 DATE & TIME: 17/7/18 @ 15:57

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name: (YS)
 NRIC/FIN No.:

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: **Lonpac Insurance Bhd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/LONPAC
Policy No:	Z/17/VP05/015486	Date of Loss:	17/07/2018
Vehicle Reg. No.:	SKT8264S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WONG FOCK HONG(HUANG FU XIONG)		
Driver:	WONG FOCK HONG(HUANG FU XIONG)		
Make/Model:	MAZDA 5, 2.0 5 DR WAGON (A)	Vehicle Reg. Date:	24/06/2015
Vehicle Colour:	BLUE		
Engine No:	PE10229258	Chassis No:	JM6CW1071F0121815
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO GIA REPORT ATTACHED.		
Remarks:	VEHICLE CURRENTLY LYING YISHUN WORKSHOP.		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

Not Authorized
11/8/18, 7605
Resurvey After Repair

COST OF CLAIMS

Parts	0.00
Miscellaneous Items	35.00
Labour	3,130.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	3,165.00
+ GST 7.00% (\$\$)	221.55
Nett Amount (\$\$)	3,386.55

This claim is handled by: **SHARON CHIONG BENG CHOON**Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

SKT 8264S

00/Longue

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 20 Jul 2018)

Parts: N/A MAZDA 5 2.0 5 DR WAGON (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SKT8264S/20/07/2018 14:11

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1 pc frt bumper	CRM 0.00	0.00	680	- ✓
2	1		*1 pc frt bumper reinforcement	0.00	0.00	180	- ✓
3	1		*1 pc frt bumper sponge	0.00	0.00	40	- ✓
4	1		*1 pc frt bumper centre lower grille	DM 0.00	0.00	420	- ✓
5	1		*1 pc frt bumper logo	RM 0.00	0.00	20	- ✓
6	1		*1 pc frt bumper RH fog lamp	0.00	0.00	140	- ✓
7	1		*1 pc frt bumper RH fog lamp garnish	0.00	0.00	35	- ✓
8	1		*1 pc frt bumper RH side retainer	DM 0.00	0.00	12	- ✓
9	1		*1 pc frt bumper tow cover	Sh 0.00	0.00	20	- ✓
10	1		*10 pcs frt bumper clips	RM 0.00	0.00	30	- ✓
11	1		*1 pc frt bumper top ganish	CRM 0.00	0.00	12	- ✓
12	1		*6 pcs frt bumper top ganish clips	RM 0.00	0.00	1100	- ✓
13	1		*2 pcs headlamps	MS MS RM 0.00	0.00	40	- ✓
14	1		*2 pcs headlamp lower inner garnish	CRM 0.00	0.00	240	- ✓
15	1		*1 pc frt support panel	RM 0.00	0.00	130	- ✓
16	1		*1 pc frt RH fender	RM 0.00	0.00	480	- ✓
17	1		*1 pc frt RH fender inner panel	RM 0.00	0.00	80	- ✓
18	1		*1 pc frt RH fender inner shield	CRM 0.00	0.00	12	- ✓
19	1		*6 pcs frt RH fender inner shield clips	RM 0.00	0.00	32	- ✓
20	1		*1 pc frt RH fender triangle garnish	DM 0.00	0.00	25	- ✓
21	1		*1 pc frt number plate garnish	0.00	0.00	100	- ✓
22	1		*1 pc wiper garnish RH extension	DM 0.00	0.00	850	- ✓
23	1		*1 pc frt wiper tank	DM 0.00	0.00	28	- ✓
24	1		*1 set power steering pump	0.00	0.00	130	- ✓
25	1		*1 pc power steering ele switch	0.00	0.00	190	- ✓
26	1		*1 pc power steering ele switch hose	0.00	0.00	800	- ✓
27	1		*1 pc engine RH mounting	0.00	0.00	280	- ✓
28	1		*1 pc engine RH mounting bracket	0.00	0.00	150	- ✓
29	1		*1 pc engine top cover	CRM 0.00	0.00	75	- ✓
30	1		*1 pc exhaust manifold assy	RM 0.00	0.00	1000	- ✓
31	1		*1 pc throttle body assy	RM 0.00	0.00	110	- ✓
32	1		*1 pc air filter housing	RM 0.00	0.00	1400	- ✓
33	1		*1 pc air filter housing ducting	DM 0.00	0.00	1300	- ✓
34	1		*1 pc steering air bag	RM 0.00	0.00	210	- ✓
35	1		*1 pc steering air bag clock spring sensor	RM 0.00	0.00	520	- ✓
36	1		*1 pc passenger air bag	RM 0.00	0.00	580	- ✓
37	1		*2 pcs frt safety belts	RM 0.00	0.00	90	- ✓
38	1		*1 pc passenger air bag cable	RM 0.00	0.00	36	- ✓
39	1		*2 pcs air bag sensors	RM 0.00	0.00	40	- ✓
40	1		*1 pc air bag ECU	RM 0.00	0.00	10	- ✓

Cheng Hoe Motor Pte Ltd/SKT8264S/20/07/2018 14:11. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Sub Total (\$\$)						0.00
+ Margin on L,N Items 15.00% (\$\$)						0.00
Total Parts (\$\$)						0.00

Cheng Hoe Motor Pte Ltd/SKT8264S/20/07/2018 14:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items


No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	1 pc frt number plate	35.00
Sub Total (\$\$)			35.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	towing	New	50.00
2	Remove & refix air-con,check,vacuum & refill gas	New	100.00
3	Panel beating including straighten frt RH chassis,renew frt support panel & frt RH fender inner panel	New	1,300.00
4	Remove & refix air-bag,safety belts & reset system	New	200.00
5	Remove & refix dashboard,meter assy & check wiring	New	250.00
6	Remove & refix engine manifold assy,steering pump assy,throttle body assy,engine mounting & reset system	New	250.00
7	Putty & respray on frt bumper,frt both fenders,bonnet,hinges,frt both wheel housing,support panel	New	980.00
Gross Labour Cost (\$\$)			3,130.00

Cheng Hoe Motor Pte Ltd/SKT8264S/20/07/2018 14:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: **Lonpac Insurance Bhd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/LONPAC
Policy No:	Z/17/VP05/015486	Date of Loss:	17/07/2018
Vehicle Reg. No.:	SKT8264S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WONG FOCK HONG(HUANG FU XIONG)		
Driver:	WONG FOCK HONG(HUANG FU XIONG)		

Make/Model:	MAZDA 5, 2.0 5 DR WAGON (A)	Vehicle Reg. Date:	24/06/2015
Vehicle Colour:	BLUE		
Engine No:	PE10229258	Chassis No:	JM6CW1071F0121815
Odometer:	0 KM		

Paint Type:
Total Loss?
Est. Duration of Repair (day)

NO
0

Description of Accident/Loss

REFER TO GIA REPORT ATTACHED.

Remarks:

VEHICLE CURRENTLY LYING YISHUN WORKSHOP.

Present Location:

CHENG HOE MOTOR PTE LTD (YISHUN)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

* Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

COST OF CLAIMS

	Amount
Parts	15,631.95
Miscellaneous Items	35.00
Labour	3,130.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	19,262.70
+ GST 7.00% (S\$)	1,315.79
Nett Amount (S\$)	20,112.74

This claim is handled by: **SHARON CHIONG BENG CHOON**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Jul 2018)
Parts:	N/A MAZDA 5 2.0 5 DR WAGON (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	Cheng Hoe Motor Pte Ltd/SKT8264S/23/07/2018 14:05
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc frt bumper	0.00	0.00	CRA *680.00 F ✓
2	1		*1 pc frt bumper reinforcement	0.00	0.00	A *180.00 F ✓
3	1		*1 pc frt bumper sponge	0.00	0.00	CM *40.00 F ✓
4	1		*1 pc frt bumper centre lower grille	0.00	0.00	DD *420.00 F ✓
5	1		*1 pc frt bumper logo	0.00	0.00	Nec *20.00 F ✓
6	1		*1 pc frt bumper RH fog lamp	0.00	0.00	CM *140.00 F ✓
7	1		*1 pc frt bumper RH fog lamp garnish	0.00	0.00	in *35.00 F X
8	1		*1 pc frt bumper RH side retainer	0.00	0.00	DIS *12.00 F ✓
9	1		*1 pc frt bumper tow cover	0.00	0.00	SVC *20.00 F X
10	1		*10 pcs frt bumper clips	0.00	0.00	Nec *30.00 F ✓
11	1		*6 pcs frt bumper top ganish clips	0.00	0.00	Nec *12.00 F ✓
12	1		*2 pcs headlamps	0.00	0.00	o/s Bro N/A *1,100.00 F ✓
13	1		*2 pcs headlamp lower inner garnish	0.00	0.00	o/s CRA *40.00 F 1pc
14	1		*1 pc frt support panel	0.00	0.00	BRO *240.00 F ✓
15	1		*1 pc frt RH fender	0.00	0.00	BT *130.00 F ✓
16	1		*1 pc frt RH fender inner panel	0.00	0.00	BT *480.00 F ✓
17	1		*1 pc frt RH fender inner shield	0.00	0.00	CRA *80.00 F ✓
18	1		*6 pcs frt RH fender inner shield clips	0.00	0.00	NEC *12.00 F ✓
19	1		*1 pc frt RH fender triangle garnish	0.00	0.00	DIS *32.00 F ✓
20	1		*1 pc wiper garnish RH extension	0.00	0.00	DD *25.00 F ✓
21	1		*1 pc frt wiper tank	0.00	0.00	del *100.00 F ✓
22	1		*1 set power steering pump	0.00	0.00	Hyg CRA *850.00 F ✓
23	1		*1 pc power steering ele switch hose	0.00	0.00	SVC *28.00 F X
24	1		*1 pc engine RH mounting	0.00	0.00	CM *130.00 F ✓
25	1		*1 pc engine top cover	0.00	0.00	nd *190.00 F ✓
26	1		*1 pc exhaust manifold assy	0.00	0.00	Bz *800.00 F ✓
27	1		*1 pc throttle body assy	0.00	0.00	CM *380.00 F ✓
28	1		*1 pc air filter housing	0.00	0.00	CM *150.00 F ✓
29	1		*1 pc air filter housing ducting	0.00	0.00	DD *75.00 F ✓
30	1		*1 pc steering air bag	0.00	0.00	Burst *1,000.00 F ✓
31	1		*1 pc steering air bag clock spring sensor	0.00	0.00	Nec *110.00 F ✓
32	1		*1 pc passenger air bag	0.00	0.00	Burst *1,400.00 F ✓
33	1		*2 pcs frt safety belts	0.00	0.00	Im *1,300.00 F ✓
34	1		*2 pcs air bag sensors	0.00	0.00	Nec *210.00 F ✓
35	1		*1 pc air bag ECU	0.00	0.00	Nec *520.00 F ✓
36	1		*1 pc bonnet	0.00	0.00	Rn *380.00 F ✓
37	1		*1 pc bonnet inner lock	0.00	0.00	Ry *80.00 F ✓
38	1		*1 pc bonnet inner lock cable	0.00	0.00	Im *36.00 F ✓
39	1		*1 pc bonnet inner sponge	0.00	0.00	Refurb *40.00 F ✓
40	1		*4 pcs bonnet inner sponge clips	0.00	0.00	in *10.00 F ✓
41	1		*1 pc bonnet inner frt rubber	0.00	0.00	CM *32.00 F ✓
42	1		*1 pc bonnet inner rear rubber	0.00	0.00	CM *20.00 F ✓
43	1		*2 pcs bonnet hinges	0.00	0.00	Ry *44.00 F ✓
44	1		*1 pc frt support panel	0.00	0.00	Ry *300.00 F ✓
45	1		*1 pc air-con condenser	0.00	0.00	Pu *320.00 F ✓

Cheng Hoe Motor Pte Ltd/SKT8264S/23/07/2018 14:05. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
46	1		*1 set radiator fan motor assy	<i>Ja</i> 0.00	0.00	*700.00 F	✓
47	1		*1 pc air-con discharge hose	0.00	0.00	<i>Ac</i> *160.00 F	✓
48	1		*1 pc air-con receiver hose	0.00	0.00	<i>As</i> *180.00 F	✓
49	1		*1 pc air-con discharge pipe	0.00	0.00	<i>At</i> *170.00 F	✓
50	1		*1 pc radiator spare tank	<i>Ad</i> 0.00	0.00	*40.00 F	✓
51	1		*1 pc radiator spare tank hose	0.00	0.00	<i>Aw</i> *32.00 F	✓
52	1		*1 pc radiator top hose	<i>Ar</i> 0.00	0.00	*39.00 F	✓
53	1		*1 pc radiator bottom hose	0.00	0.00	<i>Aw</i> *39.00 F	✓

F=Franchise part.

Sub Total (S\$)	13,593.00
+ Margin on L,N Items 15.00% (S\$)	2,038.95
Total Parts (S\$)	15,631.95

Cheng Hoe Motor Pte Ltd/SKT8264S/23/07/2018 14:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	1 pc frt number plate	35.00 ✓
Sub Total (S\$)			35.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	towing	New	50.00 ✓
2	Remove & refix air-con,check,vaccum & refill gas	New	100.00 ✓
3	Panel beating including straighten frt RH chassis,renew frt support panel & frt RH fender inner panel	New	1,300.00 / 200 ✓
4	Remove & refix air-bag,safety belts & reset system	New	200.00 ✓
5	Remove & refix dashboard,meter assy & check wiring	New	250.00 ✓
6	Remove & refix engine manifold assy,steering pump assy,throttle body assy,engine mounting & reset system	New	250.00 200 ✓
7	Putty & respray on frt bumper,frt both fenders,bonnet,hinges,frt both wheel housing,support panel	New	980.00 900 ✓
Gross Labour Cost (S\$)			3,130.00

Cheng Hoe Motor Pte Ltd/SKT8264S/23/07/2018 14:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 03 Sep 2018)**Parts:** N/A MAZDA 5 2.0 5 DR WAGON (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Cheng Hoe Motor Pte Ltd/SKT8264S/03/09/2018 18:38**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc engine valve cover	0.00	0.00	CM *270.00 F ✓
2	1	55	*1 pc power steering oil tank	0.00	0.00	CM *55.00 F ✓
3	1		*1 pc radiator filler	0.00	0.00	CM *80.00 F ✓
Sub Total (S\$)						405.00
+ Margin on L,N Items 15.00% (S\$)						60.75
Total Parts (S\$)						465.75

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SKT8264S/03/09/2018 18:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jul 2018 Sendback Est	23 Jul 2018 14:05 \$18,796.95	20 Jul 2018 14:19 Edit Adj Rpt	\$14,750.00 Edit Estimates	\$14,750.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	03 Sep 2018 18:36	03 Sep 2018 18:38 \$465.75	03 Sep 2018 18:38			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	WONG FOCK HONG(HUANG FU XIONG) , ID: S74117891		
Vehicle Reg. No.:	SKT8264S	Date of Loss:	17/07/2018 15:00 - :59 [36 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 17/18/18/VP05/020761	Policy/Cover Note No.:	Z/17/VP05/015486 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	Lompac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 31/07/2018]		
Driver/Custodian:	WONG FOCK HONG(HUANG FU XIONG) (), NRIC: S74117891		
Adj Asg. Remarks:	SURVEY & REVERT. WORKSHOP HAS YET TO UPLOAD ESTIMATES.		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- LONPAC_HQ (30/07/2018): Alert - Adj Mandate Approved (\$14750.00) - SKT8264S - Claim Handler: Gerald Poh
- LONPAC_HQ (30/07/2018): Alert - Adj Mandate Approved (\$14750.00) - SKT8264S - Claim Handler: Gerald Poh

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)





































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKT8264S (17/18/18/VP05/020761)
OD
Jul 17 2018 3:00PM
[WONG FOCK HONG(HUANG FU XIONG)]
Cheng Hoe Motor Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print	
1	23/07/18 14:05	Repairer Estimates	 Load HTM		
2	03/09/18 18:38	Repairer Estimates Suppl. #1	 Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	24/07/18 15:34	Adjuster Immediate Advice	 Load HTM		
2	27/07/18 16:20	Adjuster Immediate Advice	 Load HTM		
3	27/07/18 16:23	Adjuster Immediate Advice	 Load HTM		
4	27/07/18 16:27	Adjuster Immediate Advice	 Load HTM		
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
22	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
23	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
24	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
25	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
26	24/07/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>	
27	18/12/18 10:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>	
28	18/12/18 10:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>	
29	18/12/18 10:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>	
30	18/12/18 10:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
31	18/12/18 10:24	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
32	18/12/18 10:24	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
33	18/12/18 10:25	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
34	18/12/18 10:25	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
35	18/12/18 10:25	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
36	18/12/18 10:25	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
37	18/12/18 10:25	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	20/07/18 14:08	IC & DL		Load JPG	<input checked="" type="checkbox"/>
2	20/07/18 14:08	GIA REPORT		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/07/18 15:41	SKT 82645 ESTIMATE		Load PDF	
2	27/07/18 16:32	LUMP SUM LETTER		Load PDF	
3	26/12/18 09:22	Supplementary		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lompac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC18013252/KRD3E2

Date: 26/12/2018

REFERENCE

Insured/Claimant: WONG FOCK HONG(HUANG FU XIONG)

Policy No: Z/17/VP05/015486

Date of Loss: 17/07/2018

Nature of Claim: OD

Claim No: 17/18/18/VP05/020761

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKT8264S

Make & Model: MAZDA 5, 2.0 5 DR WAGON (A)

Engine No: PE10229258

Reg. Date: 24/06/2015 (Man. Year: 2015)

Chassis No: JM6CW1071F0121815

Colour: Metallic Dark Blue

Odometer: 0 km

Engine Capacity: 1998 cc

Market Value/New Car Price: S\$76,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 7 mm

Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm

Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,097.70	15,979.25	118.45	0.74
Miscellaneous Items	35.00	35.00	0.00	0.00
Labour	3,130.00	2,900.00	230.00	7.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,262.70	18,914.25	348.45	1.81
Approved Total (Overridden) (S\$)		14,750.00		
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	19,262.70	14,250.00	5,012.70	26.02
+ GST 7.00/7.00% (S\$)	1,348.39	997.50	350.89	26.02
Nett Amount (S\$)	20,611.09	15,247.50	5,363.59	26.02

INSPECTION

Date of Assignment: 20/07/2018 Present Location:

Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 20/07/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial
Park A
Singapore 768761

Estimated Period of Repair: 14.0 days

Adjuster: KENNETH KONG**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Dec 2018)	
Parts:	N/A	MAZDA 5 2.0 5 DR WAGON (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT8264S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 pc frt bumper (WCP)	Cracked	680.00 F	*680.00 F
2	1		*1 pc frt bumper reinforcement (WCP)	Bent	180.00 F	*180.00 F
3	1		*1 pc frt bumper sponge (WCP)	Cracked	40.00 F	*40.00 F
4	1		*1 pc frt bumper centre lower grille (WCP)	Dented	420.00 F	*420.00 F
5	1		*1 pc frt bumper logo (WCP)	Necessary	20.00 F	*20.00 F
6	1		*1 pc frt bumper RH fog lamp (WCP)	Cracked	140.00 F	*140.00 F
7	1		*1 pc frt bumper RH fog lamp garnish (WCP)	Serviceable	35.00 F	*- F
8	1		*1 pc frt bumper RH side retainer (WCP)	Distorted	12.00 F	*12.00 F
9	1		*1 pc frt bumper tow cover (WCP)	Serviceable	20.00 F	*- F
10	1		*10 pcs frt bumper clips (WCP)	Necessary	30.00 F	*30.00 F
11	1		*6 pcs frt bumper top ganish clips (WCP)	Necessary	12.00 F	*12.00 F
12	1		*2 pcs headlamps (WCP)	O/S Broken / N/S Mtg Broken	1,100.00 F	*1,100.00 F
13	1		*2 pcs headlamp lower inner garnish (WCP)	O/S Cracked	40.00 F	*20.00 F
14	1		*1 pc frt support panel (WCP)	Broken	240.00 F	*240.00 F
15	1		*1 pc frt RH fender (WCP)	Bent	130.00 F	*130.00 F
16	1		*1 pc frt RH fender inner panel (WCP)	Bent	480.00 F	*480.00 F
17	1		*1 pc frt RH fender inner shield (WCP)	Cracked	80.00 F	*80.00 F
18	1		*6 pcs frt RH fender inner shield clips (WCP)	Necessary	12.00 F	*12.00 F
19	1		*1 pc frt RH fender triangle garnish (WCP)	Distorted	32.00 F	*32.00 F
20	1		*1 pc wiper garnish RH extension (WCP)	Dented	25.00 F	*25.00 F
21	1		*1 pc frt wiper tank (WCP)	Dented	100.00 F	*100.00 F
22	1		*1 set power steering pump (WCP)	Mtg Cracked	850.00 F	*850.00 F
23	1		*1 pc power steering ele switch hose (WCP)	Serviceable	28.00 F	*- F
24	1			Cracked	130.00 F	*130.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
		*1 pc engine RH mounting (WCP)			
25	1	*1 pc engine top cover (WCP)	Dented	190.00 F	*190.00 F
26	1	*1 pc exhaust manifold assy (WCP)	Broken	800.00 F	*800.00 F
27	1	*1 pc throttle body assy (WCP)	Cracked	380.00 F	*380.00 F
28	1	*1 pc air filter housing (WCP)	Cracked	150.00 F	*150.00 F
29	1	*1 pc air filter housing ducting (WCP)	Dented	75.00 F	*75.00 F
30	1	*1 pc steering air bag (WCP)	Burst	1,000.00 F	*1,000.00 F
31	1	*1 pc steering air bag clock spring sensor (WCP)	Necessary	110.00 F	*110.00 F
32	1	*1 pc passenger air bag (WCP)	Burst	1,400.00 F	*1,400.00 F
33	1	*2 pcs frt safety belts (WCP)	Jammed	1,300.00 F	*1,300.00 F
34	1	*2 pcs air bag sensors (WCP)	Necessary	210.00 F	*210.00 F
35	1	*1 pc air bag ECU (WCP)	Necessary	520.00 F	*520.00 F
36	1	*1 pc bonnet (WCP)	Buckled	380.00 F	*380.00 F
37	1	*1 pc bonnet inner lock (WCP)	Bent	80.00 F	*80.00 F
38	1	*1 pc bonnet inner lock cable (WCP)	Jammed	36.00 F	*36.00 F
39	1	*1 pc bonnet inner sponge (WCP)	Deformed	40.00 F	*40.00 F
40	1	*4 pcs bonnet inner sponge clips (WCP)	Necessary	10.00 F	*10.00 F
41	1	*1 pc bonnet inner frt rubber (WCP)	Cut	32.00 F	*32.00 F
42	1	*1 pc bonnet inner rear rubber (WCP)	Cut	20.00 F	*20.00 F
43	1	*2 pcs bonnet hinges (WCP)	Bent	44.00 F	*44.00 F
44	1	*1 pc frt support panel (WCP)	Bent	300.00 F	*300.00 F
45	1	*1 pc air-con condenser (WCP)	Punctured	320.00 F	*320.00 F
46	1	*1 set radiator fan motor assy (WCP)	Jammed	700.00 F	*700.00 F
47	1	*1 pc air-con discharge hose (WCP)	Punctured	160.00 F	*160.00 F
48	1	*1 pc air-con receiver hose (WCP)	Bent	180.00 F	*180.00 F
49	1	*1 pc air-con discharge pipe (WCP)	Bent	170.00 F	*170.00 F
50	1	*1 pc radiator spare tank (WCP)	Dented	40.00 F	*40.00 F
51	1	*1 pc radiator spare tank hose (WCP)	Cut	32.00 F	*32.00 F
52	1	*1 pc radiator top hose (WCP)	Punctured	39.00 F	*39.00 F
53	1	*1 pc radiator bottom hose (WCP)	Cut	39.00 F	*39.00 F
Supplementary #1					
54	1	*1 pc engine valve cover (WCP)	Cracked	270.00 F	*270.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1	55	*1 pc power steering oil tank (WCP)	Cracked	55.00 F	*55.00 F
56	1		*1 pc radiator filler (WCP)	Cracked	80.00 F	*80.00 F
F=Franchise part.						
Sub Total (\$\$)					13,998.00	13,895.00
+ Margin on L,N Items 15.00/15.00% (\$\$)					2,099.70	2,084.25
Total Parts (\$\$)					16,097.70	15,979.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 pc frt number plate (DENTED)	35.00	35.00
Sub Total (S\$)			35.00	35.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	towing	New	50.00	50.00
2	Remove & refix air-con,check,vaccum & refill gas	New	100.00	100.00
3	Panel beating including straighten frt RH chassis,renew frt support panel & frt RH fender inner panel	New	1,300.00	1,200.00
4	Remove & refix air-bag,safety belts & reset system	New	200.00	200.00
5	Remove & refix dashboard,meter assy & check wiring	New	250.00	250.00
6	Remove & refix engine manifold assy,steering pump assy,throttle body assy,engine mounting & reset system	New	250.00	200.00
7	Putty & respray on frt bumper,frt both fenders,bonnet,hinges,frt both wheel housing,support panel	New	980.00	900.00
Gross Labour Cost (S\$)			3,130.00	2,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >