



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

5 Benoi Place Singapore 629926

Tel: 6861 0908 Fax: 6515 2948

Date: 19.07.2018

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO SHD2169T TOYOTA VELLFIRE (2014)

To Supply

1)	1pc	tailgate	\$	2,200.00	Bl ✓
2)	1pc	tailgate "Vellfire" emblem	\$	80.00	ne ✓
3)	1pc	tailgate "Toyota" logo	\$	90.00	ne ✓
4)	1pc	tailgate "E-Four" emblem	\$	70.00	ne ✓
5)	1pc	tailgate "Hybrid Synergy Drive" emblem	\$	60.00	ne ✓
6)	1pc	tailgate weatherstrip	\$	400.00	ne ✓
7)	1pc	rear bumper	\$	1,050.00	DE ✓
8)	1pc	rear bumper right retainer	\$	130.00	ne ✓
9)	1pc	rear bumper right bracket	\$	145.00	ne ✓
10)	2pcs	rear bumper left & right tow hook cover	\$	70.00	X in consist ✓
			@\$35.00		
11)	1set	rear bumper clip	\$	50.00	ne ✓
12)	1pc	rear bumper right reflector	\$	90.00	mis ✓
13)	1pc	right rear wheel house plate 65631-58010	\$	43.32	? X sur ✓
14)	1pc	right side back door opening frame 61775-58030	\$	205.50	? X sur ✓
15)	1pc	right rear wheel opening extension 61681-58030	\$	76.50	? X sur ✓
16)	1pc	right quarter wheel house outer panel 61631-58020	\$	620.70	Bl ✓
17)	1pc	exhaust tail pipe	\$	430.00	repair ✓
18)	1pc	rear bumper right parking sensor	\$	290.00	mis ✓
19)	1pc	rear bumper center parking sensor cover	\$	25.00	ne ✓
20)	1pc	right tail lamp lower corner panel	\$	200.00	DE X sur ✓

Sub total parts	\$	6,326.02
Less:25% discount	\$	(1,581.51)
	\$	4,744.51