

ASS. REC. BY

REF CS/FCI18013260/R19d3n2

Special Instruction

Surveyor

CWS

Rasul
Suzene Ler

ASSIGNMENT (Office)

From (Person)

of FCI

Date/Time: 20/7/18 @ 9.26am

Estimated Cost

Bill to:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SLP 8772B

Insured:

SHC 1729P

at Workshop n/z

Pegasus Engineering,
74 Kien Teck Rd

Tel:

65137748

of

Policy No.

Claim No:

D18005556MFSH

Sum Insured

Excess:

Make of Veh:

(Client's Record)

D.O.A 18/07/2018

CA / REV / REP. / REV 24 HRS 'DS'

Date/Time: 11.49am @ 20/7/18

Person Contacted

Alvin

H.O.D. Endorsement:

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLP 8772B-X
	SHC 1729P-CS/FCI 14020903/Uvj 3d1
24/7/18 @ 11.26am	Verified to Suzene Ler by email.
	Report finalised from fig \$4322.48, 8 days.
	CRK \$9817.68, 69.1%

Surveyor

REF:


13452

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SLP 8772B
 at Workshop m/s PELHUS
 of _____
 Insured: FCI / TP
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 8 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLP 8772B Yr Regn: 2017 / Sun
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: MAZDA 3 1.5 A c.c. 1496
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 45450 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 3M 6BN 22A 8461525 38
 Gen. Cond: Good / ☒ Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/60R16
 R: ~
☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 18/07/18 D.O.I. 20/07/18
 Survey held at PELHUS
 Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 12 MAR 2019.

24/7

Date/Time, File Pass to? ☐ : Preli. Report

1) 12/3 transit ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee: _____
 Transportation: _____
) \$ + RS. \$ _____
) Photos _____
) Others _____

TOTAL

Report Format : 7P

Lump Sum / I.B.I. (\$) 4320.48

4x15 = 60

170 + 60
 50
 50
 52

382



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18013260/R1qd3

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 20-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1729P	Veh. Inspected	SLP 8772B
Policy No.		Coverage (\$)	0.00
Claim No.	D18005556MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	20/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/07/2018	Inspection Date	20/07/2018
Survey held at	74 KIAN TECK ROAD		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005556MFSH

Date: 24 July 2018

Our Ref: CS/FCI18013260/R1qd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLP 8772B.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/07/2018 at the premises of M/s PEGASUS ENGINEERING, and have the following to report:-

Workshop Estimate Amount	: S\$ 14,138.16 .
Revised Estimate Amount	: S\$ 4,240.48 .
"Check" Items Amount	: S\$ 343.44 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the n/s portion.



Yours faithfully

Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	19-07-2018	Our Ref No. D18005556MFSH
Accident Date	18-07-2018	Claim Type. Third Party
Insured Vehicle	SHC1729P	Third Party Vehicle. SLP8772B
Survey Location	74 KIAN TECK ROAD	
Contact Person.	ALVIN LOW	
Contact No.	65137748/ 0	Fax No. 62513161
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED (NO EST. PROVIDED)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PEGASUS ENGINEERING & TRADING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 24 July 2018 11:26 AM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005556MFSH/1
Attachments: CSFC18013260R1qd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SLP 8772B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)

Sent: Friday, 20 July 2018 12:00 PM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18005556MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Thursday, 19 July 2018 9:25 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18005556MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	1345N

Vehicle Details

Vehicle No.:	SLP8772B
Vehicle to be Exported:	Yes
Intended De-registration Date:	19 Jul 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	P520444151
Chassis No.:	JM6BN22A8H0152536
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,761.00
Original Registration Date:	21 Jun 2017
First Registration Date:	21 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$9,761.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jun 2027
PARF Rebate Amount:	\$7,320.00

Intended COE Rebate Details

COE Expiry Date:	20 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,489.00
COE Rebate Amount:	\$37,191.00
Total Rebate Amount:	\$44,511.00

The information contained herein is correct as at 19 Jul 2018

OK



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO18/07-1250	Quotation Date : 19/07/2018	Terms : 30 DAYS
Vehicle No. : SLP8772B	Chassis No. : JM6BN22A8H0152536	Third Party Insurer : FIRST CAPITAL
Model : MAZDA 3	Date of Accident : 18/07/2018	
Remarks : INSURED'S VEH NO: SHC1729P		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	FRONT FENDER LH	1	1,175.0000 <i>repair</i>	1,175.00
2	FRONT FENDER INNER COWLING LH	1	235.0000 <i>X</i>	235.00
3	FRONT FENDER INNER COWLING CLIPS	4	5.0000 <i>new</i>	20.00
4	FRONT DOOR LH	1	1,062.0000 <i>BA</i>	1,062.00
5	FRONT DOOR INNER LOCK	1	214.0000 <i>X</i>	214.00
6	FRONT DOOR INNER LOCK STRIKER	1	26.0000 <i>X</i>	26.00
7	FRONT DOOR POWER WINDOW MOTOR	1	106.0000 <i>?</i>	106.00
8	FRONT DOOR REGULATOR	1	120.0000 <i>?</i>	120.00
9	FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	1	165.0000 <i>X</i>	165.00
10	FRONT DOOR OUTER WEATHERSTRIP MOULDING	1	77.0000 <i>new</i>	77.00
11	FRONT DOOR HINGE TOP	1	42.0000 <i>X</i>	42.00
12	FRONT DOOR HINGE BOTTOM	1	40.0000 <i>?</i>	40.00
13	FRONT DOOR CHECKER/ARRESTOR	1	37.0000 <i>X</i>	37.00
14	FRONT DOOR WEATHERSTRIP	1	107.0000 <i>new</i>	107.00
15	REAR DOOR LH	1	999.4000 <i>BA</i>	999.40
16	REAR DOOR OUTER HANDLE	1	60.1000 <i>X</i>	60.10
17	REAR DOOR OUTER HANDLE GARNISH EXTENSION	1	18.0000 <i>X</i>	18.00
18	REAR DOOR OUTER HANDLE INNER BASE	1	57.0000 <i>X</i>	57.00
19	REAR DOOR POWER WINDOW MOTOR	1	106.6000 <i>X</i>	106.60
20	REAR DOOR INNER LOCK	1	179.7000 <i>X</i>	179.70
21	REAR DOOR INNER LOCK STRIKER	1	26.0000 <i>X</i>	26.00
22	REAR DOOR WEATHERSTRIP	1	120.7000 <i>new</i>	120.70
23	REAR DOOR INNER TRIMBOARD	1	392.0000 <i>X</i>	392.00

C/F 0.00

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :

Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO18/07-1250	Quotation Date : 19/07/2018	Terms : 30 DAYS
Vehicle No. : SLP8772B	Chassis No. : JM6BN22A8H0152536	Third Party Insurer : FIRST CAPITAL
Model : MAZDA 3	Date of Accident : 18/07/2018	
Remarks : INSURED'S VEH NO: SHC1729P		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	REAR DOOR HINGE TOP	1	46.0000 X	46.00
25	REAR DOOR HINGE BOTTOM	1	42.6000 X	42.60
26	REAR DOOR CHECKER/ARRESTOR	1	37.0000 X	37.00
27	REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	1	166.8000 X	166.80
28	REAR DOOR WINDOW GLASS FRAME GARNISH FRONT	1	108.0000 X	108.00
29	REAR DOOR WINDOW GLASS FRAME GARNISH REAR	1	49.0000 X	49.00
30	REAR DOOR 1/4 GLASS PILLAR	1	110.0000 X	110.00
31	REAR DOOR 1/4 GLASS WEATHERSTRIP	1	41.6000 X	41.60
32	REAR DOOR WINDOW GLASS FRAME MOULDING TOP	1	72.0000 X	72.00
33	REAR DOOR OUTER WEATHERSTRIP CHROME MOULDING	1	141.0000 X	141.00
34	REAR DOOR RUBBER STOPPER	1	12.0000 ne	12.00
35	REAR DOOR REGULATOR	1	120.7000 ?	120.70
36	DOOR CENTRE B PILLAR WITH ROCKER PANEL	1	900.0000 X	900.00
37	FRONT SIDE MIRROR COVER LH	1	123.0000 X	123.00
38	FRONT SIDE MIRROR MOTOR LH	1	378.0000 X	378.00
39	FRONT SIDE MIRROR GLASS LH	1	103.0000 X	103.00
40	REAR FENDER	1	1,175.0000 Repair	1,175.00
41	REAR FENDER INNER COWLING	1	235.0000 X	235.00
42	REAR FENDER INNER COWLING CLIPS	4	5.0000 X	20.00
43	REAR SHOCK ABSORBER	1	307.0000 X	307.00
44	REAR LOWER ARM	1	250.0000 X	250.00
45	REAR WHEEL HUB CAP LH	1	90.0000 self	90.00

Rear fender seal (LHS) ne ✓

Rear fender sticker (LHS) ne ✓

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800
Officer in Charge : WEE TZE FAH Tel : Email :

Customer :
GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn : Tel : Fax No. :

Quotation No. : QO18/07-1250	Quotation Date : 19/07/2018	Terms : 30 DAYS
Vehicle No. : SLP8772B	Chassis No. : JM6BN22A8H0152536	Third Party Insurer : FIRST CAPITAL
Model : MAZDA 3	Date of Accident : 18/07/2018	
Remarks : INSURED'S VEH NO: SHC1729P		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
46	FRONT WHEEL HUB CAP LH	1	90.0000 X 3m	90.00
47	REAR WINDSHIELD GLASS WEATHERSTRIP	1	120.0000 X 1m	120.00
48	REAR BUMPER	1	1,075.0000 repair	1,075.00
49	REAR BUMPER SIDE RETAINER LH	1	37.0000 X 1m	37.00
50	REAR BUMPER CLIPS	10	5.0000 na	50.00
51	LESS 20% ON ITEM 1 - 50	1	-2,257.0400	-2,257.04
52	REAR WHEEL TYRE LH	1	250.0000 X 9	250.00
53	REAR WHEEL RIM LH	1	550.0000 X 1m	550.00
54	REAR WINDSCREEN GLASS SEALANT	1	120.0000 X 1m	120.00
55	REAR WINDSCREEN GLASS SPONGE	1	100.0000 X 1m	100.00
56	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1	120.0000 X 1m	120.00
57	TO TRANSFER OF REAR TYRE, RIM AND ON WHEEL BALANCING	1	100.0000 30	100.00
58	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	1	100.0000 60	100.00
59	TO DROP REAR AXLE AND SUSPENSION ASSY, REMOVE AND RENEWAL OF THE NECESSARY PARTS, TO CONDUCT FINAL CHECKING AND TESTING	1	150.0000 X 1m	150.00
60	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	150.0000 60	150.00
61	TO RUST-PROOFING OF THE AFFECTED AREAS	1	120.0000 80	120.00
62	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	100.0000 60	100.00
63	TO TRANSFER OF FRONT AND REAR LH DOOR FITTINGS, FIXTURE AND CONDUCT WATER SEEPAGE AND WINDS NOISE TEST	1	250.0000 120	250.00

C/F 0.00

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :

Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No :
--

Quotation No. : QO18/07-1250	Quotation Date : 19/07/2018	Terms : 30 DAYS
Vehicle No. : SLP8772B	Chassis No. : JM6BN22A8H0152536	Third Party Insurer : FIRST CAPITAL
Model : MAZDA 3	Date of Accident : 18/07/2018	
Remarks : INSURED'S VEH NO: SHC1729P		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
64	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	1,400.0000 <i>800</i>	1,400.00
65	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,600.0000 <i>1000</i>	1,600.00

LKIS Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Form
Hp 90010068
8 days
P/P
20/07/18 @ 1740
Rey bf paint

24/7/18

Sub Total	14,138.16
GST(7.00%)	989.67
Total (SGD)	15,127.83

Please conduct the survey at
 Pegasus Engineering @ 74 Kian Teck Road Singapore 628800



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800
Officer in Charge : WEE TZE FAH Tel : Email :

Customer :
GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn : Tel : Fax No. :

Quotation No. : QO18/07-1250	Quotation Date : 19/07/2018	Terms : 30 DAYS
Vehicle No. : SLP8772B	Chassis No. : JM6BN22A8H0152536	Third Party Insurer : FIRST CAPITAL
Model : MAZDA 3	Date of Accident : 18/07/2018	
Remarks : INSURED'S VEH NO: SHC1729P		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	FRONT FENDER LH	1	1,175.0000 <i>repair</i>	1,175.00
2	FRONT FENDER INNER COWLING LH	1	235.0000 <i>X Sur</i>	235.00
3	FRONT FENDER INNER COWLING CLIPS	4	5.0000 <i>Rece</i>	20.00
4	FRONT DOOR LH	1	1,062.0000 <i>BA</i>	1,062.00
5	FRONT DOOR INNER LOCK	1	214.0000 <i>X</i>	214.00
6	FRONT DOOR INNER LOCK STRIKER	1	26.0000 <i>X</i>	26.00
7	FRONT DOOR POWER WINDOW MOTOR	1	106.0000 <i>X Sur</i>	106.00
8	FRONT DOOR REGULATOR	1	120.0000 <i>X</i>	120.00
9	FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	1	165.0000 <i>X</i>	165.00
10	FRONT DOOR OUTER WEATHERSTRIP MOULDING	1	77.0000 <i>an</i>	77.00
11	FRONT DOOR HINGE TOP	1	42.0000 <i>X</i>	42.00
12	FRONT DOOR HINGE BOTTOM	1	40.0000 <i>? } an</i>	40.00
13	FRONT DOOR CHECKER/ARRESTOR	1	37.0000 <i>X</i>	37.00
14	FRONT DOOR WEATHERSTRIP	1	107.0000 <i>an</i>	107.00
15	REAR DOOR LH	1	999.4000 <i>BA</i>	999.40
16	REAR DOOR OUTER HANDLE	1	60.1000 <i>X</i>	60.10
17	REAR DOOR OUTER HANDLE GARNISH EXTENSION	1	18.0000 <i>X</i>	18.00
18	REAR DOOR OUTER HANDLE INNER BASE	1	57.0000 <i>X an</i>	57.00
19	REAR DOOR POWER WINDOW MOTOR	1	106.6000 <i>X</i>	106.60
20	REAR DOOR INNER LOCK	1	179.7000 <i>X</i>	179.70
21	REAR DOOR INNER LOCK STRIKER	1	26.0000 <i>X</i>	26.00
22	REAR DOOR WEATHERSTRIP	1	120.7000 <i>an</i>	120.70
23	REAR DOOR INNER TRIMBOARD	1	392.0000 <i>X an</i>	392.00

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO18/07-1250	Quotation Date : 19/07/2018	Terms : 30 DAYS
Vehicle No. : SLP8772B	Chassis No. : JM6BN22A8H0152536	Third Party Insurer : FIRST CAPITAL
Model : MAZDA 3	Date of Accident : 18/07/2018	
Remarks : INSURED'S VEH NO: SHC1729P		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	REAR DOOR HINGE TOP	1	46.0000 X	46.00
25	REAR DOOR HINGE BOTTOM	1	42.6000 X	42.60
26	REAR DOOR CHECKER/ARRESTOR	1	37.0000 X	37.00
27	REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	1	166.8000 X	166.80
28	REAR DOOR WINDOW GLASS FRAME GARNISH FRONT	1	108.0000 X	108.00
29	REAR DOOR WINDOW GLASS FRAME GARNISH REAR	1	49.0000 X	49.00
30	REAR DOOR 1/4 GLASS PILLAR	1	110.0000 X	110.00
31	REAR DOOR 1/4 GLASS WEATHERSTRIP	1	41.6000 X	41.60
32	REAR DOOR WINDOW GLASS FRAME MOULDING TOP	1	72.0000 X	72.00
33	REAR DOOR OUTER WEATHERSTRIP CHROME MOULDING	1	141.0000 X	141.00
34	REAR DOOR RUBBER STOPPER	1	12.0000 ne	12.00
35	REAR DOOR REGULATOR	1	120.7000 ?	120.70
36	DOOR CENTRE B PILLAR WITH ROCKER PANEL Repair	1	900.0000 X	900.00
37	FRONT SIDE MIRROR COVER LH	1	123.0000 X	123.00
38	FRONT SIDE MIRROR MOTOR LH	1	378.0000 X	378.00
39	FRONT SIDE MIRROR GLASS LH	1	103.0000 X	103.00
40	REAR FENDER	1	1,175.0000 Repair	1,175.00
41	REAR FENDER INNER COWLING	1	235.0000 X	235.00
42	REAR FENDER INNER COWLING CLIPS	4	5.0000 X	20.00
43	REAR SHOCK ABSORBER	1	307.0000 X	307.00
44	REAR LOWER ARM	1	250.0000 X	250.00
45	REAR WHEEL HUB CAP LH	1	90.0000 ref	90.00

Rear fender seal (LHS) ne ✓

Rear fender skeleton (LHS) ne ✓

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO18/07-1250	Quotation Date : 19/07/2018	Terms : 30 DAYS
Vehicle No. : SLP8772B	Chassis No. : JM6BN22A8H0152536	Third Party Insurer : FIRST CAPITAL
Model : MAZDA 3	Date of Accident : 18/07/2018	
Remarks : INSURED'S VEH NO: SHC1729P		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
46	FRONT WHEEL HUB CAP LH	1	90.0000	90.00
47	REAR WINDSHIELD GLASS WEATHERSTRIP	1	120.0000	120.00
48	REAR BUMPER	1	1,075.0000	1,075.00
49	REAR BUMPER SIDE RETAINER LH	1	37.0000	37.00
50	REAR BUMPER CLIPS	10	5.0000	50.00
51	LESS 20% ON ITEM 1 - 50	1	-2,257.0400	-2,257.04
52	REAR WHEEL TYRE LH	1	250.0000	250.00
53	REAR WHEEL RIM LH	1	550.0000	550.00
54	REAR WINDSCREEN GLASS SEALANT	1	120.0000	120.00
55	REAR WINDSCREEN GLASS SPONGE	1	100.0000	100.00
56	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1	120.0000	120.00
57	TO TRANSFER OF REAR TYRE, RIM AND ON WHEEL BALANCING	1	100.0000	100.00
58	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	1	100.0000	100.00
59	TO DROP REAR AXLE AND SUSPENSION ASSY, REMOVE AND RENEWAL OF THE NECESSARY PARTS, TO CONDUCT FINAL CHECKING AND TESTING	1	150.0000	150.00
60	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	150.0000	150.00
61	TO RUST-PROOFING OF THE AFFECTED AREAS	1	120.0000	120.00
62	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	100.0000	100.00
63	TO TRANSFER OF FRONT AND REAR LH DOOR FITTINGS, FIXTURE AND CONDUCT WATER SEEPAGE AND WINDS NOISE TEST	1	250.0000	250.00

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No :
---	--

Quotation No. : QO18/07-1250	Quotation Date : 19/07/2018	Terms : 30 DAYS
Vehicle No. : SLP8772B	Chassis No. : JM6BN22A8H0152536	Third Party Insurer : FIRST CAPITAL
Model : MAZDA 3	Date of Accident : 18/07/2018	
Remarks : INSURED'S VEH NO: SHC1729P		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
64	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	1,400.0000 800	1,400.00
65	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,600.0000 1000	1,600.00

Form Resurvey 23/7/18
Hp 90010068

8 days

P/P

20/07/18 @ 1740

Rey bf paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total	14,138.16
GST(7.00%)	989.67
Total (SGD)	15,127.83

30/07/2018



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573980 Attn : Tel : Fax No :
---	--

Quotation No. : QO18/07-1250	Quotation Date : 19/07/2018	Terms : 30 DAYS
Vehicle No. : SLP8772B	Chassis No. : JM6BN22A8H0152536	Third Party Insurer : FIRST CAPITAL
Model : MAZDA 3	Date of Accident : 18/07/2018	
Remarks : INSURED'S VEH NO: SHC1729P		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	FRONT FENDER LH	1	1,175.0000 <i>repair</i>	1,175.00
2	FRONT FENDER INNER COWLING LH	1	235.0000 <i>Xsu</i>	235.00
3	FRONT FENDER INNER COWLING CLIPS	4	5.0000 <i>new</i>	20.00
4	FRONT DOOR LH	1	1,062.0000 <i>BT</i>	1,062.00
5	FRONT DOOR INNER LOCK	1	214.0000 <i>Xsu</i>	214.00
6	FRONT DOOR INNER LOCK STRIKER	1	26.0000 <i>Xsu</i>	26.00
7	FRONT DOOR POWER WINDOW MOTOR	1	106.0000 <i>? Xsu</i>	106.00
8	FRONT DOOR REGULATOR	1	120.0000 <i>? Xsu</i>	120.00
9	FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	1	165.0000 <i>Xsu</i>	165.00
10	FRONT DOOR OUTER WEATHERSTRIP MOULDING	1	77.0000 <i>m</i>	77.00
11	FRONT DOOR HINGE TOP	1	42.0000 <i>X</i>	42.00
12	FRONT DOOR HINGE BOTTOM	1	40.0000 <i>? X</i>	40.00
13	FRONT DOOR CHECKER/ARRESTOR	1	37.0000 <i>? X</i>	37.00
14	FRONT DOOR WEATHERSTRIP	1	107.0000 <i>m</i>	107.00
15	REAR DOOR LH	1	999.4000 <i>HA</i>	999.40
16	REAR DOOR OUTER HANDLE	1	60.1000 <i>X</i>	60.10
17	REAR DOOR OUTER HANDLE GARNISH EXTENSION	1	18.0000 <i>X</i>	18.00
18	REAR DOOR OUTER HANDLE INNER BASE	1	57.0000 <i>X m</i>	57.00
19	REAR DOOR POWER WINDOW MOTOR	1	106.6000 <i>X</i>	106.60
20	REAR DOOR INNER LOCK	1	179.7000 <i>X</i>	179.70
21	REAR DOOR INNER LOCK STRIKER	1	26.0000 <i>X</i>	26.00
22	REAR DOOR WEATHERSTRIP	1	120.7000 <i>m</i>	120.70
23	REAR DOOR INNER TRIMBOARD	1	392.0000 <i>X m</i>	392.00

2386.10
 102.50
 50 W
 +
 2538.10
 507.62
 2030.48

C/F 0.00

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
---	---

Quotation No. : QO18/07-1250	Quotation Date : 19/07/2018	Terms : 30 DAYS
Vehicle No. : SLP8772B	Chassis No. : JM6BN22A8H0152538	Third Party Insurer : FIRST CAPITAL
Model : MAZDA 3	Date of Accident : 18/07/2018	
Remarks : INSURED'S VEH NO: SHC1729P		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	REAR DOOR HINGE TOP	1	46.0000	46.00
25	REAR DOOR HINGE BOTTOM	1	42.6000	42.60
26	REAR DOOR CHECKER/ARRESTOR	1	37.0000	37.00
27	REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	1	166.8000	166.80
28	REAR DOOR WINDOW GLASS FRAME GARNISH FRONT	1	108.0000	108.00
29	REAR DOOR WINDOW GLASS FRAME GARNISH REAR	1	49.0000	49.00
30	REAR DOOR 1/4 GLASS PILLAR	1	110.0000	110.00
31	REAR DOOR 1/4 GLASS WEATHERSTRIP	1	41.6000	41.60
32	REAR DOOR WINDOW GLASS FRAME MOULDING TOP	1	72.0000	72.00
33	REAR DOOR OUTER WEATHERSTRIP CHROME MOULDING	1	141.0000	141.00
34	REAR DOOR RUBBER STOPPER	1	12.0000	12.00
35	REAR DOOR REGULATOR	1	120.7000	120.70
36	DOOR CENTRE B PILLAR WITH ROCKER PANEL	1	900.0000	900.00
37	FRONT SIDE MIRROR COVER LH	1	123.0000	123.00
38	FRONT SIDE MIRROR MOTOR LH	1	378.0000	378.00
39	FRONT SIDE MIRROR GLASS LH	1	103.0000	103.00
40	REAR FENDER	1	1,175.0000	1,175.00
41	REAR FENDER INNER COWLING	1	235.0000	235.00
42	REAR FENDER INNER COWLING CLIPS	4	5.0000	20.00
43	REAR SHOCK ABSORBER	1	307.0000	307.00
44	REAR LOWER ARM	1	250.0000	250.00
45	REAR WHEEL HUB CAP LH	1	90.0000	90.00

Rear fender seal (LHS) ne ✓ 65
 Rear fender steel (LHS) ne c ✓ 35

C/F 0.00

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No :
---	--

Quotation No. : QO18/07-1250	Quotation Date : 19/07/2018	Terms : 30 DAYS
Vehicle No. : SLP8772B	Chassis No. : JM6BN22A8H0152538	Third Party Insurer : FIRST CAPITAL
Model : MAZDA 3	Date of Accident : 18/07/2018	
Remarks : INSURED'S VEH NO: SHC1729P		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
46	FRONT WHEEL HUB CAP LH	1	90.0000	90.00
47	REAR WINDSHIELD GLASS WEATHERSTRIP	1	120.0000	120.00
48	REAR BUMPER	1	1,075.0000	1,075.00
49	REAR BUMPER SIDE RETAINER LH	1	37.0000	37.00
50	REAR BUMPER CLIPS	10	5.0000	50.00
51	LESS 20% ON ITEM 1 - 50	1	-2,257.0400	-2,257.04
52	REAR WHEEL TYRE LH	1	250.0000	250.00
53	REAR WHEEL RIM LH	1	550.0000	550.00
54	REAR WINDSCREEN GLASS SEALANT	1	120.0000	120.00
55	REAR WINDSCREEN GLASS SPONGE	1	100.0000	100.00
56	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1	120.0000	120.00
57	TO TRANSFER OF REAR TYRE, RIM AND ON WHEEL BALANCING	1	100.0000	100.00
58	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	1	100.0000	100.00
59	TO DROP REAR AXLE AND SUSPENSION ASSY, REMOVE AND RENEWAL OF THE NECESSARY PARTS, TO CONDUCT FINAL CHECKING AND TESTING	1	150.0000	150.00
60	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	150.0000	150.00
61	TO RUST-PROOFING OF THE AFFECTED AREAS	1	120.0000	120.00
62	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	100.0000	100.00
63	TO TRANSFER OF FRONT AND REAR LH DOOR FITTINGS, FIXTURE AND CONDUCT WATER SEEPAGE AND WINDS NOISE TEST	1	250.0000	250.00

Parts : 42,538.10

C/F 0.00

Page 3 of 4

2,030.48
 2,210.00

 4,240.48

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No :
---	--

Quotation No. : QO18/07-1250	Quotation Date : 19/07/2018	Terms : 30 DAYS
Vehicle No. : SLP8772B	Chassis No. : JM6BN22A8H0152536	Third Party Insurer : FIRST CAPITAL
Model : MAZDA 3	Date of Accident : 18/07/2018	
Remarks : INSURED'S VEH NO: SHC1729P		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
64	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	1,400.0000	1,400.00
65	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,600.0000	1,600.00

P — # 2030.48
 L — # 2210.50
 Suppl — # 85.60
 P — # 4326.08
 P/P
 4320.48

Reay 25/7/18
 From
 Hp 90010068

8 days
 P/P
 20/07/18 @ 1740

Reay bf paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Sub Total	14,138.16
GST(7.00%)	989.67
Total (SGD)	15,127.83

Please conduct the survey at
 Pegasus Engineering @ 74 Kian Teck Road Singapore 628800



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No :
---	--

Quotation No. : QO18/08-1250	Quotation Date : 21/08/2018	Terms : 30 DAYS
Vehicle No. : SLP8772B	Chassis No. : JM6BN22A8H0152536	Third Party Insurer : FIRST CAPITAL
Model : MAZDA 3		Date of Accident : 18/07/2018
Remarks : SUPPLEMENTARY ITEM FOR SLP8772B		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR FENDER SEAL LHS	1	65.0000	65.00
2	REAR FENDER STICKER	1	35.0000	35.00
3	LESS 20% ON ITEM 1 - 2	1	-20.0000	-20.00

Sub Total	80.00
GST(7.00%)	5.60
Total (SGD)	85.60

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18013260/R1qd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-03-2019



Code : FCI2

Policy Particulars :- THIRD PARTY CLAIM

1.

Insured Veh.	SHC 1729P	Veh. Inspected	SLP 8772B
Policy No.		Coverage (\$)	0.00
Claim No.	D18005556MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	20/07/2018

Vehicle Particulars & Condition

2.

Make & Model	MAZDA 3 1.5 A	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0152536	Colour	BLUE
Odometer	45450	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

Conditions of Tyres

3.

	Size	Make	Balance
R/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm

Description of Damages

4.

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

General Information

5.

Accident Date	18/07/2018	Inspection Date	20/07/2018
Survey held at	74 KIAN TECK ROAD		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		

Remarks

5a.

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Estimate Days of Repair

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 8772B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	1,175.00	-
1	FRONT FENDER INNER COWLING LH	SERVICEABLE	235.00	-
4	FRONT FENDER INNER COWLING CLIPS @\$5.00	NECESSARY	20.00	20.00
1	FRONT DOOR LH	BENT	1,062.00	1,062.00
1	FRONT DOOR INNER LOCK	SERVICEABLE	214.00	-
1	FRONT DOOR INNER LOCK STRIKER	SERVICEABLE	26.00	-
1	FRONT DOOR POWER WINDOW MOTOR	SERVICEABLE	106.00	-
1	FRONT DOOR REGULATOR	SERVICEABLE	120.00	-
1	FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	SERVICEABLE	165.00	-
1	FRONT DOOR OUTER WEATHERSTRIP MOULDING	NECESSARY	77.00	77.00
1	FRONT DOOR HINGE TOP	NOT NECESSARY	42.00	-
1	FRONT DOOR HINGE BOTTOM	NOT NECESSARY	40.00	-
1	FRONT DOOR CHECKER/ARRESTOR	NOT NECESSARY	37.00	-
1	FRONT DOOR WEATHERSTRIP	NECESSARY	107.00	107.00
1	REAR DOOR LH	BENT	999.40	999.40
1	REAR DOOR OUTER HANDLE	NOT NECESSARY	60.10	-
1	REAR DOOR OUTER HANDLE GARNISH EXTENSION	NOT NECESSARY	18.00	-
1	REAR DOOR OUTER HANDLE INNER BASE	NOT NECESSARY	57.00	-
1	REAR DOOR POWER WINDOW MOTOR	NOT NECESSARY	106.60	-
1	REAR DOOR INNER LOCK	NOT NECESSARY	179.70	-
1	REAR DOOR INNER LOCK STRIKER	NOT NECESSARY	26.00	-
1	REAR DOOR WEATHERSTRIP	NECESSARY	120.70	120.70
1	REAR DOOR INNER TRIMBOARD	NOT NECESSARY	392.00	-
1	REAR DOOR HINGE TOP	NOT NECESSARY	46.00	-
1	REAR DOOR HINGE BOTTOM	NOT NECESSARY	42.60	-
1	REAR DOOR CHECKER/ARRESTOR	NOT NECESSARY	37.00	-
1	REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	NOT NECESSARY	166.80	-
1	REAR DOOR WINDOW GLASS FRAME GARNISH FRONT	NOT NECESSARY	108.00	-
1	REAR DOOR WINDOW GLASS FRAME GARNISH REAR	NOT NECESSARY	49.00	-

Report Ref No. CS/FCI18013260/R1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR DOOR 1/4 GLASS PILLAR	NOT NECESSARY	110.00	-
1	REAR DOOR 1/4 GLASS WEATHERSTRIP	NOT NECESSARY	41.60	-
1	REAR DOOR WINDOW GLASS FRAME MOULDING TOP	NOT NECESSARY	72.00	-
1	REAR DOOR OUTER WEATHERSTRIP CHROME MOULDING	NOT NECESSARY	141.00	-
1	REAR DOOR RUBBER STOPPER	NECESSARY	12.00	12.00
1	REAR DOOR REGULATOR	NOT NECESSARY	120.70	-
1	DOOR CENTRE B PILLAR WITH ROCKER PANEL	NOT NECESSARY	900.00	-
1	FRONT SIDE MIRROR COVER LH	NOT NECESSARY	123.00	-
1	FRONT SIDE MIRROR MOTOR LH	NOT NECESSARY	378.00	-
1	FRONT SIDE MIRROR GLASS LH	NOT NECESSARY	103.00	-
1	REAR FENDER	TO REPAIR SEE LABOUR	1,175.00	-
1	REAR FENDER INNER COWLING	NOT NECESSARY	235.00	-
4	REAR FENDER INNER COWLING CLIPS @\$5.00	NOT NECESSARY	20.00	-
1	REAR SHOCK ABSORBER	NOT NECESSARY	307.00	-
1	REAR LOWER ARM	NOT NECESSARY	250.00	-
1	REAR WHEEL HUB CAP LH	SCRATCHED	90.00	90.00
1	REAR FENDER SEAL (LHS)(ADDITIONAL)	NECESSARY	65.00	65.00
1	REAR FENDER STICKER (ADDITIONAL)	NECESSARY	35.00	35.00
1	FRONT WHEEL HUB CAP LH	NOT NECESSARY	90.00	-
1	REAR WINDSHIELD GLASS WEATHERSTRIP	NOT NECESSARY	120.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,075.00	-
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	37.00	-
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
	LESS 20% DISCOUNT		-2,277.04	-527.62
			9,108.16	2,110.48
	SPECIAL NETT ITEMS			
1	REAR WHEEL TYRE LH (SN)	NOT NECESSARY	250.00	-
1	REAR WHEEL RIM LH (SN)	NOT NECESSARY	550.00	-
1	REAR WINDSCREEN GLASS SEALANT (SN)	NOT NECESSARY	120.00	-

Report Ref No. CS/FCI18013260/R1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN GLASS SPONGE (SN)	NOT NECESSARY	100.00	-
			1,020.00	-
	LABOUR			
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	TO TRANSFER OF REAR TYRE,RIM AND ON WHEEL BALANCING.		100.00	30.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		100.00	60.00
	TO DROP REAR AXLE AND SUSPENSION ASSY.REMOVE AND RENEWAL OF THE NECESSARY PARTS.TO CONDUCT FINAL CHECKING AND TESTING.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMMINGS,GARNISH AND OTHER,TO ENABLE REPAIR.		150.00	60.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		120.00	80.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		100.00	60.00
	TO TRANSFER OF FRONT AND REAR LH DOOR FITTINGS,FIXTURE AND CONDUCT WATER SEEPAGE AND WINDS NOISE TEST.		250.00	120.00
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION.REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FRONT FENDER LH,REAR FENDER AND REAR BUMPER.		1,400.00	800.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,600.00	1,000.00
			4,090.00	2,210.00
	GRAND TOTAL		14,218.16	4,320.48
RECOMMENDED COST OF REPAIRS				4,320.48

Report Ref No. CS/FCI18013260/R1qd3n2

MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.