



TO: LONPAC INSURANCE BHD
ATTN: MOTOR CLAIMS DEPT

DATE : 20-Aug-18

JOB TYPE: 3rd Party claim

VEH NO : SGQ3991Y

ESTIMATE REPORT

OWNER'S PARTICULAR

NAME: HO YIZHEN

ADDRESS:

MODEL :

NISSAN / LATIO 1.5L A

CHASSIS NO : JN1BAAC11Z0003434

ENGINE NO:

CONTACT NO H/P:

ACCIDENT DATE : 19/07/2018

TEL:

OWNERS INSURER : CHINA TAIPING

POLICY NO: DMPCSN3005461801

QUOTATION SUMMARY

CLAIM DETAIL: PARTS

REQUESTOR CONTACT :

HO / 67810300

S/NO	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER	1	\$436.00	\$436.00
2	FRONT BUMPER BRACKET	2	\$145.60	\$291.20
3	FRONT BUMPER RETAINER	2	\$22.10	\$44.20
4	FRONT BUMPER LOGO	1	\$40.50	\$40.50
5	FRONT BUMPER REINFORCEMENT	1	\$444.90	\$444.90
6	FRONT BUMPER SPONGE	1	\$207.20	\$207.20
7	FRONT BUMPER GRILLE	2	\$150.00	\$300.00
8	FRONT BUMPER LOWER GRILLE	1	\$137.80	\$137.80
9	FRONT BUMPER CLIP	13	\$2.60	\$33.80
10	FRONT HEADLAMP LH & RH	2	\$344.30	\$688.60
11	FRONT HEADLAMP BRACKET RH	2	\$45.00	\$90.00
12	FRONT RADIATOR ASSY	1	\$450.00	\$450.00
13	FRONT RADIATOR LOWER SIDE PANEL RH	1	\$98.00	\$98.00
14	FRONT RADIATOR SUPPORT PANEL	1	\$345.80	\$345.80
15	FRONT RADIATOR BRACE	1	\$56.00	\$56.00
16	FRONT RADIATOR GRILLE	2	\$95.00	\$190.00
17	FRONT RADIATOR TOP COVER	1	\$150.00	\$150.00
18	FRONT A/C CONDENSER	1	\$560.00	\$560.00
19	FRONT COOLINIG FAN BLADE	1	\$135.00	\$135.00

20 FRONT COOLING FAN MOTOR
21 FRONT COOLING FAN COWLING

1	\$240.00	\$240.00
1	\$155.00	\$155.00
PARTS PRICE :		\$5,094.00
LESS 30% :		\$1,528.20
TOTAL PARTS PRICE :		\$3,565.80

2 OF 2
ene/sm —
Xne —

2-4025.3
28/7-71


LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



CAR CITY AUTO CENTRE PTE LTD
Car City Always

Make / Model:

NISSAN LATIO 1.5 LA

Veh.Number:

SGQ3991Y

NO.	LABOUR AND SPRAY	LABOUR PRICE
1	TO REMOVE & REFIT ENGINE FOR PANEL BEATING ON DAMAGED AREA. KNOCK; STRAIGHTEN & RESHAPE.	\$1,200.00
2	TO CHECK & REPAIR WIRING SYSTEM, REMOVE & REPLACE DAMAGED WIRE.SIGNAL LIGHT WIRE, ALL LAMP WIRE, SENSOR WIRE & OTHER WIRING.	\$40.00
3	TO APPLY ANTI-RUST UNDERCOAT ON REPLACE & REPAIRED PANELS.	\$50.00
4	TO PUTTY, CLEANING, SANDING, POLISHING, WAXING & SPRAY PAINT ON ALL NECESSARY PARTS AND	\$1,000.00
5	TO REMOVE & VACUUM AIR-CON SYSTEM & CHARGE UP AIR-CON GAS.	\$120.00
6	TO CHECK STEERING GEOMETRY & CONDUCT 4-WHEEL ALIGNMENT. ROTATION OF 4 WHEEL & COMPUTED 4 WHEEL BALANCE	\$120.00
7	TOWING FEE	\$60.00
8	TO CHECK & COMPUTED; RESET ON FATAL SYSTEM SIGNAL. ENGINE LIGHT, SIT BELT LIGHT, ABS LIGHT...& OTHER	\$80.00
9	TO REMOVE & REPLACE AIR-CON CONDENSER & ALL PIPE OR HOSE.	\$100.00
10	TO REMOVE & REPLACE COOLING FAN ASSY. ALSO CHECK THE CONDITION OF ELECTRIC FANS, WIRE & SENSOR..	\$80.00
TOTAL		\$2,850

800

20

✓

900

100

50

30

Repld x

x