

Blk 9006 Tampines st93 #01-198 S'pore 528840

TEL: 6781 0300

FAX: 6782 0300

E- mail: ccacpl@singnet.com.sg

TO: LONPAC INSURANACE BHD

ATTN: MOTOR CLAIMS DEPT

ESTIMATE REPORT

OWNER'S PARTICULAR

NAME: HO YIZHEN

ADDRESS:

CHASSIS NO: JN1BAAC11Z0003434

VEH NO: SGQ3991Y

not Adril OF 2
now
n/531

DATE: 20-AUG-18

JOB TYPE: 3rd Party claim

NISSAN / LATIO 1.5L A

ENGINE NO:

ACCIDENT DATE: 19/07/2018

MODEL:

CONTACT NO H/P:

QUOTATION SUMMARY **CLAIM DETAIL: PARTS**

TEL:

OWNERS INSURER: CHINA TAIPING

POLICY NO: DMPCSN3005461801

HO / 67810300

REQUESTOR CONTACT:

S/NO	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	FRONT BUMPER	1	\$436.00	\$436.00	} .
2	FRONT BUMPER BRACKET	2	\$145.60	\$291.20	
3	FRONT BUMPER RETAINER	2	\$22.10	\$44.20 34]_
4	FRONT BUMPER LOGO	1	\$40.50	\$40.50 ne	
5	FRONT BUMPER REINFORCEMENT	1	\$444.90	\$444.90	5-

L	3	FRONT BUMPER RETAINER	2	\$22.10	\$44.20	14
	4	FRONT BUMPER LOGO	1	\$40.50	\$40.50	ner -
	5	FRONT BUMPER REINFORCEMENT	1	\$444.90	\$444.90	7-5-
	6	FRONT BUMPER SPONGE	1	\$207.20	\$207.20	73
	7	FRONT BUMPER GRILLE	2	\$150.00	\$300.00	cre -
	8	FRONT BUMPER LOWER GRILLE	1	\$137.80	\$137.80	741
	9	FRONT BUMPER CLIP	13	\$2.60	\$33.80	ru -
	10	FRONT HEADLAMP LH & RH	2	\$344.30	\$688.60	11550017C
	11	FRONT HEADLAMP BRACKET RH	2	\$45.00	\$90.00	11X
	12	FRONT RADIATOR ASSY	1	\$450.00	\$450.00	?
	13	FRONT RADIATOR LOWER SIDE PANEL RH	1	\$98.00	\$98.00	7.
	14	FRONT RADIATOR SUPPORT PANEL	1	\$345.80	\$345.80	51-
	15	FRONT RADIATOR BRACE	1	\$56.00	\$56.00	?
	16	FRONT RADIATOR GRILLE	2	\$95.00	\$190.00	(ne /
	17	FRONT RADIATOR TOP COVER	1	\$150.00	\$150.00	?
	18	FRONT A/C CONDENSER	1	\$560.00	\$560.00	?
	19	FRONT COOLINIG FAN BLADE	1	\$135.00	\$135.00	?

20 FRONT COOLING FAN MOTOR

21 FRONT COOLING FAN COWLING

\$240.00

\$155.00

\$240.00 **?** \$155.00 **?**

1 PARTS PRICE :

1

\$5,094.00

LESS 30% :

\$1,528.20

TOTAL PARTS PRICE:

\$3,565.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Make / Model:

NISSAN LATIO 1.5 LA

Veh.Number:

SGQ3991Y

NO.	LABOUR AND SPRAY	LABOUR PRICE	
	TO REMOVE & REFIT ENGINE FOR PANEL BEATING ON DAMAGED AREA. KNOCK; STRAIGHTEN & RESHAPE.		
1		\$1,200.00	700
	TO CHECK & REPAIR WIRING SYSTEM, REMOVE & REPLACE DAMAGED WIRE.SIGNAL LIGHT WIRE, ALL LAMP WIRE, SENSOR WIRE & OTHER WIRING.	640.00	20
3	TO APPLY ANTI-RUST UNDERCOAT ON REPLACE & REPAIRED PANELS.	\$40.00 \$50.00	
4	TO PUTTY, CLEANING, SANDING, POLISHING, WAXING & SPRAY PAINT ON ALL NECESSARY PARTS AND	\$1,000.00	900
5	TO REMOVE & VACUUM AIR-CON SYSTEM & CHARGE UP AIR-CON GAS.	\$120.00	100
6	POTATION OF A WHEEL & COMPUTED A WHEEL PALANCE	\$120.00	
7	TOWING FEE	\$60.00	50
8	TO CHECK & COMPUTED; RESET ON FATAL SYSTEM SIGNAL. ENGINE LIGHT, SIT BELT LIGHT, ABS LIGHT& OTHER	\$80.00	30
9	TO REMOVE & REPLACE AIR-CON CONDENSER & ALL PIPE OR HOSE.	\$100.00	Replax
10	TO REMOVE & REPLACE COOLING FAN ASSY. ALSO CHECK THE CONDITION OF ELECTRIC FANS, WIRE & SENSOR	م \$80.00	X

TOTAL

\$2,850