

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6403R
 Ref. No : TAX/07/18/2080
 Reg. Date : 28/11/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : YAP JIN YOKE
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 17/07/2018 10:40:00 PM
 Accident Reported Date / Time : 18/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024097085
 Special Instruction to ARC, if any :
 SLM8782M / AIG / Remy SP paint
 Prepared Date : 18/07/2018 01:59:09 PM



LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU603575278

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	676.00	0.00
Total Spray Painting Charges :	1,296.00	0.00
Total Material Charges :	4,265.61	4,265.61
Other Charges :	580.00	0.00
TOTAL :	6,817.61	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	5.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	18/07/2018 07:48:59 PM	01/01/1900 12:00:00 AM

4 days - p/p*Rel 19/07/18 @ 1510*

Prepared / Adjusted Date :

Remarks :

Prepared Date : 18/07/2018 07:48:59 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 7/18/2018 7:47:51 PM

Section B - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	676.00	0.00 400
Total Labour	676.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 50
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00 80
TO RESPRAY REAR PANEL	180.00	0.00 X
Total Spray Painting & Panel Beating	1,296.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 20
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	580.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
61602471 60			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	25.00	618.60	Replace	Replace <i>Repair</i>	No
42611474 50			WHEEL, DISC	1	1,555.10	25.00	1,166.32	Replace	Replace <i>Repair</i>	No
52159479 13			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace <i>DE</i>	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>neu</i>	No
52576470 40			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace <i>ne</i>	No
52462470 30			PAD, RR BUMPER, RH & LH, 1	2	3.80	25.00	5.70	Replace	Replace <i>?</i>	No
52462470 20			PAD, RR BUMPER, RH & LH, 2	2	3.80	25.00	5.70	Replace	Replace <i>?</i>	No
52462470 10			PAD, RR BUMPER, RH & LH, 3	2	3.80	25.00	5.70	Replace	Replace <i>?</i>	No
52191470 30			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace <i>?</i>	No
81591470 10			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	10.00	438.12	Replace	Replace <i>Ch</i>	No
81561471 51			LENS & BODY, REAR COMBINATION LAMP , LH	1	438.10	10.00	394.29	Replace	Replace <i>?</i>	No
52566479 00			FILLER, RR BUMPER , LH	1	119.90	25.00	89.92	Replace	Replace <i>sup 4</i>	No
52161160 10			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace <i>ne</i>	No
52453470 10			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace <i>cut</i>	No
58307470 90			END PANEL SUB- ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Replace <i>X</i>	No
52592470 40			SEAL, RR BUMPER, LH	1	85.20	25.00	63.90	Replace	Replace <i>?</i>	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace <i>X</i>	No
TOTAL MATERIALS								4,265.64	4,265.61	
TOTAL MATERIALS(Discounted)								4,265.61	4,265.61	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									