

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

AIG

Jkk

VEHICLE NO: SHD 7091A

DATE : 20.07.2018

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR FENDER, RH <i>Deval</i>			\$ 817.50	<i>X</i> ✓
REAR FENDER INNER PANEL, RH <i>NH</i>			\$ 728.00	<i>X</i>
REAR FENDER OUTER PANEL, RH <i>NH</i>			\$ 486.00	<i>X</i>
REAR FENDER PANEL, ROOF SIDE OUTER, RH <i>NH</i>			\$ 311.00	<i>X</i>
REAR FENDER REINFORCEMENT SUB.ROCKER PANEL, RH <i>NH</i>			\$ 552.30	<i>X</i>
REAR FENDER EXTENSION, ROOF SIDE INNER FRT, RH <i>NH</i>			\$ 265.10	<i>X</i>
REAR FENDER SHEILD (RH) <i>SVC</i>			\$ 134.20	<i>X</i>
FRONT DOOR SIDE MIRROR, RH <i>Crack</i>			\$ 1,374.00	✓
SIDE MIRROR COVER, RH <i>NH</i>			\$ 141.90	<i>X</i>
MIRROR OUTER, RH <i>NH</i>			\$ 212.80	<i>X</i>
PANEL SUB-ASSY, FRONT DOOR, RH <i>SVC</i>			\$ 1,227.00	✓
FRONT DOOR HINGE UPPER <i>NH</i>			\$ 91.20	<i>X</i>
FRONT DOOR HINGE LOWER <i>NH</i>			\$ 91.20	<i>X</i>
FRONT DOOR CHECK <i>NH</i>			\$ 153.00	<i>X</i>
FRONT DOOR TRIMBOARD <i>7 monthy crack</i>			\$ 725.00	<i>X</i> ✓
FRONT DOOR INNER LOCK <i>NH Dam</i>			\$ 688.80	<i>X</i> ✓
PANEL SUB-ASSY, REAR DOOR, RH <i>Deval</i>			\$ 1,227.00	✓
REAR DOOR HINGE UPPER <i>NH</i>			\$ 82.30	<i>X</i>
REAR DOOR HINGE LOWER <i>NH</i>			\$ 82.30	<i>X</i>
REAR DOOR CHECK <i>NH</i>			\$ 153.00	<i>X</i>
REAR DOOR TRIMBOARD <i>7 monthy crack</i>			\$ 725.00	<i>X</i> ✓
REAR DOOR INNER LOCK <i>NH Dam</i>			\$ 644.70	<i>X</i> ✓
REAR DOOR INNER MOULDING <i>NH</i>			\$ 141.00	✓
REAR DOOR OUTER SEAL <i>torn</i>			\$ 257.90	✓
DOOR CENTRE PILLAR. <i>Deval</i>			\$ 1,590.60	✓
MOTOR ASSY, POWER WINDOW REGULATOR FRT, RH <i>NH</i>			\$ 941.80	<i>X</i>
MOTOR ASSY, POWER WINDOW REGULATOR REAR, RH <i>NH</i>			\$ 941.80	<i>X</i>
REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH <i>7 1/2</i>			\$ 228.40	<i>X</i> ✓
REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH <i>7 1/2</i>			\$ 228.40	<i>X</i> ✓
REINFORCE SUB-ASSY, ROCKER, OUTER RH <i>NH</i>			\$ 519.80	<i>X</i>
CENTRE ROCKER PANEL (GARNISH) <i>Cut</i>			\$ 576.00	✓
REAR TYRE RIM, RH <i>2 distubal</i>			\$ 1,555.00	<i>X</i> ✓
REAR WHEEL HUB CAP, RH <i>NH</i>			\$ 177.70	✓
REAR WHEEL BEARING ING & HUB, RH <i>7 Dam</i>			\$ 560.10	<i>X</i> ✓
REAR CROSS MEMBER <i>2 distubal</i>			\$ 2,179.40	<i>X</i> ✓
REAR SHOCK ABSORBER, RH <i>2 distubal</i>			\$ 116.00	<i>X</i> ✓
REAR SHOCK ABSORBER MOUNTING, RH <i>NH</i>			\$ 125.30	<i>X</i>
REAR LOWER ARM, RH <i>2 distubal</i>			\$ 345.70	<i>X</i> ✓
REAR UPPER ARM, RH <i>2 distubal</i>			\$ 348.80	<i>X</i> ✓
REAR KNUCKLE ARM, RH <i>2 distubal</i>			\$ 800.73	<i>X</i> ✓
REAR BRAKE ABS SENSOR (WIRE) <i>NH</i>			\$ 78.80	<i>X</i>
REAR STABILIZER BAR <i>2 distubal</i>			\$ 311.50	<i>X</i> ✓
REAR STABILIZER LINK, RH <i>2 distubal</i>			\$ 151.60	<i>X</i> ✓
REAR TRAILING ARM, RH <i>2 distubal</i>			\$ 314.20	<i>X</i> ✓
REAR ASSIST ARM, RH <i>2 distubal</i>			\$ 342.20	<i>X</i> ✓

SHD 7091A

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
SUB TOTAL		17654.23	\$ 23,746.03
LESS 20% 25%			\$ 4,749.21
DISCOUNTED TOTAL		13240.67	\$ 18,996.82
FRONT DOOR COMFORT LOGO <i>NCC</i>			\$ 75.00
REAR DOOR COMFORT & APPS STICKER <i>NCC</i>			\$ 80.00
REAR TYRE .RH <i>SVL</i>		155.00	\$ 216.00
			\$ 371.00
LABOUR CHARGE			
Panel Beating			\$ 1,200.00
Spray Painting Charge			\$ 950.00
Wiring Charge			\$ 100.00
Tuff Kote			\$ 100.00
Towing Charge			\$ 50.00
Remove/Refix Cushion & Upholstery Rear			\$ 150.00
Remove/Refix Rear Windscreen Glass			\$ 120.00
Remove/Refix Reverse Sensor			\$ 120.00
Transfer of Door		\$ 120.00	\$ 240.00
Remove/Refix Undercarriage (RR)			\$ 200.00
Rear Wheel Alignment		2060.00	\$ 120.00
			\$ 3,350.00
TOTAL LABOUR			\$ 3,350.00
ESTIMATE TOTAL			\$ 22,717.82
			15455.67
		4/S	12350/-

24/07/2018 @ 1145w
 H&A Antenna
 2/Sun 7 days
 Ryan
 LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.