

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE**

AIG

Jkk

VEHICLE NO: SHD 7091A

DATE : 20.07.2018

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR FENDER, RH			\$ 817.50	X
REAR FENDER INNER PANEL, RH NH			\$ 728.00	X
REAR FENDER OUTER PANEL, RH NH			\$ 486.00	X
REAR FENDER PANEL, ROOF SIDE OUTER, RH NH			\$ 311.00	X
REAR FENDER REINFORCEMENT SUB.ROCKER PANEL, RH NH			\$ 552.30	X
REAR FENDER EXTENSION, ROOF SIDE INNER FRT, RH NH			\$ 265.10	X
REAR FENDER SHEILD (RH) SVL			\$ 134.20	X
FRONT DOOR SIDE MIRROR, RH CRACK			\$ 1,374.00	✓
SIDE MIRROR COVER, RH			\$ 141.90	X
MIRROR OUTER, RH NH			\$ 212.80	X
PANEL SUB-ASSY, FRONT DOOR, RH SNG			\$ 1,227.00	✓
FRONT DOOR HINGE UPPER NH			\$ 91.20	X
FRONT DOOR HINGE LOWER NH			\$ 91.20	X
FRONT DOOR CHECK NH			\$ 153.00	X
FRONT DOOR TRIMBOARD 2 mounty CRACK			\$ 725.00	✓
FRONT DOOR INNER LOCK NH D=			\$ 688.80	X
PANEL SUB-ASSY, REAR DOOR, RH Replaced			\$ 1,227.00	✓
REAR DOOR HINGE UPPER NH			\$ 82.30	X
REAR DOOR HINGE LOWER NH			\$ 82.30	X
REAR DOOR CHECK NH			\$ 153.00	X
REAR DOOR TRIMBOARD 2 mounty CRACK			\$ 725.00	X
REAR DOOR INNER LOCK NH D=			\$ 644.70	X
REAR DOOR INNER MOULDING HIC			\$ 141.00	✓
REAR DOOR OUTER SEAL torn			\$ 257.90	✓
DOOR CENTRE PILLAR. Replaced			\$ 1,590.60	✓
MOTOR ASSY, POWER WINDOW REGULATOR FRT, RH NH			\$ 941.80	X
MOTOR ASSY, POWER WINDOW REGULATOR REAR, RH NH			\$ 941.80	X
REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH 2 1st			\$ 228.40	✓
REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH NH 1st			\$ 228.40	X
REINFORCE SUB-ASSY, ROCKER, OUTER RH NH			\$ 519.80	X
CENTRE ROCKER PANEL (GARNISH) CRACK			\$ 576.00	✓
REAR TYRE RIM, RH 2 distributed			\$ 1,555.00	✓
REAR WHEEL HUB CAP, RH CRACK			\$ 177.70	✓
REAR WHEEL BEARING IN & HUB, RH 2 D=			\$ 560.10	✓
REAR CROSS MEMBER 2 distributed			\$ 2,179.40	✓
REAR SHOCK ABSORBER, RH 2 distributed			\$ 116.00	✓
REAR SHOCK ABSORBER MOUNTING, RH NH			\$ 125.30	X
REAR LOWER ARM, RH 2 distributed			\$ 345.70	✓
REAR UPPER ARM, RH 2 distributed			\$ 348.80	✓
REAR KNUCKLE ARM, RH 2 distributed			\$ 800.73	✓
REAR BRAKE ABS SENSOR (WIRE) NH			\$ 78.80	X
REAR STABILIZER BAR 2 distributed			\$ 311.50	✓
REAR STABILIZER LINK, RH 2 distributed			\$ 151.60	✓
REAR TRAILING ARM, RH 2 distributed			\$ 314.20	✓
REAR ASSIST ARM, RH 2 distributed			\$ 342.20	✓

SHD 7091A

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
SUB TOTAL			\$ 23,746.03
LESS 20% 25%			\$ 4,749.21
DISCOUNTED TOTAL			\$ 18,996.82
FRONT DOOR COMFORT LOGO <i>Nuc</i>			\$ 75.00
REAR DOOR COMFORT & APPS STICKER <i>Nuc</i>			\$ 80.00
REAR TYRE ,RH <i>SVL</i>			\$ 216.00
			\$ 371.00
LABOUR CHARGE			
Panel Beating			\$ 1,200.00
Spray Painting Charge			\$ 950.00
Wiring Charge			\$ 100.00
Tuff Kote			\$ 100.00
Towing Charge			\$ 50.00
Remove/Refix Cushion & Upholstery Rear			\$ 150.00
Remove/Refix Rear Windscreen Glass			\$ 120.00
Remove/Refix Reverse Sensor			\$ 120.00
Transfer of Door		\$ 120.00	\$ 240.00
Remove/Refix Undercarriage (RR)			\$ 200.00
Rear Wheel Alignment			\$ 120.00
			\$ 3,350.00
TOTAL LABOUR			\$ 3,350.00
ESTIMATE TOTAL			\$ 22,717.82
24/07/2018 @ 1145h H/A Antenna 10 2/5mm * days <i>ryan</i> LKK Auto <i>Q</i>			
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.