

INS. CASE OWNER:

SUNDARI

CC 6 / III 1801

7/10, 4/10/18

LKK:

IDAC:

Surveyor:

Marius

DOI:

ASSIGNMENT

7/10/18

Date / Time:

7/10/18

Registered in Merimen:

7/10/18

Pre-assign / CCU / FTE

SHB 6/10/18



Insured Vehicle No.:

(Unlabeled) Transportation Pte Ltd

Claim No.:

MOT 18070612

Name of Insured:

(Unlabeled)

Policy No.:

MECOMBIS

Insured Tel No.:

65005768

HP:

7/10/18

Make / Model:

Toucan Plus

Excess Sec II :SS

D.O.A.:

Place of Accident:

Republic Ave > BP

Is driver the owner?

(YES) (NO)

Nature of Accident:

If NO, Driver Name / Age:

Ismail B Hassan

OI GIA REPORT: YES / NO TP GIA REPORT: YES / NO

Driver Tel No.:

83457888

(V/L: YES / NO)

Insured Liability:

Final ? Yes / No

SJZ 7/10



INSRS:
WSP:
Tel:
Liability:
RMKS:

Unlabeled motor



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

7/10/18

SJZ 7/10-X

SHB 6/10/18-X

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA/GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

02/10/18

Blue envelope. Old rate - entered TP
Check liability attached
In approved BLS
Small utility claim
Finalized.
Original TP LOP in.

02/10/18

12/10/18

TP report for mandate approval.
Report done

01/11/18

Check mandate to be by submission

09/11/18

11/11/18

In approved mandate
Send 1st offer to TP.
TP accepted offer.
All good in order.
To close.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

Lis

SS 7,500.00 / 10 days) Reduction: 54 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS

7,500.00

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

80.00 x 11 days)

Loss of Income (LOI):

SS

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost:

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 600.00

Total:

SS

8,387.45

Global Sum SS:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

8,387.45

Name 1:

CHOO MOTOR SPRAY PHOTER

Payee 2: (Strike if N.A.)

SS

Name 2:

-

Payee 3: (Strike if N.A.)

SS

Name 3:

-

11/13) wef

S. REC. BY: MARUS

REF:

111
ASSIGNMENT

Jm: _____ Date: _____

Estimated Cost: _____

2 (TP/WS/TP RES/OD RES/EVA/INV/MV

Inspect Vehicle No: SJ22151DWorkshop m/s Choo mto.sured: SH3621314

Policy No. _____

Claims No. _____

Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.il. or Market Value: 834

AC Accident Rpt: _____ Consistent? : Yes or No

A / PR Seen: _____ Consistent? : Yes or No

t. Repairs _____ days Res.: Yes or No

m Sum: _____ % 3 Val.: Yes or No

k / REV / REP. / 24 HRS 1775L

ite: _____ Person Contacted: _____

late / Time Action / Instruction

L1A 26651 24rs Yndi. Dep 9800 net 7349Veh No: SJ22151D Yr Regn: 3/12 10Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Honda civic c.c. 1799Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 170656 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMFD1630AS200151

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Cinturato

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 21/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Time, File Pass to?

☐

Prel. Report

☐

Final Report

Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

Survey Fee:

Transportation:

Photos

Others

Report Format: _____

mp Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CC6/III18013320/Uhb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 23-07-2018	
			Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 6213H		Veh. Inspected	SJZ 2151D
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	23/07/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/07/2018		Inspection Date	23/07/2018
Survey held at	CHOO MOTOR SPRAY PAINTER 1 KAKI BUKIT AVENUE 6 #01-39 AUTOBAY@KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6

#01-39 Autobay

SINGAPORE 417883

VEHICLE NO: SJZ 2151D

QTY	PARTICULAR			
1 PCS	REAR BUMPER	638	2.5	\$745.10
2 PCS	REAR BUMPER SIDE RETAINERS @\$25.20		Set	\$50.40
1 SET	REAR BUMPER CLIPS		RM	\$30.00
1 PCS	BOOTLID	- 610.70	Sub	\$810.70
1 PCS	BOOTLID 'H' LOGO		RM	\$28.80
1 PCS	BOOTLID 'CIVIC' EMBLEM		RM	\$36.60
1 PCS	BOOTLID 'IVTEC' EMBLEM		RM	\$38.20
1 PCS	BOOTLID '1.8' EMBLEM		RM	\$35.50
2 PCS	BOOTLID REFLECTORS @\$320.20	2x5.50x2=491	RM	\$640.40
1 PCS	BOOTLID WEATHERSTRIP		RM	\$197.60
1 PCS	BOOTLID INNER LOCK	198.50	RM	\$299.50
1 PCS	BOOTLID LOCK STRIKER		RM	\$48.50
2 PCS	BOOTLID HINGES @\$148.50		RM	\$297.00
1 PCS	BOOTLID INNER TRIM		RM	\$252.30
1 SET	BOOTLID INNER TRIM CLIPS		RM	\$40.00
2 PCS	TAILLAMPS @\$365.50	2x5.30x2=570.60	RM	\$731.00
2 PCS	TAILLAMP HOUSING PANELS @\$245.50		MS set	\$491.00
1 PCS	REAR END PANEL		Body	\$316.60
1 PCS	REAR END PANEL TOP GARNISH		RM	\$160.80
2 PCS	REAR FENDERS @\$899.10		MS set/3uc	\$1,798.20
2 PCS	REAR FENDER INNER TRIMS @\$366.20		2x1/2m	\$732.40
1 SET	REAR FENDER INNER TRIM CLIPS		RM	\$50.00
1 PCS	REAR FLOOR PANEL	911.40	Crushed/3uc	\$966.50
1 PCS	REAR FLOOR PANEL TOP BOARD		unqrd/3uc	\$316.00
1 PCS	REAR FLOOR PANEL TOP TOOLS SPONGE	205	Trim	\$305.20
1 PCS	REAR EXHAUST		RM	\$699.50
1 PCS	REAR EXHAUST HEAT SHIELD		RM	\$121.00
2 PCS	REAR EXHAUST MOUNTINGS @\$35.00		RM	\$70.00
1 PCS	REAR WINDSCREEN MOULDING		RM	\$68.50
2 PCS	REAR MUDFLAPS @\$80.50		MS set	\$161.00
				\$10,538.30
	S.NETT			
1 SET	REAR BUMPER REVERSE SENSOR		Shold	\$280.00
1 PCS	REAR END PANEL SEALANT		RM	\$50.00
1 SET	REAR FLOOR PANEL INSULATOR		RM	\$300.00
1 SET	REAR EXHAUST CHROME PIPE		RM	\$180.00

not Adward
2hr
4/5 @ 7500
10 day.
23/7/18

212

6844.2
6475.36

1 PCS	REAR WINDSCREEN SEALANT	RM	\$50.00	40
1 PCS	BOOTLID TOP SPOILER	RM	\$680.00	x
1 PCS	REAR LICENCE PLATE W/HOLDER	11	\$50.00	x
LABOUR CHARGES:				
	TO CHECK WIRING		\$80.00	30
	TO DISMENTLE & REPLACING REVERSE SENSOR		\$80.00	50
	TO DISMENTLE & REPLACING REAR EXHAUST		\$100.00	60
	TO DISMENTLE & REFIX PETROL TANK		\$100.00	60
	TO DISMENTLE & REFIX BOOTLID MECHANISM		\$100.00	60
	TO DISMENTLE & REFIX REAR WINDSCREEN		\$150.00	120
	TO MOUNT VEHICLE ON CAR O-LINER	11	\$380.00	x
	TO DISMENTLE & REFIX SEAT,CUSHION,UPHOLSTREY		\$180.00	80
	TO SPRAY RUST PROOFING		\$150.00	100
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED & REPLACING PARTS		\$1,800.00	1680
	TO PUTTY & SPRAY PAINTING		\$1,100.00	1180
TOTAL			\$16,448.30	

3930

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Singapore NRIC
Owner ID: 1775C

Vehicle No.:	SJZ2151D
Vehicle to be Exported:	No
Intended De-registration Date:	23 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.8L 5AT
Primary Colour:	Brown
Manufacturing Year:	2009

Engine No.:	R18A15000305
Chassis No.:	JHMF1630AS200151
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$25,597.00
Original Registration Date:	03 Dec 2010
First Registration Date:	03 Dec 2010
Transfer Count:	0
Actual ARF Paid:	\$25,597.00 12780

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Dec 2020
PARF Rebate Amount:	\$15,358.00

COE Expiry Date:	02 Dec 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$47,890.00
COE Rebate Amount:	\$11,293.00
Total Rebate Amount:	\$26,651.00

OK

Free Car Valuation

Unsure of how much your car is worth?
Let us tell you how much is the value - no charges & no obligations!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an AdAdvertiser LoginWays of Selling

Aug 12 Lexus IS250C. Well Maintained By Owner.



Smooth & Quiet V6 Engine With
The Power Hard Top
Convertible High A/RF \$57,733.
Shine Connect StarAd

PRIME MOTOR & LEASING

100% FINANCING THROUGH PRIME MOTOR & LEASING

With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.

Browse by Category

Sort by Date Posted20 results/page

5 vehicles

Honda Civic

Advanced SearchSubmit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Civic		Any	Any	2011	Any	Any	Any	Available
	Honda Civic	1.8A	\$47,500	\$10,020 /yr	19-Dec-2011	1,799 cc	-	Sedan	Available
1 Careful Owner, High Paper Value, Low Mileage, Excellent Fuel Efficient And Responsive. Accident Free, Low Depreciation, Low Down Payment, 6 Months Free Servicing By Reputable Workshop With 40 Years ...									
Posted: 20-Jul-2018Tags: 2011 Honda Civic, Honda Civic, Honda, Civic, Used Honda									
	Honda Civic	1.8A	\$39,800	\$9,320 /yr	23-Jun-2011	1,799 cc	102,390 km	Sedan	Available
Price Negotiable. Low Mileage, Excellent Fuel Efficient And Responsive. Accident Free, Low Depreciation! Well Maintained By Previous Owner. Kindly Contact Our Friendly Sales Executives Directly For Vi...									
Posted: 19-Jul-2018Tags: 2011 Honda Civic, Honda Civic, Honda, Civic, Used Honda									
	Honda Civic	2.0A	\$45,800	\$10,950 /yr	25-Jun-2011	1,998 cc	88,000 km	Sedan	Available
With Fresh Renew 6 Months Road Tax, Well Maintained. Must See To Believe. Call And Arrange For A Test Drive Now! Trade In Welcome.									
Posted: 16-Jul-2018Tags: 2011 Honda Civic, Honda Civic, Honda, Civic, Used Honda									
	Honda Civic	1.8A VTI-S	\$41,800	\$11,700 /yr	10-Jan-2011	1,799 cc	82,401 km	Sedan	Available
Pristine Conditions, Civic 1.8L Hot In Market, Superb Well Maintained, 1 Careful Owner, Brand New Leather Seats, Brand New Paint Work, No Repaired Needed, 100% Accident Free, Superb Low Mileage At 82k...									
Posted: 14-Jul-2018Tags: 2011 Honda Civic, Honda Civic, Honda, Civic, Used Honda									
Car Buying	Car Selling	Car Ownership	Buying a pre-owned car, but Unsure of its Condition? Get STA Car Evaluation						
Car Aftermarket	On The Move	Lifestyle							
	Honda Civic	2.0M Si	\$39,800	\$8,970 /yr	19-Jul-2011	1,998 cc	80,000 km	Sedan	Available
1 Owner, Low Mileage Done, Nice Number Plate, Cheapest In Market, High Paper Rebate. Well Maintained, High COE! Trade In Welcome! 100% Accident Free! Previous Owner's Baby! Reluctant Sale! Low Down Pa...									
Posted: 07-Jun-2018Tags: 2011 Honda Civic, Honda Civic, Honda, Civic, Used Honda									

Save this search criteria, to get email alerts whenever a match is found.

MakeModelPriceDepreciationReg DateEng CapMileageVeh TypeStatus

For old advertisements, view Expired ads

20 results/page

Print Received Message

This mail is associated with :

***SJZ2151D (MCT18070612)**

[SHB6213H]

TP

SUKHWANT SINGH S/O GURCHARAN SIGH

Jul 21 2018 12:00AM

[COMFORT TRANSPORTATION PTE LTD]

Choo Motor Spray Painter

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 01/11/2018 17:52 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8387.45) - SJZ2151D - Claim Handler: Sundari Nagarajan

Approved:8387.45:

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait photo of Arveet Kaur

Licence Number: **S9207389J**

Name: **ARVEET KAUR**

Birth Date: **25 Feb 1992**

Issue Date: **19 Oct 2010**

Barcode: 0019028170

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S9207389J

Portrait photo of Arveet Kaur

Name: **ARVEET KAUR**

Race: **SIKH**

Date of Birth: **25-02-1992**

Sex: **F**

Country of Birth: **SINGAPORE**

Barcode: 00207389J

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class	Description	Expiry Date
Class 1	MOTOR CARS AND MOTOR TRACTORS WITH/OUT CLUTCH PEDAL THE WEIGHT OF WHICH ENLARGES DOES NOT EXCEED 2000 KILOGRAMS	19 Oct 2010
Class 2	MOTOR CARS AND MOTOR TRACTORS THE WEIGHT OF WHICH ENLARGES DOES NOT EXCEED 2000 KILOGRAMS	09 Oct 2010

Portrait photo of Arveet Kaur

S / No. 0000225878

Barcode: Licence No: S9207389J

Barcode: 4072828

Barcode: 00207389J

Portrait photo of Arveet Kaur

Date of Issue: **09-03-2007**

Address: **APT. BLK 158D RIVERVALE DRIVE #13-838 SINGAPORE 544186**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 1775C

Vehicle Details

Vehicle No.: SJZ2151D
Vehicle to be Exported: No
Intended De-registration Date: 23 Jul 2018
Vehicle Make: HONDA
Vehicle Model: CIVIC 1.8L 5AT
Primary Colour: Brown
Manufacturing Year: 2009
Engine No.: R18A15000305
Chassis No.: JHMFD1630AS200151
Maximum Power Output: 103.0 kW (138 bhp)
Open Market Value: \$25,597.00
Original Registration Date: 03 Dec 2010
First Registration Date: 03 Dec 2010
Transfer Count: 0
Actual ARF Paid: \$25,597.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 02 Dec 2020
PARF Rebate Amount: \$15,358.00

Intended COE Rebate Details

COE Expiry Date: 02 Dec 2020
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$47,890.00
COE Rebate Amount: \$11,293.00
Total Rebate Amount: \$26,651.00

The information contained herein is correct as at 23 Jul 2018

OK

CHOO MOTOR SPRAY PAINTER



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 03 Sep 2018 / 15:07:47

Receipt Date/Time : 03 Sep 2018 / 15:07:47

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180903-001688

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Result of Insurance Enquiry - SHB6213H				
As at 21 Jul 2018/00:30:00				
Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - SHB6213H Enquiry Fee 20180903150652472283	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20180903150709871	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jul 2018 Edit Reg		23 Jul 2018 00:00 Edit Adj Rpt	S\$7,500.00 Edit Estimates	S\$7,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: -								
Main Claimant:	SUKHWANT SINGH S/O GURCHARAN SIGH , Co. Reg. No.: S6921775C								
Vehicle Reg. No.:	SJZ2151D	Date of Loss:	21/07/2018 00:00 - :59 [91 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18070612	Policy/Cover Note No.:	MCOM0015 (Third Party Only)						
Vehicle Reg. No. (Insured):	SHB6213H	Policy No. (Claimant):							
		Excess:							
Repairer:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 5, #01-39 AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 67453897								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 01/08/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• III_SG (01/11/2018): Alert - Adj Mandate Approved (S\$8387.45) - SJZ2151D - Claim Handler: Sundari Nag... • III_SG (03/08/2018): Alert - Adj Mandate Approved (S\$0.00) - SJZ2151D - Claim Handler: Sundari Nagara...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJZ2151D (MCT18070612)

[SHB6213H]

TP

SUKHWANT SINGH S/O GURCHARAN SINGH

Jul 21 2018 12:00AM

[COMFORT TRANSPORTATION PTE LTD]

Choo Motor Spray Painter

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/10/18 14:33	Chassis Number	 Load JPG	☒
2	12/10/18 14:33	Odometer Reading	 Load JPG	☒
3	12/10/18 14:33	General View	 Load JPG	☒
4	12/10/18 14:33	General View	 Load JPG	☒
5	12/10/18 14:33	General View	 Load JPG	☒
6	12/10/18 14:33	General View	 Load JPG	☒
7	12/10/18 14:33	General View	 Load JPG	☒
8	12/10/18 14:33	General View	 Load JPG	☒
9	12/10/18 14:33	General View	 Load JPG	☒
10	12/10/18 14:33	General View	 Load JPG	☒
11	12/10/18 14:33	General View	 Load JPG	☒
12	12/10/18 14:33	General View	 Load JPG	☒
13	12/10/18 14:33	General View	 Load JPG	☒
14	12/10/18 14:33	General View	 Load JPG	☒
15	12/10/18 14:33	General View	 Load JPG	☒
16	12/10/18 14:33	General View	 Load JPG	☒
17	12/10/18 14:33	General View	 Load JPG	☒
18	12/10/18 14:33	General View	 Load JPG	☒
19	12/10/18 14:33	General View	 Load JPG	☒
20	12/10/18 14:33	General View	 Load JPG	☒
21	12/10/18 14:33	General View	 Load JPG	☒
22	12/10/18 14:33	General View	 Load JPG	☒
23	12/10/18 14:33	General View	 Load JPG	☒
24	12/10/18 14:33	General View	 Load JPG	☒
25	12/10/18 14:33	General View	 Load JPG	☒
26	12/10/18 14:33	General View	 Load JPG	☒
27	12/10/18 14:33	General View	 Load JPG	☒
28	12/10/18 14:33	General View	 Load JPG	☒
29	12/10/18 14:33	General View	 Load JPG	☒
30	12/10/18 14:33	General View	 Load JPG	☒
31	12/10/18 14:33	General View	 Load JPG	☒
32	12/10/18 14:33	General View	 Load JPG	☒
33	12/10/18 14:33	General View	 Load JPG	☒
34	12/10/18 14:33	General View	 Load JPG	☒
35	12/10/18 14:33	General View	 Load JPG	☒
36	12/10/18 14:33	General View	 Load JPG	☒
37	12/10/18 14:33	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LIK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	12/10/18 14:33	General View	 Load JPG	☒
39	12/10/18 14:33	General View	 Load JPG	☒
40	12/10/18 14:33	General View	 Load JPG	☒
41	12/10/18 14:33	General View	 Load JPG	☒
42	12/10/18 14:33	General View	 Load JPG	☒
43	12/10/18 14:33	General View	 Load JPG	☒
44	12/10/18 14:33	General View	 Load JPG	☒
45	12/10/18 14:33	General View	 Load JPG	☒
46	12/10/18 14:33	General View	 Load JPG	☒
47	12/10/18 14:33	General View	 Load JPG	☒
48	12/10/18 14:33	General View	 Load JPG	☒
49	12/10/18 14:33	General View	 Load JPG	☒
50	12/10/18 14:33	General View	 Load JPG	☒
51	12/10/18 14:33	General View	 Load JPG	☒
52	12/10/18 14:33	General View	 Load JPG	☒
53	12/10/18 14:33	General View	 Load JPG	☒
54	12/10/18 14:33	General View	 Load JPG	☒
55	12/10/18 14:33	General View	 Load JPG	☒
56	12/10/18 14:33	General View	 Load JPG	☒
57	12/10/18 14:33	General View	 Load JPG	☒
58	12/10/18 14:33	General View	 Load JPG	☒
59	12/10/18 14:33	General View	 Load JPG	☒
60	12/10/18 14:33	General View	 Load JPG	☒
61	12/10/18 14:33	General View	 Load JPG	☒
62	12/10/18 14:33	General View	 Load JPG	☒
63	12/10/18 14:33	General View	 Load JPG	☒
64	12/10/18 14:33	General View	 Load JPG	☒
65	12/10/18 14:33	General View	 Load JPG	☒
66	12/10/18 14:33	General View	 Load JPG	☒
67	12/10/18 14:33	General View	 Load JPG	☒
68	12/10/18 14:33	General View	 Load JPG	☒
69	12/10/18 14:33	General View	 Load JPG	☒
70	12/10/18 14:33	General View	 Load JPG	☒
71	12/10/18 14:33	General View	 Load JPG	☒
72	12/10/18 14:33	General View	 Load JPG	☒
73	12/10/18 14:33	General View	 Load JPG	☒
74	12/10/18 14:33	General View	 Load JPG	☒
75	12/10/18 14:33	General View	 Load JPG	☒
76	12/10/18 14:33	General View	 Load JPG	☒
77	12/10/18 14:33	General View	 Load JPG	☒
78	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
79	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
80	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
81	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
82	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
83	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
84	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
85	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
86	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
87	12/10/18 14:34	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
89	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
90	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
91	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
92	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
93	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
94	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
95	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
96	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
97	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
98	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
99	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
100	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
101	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
102	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
103	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
104	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
105	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
106	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
107	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
108	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
109	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
110	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
111	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
112	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
113	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
114	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
115	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
116	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
117	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
118	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
119	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
120	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
121	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
122	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
123	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
124	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
125	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
126	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
127	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
128	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
129	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
130	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
131	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
132	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
133	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
134	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
135	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
136	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
137	12/10/18 14:34	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
139	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
140	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
141	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
142	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
143	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
144	12/10/18 14:34	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/07/18 17:19	TP GIA REPORT	 Load PDF	
2	12/10/18 14:28	TP ESTIMATE - MARKED	 Load PDF	
3	30/10/18 16:12	WORKSHOP INVOICE	 Load PDF	
4	30/10/18 16:12	LTA SEARCH	 Load PDF	
5	30/10/18 16:12	LOD	 Load PDF	
6	15/01/19 09:40	AUTHORISATION TO ACT FORM	 Load PDF	
7	15/01/19 09:40	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	24/07/18 09:00	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18013320/UHB3Q2

Date: 15/01/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SJZ2151D	Insured Vehicle No :	SHB6213H
Date of Loss:	21/07/2018	Nature of Claim:	TP
		Claim No:	MCT18070612

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ2151D	Engine No:	R18A15000305
Make & Model:	HONDA CIVIC, 1.3 EC8 (M)	Chassis No:	JHMF1630AS200151
Reg. Date:	03/12/2010 (Man. Year: 2009)	Odometer:	170656 km
Colour:	Blue		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Cinturato 6 mm	Rear Left Side:	Cinturato 6 mm
Front Right Side:	Cinturato 6 mm	Rear Right Side:	Cinturato 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,128.30	6,040.16	6,088.14	50.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,320.00	3,420.00	900.00	20.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,448.30	9,460.16	6,988.14	42.49
Approved Total (Overridden) (S\$)		7,500.00		
Nett Amount (S\$)	16,448.30	7,500.00	8,948.30	54.40
+ Loss of Use (11.0 x S\$80.00/day) (S\$)		880.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,387.45		

INSPECTION

Date of Assignment:	23/07/2018	
Date Inspected:	23/07/2018 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	10.0 days	

Adjuster: MARCUS CHUA**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2018)
Parts: 144	HONDA CIVIC 1.3 EC8 (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJZ2151D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	745.10 F	*638.00 FL
2	2		*REAR BUMPER SIDE RETAINERS	Bent	50.40 F	*50.40 FL
3	1		*SET REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
4	1		*BOOTLID	Badly Dented	810.70 F	*610.70 FL
5	1		*BOOTLID H LOGO	Necessary	28.80 F	*28.80 FL
6	1		*BOOTLID CIVIC EMBLEM	Necessary	36.60 F	*36.60 FL
7	1		*BOOTLID IVTEC EMBLEM	Necessary	38.20 F	*38.20 FL
8	1		*BOOTLID 1.8 EMBLEM	Necessary	35.50 F	*35.50 FL
9	2		*BOOTLID REFLECTORS	Cracked	640.40 F	*491.00 FL
10	1		*BOOTLID WEATHERSTRIP	Twisted	197.60 F	*197.60 FL
11	1		*BOOTLID INNER LOCK	Twisted	299.50 F	*199.50 FL
12	1		*BOOTLID LOCK STRIKER	Not Necessary	48.50 F	*- FL
13	2		*BOOTLID HINGES	Repair	297.00 F	*- FL
14	1		*BOOTLID INNER TRIM	Not Necessary	252.30 F	*- FL
15	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	40.00 F	*- FL
16	2		*TALLAMPS	Cracked	731.00 F	*570.60 FL
17	1		*TALLAMP HOUSING PANELS	N/S Bent	491.00 F	*245.50 FL
18	1		*REAR END PANEL	Badly Dented	316.60 F	*316.60 FL
19	1		*REAR END PANEL TOP GARNISH	Twisted	160.80 F	*160.80 FL
20	1		*REAR FENDERS	N/S Warped / Buckled	1,798.20 F	*899.10 FL
21	2		*REAR FENDER INNER TRIMS	Deformed / Torn	732.40 F	*732.40 FL
22	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	50.00 F	*50.00 FL
23	1		*REAR FLOOR PANEL	Crumpled / Buckled	966.50 F	*911.40 FL
24	1		*REAR FLOOR PANEL TOP BOARD	Warped / Torn	316.00 F	*316.00 FL
25	1		*REAR FLOOR PANEL TOP TOOLS SPONGE	Torn	305.20 F	*205.00 FL
26	1		*REAR EXHAUST	Repair	699.50 F	*- FL
27	1		*REAR EXHAUST HEAT SHIELD	Repair	121.00 F	*- FL
28	2		*REAR EXHAUST MOUNTINGS	Not Necessary	70.00 F	*- FL
29	1		*REAR WINDSCREEN MOULDING	Necessary	68.50 F	*68.50 FL
30	1		*REAR MUDFLAPS	N/S Torn	161.00 F	*80.50 FL
31	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
32	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
33	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	300.00 FS	*120.00 FS
34	1		*SET REAR EXHAUST CHROME PIPE	Dented	180.00 FS	*100.00 FS
35	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
36	1		*BOOTLID TOP SPOILER	Repair	680.00 FS	*- FS
37	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$) 12,128.30 7,422.70

- List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 1,382.54

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	12,128.30
						6,040.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REPLACING REAR EXHAUST	New	100.00	60.00
4	TO DISMANTLE & REFIX PETROL TANK	New	100.00	60.00
5	TO DISMANTLE & REFIX BOOTLID MECHANISM	New	100.00	60.00
6	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
7	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
8	TO DISMANTLE & REFIX SEAT ,CUSHION ,UPHOLSTERY	New	180.00	80.00
9	TO SPRAY RUST PROOFING	New	150.00	100.00
10	LABOUR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS	New	1,800.00	1,680.00
11	TO PUTTY & SPRAY PAINTING	New	1,200.00	1,180.00
Gross Labour Cost (S\$)			4,320.00	3,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >