# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited From: LKK Auto Consultants Pte Ltd 7 Temasek Boulevard 51 Ubi Ave 1 #01-25

#10-01 Suntec Tower One Paya Ubi Industrial Park Singapore 038987 Singapore 408933

Attn: Date: 16 Aug 2018

## **Preliminary Advice**

Insured Vehicle No : SJT975R

TP Vehicle No : SGG7767E Accident Date : 14/07/2018

Make : NISSAN TEANA Assignment Date : 20/07/2018

Date of Inspection : 20/07/2018 Est. Duration of Repair : 12DAYS

Inspection At : LEANG AUTOMOTIVE

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...FRT.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,264.70
Revised Amount	:S\$	18,051.53
Check Items (Estimated)	:S\$	0.00
Total	:S\$	18,051.53
Lump Sum Repair	:S\$	12,000.00

### **Total Loss Consideration**

Other comments: We have not authorized repairs.

New for Old Value:S\$Pre-Accident Value:S\$COE / PARF Rebate:S\$Salvage Value:S\$Margin for Repair:S\$

#### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(	)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.