

SGG 7767E NISSAN TEANA.

MNTBBAL33Z0003622.

FR7 bonnet. 937.90N ✓ Distorted.

2pcs FR7 bonnet hinge \$25.10N x 2 = 50.20 (N) X Not nec

FR7 bonnet lock. \$63.20N ✓ Damaged.

FR7 bonnet insulator \$154.70N X Not nec.

8pcs insulator clips \$5N x 8 = 40 (N) X Not nec.

FR7 bonnet rubber. \$68.50N X Not nec.

FR7 grille \$341.20N ✓ cracked

grille centre logo \$73.60N ✓ Nec.

4pcs grille clips \$4.80N x 4 = 19.20 (N) ✓

FR7 bumper. \$890.30N ✓ Distorted

3pcs FR7 bumper retainers \$20.90N x 2 = 41.80 ✓

12pcs FR7 bumper clips \$5N x 12 = 60 (N) 30 (N) ✓

FR7 bumper towing bar. \$20N ✓ Distorted

Number plate garnish \$129.60N ✓ Distorted

FR7 bumper inner sponge. \$265.10N ✓ cracked

FR7 bumper reinforcement \$533.80N ✓ Best.

2pcs headlamp lower bracket. \$142.10N x 2 = 284.20 (N)

FR7 bumper signal lamp RH. \$154.60N X Not nec.

2pcs headlamp. \$549.30N x 2 = 1098.60 (N)

headlamp support panel. \$1884.90N X Not nec.

brace panel.

Aircon Condenser. \$969.60 S/N ✓ Best

Radiator \$707.30 S/N ✓ cracked

Aircon fan motor. \$377.10 S/N X Not nec

Aircon fan blade. \$65.60 S/N X Not nec.

Aircon fan winding \$335.30 S/N ✓ cracked.

Radiator fan motor. \$377.10 S/N X Not nec

Radiator fan blade. \$240.40 S/N X Not nec.

Steering airbag \$2326.80N

FR7 passenger airbag \$2390.20N

Airbag control unit \$1445 S/N

Clock Sensor. \$242.70 S/N

} ✓ Activated.

SGG 7767E

Dashboard - \$1928.40N ✓ torn.

2pcs FR7 safety belt. \$820.90 s/N ✓ Activated

FR7 bumper top beam \$252N ✓ Bent

headlamp support top garnish \$168N ✓ Deformed

8pcs support top garnish clips \$5N x 8 = 40(N) - 30(N) ✓ Nec.

ECU \$4826 s/N x 1pc nec.

Battery bracket \$50N x 1pc nec.

Air duct \$144N ✓ Dehd.

~~Radiator top garnish~~

Engine under cover. \$128N ✓ to/n

6pcs Engine under cover clips \$5N x 6 = 30(N) ✓ Nec.

FR7 LH fender \$621N x Repair

2pcs FR7 fender inner bowling \$81.60N x 2 = 163.20(N) x 1pc nec.

20pcs inn bowling clips \$5N x 20 = 100(N) x 1pc nec.

Nett: 12089.70

Ten 10%: 10880.73.

S.N: 3699.90

Number plate (with casing) \$50 ✓ Best

Radiator Coolant \$30 ~~Nec~~ Nec.

Battery \$250 X ~~Nec~~ Nec.

SN: 50

To check wiring ~~\$50~~ 30

To remove and refix aircon and gas \$120 ✓

To remove and replace dashboard ~~\$300~~ 220

To remove and replace 2ps safety belt and airbags system ~~\$400~~ 300

To reprogramme airbag system ~~\$350~~ 250

To replace and reprogramme ECU ~~\$500~~ 250

To cut, weld, straighten and realign all affected parts ~~\$900~~ 800

To spray paint on all affected areas ~~\$1000~~ 600.

2570

total: 17200.63

1/5: 12K (Nett Value).

12 Days.

12K

12 Days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: