

CL

204, Arm 180 (3330), Uha3G

59033

Surveyor:

MARCUS

DOI:

ASSIGNMENT

26/07/18

Date / Time:

23/8/2018

Registered in Merimen:

Pre-assign / CCU / FTE

SJN 2701E

Sem 0007



Insured Vehicle No.

Claim No.:

Name of Insured

Policy No.:

Insured Tel No.

HP:

Make / Model:

Excess Sec II :SS

22,000.00

D.O.A.:

15/1/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

PRAVEEN S/O JAGANATHAN

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

8191080

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SKX 7954 U



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kah Motor
UBI

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

23/8

SKX 7954U-X; SJN 2701E-X

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

25/07/18 @ 3:07PM

@ 4:09PM

22/10/18
02/11/18
14/11/18

28/11/18

TP provided adv.
 TP video uploaded in SUBMITTING.
 HANDING DS.
 CALL OLD. NO RESPONSE. PUE REVIEWED.
 OLD REAR- BOUND TP. SEND LETTER TO
 OI 4 EMAIL TO OLD TO NOTIFY TP CLAIM.
 OLD CLAIM IN. COMPLETION ACCIDENT DURING
 A REAR- BOUND TP. INFORMED TP CLAIM,
 AGREED TO SETTLE 4 AWKES HOD LOUERS.
 PINKUETED. TP LOD IN BY EMAIL.
 UPLOADED 4 HANDOVER IN GC.
 GIVE UPDATES BY PC.
 ASK APPROVED HANDOVER.
 SEND ACCEPTANCE EMAIL TO TP
 RECEIVED BY. ALL GOOD IN ORDER.
 TO CLOSE.
 RECEIVED 28 NOV 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: 7/18

SS 7,895.66 / 7 days) Reduction: 51 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lin:

Repair Cost: 2/18

SS 8,448.36

(OI REAR- BOUND TP)

Loss of Rental (LOR):

SS (days)

Loss of Use (LOU):

SS 350.00 x 7 days)

Loss of Income (LOI):

SS (5 x days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4550.00

Total:

SS 8,798.36

Global Sum SS:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS 8,798.36

Name 1:

KAH MOTOR CO. SDN. BHD.

Payee 2: (Strike if N.A.)

SS

Name 2:

-

Payee 3: (Strike if N.A.)

SS

Name 3:

-

2011/12

ASS. REC. BY: MDV 65

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / OWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKX79544

at Workshop m/s: Kohutator

of _____

Insured _____

Policy No: _____

Claims No: _____

Sum Insured _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value: \$64k.

IDAC Accident Report: _____

Consistent?: Yes or No

GIA / PR Seen: 9

Consistent?: Yes or No

Est. Repairs: 7 days

Res.: Yes or No

Lump Sum: - %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

21A0341

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: SKX79544 Yr Regn: 12/15

Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Honda Jazz

CC: 1498

Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 387/10

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JHMAK5850GX201247

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Border / Jammed / Leaked / Burnt or

Brake: Border / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

185/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6

Rear: 6

R/Bal: _____ mm

R/Bal: _____ mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 15/7/18

D.O.A: 26/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: 7 yrs. 5 mks.

MP \$7,895.00

(CRP: \$8,366.00 (51%))

MV: \$64,000.00 (est)

LCA: \$50,341.00 (est)

NETC: \$13,659.00 (est)

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee

Transportation

\$ - RS - \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

HONDA

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance: Call 98203838

QUOTATION

GST Reg No: M200050223

Company Ref No: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SKX7954U
Chassis No : JHMDK5850GX201247
Model : JAZZ 1.5VTIR CVT 16YM
Owner's Name : JOE WALDY
Ins Policy No : 5087075175-01
Date of Accident : 15/7/2018

Document No : SQT18003028
Date : 21 Jul 2018
Customer No : WZA006
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15B31020386
Date / Time : 21 Jul 2018 8:55:55 AM
Surveyor Name :
Survey Date :
Authorisation Date :
E-mail: aychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (JIND 70912)						
	OWNER: JOE WALDY						
	OWNER INSURER: NTUC INCOME INSURANCE CO-OP LTD						
	ACC DATE: 15/07/2018 @ 16:00PM						
	SURVEYED BY:						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SJN2701E						
BO-R-COOL-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN	1	300.00	1%	300.00	21.00	321.00
			Sum Ext. Service		390.00	21.00	411.00
91505-TM8-003	CLIPBUMPER <i>rel</i>	14	2.00	25	21.00	1.47	22.47
75722-T5L-T01	EMBLEMRR <i>rel</i>	1	10.50	25	7.87	0.55	8.42
04715-T5B-000ZZ	FACERR BUMPER <i>rel</i>	1	492.50	25	369.45	25.86	395.31
71593-T5A-000	SPACERR RR BUMPER <i>rel</i>	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL RR BUMPER <i>rel</i>	1	11.50	25	8.62	0.60	9.22
71502-T5A-000	GARNISHR RR BUMPER <i>rel</i>	1	14.00	25	10.50	0.74	11.24
71507-T5A-000	GARNISHL RR BUMPER <i>rel</i>	1	14.00	25	10.50	0.74	11.24
84521-T5A-9012A	LID ASSYSPARE TIRE <i>rel</i>	1	186.00	25	139.50	9.77	149.27
84550-T5S-M10	BOX ASSYCARGO FLOOR <i>rel</i>	1	103.90	25	77.92	5.45	83.37
84405-SF4-003	HOCKCENTER SHELF <i>rel</i>	2	3.60	25	5.40	0.38	5.78
84640-T5A-0032A	LINING ASSYRR PANEL <i>rel</i>	1	60.80	25	45.60	3.19	48.79
84601-TAR-Z032A	LINING ASSYR TRUNK <i>rel</i>	1	165.60	25	124.20	8.69	132.89
84651-TAR-Z032A	LINING ASSYL TRUNK <i>rel</i>	1	165.60	25	124.20	8.69	132.89
34150-T5A-J01	LIGHT ASSYR LID <i>rel</i>	1	79.30	25	59.47	4.16	63.63
34155-T5A-J01	LIGHT ASSYL LID <i>rel</i>	1	79.30	25	59.47	4.16	63.63
33500-T5A-J02	TAILLIGHT ASSYR <i>rel</i>	1	235.10	25	176.32	12.34	188.66
33550-T5A-J02	TAILLIGHT ASSYL <i>rel</i>	1	217.40	25	163.05	11.41	174.46
75701-T5A-000	EMBLEMH <i>rel</i>	1	10.70	25	8.02	0.56	8.58

HONDA**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6641 3836

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 95203838

QUOTATION

GST Reg No: M200050223

Company Ref No: S60FC1380G

Customer: AXA INSURANCE S'PORE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

Registration No: SKX7954U
 Chassis No: JHMGK5850GX201247
 Model: JAZZ 1.5VTIR CVT 16YM
 Owner's Name: JOE WALDY
 Ins Policy No: 5087075175-01
 Date of Accident: 15/7/2018

Document No: SQT18003028
 Date: 21 Jul 2018
 Customer No: WZA006
 Svc Advisor: ARY CHUA WAI NGEE
 Engine No: L15B31020386
 Date / Time: 21 Jul 2018 8:55:55 AM
 Surveyor Name: [Signature]
 Survey Date: [Signature]
 Authorisation Date: [Signature]

Page: 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	2.85	0.20	3.05
74890-T5B-911	GARNISH ASSYRR LICENSE	1	194.70	25	146.02	10.22	156.24
74940-TZ5-A01	BUZZER ASSYSMART	1	59.30	25	44.47	3.11	47.58
38387-TZ5-A01	ANTENNA ASSYLF	1	58.10	25	43.57	3.05	46.62
66100-TAR-T10ZZ	PANEL COMPRR	1	314.00	25	235.50	16.49	251.99
04655-TAS-300ZZ	PANEL SET RR FLOOR	1	689.90	25	502.42	35.17	537.59
65540-T5A-310ZZ	STIFFENER COMPR RR	1	66.90	25	50.17	4.56	54.73
65590-T5A-310ZZ	STIFFENER COMPL RR	1	66.90	25	50.17	4.56	54.73
6R100-TA5-Z50ZZ	TAILGATE COMP	1	716.30	25	537.22	37.61	574.83
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07
74800-T5A-J01	LOCK ASSYTAILGATE	1	75.00	25	56.25	4.02	60.27
73211-T5A-J01	GLASS SETRR WINDSHIELD	1	625.60	25	469.20	32.84	502.04
73127-TY0-000	RUBBER CWINDOWSHIELD DAMPER	1	11.20	25	8.40	0.59	8.99
73214-T5A-013	RUBBERWINDOWSHIELD DAMPER	2	6.30	25	9.45	0.66	10.11
73226-SZW-000	DAMPERSTD SX5	1	6.30	25	4.72	0.44	5.16
BO-W5-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
Sum Item:					2742.04	261.93	4,003.97

BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	1	180.00		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	240.00		240.00	16.80	256.80
BP00R	APPLY BODY UNDERSIDE COATING (N)	1	250.00		250.00	17.50	267.50
BG02D	REMOVE & INSTALL RR WINDSCREEN (N)	1	350.00		350.00	24.50	374.50
BOMISC1	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION	1	350.00		350.00	24.50	374.50
BOMISC1	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM	1	350.00		350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00		450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &	1	550.00		550.00	38.50	588.50

Printed on 21/7/2018 9:29:57 AM

This is a computer-generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair does not include any unforeseen damages.

GST amount is calculated from individual item(s).

HONDA

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No: M000050223

Company Ref No: S60FC13800

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SKX7954U
Chassis No : JHMGK5650GX201247
Model : JAZZ 1.5VTIR CVT 16YM
Owner's Name : JOE WALDY
Ins Policy No : 5087075175-01
Date of Accident : 15/7/2018

Document No : SQT18003028 Page : 3
Date : 21 Jul 2018
Customer No : WZA006
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15B31020386
Date | Time : 21 Jul 2018 8:55:55 AM
Surveyor Name : JC -65 6845 5671
Survey Date : -65 8100 1304
Authorisation Date : 21 Jul 2018 8:55:55 AM

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
BP06R	SPRAY PAINT ON REPAIRED/REPLACED AREAS (BPX \$450)	1	3600.00	22.50	3600.00	252.00	3852.00
BKRP02M	CUT OFF & RENEW RR PANEL & FLOOR PANER	1	5800.00		5800.00	392.00	5992.00
Sum Labor					12220.00	855.40	13075.40

Survey By : MORCAY ALAN
Date & Time : 26/7/18
Excess : not apply
Status : take photo before repair
Signature : HP: 62863561
7dy.

Total Amount : 15,252.04 1,136.33 17,400.37
Total (Inclusive of GST) : 17,400.37

confirmed \$ 7895.66 with Ary
13/8/18

- KAH MOTOR CO. SDN. BHD. hereby notify the customer of the following:
- All repair work is done on the spot.
 - All repair work is done on the spot during business hours.
 - All repair work is done on the spot during business hours.
 - All repair work is done on the spot during business hours.
 - All repair work is done on the spot during business hours.
 - All repair work is done on the spot during business hours.
 - All repair work is done on the spot during business hours.
 - All repair work is done on the spot during business hours.

Acknowledged by Repairer

Signature

Date

Printed on 21/7/2018 9:29:57 AM

This is a computer generated invoice. No signature is required.

Prices are subject to change without notice.

The above estimated cost of repair do not include any unforeseen damage.

GST Amount is calculated from individual items.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
Chassis No: JHMGK5850GX201247
License No: SKX7954U
Mileage: 39045
Engine No: L15B31020386

Document No: SVO18045230
Printed By: ARYCHUA
Order Date: 2. August 2018
Order Time: 4:33:13 PM
Service Advisor: ARY CHUA WAI NGE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Includ GST
TP DIRECT SETTLEMENT (J/NO: 70912)							
OWNER: JOE WALDY							
OWNER INSURER: NTUC INCOME INSURANCE CO-OP LTD							
ACC DATE: 15/07/2018@18.00PM							
SURVEYED BY: MARCUS CHUA(LKK AUTO)26/07/2018@14.14							
REF NO:CC4/ASM18013330/HA3							
TP INSURER: AXA INSURANCE S'PORE PTE LTD							
TP VEH: SJN2701E							
91505-TM8-003	CLIPBUMPER	14	2.00	25	21.00	1.47	22.47
75722-T5L-T01	EMBLEMRR.	1	10.50	25	7.87	0.55	8.42
04715-T5B-000ZZ	FACERR.BUMPER	1	492.60	25	369.45	25.86	395.31
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
84640-T5A-003ZA	LINING ASSYRR.PANEL	1	60.80	25	45.60	3.19	48.79
33500-T5A-J02	TAILLIGHT ASSY.R.	1	235.10	25	176.32	12.34	188.66
66100-TAR-T10ZZ	PANEL COMPRR.	1	314.00	25	235.50	16.49	251.99
68100-TAS-Z50ZZ	TAILGATE COMP	1	716.30	25	537.22	37.61	574.83
74800-T5S-K61	LOCK ASSY,TAILGATE	1	77.10	25	57.82	4.05	61.87
73127-TY0-000	RUBBER CWINDOWSHIELD DAMPER	1	11.20	25	8.40	0.59	8.99
73214-T5A-013	RUBBERWINDOWSHIELD DAMPER	2	6.30	25	9.45	0.66	10.11
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
38387-TZ5-A01	ANTENNA ASSYL.F.	1	58.10	25	43.57	3.05	46.62
SUM PARTS:					1,595.66	111.70	1,707.36
BOSUN	0672	1	20.00		20.00	1.40	21.40
SUNDRIES							
BML02I	EXT-YJ	1	80.00		80.00	5.60	85.60
INSPECT RR LIGHTING MECHANISMS.							
PERFORM WATER							
TEST.(N)							
BOBC	EXT-YJ	1	100.00		100.00	7.00	107.00
BODY UNDERSIDE COATING (N)							
BOJSE	0672	1	100.00		100.00	7.00	107.00
BODY JOINT SEALANT.							
BA02R	EXT-YJ	1	140.00		140.00	9.80	149.80
REMOVE & RENEW REVERSE							
SENSORS-4 PCS (N)							
BP00R	EXT-YBH	1	200.00		200.00	14.00	214.00
APPLY BODY UNDERSIDE COATING (N).							
BM103D	EXT-YJ	1	250.00		250.00	17.50	267.50
REMOVE & INSTALL REAR							
COMPARTMENT LININGS							
GARNISHES.(N)							
BG02D	EXT-YJ	1	300.00		300.00	21.00	321.00
REMOVE & INSTALL RR. WINDSCREEN.							
(N)							
BOMISC1	EXT-YJ	1	300.00		300.00	21.00	321.00
REMOVE & INSTALL REVERSE CAMERA							
& CALIBRATION							
BOMISC1	EXT-YJ	1	300.00		300.00	21.00	321.00
RESET VEHICLE SMART KEY							
ACCESS/ENTRY SYSTEM							

WD = 7

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408551. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE**Chassis No:** JHMGK5850GX201247**License No:** SKX7954U**Mileage:** 39045**Engine No:** L15B31020386**Document No:** SVO18045230**Printed By:** ARYCHUA**Order Date:** 2. August 2018**Order Time:** 4:33:13 PM**Service Advisor:** ARY CHUA WAI NGEE

BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	300.00	300.00	21.00	321.00
BKRP02M	EXT-YJ CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.	1	1,960.00	1,960.00	137.20	2,097.20
BP05R	EXT-YBH SPRAY PAINT ON REPAIRED/REPLACED AREAS.(5PX\$450)	1	2,250.00	2,250.00	157.50	2,407.50
			SUM LABOUR:	6,300.00	441.00	6,741.00
			TOTAL SGD	7,895.66	552.70	8,448.36
Total Payable (SGD)						8,448.36

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

11/5/2018
 @ 16 JUL 2018
 → Mei Kwan
 Lkt auto
 63660055

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811
 Registration No : SKX7954U
 Chassis No : JHMGK5850GX201247
 Model : JAZZ 1.5VTIR CVT 16YM
 Owner's Name : JOE WALDY
 Ins Policy No. : 5087075175-01
 Date of Accident : 15/7/2018

Document No. : SQT18003028 Page 1
 Date : 21. Jul 2018
 Customer No. : WZA006
 Svc Advisor : ARY CHUA WAI NGEE
 Engine No : L15B31020386
 Date | Time : 21. Jul 2018 8:55:55 AM
 Surveyor Name : DND : +65 6846 5873
 Survey Date : HP : +65 8100 5306
 Authorisation Date : Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO: 70912)						
	OWNER: JOE WALDY						
	OWNER INSURER: NTUC INCOME INSURANCE CO-OP LTD						
	ACC DATE: 15/07/2018@18.00PM						
	SURVEYED BY:						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SJN2701E						
BO-R-COOL-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN.	1	300.00	11	300.00	21.00	321.00
					Sum Ext. Service	300.00	321.00
91505-TM8-003	CLIPBUMPER <i>ner</i>	14	2.00	25	21.00	1.47	22.47
75722-T5L-T01	EMBLEMRR. <i>ni</i>	1	10.50	25	7.87	0.55	8.42
04715-T5B-000ZZ	FACERR.BUMPER <i>ni/pe</i>	1	492.60	25	369.45	25.86	395.31
71593-T5A-000	SPACERR.RR.BUMPER <i>set</i>	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER <i>set</i>	1	11.50	25	8.62	0.60	9.22
71502-T5A-000	GARNISHR.RR.BUMPER <i>17</i>	1	14.00	25	10.50	0.74	11.24
71507-T5A-000	GARNISHL.RR.BUMPER <i>17</i>	1	14.00	25	10.50	0.74	11.24
84521-T5A-901ZA	LID ASSYSAPRE TIRE <i>11</i>	1	186.00	25	139.50	9.77	149.27
84550-T5S-M10	BOX ASSYCARGO FLOOR	1	103.90	25	77.92	5.45	83.37
84405-SF4-003	HOOKCENTER SHELF	2	3.60	25	5.40	0.38	5.78
84640-T5A-003ZA	LINING ASSYRR.PANEL <i>2m</i>	1	60.80	25	45.60	3.19	48.79
84601-TAR-Z03ZA	LINING ASSYR.TRUNK	1	165.60	25	124.20	8.69	132.89
84651-TAR-Z03ZA	LINING ASSYL.TRUNK	1	165.60	25	124.20	8.69	132.89
34150-T5A-J01	LIGHT ASSYR.LID	1	79.30	25	59.47	4.16	63.63
34155-T5A-J01	LIGHT ASSYLLID	1	79.30	25	59.47	4.16	63.63
33500-T5A-J02	TAILLIGHT ASSY.R. <i>cm</i>	1	235.10	25	176.32	12.34	188.66
33550-T5A-J02	TAILLIGHT ASSYL	1	217.40	25	163.05	11.41	174.46
75701-T5A-000	EMBLEMH <i>11</i>	1	10.70	25	8.02	0.56	8.58

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance. Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SKX7954U

Chassis No : JHMGK5850GX201247

Model : JAZZ 1.5VTIR CVT 16YM

Owner's Name : JOE WALDY

Ins Policy No. : 5087075175-01

Date of Accident : 15/7/2018

Document No. : SQT18003028 Page 2

Date : 21. Jul 2018

Customer No. : WZA006

Svc Advisor : ARY CHUA WAI NGEE

Engine No : L15B31020386

Date | Time : 21. Jul 2018 8:55:55 AM

Surveyor Name : DID : +65 6345 5673

Survey Date : HP : +65 8100 6306

Authorisation Date : Email : ary.chua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
90301-ST0-003	NUTPUSH 3MM 11	2	1.90	25	2.85	X 0.20	3.05
74890-T5B-911	GARNISH ASSYRR.LICENSE 11	1	194.70	25	146.02	X 10.22	156.24
74940-TZ5-A01	BUZZER ASSYSMART	1	59.30	25	44.47	? 3.11	47.58
38387-TZ5-A01	ANTENNA ASSYL.F.	1	58.10	25	43.57	? 3.05	46.62
66100-TAR-T10ZZ	PANEL COMPRR. 3.15.00	1	314.00	25	235.50	16.49	251.99
04655-TAS-300ZZ	PANEL SET,RR.FLOOR R	1	669.90	25	502.42	X 35.17	537.59
65540-T5A-310ZZ	STIFFENER COMP,R.RR. 11	1	86.90	25	65.17	X 4.56	69.73
65590-T5A-310ZZ	STIFFENER COMP,L.RR. 11	1	86.90	25	65.17	X 4.56	69.73
68100-TAS-Z50ZZ	TAILGATE COMP 3.15.00	1	716.30	25	537.22	? 37.61	574.83
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	? 4.85	74.07
74800-T5A-J01	LOCK ASSYTAILGATE R	1	76.60	25	57.45	4.02	61.47
73211-T5A-J01	GLASS SETRR.WINDSHIELD 11	1	625.60	25	469.20	X 32.84	502.04
73127-TY0-000	RUBBER CWINDSHIELD DAMPER R	1	11.20	25	8.40	0.59	8.99
73214-T5A-013	RUBBERWINDSHIELD DAMPER R	2	6.30	25	9.45	0.66	10.11
73226-SZW-000	DAMPERSTD 5X5 R	1	8.30	25	6.22	0.44	6.66
BO-WS-SEALANT	WINDSCREEN SEALANT (N) R	1	60.00		60.00	4.20	64.20
Sum Item					3742.04	261.93	4,003.97
BOSUN	SUNDRIES	1	100.00	R 20	100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	80	180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	240.00	140	240.00	16.80	256.80
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	200	250.00	17.50	267.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN (N)	1	350.00	300	350.00	24.50	374.50
BOMISC1	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION1	1	350.00	300	350.00	24.50	374.50
BOMISC1	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM	1	350.00	300	350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00	250	450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	550.00	300	550.00	38.50	588.50

Printed on 21/7/2018 9:29:57 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SKX7954U
Chassis No : JHMGK5850GX201247
Model : JAZZ 1.5VTIR CVT 16YM
Owner's Name : JOE WALDY
Ins Policy No. : 5087075175-01
Date of Accident : 15/7/2018

Document No. : SQT18003028 Page 3
Date : 21. Jul 2018
Customer No. : WZA006
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15B31020386
Date | Time : 21. Jul 2018 8:55:55 AM
Surveyor Name : DID : +65 6846 5673
Survey Date : HP : +65 8100 5306
Authorisation Date : Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BP06R	SPRAY PAINT ON REPAIRED/REPLACED AREAS. (6PX \$450)	1	3600.00	22.50	3600.00	252.00	3852.00
BKRP02M	CUT OFF & RENEW RR PANEL & FLOOR PANER	1	5600.00		5600.00	392.00	5992.00
Sum Labor					12220.00	855.40	13,075.40

Survey By : Marcus LAL
Date & Time : 26/7/18
Excess : Not Applicable
Status : Not yet started
Signature : John Shih. Before policy.
HP: 62563561
Tdy.

Total Amount 16,262.04 1,138.33 17,400.37
Total (Inclusive of GST) 17,400.37

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 21/7/2018 9:29:57 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

Vic (LKKAUTO)

From: Emillin Liew <emillinliew@honda.com.sg>
Sent: Wednesday, 28 November, 2018 1:59 PM
To: Vic (LKKAUTO)
Cc: Admin A; Daryle Tan; Faeaz
Subject: RE: LKK C/O AXA- Submission of Third Party Direct Settlement, Y/R: CC4/ASM18013330/ha3 : O/R: SKX7954U LKK REF CC4/ASM18013330/Uha3
Attachments: AXA-LKK SKX7954U DV.pdf

Dear Vic,

Attached signed DV for your retention.

We would appreciate if you could process payment for our claim soonest possible.

Regards,
Emillin

From: Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Sent: Wednesday, 14 November 2018 2:10 PM
To: Faeaz <faeaz@honda.com.sg>
Cc: Emillin Liew <emillinliew@honda.com.sg>; Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Subject: RE: LKK C/O AXA- Submission of Third Party Direct Settlement, Y/R: CC4/ASM18013330/ha3 : O/R: SKX7954U LKK REF CC4/ASM18013330/Uha3

Without Prejudice

Dear Faez,

We refer further to our below email.

Purely for an amicable settlement on a without prejudice basis and without admission of liability to our Insured's part, we have our principal's mandate and we confirm acceptance of your offer of **\$8,798.36** (all in) to settle your client's claim.

Kindly let the owner sign the attached DV and forward a copy to us for payment processing.

The above amount is to be made payable to **KAH MOTOR CO. SDN. BHD.**

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Vic (LKKAuto)

Sent: Friday, 2 November, 2018 1:18 PM

To: Faeaz

Cc: Emillin Liew; Admin A; Vic (LKKAuto)

Subject: RE: LKK C/O AXA- Submission of Third Party Direct Settlement, Y/R: CC4/ASM18013330/ha3 : O/R: SKX7954U LKK REF CC4/ASM18013330/Uha3

Without Prejudice

Dear Faez,

We refer to your below email.

Please be informed that we are still pending for mandate approval from our principal.

We will follow up and will get back to you for an update.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Faeaz [<mailto:faeaz@honda.com.sg>]

Sent: Friday, 2 November, 2018 11:57 AM

To: Admin A; Vic (LKKAuto)

Cc: Emillin Liew

Subject: FW: LKK C/O AXA- Submission of Third Party Direct Settlement, Y/R: CC4/ASM18013330/ha3 : O/R: SKX7954U

Dear Vic,

Refer to our below email dated 26/9/18.

To date we still have yet to receive your response on the above claim settlement.

We appreciate if you could kindly expedite the process and let us have your settlement Offer soonest possible.

Best Regards

Mohd Faeaz Bin Yaacob
Senior Executive
Kah Motor Body Repair Centre
15, Ubi Road 4
Singapore 408610
Tel : 68465678
Hp : 82886304

From: Emillin Liew
Sent: Wednesday, 26 September, 2018 10:08 AM
To: Admin A (admin-a@lkkauto.com) <admin-a@lkkauto.com>; 'vicalpeh@lkkauto.com' <vicalpeh@lkkauto.com>
Cc: Marcus Chua (LKKAuto) <MarcusChua@lkkauto.com>; Faeaz <faeaz@honda.com.sg>
Subject: LKK C/O AXA- Submission of Third Party Direct Settlement, Y/R: CC4/ASM18013330/ha3 : O/R: SKX7954U

Dear Vic,

RE: ACCIDENT INVOLVING SKX7954U AND SJN2701E ON 15.07.18

Attached please find our repair invoice and other relevant documents for the above direct settlement claim.

Kindly email me the DV as soon as possible.

Warmest Regards,

Emillin Liew
DID: +65 6514 5684
Email: emillinliew@honda.com.sg

KAH MOTOR CO. SDN. BHD.
(A member of Oriental Holdings Berhad)
15 Ubi Road 4 Singapore 408610
Tel: +65 6743 4333 Fax: +65 6748 0770



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



**Re:<SEEK MANDATE> S8M00OP7 ACCIDENT
INVOLVING VEHICLES SJN 2701E(OI) AND SKX
7954U(TP) ON 15/07/18 TOTAL: \$8,798.36**

Type

 Question

Message

Mandate approved

Reply



Kah Motor Co. Sdn. Bhd.
(A Member of Oriental Holdings Berhad)
15 Ubi Road 4
Singapore 408610
Tel: +65 6841 3838
Fax: +65 6748 0770
www.honda.com.sg

M/s **AXA Insurance Singapore Pte Ltd**
C/o LKK Auto Consultants Pte Ltd
8 Shenton Way
#27-01
Singapore 068811

Date:

26/9/18

Your ref: CC4/ASM18013330/ha3

Our ref: SKX7954U

Attn: Motor Claims Department

Dear Sir / Madam,

THIRD PARTY DIRECT SETTLEMENT

ACCIDENT INVOLVING SKX7954U AND SJN2701E ON 15.07.18

We refer to the items(s) marked (✓) below:

- (✓) We refer to LKK-Vic's email dated 02.08.18
- (✓) We enclosed herewith the repair invoice / Third Party Direct Settlement Agreement.
- (✓) Kindly forward the discharge voucher for our client's signature within 2 weeks via email to emillinliew@honda.com.sg or faeaz@honda.com.sg
- (✓) We return your discharge voucher duly completed.
- (✓) Kindly expedite settlement the following:-

Repair Cost	S\$8,448.36 payable to Kah Motor Co Sdn Bhd
Loss of Use	S\$50.00 X 7 Days = S\$350.00 payable to Joe Waldy
Rental	NIL
TP Search Bill	NIL
LTA Search Bill	NIL
- (✓) Kindly let us have your cheque made in favour of the above mentioned names(s) for our transmission as soon as possible.
- (✓) Letter of Authority

Thank you.

Yours faithfully,

Ary Chua



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

25 JULY 2018

**NOBLE CHAUFFERING
BLOCK 153 GANGSA ROAD
#05-325
SINGAPORE 670153**

By Post and By Email

Dear Sir/Madam,

OUR REF : CC4/ASM18013330/ha3

YOUR REF : SJN 2701E

**ACCIDENT INVOLVING SJN 2701E AND SKX 7954U ALONG BALESTIER ROAD ON
15.07.18**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third-party claim against your policy.

We have received a claim from M/s KAH MOTOR CO. SDN BHD, acting on behalf of the owner of SKX 7954U against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SKX 7954U. As such, liability may not be on your favour unless proven otherwise.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

PRAVEEN.SO.JAGANATHAN@GMAIL.COM
(Email)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Wednesday, 25 July, 2018 4:10 PM
To: PRAVEEN.SO.JAGANATHAN@GMAIL.COM
Cc: Admin A; Vic (LKKAUTO)
Subject: YOUR REF: SJN 2701E_ACCIDENT INVOLVING SJN 2701E AND SKX 7954U ALONG BALESTIER ROAD ON 15.07.18



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

25 JULY 2018

**NOBLE CHAUFFERING
BLOCK 153 GANGSA ROAD
#05-325
SINGAPORE 670153**

By Post and By Email

Dear Sir/Madam,

OUR REF : CC4/ASM18013330/ha3

YOUR REF : SJN 2701E

ACCIDENT INVOLVING SJN 2701E AND SKX 7954U ALONG BALESTIER ROAD ON 15.07.18 ✓

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third-party claim against your policy.

We have received a claim from M/s KAH MOTOR CO. SDN BHD, acting on behalf of the owner of SKX 7954U against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SKX 7954U. As such, liability may not be on your favour unless proven otherwise.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

LETTER OF AUTHORITY

TO WHOM IT MAY CONCERN

ACCIDENT INVOLVING (OWNER'S VEHICLE NO.) SKX7954U
& (THIRD PARTY'S VEHICLE NO.) SJN 2701E
ON 15 July 2018 ALONG Balestier Road

- I hereby authorize Kah Motor Co Sdn Bhd and its agents or any person authorized by Kah Motor to do all or any of the following.
- To submit, resolve and make any claims(s) which I may have against the 3rd party insurers.
- To execute, sign discharge voucher / indemnity forms and all necessary documents in connection with and arising out of the above claim

Any payment should be made in favour of my name / Kah Motor Co Sdn Bhd



Owner Signature

(Co stamp & authorized signature if it's Co. registered vehicle)

Name : JOE WALDOY
NRIC No : S8572581E
Vehicle No : SKX 7954U
Date : 16 July 2018



redefining / insurance

WITHOUT PREJUDICE to:

CLAIM REF : S8M00P7
INSURED : NOBLE CHAUFFERING

Any Personal Injury Claims:

DISCHARGE VOUCHER

We/I, JOE WALDY, NRIC NO. S8572581E hereby agree to accept the sum of dollars EIGHT THOUSAND SEVEN HUNDRED NINETY EIGHT AND CENTS THIRTY SIX ONLY (S\$8,798.36) paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their Insured or the driver of motor vehicle no. SJN 2701E as a result of an accident along BALESTIER ROAD on 15.07.2018 of which we/I were/was the driver/owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SKX 7954U.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. SJN 2701E in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SJN 2701E.

Dated this 26 day of Nov 2018

Claimant's Signature

NRIC no./ Company Stamp

S8572581E

Occupation/ Business

Address

BLK 116A Jalan Tanteran #28-527 Singapore 32116

Telephone No.

98346985

Witness's Name

KATHIRAVELU S. SUBRAMANIAM

Witness's Signature

15, UBI ROAD #4

Witness's NRIC No.

SINGAPORE 400110

AXA Insurance Pte Ltd (Company Reg. No. 199903512M)

8 Shenton Way, #24-01 AXA Tower, Singapore 068811

Customer Centre #B1-01

Tel: +65 6880 4888 Fax: +65 6338 2522 Website: www.axa.com.sg

**Kah Motor Co. Sdn. Bhd.**

(A Member of Oriental Holdings Berhad)

15 Ubi Road 4, SINGAPORE 408610

Ubi Parts Centre

Phone No. : +65 6841 3838 Fax No. :

AXA INSURANCE S'PORE PTE LTD

MOTOR CLAIMS DEPT

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE, 068811

Customer No. : WZA008

Service Tax Invoice

GST Reg No. M200050223

Company Ref. No. S80FC1380G

Invoice No. : SINV-BS18001708
 Invoice Date : 25/09/18
 Order No. : SVO18045230
 Reference :
 Job Card No. : 70912
 Date/Time Received : 21/07/18 / 8:55:55 AM
 Licence No. : SKX7954U
 Model : JAZZ 1.5VTIR CVT 16YM
 Car Chassis No. : JHMGK5850GX201247
 Car Engine No. : L15B31020386
 Mileage : 39045
 Service Advisor : ARY CHUA WAI NGEE 1490A
 Served By : ARYCHUA
 Page : 1

No.	Description	Qty.	UoM	U. Price	Disc %	Amount	7% GST Amount	Incl GST
	TP DIRECT SETTLEMENT (J/NO: 70912)							
	OWNER: JOE WALDY							
	OWNER INSURER: NTUC INCOME INSURANCE CO-OP LTD							
	ACC DATE: 15/07/2018@18.00PM							
	SURVEYED BY: MARCUS CHUA(LKK AUTO)26/07/2018@14.14							
	REF NO:CC4/ASM18013330/UHA3							
	TP INSURER: AXA INSURANCE S'PORE PTE LTD							
	TP VEH: SJN2701E							
BOSUN	0672 SUNDRIES	1	Hours	20.00		20.00	1.40	21.40
BML02I	EXT-YJ INSPECT RR LIGHTING MECHANISMS.	1	Hours	80.00		80.00	5.60	85.60
	PERFORM WATER TEST.(N)							
BOBC	EXT-YJ BODY UNDERSIDE COATING (N)	1	Hours	100.00		100.00	7.00	107.00
BOJSE	0672 BODY JOINT SEALANT.	1	Hours	100.00		100.00	7.00	107.00
BA02R	EXT-YJ REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	Hours	140.00		140.00	9.80	149.80
BP00R	EXT-YBH APPLY BODY UNDERSIDE COATING (N).	1	Hours	200.00		200.00	14.00	214.00
BMI03D	EXT-YJ REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	Hours	250.00		250.00	17.50	267.50
BG02D	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN.(N)	1	Hours	300.00		300.00	21.00	321.00
BOMISC1	EXT-YJ REMOVE & INSTALL REVERSE CAMERA & CALIBRATION	1	Hours	300.00		300.00	21.00	321.00
BOMISC1	EXT-YJ RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM	1	Hours	300.00		300.00	21.00	321.00
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	Hours	300.00		300.00	21.00	321.00
BKRP02M	EXT-YJ CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	Hours	1,960.00		1,960.00	137.20	2,097.20
	ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.							
BP05R	EXT-YBH SPRAY PAINT ON REPAIRED/REPLACED AREAS.(5PX\$450)	1	Hours	2,250.00		2,250.00	157.50	2,407.50
91505-TM8-003	CLIPBUMPER	14	Each	2.00	25	21.00	1.47	22.47
75722-T5L-T01	EMBLEMRR.	1	Each	10.50	25	7.87	0.55	8.42
04715-T5B-000ZZ	FACERR.BUMPER	1	Each	492.60	25	369.45	25.86	395.31
71593-T5A-000	SPACERR.RR.BUMPER	1	Each	11.50	25	8.62	0.60	9.22
71596-T5A-000	SPACERL.RR.BUMPER	1	Each	11.50	25	8.62	0.60	9.22
84640-T5A-003ZA	LINING ASSYRR.PANEL	1	Each	60.80	25	45.60	3.19	48.79
33500-T5A-J02	TAILLIGHT ASSY,R.	1	Each	235.10	25	176.32	12.34	188.66

Printed by ARYCHUA on 25 Sep 2018 at 8:10:58 AM

This is a computer generated invoice. No signature is required.

Please review your bill and advise us of any errors or omissions.

Kah Motor reserves the right to deliver a subsequent bill for any charge omitted.

GST Amount is calculated from individual line(s).

Please give us your
 feedback by scanning
 the QR Code using
 mobile device



**Kah Motor Co. Sdn. Bhd.**

(A Member of Oriental Holdings Berhad)

15 Ubi Road 4, SINGAPORE 408610

Ubi Parts Centre

Phone No. : +65 6841 3838 Fax No. :

AXA INSURANCE S'PORE PTE LTD

MOTOR CLAIMS DEPT

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE, 068811

Customer No. : WZA006

Service Tax Invoice

GST Reg No. M200050223

Company Ref. No. S80FC1380G

Invoice No. : SINV-BS18001708
Invoice Date : 25/09/18
Order No. : SVO18045230
Reference :
Job Card No. : 70912
Date/Time Received : 21/07/18 / 8:55:55 AM
Licence No. : SKX7954U
Model : JAZZ 1.5VTIR CVT 16YM
Car Chassis No. : JHMGK5850GX201247
Car Engine No. : L15B31020386
Mileage : 39045
Service Advisor : ARY CHUA WAI NGEE 1490A
Served By : ARYCHUA
Page : 2

No.	Description	Qty.	UoM	U. Price	Disc %	7% GST Amount incld	
						Amount	GST
68100-TAR-T10ZZ	PANEL COMPR.	1	Each	314.00	25	235.50	16.49
68100-TAS-Z50ZZ	TAILGATE COMP	1	Each	716.30	25	537.22	37.61
74800-T5S-K61	LOCK ASSY, TAILGATE	1	Each	77.10	25	57.82	4.05
73127-TY0-000	RUBBER C WINDSHIELD DAMPER	1	Each	11.20	25	8.40	0.59
73214-T5A-013	RUBBER WINDSHIELD DAMPER	2	Each	6.30	25	9.45	0.66
73226-SZW-000	DAMPER STD 5X5	1	Each	8.30	25	6.22	0.44
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	Each	60.00		60.00	4.20
38387-TZ5-A01	ANTENNA ASSY L.F.	1	Each	58.10	25	43.57	3.05

Sum Labor	6,300.00	441.00	6,741.00
Sum Item	1,595.66	111.70	1,707.36
Total SGD	7,895.66	552.70	8,448.36
Total Payable (SGD)			8,448.36

Printed by ARYCHUA on 25 Sep 2018 at 8:10:59 AM

This is a computer generated invoice. No signature is required.

Please review your bill and advise us of any errors or omissions.

Kah Motor reserves the right to deliver a subsequent bill for any charge omitted.

GST Amount is calculated from individual line(s).

Please give us your
feedback by scanning
the QR Code using
mobile device.



THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJN 2701E (Insd veh)	Model:	HONDA JAZZ (A)
	SKX 7954U (TP veh)		
Date of Accident:	15/07/2018		

Global Sum Settlement	: [] Yes	[X] No
Repair Estimate	: \$	17,400.78
Final Repair Cost	: \$	8,448.36
Loss of Use	: \$	350.00
Rental (if any)	: \$	7 days at \$50.00 per day
LTA / GIA Search Fee	: \$	days

Others:	: \$	0.00
---------	------	------

	: \$	
Final Settlement Sum	: \$	8,798.36

Is Third Party Workshop GIA Registered?		[X] YES	[] NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filed only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown		
1)	KAH MOTOR CO.SDN.BHD.	: \$ 8,798.36

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

17/12/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18013330/Uha3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CYNTHIA LOH		Date : 17-12-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 2701E	Veh. Inspected	SKX 7954U	
Policy No.	VCX/P1904426	Coverage (\$)	0.00	
Claim No.	S8M00OP7	Excess (\$)	0.00	
Assign From		Assign Date	23/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ (A)	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JHMGK5850GX201247	Colour	WHITE	
Odometer	38710	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	185/55 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	185/55 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	185/55 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/07/2018	Inspection Date	26/07/2018	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 7954U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
14	CLIPBUMPER (SN) (CONSISTENT)	NECESSARY	21.00	21.00
1	EMBLEMRR (SN) (CONSISTENT)	NECESSARY	7.87	7.87
1	FACERR.BUMPER (SN) (CONSISTENT)	DENTED / DEFORMED	369.45	369.45
1	SPACERR.RR BUMPER (SN) (CONSISTENT)	BENT	8.62	8.62
1	SPACERL.RR.BUMPER (SN) (CONSISTENT)	BENT	8.62	8.62
1	GARNISHR.RR.BUMPER (SN) (CONSISTENT)	NOT NECESSARY	10.50	-
1	GARNISHL.RR.BUMPER (SN) (CONSISTENT)	NOT NECESSARY	10.50	-
1	LID ASSYSARE TIRE (SN) (CONSISTENT)	NOT NECESSARY	139.50	-
1	BOX ASSYCARGO FLOOR (SN) (CONSISTENT)	NOT NECESSARY	77.92	-
2	HOOKCENTER SHELF (SN) (CONSISTENT)	NOT NECESSARY	5.40	-
1	LINING ASSYRR.PANEL (SN) (CONSISTENT)	TWISTED	45.60	45.60
1	LINING ASSYR.TRUNK (SN) (CONSISTENT)	NOT NECESSARY	124.20	-
1	LINING ASSYL.TRUNK (SN) (CONSISTENT)	NOT NECESSARY	124.20	-
1	LIGHT ASSYR.LID (SN) (CONSISTENT)	NOT NECESSARY	59.47	-
1	LIGHT ASSYL.LID (SN) (CONSISTENT)	NOT NECESSARY	59.47	-
1	TAILLIGHT ASSY.R (SN) (CONSISTENT)	CRACKED	176.32	176.32
1	TAILLIGHT ASSYL (SN) (CONSISTENT)	NOT NECESSARY	163.05	-
1	EMBLEMH (SN) (CONSISTENT)	NOT NECESSARY	8.02	-
2	NUTPUSH 3MM (SN) (CONSISTENT)	NOT NECESSARY	2.85	-
1	GARNISH ASSYRR.LICENSE (SN) (CONSISTENT)	NOT NECESSARY	146.02	-
1	BUZZER ASSYSMART (SN) (CONSISTENT)	NOT NECESSARY	44.47	-
1	ANTENNA ASSYL.F (SN) (CONSISTENT)	CRACKED	43.57	43.57
1	PANEL COMPRR (SN) (CONSISTENT)	BADLY DENTED	235.50	235.50
1	PANEL SET .RR.FLOOR (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	502.42	-
1	STIFFENER COMP.R.RR (SN) (CONSISTENT)	NOT NECESSARY	65.17	-
1	STIFFENER COMP.L.RR (SN) (CONSISTENT)	NOT NECESSARY	65.17	-
1	TAILGATE COMP (SN) (CONSISTENT)	BADLY DENTED	537.22	537.22
1	WEATHERSTRIPTAILGATE (SN) (CONSISTENT)	NOT NECESSARY	69.22	-
1	LOCK ASSYTAILGATE (SN) (CONSISTENT)	TWISTED	57.82	57.82

Report Ref No. CC4/ASM18013330/Uha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GLASS SETRR WINDSHIELD (SN) (CONSISTENT)	NOT NECESSARY	469.20	-
1	RUBBER CWINDSHIELD DAMPER (SN) (CONSISTENT)	NECESSARY	8.40	8.40
2	RUBBERWINDSHIELD DAMPER (SN) (CONSISTENT)	NECESSARY	9.45	9.45
1	DAMPERSTD 5X5 (SN) (CONSISTENT)	NECESSARY	6.22	6.22
1	WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	60.00	60.00
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	100.00	20.00
			3,842.41	1,615.66
	LABOUR			
	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN.	NOT NECESSARY	300.00	-
	BODY UNDERSIDE COATING		100.00	100.00
	BODY JOINT SEALANT		100.00	100.00
	INSPECT RR LIGHTING MECHANISMS PERFORM WATER.		180.00	80.00
	REMOVE & RENEW REVERSE SENSORS		240.00	140.00
	APPLY BODY UNDERSIDE COATING.		250.00	200.00
	REMOVE & INSTALL RR WINDSCREEN.		350.00	300.00
	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION.		350.00	300.00
	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM.		350.00	300.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		450.00	250.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &		550.00	300.00
	SPRAY PAINT ON REPAIRED /REPLACED AREAS.		3,600.00	2,250.00
	CUT OFF & RENEW RR PANEL & FLOOR PANEL INCLUSIVE OF THE REPAIR OF PANEL SET RR.FLOOR.		5,600.00	1,960.00
			12,420.00	6,280.00
GRAND TOTAL			16,262.41	7,895.66
RECOMMENDED COST OF REPAIRS				7,895.66

Report Ref No. CC4/ASM18013330/Uha3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	SIM0000P7
Reference	CCA/ASM18013330/Uha3q2
Loss Date	15 July 2018
Request Date	23 July 2018
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

Add Photos

Vehicle Information	
Incident Vehicle Registration #	3KX7954U
Make	TPVD HONDA
Model	JAZZ-1.5(A)
Service Address	
...	

Primary Contact/Insured	
MOBILE CHAUFFERING	
BLK 153 GANSA ROAD, #05-325, 670153, Singapore	
81451080	
PRAVEEN.SO.JAGANATHAN@GMAIL.COM	

Claim Handler	
LOH Cynthia	
6568804843	
cynthia.loh@axa.com.sg	

Additional Instructions

MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (5).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	19 December 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 payment breakdown.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 December 2018
 LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 December 2018
 LKKInspection (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 December 2018
 LKKAdjustment1a (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 December 2018
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	19 December 2018
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	PQA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	19 December 2018
 WORKSHOP INVOICE.pdf	Invoice	Repairs	LKK AUTO CONSULTANTS PTE LTD (TP)	19 December 2018
 TP LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 November 2018
 AXA IMMEDIATE ADVICE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	22 October 2018
 LKK REINSPECTION PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	22 October 2018
 LKK INSPECTION PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	22 October 2018
 TP ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	9 August 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LETTER TO OI.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 July 2018
 LETTER TO OI.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 July 2018
 Email to OI dtd 250718.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 July 2018
 EMAIL FROM WORKSHOP INCLUDING SOKX7954U ESTIMATE & TP GIA IMAGES.mng	Letters and Correspondence	Workshop	NIKAM Santosh Pandurang	23 July 2018
 SJK2701E INSD GIA PDF	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	23 July 2018
 TP VIDEO.mp4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	23 July 2018