

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

11:30am
26 JUL 2018
→ Mei Kwan
Lkk auto
63660055

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SKX7954U
Chassis No : JHMGK5850GX201247
Model : JAZZ 1.5VTIR CVT 16YM
Owner's Name : JOE WALDY
Ins Policy No. : 5087075175-01
Date of Accident : 15/7/2018

Document No. : SQT18003028 Page 1
Date : 21. Jul 2018
Customer No. : WZA006
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15B31020386
Date | Time : 21. Jul 2018 8:55:55 AM
Surveyor Name : DID : +65 6846 5673
Survey Date : HP : +65 8100 6306
Authorisation Date : Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 70912)						
	OWNER: JOE WALDY						
	OWNER INSURER: NTUC INCOME INSURANCE CO-OP LTD						
	ACC DATE: 15/07/2018@18.00PM						
	SURVEYED BY:						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SJN2701E						
BO-R-COOL-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN.	1	300.00	11	300.00	21.00	321.00
					Sum Ext. Service	300.00	21.00
							321.00
91505-TM8-003	CLIPBUMPER <i>rel</i>	14	2.00	25	21.00	1.47	22.47
75722-T5L-T01	EMBLEMRR. <i>rel</i>	1	10.50	25	7.87	0.55	8.42
04715-T5B-000ZZ	FACERR.BUMPER <i>rel</i>	1	492.60	25	369.45	25.86	395.31
71593-T5A-000	SPACERR.RR.BUMPER <i>rel</i>	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER <i>rel</i>	1	11.50	25	8.62	0.60	9.22
71502-T5A-000	GARNISHR.RR.BUMPER <i>rel</i>	1	14.00	25	10.50	0.74	11.24
71507-T5A-000	GARNISHL.RR.BUMPER <i>rel</i>	1	14.00	25	10.50	0.74	11.24
84521-T5A-901ZA	LID ASSYSAPARE TIRE <i>rel</i>	1	186.00	25	139.50	9.77	149.27
84550-T5S-M10	BOX ASSYCARGO FLOOR	1	103.90	25	77.92	5.45	83.37
84405-SF4-003	HOOKCENTER SHELF	2	3.60	25	5.40	0.38	5.78
84640-T5A-003ZA	LINING ASSYRR.PANEL <i>rel</i>	1	60.80	25	45.60	3.19	48.79
84601-TAR-Z03ZA	LINING ASSYR.TRUNK	1	165.60	25	124.20	8.69	132.89
84651-TAR-Z03ZA	LINING ASSYL.TRUNK	1	165.60	25	124.20	8.69	132.89
34150-T5A-J01	LIGHT ASSYR.LID	1	79.30	25	59.47	4.16	63.63
34155-T5A-J01	LIGHT ASSYL.LID	1	79.30	25	59.47	4.16	63.63
33500-T5A-J02	TAILLIGHT ASSY.R. <i>cm</i>	1	235.10	25	176.32	12.34	188.66
33550-T5A-J02	TAILLIGHT ASSYL.	1	217.40	25	163.05	11.41	174.46
75701-T5A-000	EMBLEMH <i>rel</i>	1	10.70	25	8.02	0.56	8.58



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SKX7954U
Chassis No : JHMGK5850GX201247
Model : JAZZ 1.5VTIR CVT 16YM
Owner's Name : JOE WALDY
Ins Policy No. : 5087075175-01
Date of Accident : 15/7/2018

Document No. : SQT18003028 Page 2
Date : 21. Jul 2018
Customer No. : WZA006
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15B31020386
Date | Time : 21. Jul 2018 8:55:55 AM
Surveyor Name : DID : +65 6846 5673
Survey Date : HP : +65 8100 6306
Authorisation Date : Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
90301-ST0-003	NUTPUSH 3MM 11	2	1.90	25	2.85	X 0.20	3.05
74890-T5B-911	GARNISH ASSYRR.LICENSE 11	1	194.70	25	146.02	X 10.22	156.24
74940-TZ5-A01	BUZZER ASSYSMART	1	59.30	25	44.47	? 3.11	47.58
38387-TZ5-A01	ANTENNA ASSYL.F.	1	58.10	25	43.57	? 3.05	46.62
66100-TAR-T10ZZ	PANEL COMPRR. 3.15.00	1	314.00	25	235.50	16.49	251.99
04655-TAS-300ZZ	PANEL SET,RR.FLOOR R	1	669.90	25	502.42	X 35.17	537.59
65540-T5A-310ZZ	STIFFENER COMP,R.RR. 11	1	86.90	25	65.17	X 4.56	69.73
65590-T5A-310ZZ	STIFFENER COMP,L.RR. 11	1	86.90	25	65.17	X 4.56	69.73
68100-TAS-Z50ZZ	TAILGATE COMP 3.15.00	1	716.30	25	537.22	? 37.61	574.83
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	? 4.85	74.07
74800-T5A-J01	LOCK ASSYTAILGATE R	1	76.60	25	57.45	4.02	61.47
73211-T5A-J01	GLASS SETRR.WINDSHIELD 11	1	625.60	25	469.20	X 32.84	502.04
73127-TY0-000	RUBBER CWINDSHIELD DAMPER R	1	11.20	25	8.40	0.59	8.99
73214-T5A-013	RUBBERWINDSHIELD DAMPER R	2	6.30	25	9.45	0.66	10.11
73226-SZW-000	DAMPERSTD 5X5 R	1	8.30	25	6.22	0.44	6.66
BO-WS-SEALANT	WINDSCREEN SEALANT (N) R	1	60.00		60.00	4.20	64.20
Sum Item					3742.04	261.93	4,003.97

BOSUN	SUNDRIES	1	100.00	R 20	100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	80	180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	240.00	140	240.00	16.80	256.80
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	200	250.00	17.50	267.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	350.00	300	350.00	24.50	374.50
BOMISC1	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION1	1	350.00	300	350.00	24.50	374.50
BOMISC1	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM	1	350.00	300	350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00	250	450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	550.00	300	550.00	38.50	588.50

Printed on 21/7/2018 9:29:57 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SKX7954U
Chassis No : JHMGK5850GX201247
Model : JAZZ 1.5VTIR CVT 16YM
Owner's Name : JOE WALDY
Ins Policy No. : 5087075175-01
Date of Accident : 15/7/2018

Document No. : SQT18003028 Page 3
Date : 21. Jul 2018
Customer No. : WZA006
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15B31020386
Date | Time : 21. Jul 2018 8:55:55 AM
Surveyor Name :
Survey Date : DID : +65 6846 5673
Authorisation Date : HP : +65 8100 6306
Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BP06R	SPRAY PAINT ON REPAIRED/REPLACED AREAS. (6PX \$450)	1	3600.00	2250	3600.00	252.00	3852.00
BKRP02M	CUT OFF & RENEW RR PANEL & FLOOR PANER	1	5600.00		5600.00	392.00	5992.00
Sum Labor					12220.00	855.40	13,075.40

Survey By

Date & Time

Excess

Status

Signature

Marcus Loke
26/7/18
not Agent
take sh. before policy.
HP: 62563561
7 Ly.

Total Amount 16,262.04 1,138.33 17,400.37

Total (Inclusive of GST) 17,400.37

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 21/7/2018 9:29:57 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)