

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	:	AXA	DATE	:	20-Jul-18
ATTENTION	:	MOTOR CLAIMS DEPT	JOB TYPE	:	T/P CLAIM
ESTIMATE REPORT	:				
<u>OWNER'S PARTICULAR</u>			<u>VEHICLE DETAILS</u>		
NAME	:		VEHICLE NO	:	SJQ39G
ADDRESS	:	Aster	MODEL	:	HONDA ODYSSEY
TEL. NO.	:		CHASSIS NO	:	
OWNER'S INSURANCE	:				JHMRC18906C204290
POLICY NO.	:				
<u>ACCIDENT DETAILS</u>					
		DATE	:		
		TIME	:		
THIRD PARTY REQUESTOR / CONTACT	:	XIONG 8121 0478			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Detled</i>	1	\$ 1,210.00	\$ <u>1,210.00</u>
2	TAILGATE OUTER CHROME MOULDING <i>near</i>	1	\$ 284.00	\$ 284.00
3	TAILGATE LOGO <i>new</i>	1	\$ 25.00	\$ 25.00
4	TAILGATE DAMPER <i>new</i>	2	\$ 154.00	\$ 308.00
5	TAILGATE REFELCTOR <i>new</i>	2	\$ 378.00	\$ 756.00
6	TAILGATE INNER LOCK <i>changed</i>	1	\$ 315.00	\$ 315.00
7	TAILGATE LOWER LOCK <i>new</i>	1	\$ 28.00	\$ 28.00
8	TAILGATE DETECTOR SENSOR <i>changed</i>	1	\$ 459.00	\$ 459.00
9	REAR DETECTOR SENSOR WIRE HARNESSER <i>new</i>	1	\$ 345.50	\$ 345.50
10	TAILGATE WEATHER STRIP <i>ht</i>	1	\$ 254.00	\$ 254.00
11	TAILGATE STOPPER <i>new</i>	2	\$ 12.00	\$ 24.00
12	TAILGATE INNER BOARD <i>new</i>	1	\$ 589.00	\$ 589.00
13	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 286.00	\$ 286.00
14	TAILLAMP <i>new</i>	2	\$ 821.00	\$ 1,642.00
15	REAR BUMPER <i>Detled</i>	1	\$ 557.00	\$ 557.00
16	REAR BUMPER REFLECTOR <i>new LHT changed</i>	1	\$ 112.00	\$ 112.00
17	REAR BUMPER CONNER <i>LHT torn</i>	2	\$ 489.00	\$ 978.00
18	REAR BUMPER SIDE MOULDING <i>new</i>	2	\$ 158.00	\$ 316.00

19	REAR BUMPER MOULDING GARNISH <i>new</i>	2	\$ 341.00	\$ 682.00	+
20	REAR BUMPER SIDE RETAINER <i>new</i>	1	\$ 110.00	\$ 110.00	+
21	REAR FENDER INNER TRIM <i>new</i>	2	\$ 745.00	\$ 1,490.00	+
22	REAR SENSOR BUZZER <i>new only</i>	1	\$ 156.00	\$ 156.00	45
23	REAR SENSOR BUZZER GARNISH <i>new</i>	1	\$ 169.00	\$ 169.00	+
24	REAR END PANEL <i>Repis</i>	1	\$ 684.00	\$ 684.00	+
25	REAR END PANEL TOP GARNISH <i>del</i>	1	\$ 354.00	\$ 354.00	205

3163-50
2530.80

TOTAL PRICE \$12,133.50
LESS 20% \$ 2,426.70
SUB TOTAL PRICE \$9,706.80

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER CLIPS <i>new</i>	10	\$ 6.50	\$ 65.00	30
2	REAR FENDER TOP TRIM (INNER) CLIP <i>3 new</i>	8	\$ 6.50	\$ 52.00	+
3	REAR FENDER INNER TRIM CLIPS <i>3 new</i>	10	\$ 6.50	\$ 65.00	+
4	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	4	\$ 8.50	\$ 34.00	10
5	TAILGATE SEALANT <i>2</i>	1	\$ 80.00	\$ 80.00	+
6	TAILGATE OUTER GARNISH CLIP <i>3 new</i>	6	\$ 6.50	\$ 39.00	+
7	TAILGATE INNER BOARD CLIP <i>new</i>	10	\$ 6.50	\$ 65.00	+
8	TAILGATE INNER SIDE GARNISH CLIP	8	\$ 6.50	\$ 52.00	+
9	TAILGATE WINDSCREEN SEALANT <i>3 new</i>	1	\$ 80.00	\$ 80.00	30
10	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	30
11	TAILLAMP CLIP <i>not new</i>	4	\$ 8.50	\$ 34.00	+
12	REAR END PANEL TOP GARNISH CLIPS <i>Repainted</i>	6	\$ 6.50	\$ 39.00	+
13	REAR END PANEL INSULATION SEAL <i>3 new</i>	1	\$ 150.00	\$ 150.00	+
14	REAR FLOOR PANEL INSULATOR SEAL	1	\$ 250.00	\$ 250.00	+
15	REVERSE SENSOR <i>Del</i>	1	\$ 350.00	\$ 350.00	200

300 TOTAL \$1,415.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$1,300.00	400	
2	TO SPRAY PAINT AFFECTED AREA	\$1,200.00	600	
3	TUFF COAT	\$250.00	x	
4	WIRING AND BULB CHECK	\$180.00	30	
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$450.00	40	

6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$120.00	40	
7	TRANFER TAILGATE MECHANISM	\$80.00	✓	
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$120.00	✓	
9	CONDUCT WATER LEAKAGE TEST	\$120.00	X	
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$380.00	X	

TOTAL

\$4,200.00

1310

ESTIMATE REPORT

TOTAL PARTS COST : \$11,121.80
TOTAL LABOUR COST : \$4,200.00
TOTAL REPAIR COST : \$15,321.80

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAY :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Adrian King, whl: 414080
1/c 24/07/18. 4/s: B.3K ✓
04 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____