

REPAIR ESTIMATE*

MAKE :

$$A \times A - CP(P)$$

DATE 23/7/2018

TS

P₁ | 2 1150

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille ✓			\$ 1,480.00
	Radiator Grille H Emblem ✕			\$ 290.80
	Radiator Grille Chrome Moulding ✕			\$ 395.50
	Front Bumper Cover ✕ repair			\$ 1,052.20
	Front Bumper Sponge ?			\$ 142.20
	Front Bumper Reinforcement ?			\$ 526.10
	Front Bumper Bracket Top (LH/RH) ?		\$ 22.40	\$ 44.80
	Front Bumper Retainer Mounting ?		\$ 9.20	\$ 18.40
	SUB TOTAL			\$ 3,950.00
	LESS 20%			\$ 790.00
	DISCOUNTED TOTAL			\$ 3,160.00
	Front Number Plate ✓			\$ 25.00
	Front No Plate Trim Cover ✓			\$ 30.00
				\$ 55.00
	Labour Charge			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 250.00
				200
	TOTAL LABOUR			\$ 600.00
	ESTIMATE TOTAL			\$ 3,815.00

Nett
Nett

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SH 6993C

DATE 23/7/2018

MAKE :

MODEL : HYUNDAI i40

AXA - (P/P)

TS

P2/2 1150

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Licence Lamp Cover <i>X 1/2</i>			\$ 100.00	
	Rear Bumper			\$ 603.60	
	Rear Bumper Reinforcement <i>?</i>			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) <i>?</i>		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket <i>?</i>		\$ 49.00	\$ 98.00	
	Rear Bumper Clips			\$ 22.00	
	Rear Bumper Sponge <i>?</i>			\$ 143.40	
	Rear Bumper Under Cover			\$ 225.00	