

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

7

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

28

(Agreed / Assessed) BOLA S/N No.:

100%.

Repair Cost:

SS

4815.00

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

540.00

(5

x 9

days)

Loss of Income (LOI):

SS

(5

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

5362.45

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

5362.45

Name 1:

Ah Lim Motor Company

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

CHEAPEST CAR INSURANCE RENEWAL



Compare
10+ Insurers

GET A CHEAPER QUOTE NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 3 Years Car Nissan Sunny 1.6A WSP



2018 Nissan Sunny 1.6A WSP
Price: \$15,000 (incl. COE)
Nissan Sunny 1.6A WSP
GV Credit Pte Ltd

PRIME MOTOR & LEASING

SHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES

With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.

Browse by Category

Sort by Date Posted

20 results/page

11 vehicles

Nissan Sunny

	Model	Price	Depreciation	Age	Eng Cap	Mileage	Veh Type	Availability
Search Selection	Nissan Sunny	Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Nissan Sunny 1.6M EX (COE till 03/2021)	\$15,000	\$5,640 /yr	22-Mar-2006	1,597 cc	-	Sedan	Available
Very Nice Car Plate Number. Lowest Price In The Market. Best Deal.								View Details
Posted: 25-Jul-2018 Tags: 2006 Nissan Sunny, Nissan Sunny, Nissan, Sunny, Used Nissan								
	Nissan Sunny 1.5M (COE till 04/2019)	\$5,500	\$7,200 /yr	12-Jun-1999	1,498 cc	-	Sedan	Available
Very Well Maintained. Clean Interior. Smooth Engine. Cooling Aircon. Coe Renewable.								View Details
Posted: 23-Jul-2018 Tags: 1999 Nissan Sunny, Nissan Sunny, Nissan, Sunny, Used Nissan								
	Nissan Sunny 1.6A EX (COE till 05/2026)	\$41,800	\$5,370 /yr	06-May-2006	1,597 cc	-	Sedan	Available
\$0 Down Payment! 100% In House Loan Available! Low Depreciation! Nice Paint. Hurry Call For Viewing!								View Details
ABWIN (1994) Pte Ltd Posted: 21-Jul-2018 Tags: 2006 Nissan Sunny, Nissan Sunny, Nissan, Sunny, Used Nissan								
	Nissan Sunny 1.6A EX (COE till 05/2021)	\$16,777	\$6,050 /yr	04-May-2006	1,597 cc	163,771 km	Sedan	Available
Practical Sunny 1.6A At \$16,777. Left 3 Years To Drive. Low Mileage. Original Condition. COE At \$23K. High Loan Avail. Affordable Depreciation. Sell As It Is Condition. Call Us To Find Out More!								View Details
Posted: 26-Jul-2018 Tags: 2006 Nissan Sunny, Nissan Sunny, Nissan, Sunny, Used Nissan								
Car Buying	Car Selling	Car Ownership						
Car Aftermarket	On The Move	Lifestyle						
	Nissan Sunny 1.6A EX (COE till 05/2020)	\$12,800	\$6,910 /yr	06-Jun-2005	1,597 cc	-	Sedan	Available
Sell At Body Plus Paper Value Only! Very Low Monthly \$300 Plus. Just 1 Owner! Very Low Mileage! Well Kept By Previous Owner In Tip Top Condition. View And Believe It! Buy It From Us With A Peace Of Min...								View Details
Dickson Automobile Posted: 14-Jul-2018 Tags: 2005 Nissan Sunny, Nissan Sunny, Nissan, Sunny, Used Nissan								
	Nissan Sunny 1.6A EX (COE till 12/2021)	\$18,800	\$5,520 /yr	20-Dec-2006	1,597 cc	-	Sedan	Available
Consignment Unit. Low Maintained Cost. High Loan And Trade In Available. Call Us Now For Test Drive								View Details
Posted: 10-Jul-2018 Tags: 2006 Nissan Sunny, Nissan Sunny, Nissan, Sunny, Used Nissan								
	Nissan Sunny 1.6A EX (COE till 04/2021)	\$17,000	\$6,160 /yr	28-Apr-2006	1,597 cc	321,340 km	Sedan	Available
Accident Free. Service Regularly Without Fail. Call/SMS Now To Arrange A Viewing And A Non Obligatory Discussion! Viewing Strictly On ment Basis!								View Details
Posted: 28-Jun-2018 Tags: 2006 Nissan Sunny, Nissan Sunny, Nissan, Sunny, Used Nissan								

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A

#01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg

GST Reg No: M9-0009639-E

TP INSURER: India International Insurance Pte Ltd (HQ)

Singapore

Claimant Insurer: AXA Insurance Pte Ltd

SURVEYOR COPY

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	17/07/2018
Vehicle Reg. No.:	SGV8226P	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	ONG TECK KHIM		
Make/Model:	NISSAN SUNNY, 1.6 EX (A)	Vehicle Reg. Date:	27/06/2007
Vehicle Colour:	SILVER		
Engine No:	QG16426618	Chassis No:	JN1CFAN16Z0110088
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	8 ✓		
Description of Accident/Loss	REFER TO THE SKETCH PLAN BY DRIVER		
Remarks:	CAR NOT IN - TO BE ARRANGE		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

Not with the
L1 Sy 87
Return After Paint

COST OF CLAIMS

	Amount
Parts	7,187.85
Miscellaneous Items	10.00
Labour	3,920.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	11,117.85
+ GST 7.00% (S\$)	778.25
Nett Amount (S\$)	11,896.10

This claim is handled by: ZILA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 2853A

Vehicle Details

Vehicle No.: SGV8226P
Vehicle to be Exported: No
Intended De-registration Date: 18 Jul 2018
Vehicle Make: NISSAN
Vehicle Model: SUNNY 1.6EXA
Primary Colour: Silver
Manufacturing Year: 2007
Engine No.: QG16426618
Chassis No.: JN1CFAN16Z0110088
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$11,737.00
Original Registration Date: 27 Jun 2007
First Registration Date: 27 Jun 2007
Transfer Count: 1
Actual ARF Paid: \$12,911.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Jun 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$25,313.00
COE Rebate Amount: \$19,941.00
Total Rebate Amount: \$19,941.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Jul 2018

OK

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jul 2018)
 Parts: 143 NISSAN SUNNY 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ah Lim Motor Company/SGV8226P/20/07/2018 14:43
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*FRONT BONNET	Ben	10.00	0.00	*893.90 FL	✓
2	1		*FRONT BONNET INNER LOCK	R	10.00	0.00	*78.70 FL	✓
3	10		*FRONT BONNET INSULATOR CLIPS	na	10.00	0.00	*44.00 FL	✓
4	2		*HEADLAMP LH & RH	sun	10.00	0.00	*973.60 FL	✓
5	4		*HEADLAMP CLIPS	na	10.00	0.00	*21.20 FL	✓
6	1		*FRONT BUMPER	Ben	10.00	0.00	*387.90 FL	✓
7	2		*FRONT BUMPER SIDE RETAINER LH & RH	sun	10.00	0.00	*46.00 FL	✓
8	15		*FRONT BUMPER CLIPS	na	10.00	0.00	*66.00 FL	✓
9	1		*FRONT BUMPER REINFORCEMENT	R	10.00	0.00	*288.20 FL	✓
10	1		*FRONT BUMPER TOP BEAM	By	10.00	0.00	*162.70 FL	✓
11	1		*FRONT BUMPER CHROME MOULDING	na	10.00	0.00	*175.20 FL	✓
12	1		*FRONT GRILLE	scot	10.00	0.00	*223.00 FL	✓
13	1		*FRONT GRILLE EMBLEM	na	10.00	0.00	*50.70 FL	✓
14	8		*FRONT GRILLE CLIPS	na	10.00	0.00	*35.20 FL	✓
15	1		*REAR BOOT	Ben	10.00	0.00	*674.60 FL	✓
16	2		*REAR BOOT HINGE LH & RH	R	10.00	0.00	*175.20 FL	✓
17	1		*REAR BOOT EMBLEM	na	10.00	0.00	*58.30 FL	✓
18	1		*REAR BOOT SUNNY LOGO	na	10.00	0.00	*95.70 FL	✓
19	1		*REAR BOOT EX.SALOON LOGO	na	10.00	0.00	*80.90 FL	✓
20	1		*REAR BOOT CIVIC LOGO	na	10.00	0.00	*56.30 FL	✓
21	1		*REAR BOOT ETHROTTLE LOGO	na	10.00	0.00	*56.30 FL	✓
22	1		*REAR BOOT CHROME MOULDING TOP	sun	10.00	0.00	*369.10 FL	✓
23	1		*REAR BOOT CHROME MOULDING LOWER	sun	10.00	0.00	*288.90 FL	✓
24	1		*REAR BOOT INNER LOCK	na	10.00	0.00	*54.50 FL	✓
25	1		*REAR BOOT INSULATOR	R	10.00	0.00	*163.80 FL	✓
26	8		*REAR BOOT INSULATOR CLIPS	sun	10.00	0.00	*35.20 FL	✓
27	1		*REAR BOOT RUBBER	na	10.00	0.00	*80.30 FL	✓
28	2		*TAILAMP LH & RH	c/s cm	10.00	0.00	*720.40 FL	✓
29	1		*REAR BUMPER	By	10.00	0.00	*452.40 FL	✓
30	2		*REAR BUMPER SIDE RETAINERS LH & RH	c/s d/r	10.00	0.00	*61.80 FL	✓
31	15		*REAR BUMPER CLIPS	na	10.00	0.00	*66.00 FL	✓
32	1		*REAR BUMPER CHROME MOULDING	d/r	10.00	0.00	*175.20 FL	✓
33	1		*REAR BUMPER REINFORCEMENT - CHECK PRICE	na	10.00	0.00	* FL	✓
34	2		*REAR BUMPER BRACKET LH & RH	R	10.00	0.00	*173.20 FL	✓
35	1		*REAR END PANEL	By	10.00	0.00	*335.60 FL	✓
36	1		*REAR END PANEL TOP GARNISH	sun	10.00	0.00	*66.50 FL	✓
37	1		*NUMBER PLATE FRONT	sun	0	0.00	*35.00 FS	✓
38	1		*NUMBER PLATE REAR	sun	0	0.00	*35.00 FS	✓
39	1		*REVERSE SENSOR	short	0	0.00	*200.00 FS	✓

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 7,956.50
 - List Item Discount on L Items (\$\$) 768.65

Total Parts (\$\$) 7,187.85

Ah Lim Motor Company/SGV8226P/20/07/2018 14:43. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00 201
2	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR FRONT FENDER LH & RH; RADIATOR SUPPORT PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	800.00 501
3	TO SPRAY FRONT BONNET;FRONT BUMPER;FRONT FENDER LH & RH;RADIATOR SUPPORT PANEL.	New	800.00 601
4	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00 201
5	TO REMOVE AND REINSTALL CUSHIONS; SEATS; BACKREST; INNER TRIM; GARNISH; ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	80.00 601
6	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	New	80.00 501
7	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	New	80.00 2
8	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL.TO KNOCK & REPAIR TAILAMP PANEL RH; REAR FENDER RH;SPARE TYRE PANEL & AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.	New	1,000.00 800
9	TO SPRAY REAR BOOT;REAR BUMPER;REAR FENDER RH;END PANEL;SPARE TYRE PANEL.	New	1,000.00 601
Gross Labour Cost (S\$)			3,920.00

Ah Lim Motor Company/SGV8226P/20/07/2018 14:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

View Received Message

This mail is associated with :

SGV8226P (MCT18070512)
[SH6434A]

TP
ONG TECK KHIM
Jul 17 2018 6:00PM
[COMFORT TRANSPORTATION PTE LTD]
Ah Lim Motor Company

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 14/12/2018 11:57 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5362.45) - SGV8226P - Claim Handler: Sundari Nagarajan

Approved:5362.45:Agreed to do direct settlement. Please revert with your quantum advice

DOCUMENTS SUMMARY

There are no documents.



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

Our Ref : MC0913280

Your Ref : SH6434A

Date : 24/11/2018

INDIA INTERNATIONAL INSURANCE P/L

64 CECIL STREET #04/#05

IOB BUILDING

SINGAPORE 049711

Dear Sir/Madam,

Request for Direct Settlement for Accident involving our client's vehicle SGV8226P and your Insured SH6434A ON 17/07/2018 18:00 ALONG AIRPORT ROAD

We refer to the above matter.

Please assess through your Insured's (SH6434A) report and our Client (SGV8226P) – ONG TECK KHIM's report as attached and advise whether there are possibilities of direct settlement.

Please find attached the following :

- 1) Final Bill
- 2) GIA Motor Accident Report form
- 3) Certificate of Insurance, IC and Driving Licence
- 4) LTA Search

The above vehicle was surveyed by Mr Kenneth from LKK as appointed by INDIA on 24/07/2018.

We would quantify our claim as below:-

Cost of Repair	: \$4,815.00
Loss Of Use	: \$540.00(9 X 60)
LTA Search	: \$7.45
=====	
Total	: \$5,362.45

Kindly acknowledge and revert on the possibility of direct settlement within 14 days.

Thank You.

Yours faithfully,

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Kee Mui Hong Fax 6483 6170


Authorisation to Act

I, ONG TECK KHIM (the third party claimant) of BLK 97, YISHUN AVE 1 #14-35 SE 769138 (address), owner of SGV8226P (Vehicle no) hereby authorise **Ah Lim Motor Company** (the workshop) to act for me in respect to my claim for repair costs and / or rental and /or loss of use (Claim) for my vehicle No. SGV 8226P that was damaged pursuant to the accident which occurred on 17/07/2018 (date) along AIRPORT ROAD (location) involving vehicle Nos SH 6434A (the Accident)

I further authorise the workshop to settle the above mentioned claim in a manner that they deem fit and the workshop is further authorised to receive the payment further to settlement of my claim with payment cheque/s made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle is concerned.

Dated this 18th day of JULY (month) 20 18 (year)


Signed by Third party claimant
Owner Veh No : SGV 8226P

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autoport 1 Singapore 568047
Tel: 6755 2244 Fax: 6755 1170

Signed by the workshop

Personal data Protection Act 2012

I/ We acknowledge and consent to Ah Lim Motor Company collecting , using and disclosing and /or processing my/our personal data to Third Party service providers and/or Insurance company my / our personal data for the purpose of processing the claim and related insurance / claim matters.


Owner Signature

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: MCT18070512
Claimant Ref: SHV 8226P

We/I, Ah Lim Motor Company ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 4,815.00 (repair cost), S\$ 540.00 (loss of use/rental), S\$ 7.45 (search fee), vehicle no. SGV 8226P that was damaged pursuant to the accident which occurred on 17/07/2018 (date) at AIRPORT RD TWDS KPE (location) involving vehicle no. SH 6434A (insured vehicle). This is pursuant to the inspection conducted on 24/07/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner ONG TECK KHIM ("the third party claimant") of vehicle no. SGV 8226P to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SGV 8226P (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 5,362.45 to Ah Lim Motor Company

Dated this 31 day of 12 2018

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Industrial Park 2A

Singapore 630047

Tel: 6292 1244 Fax: 6482 0170

Signed by "the workshop" (with chop)

kee mei lim

ST644421E

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

KSC

Signed by appointed Surveyor

LKK Auto Consultants Pte Ltd

501, Upper Macao Road

Singapore 408933

Tel: 6256 3561

51 Ubi Ave 1, #01-03

Paya Ubi Industrial Park

Singapore 408933

Tel: 6256 3561

LKK AUTO CONSULTANTS

51 Ubi Ave 1, #01-03

Paya Ubi Industrial Park

Singapore 408933

Tel: 6256 3561



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST: M9-0009639-E RCB NO: 06470300B

M/S : ONG TECK KHIM
BLK 97 YISHUN AVE 1 #14-35

SINGAPORE 769138

ATTN:

Your Ref No: SGV8226P
Claim Type: Third Party
Accident Date: 17/07/2018

Final No: AL0929258
Claim No: MC0913280
Date: 24 Nov 2018
Policy No: GA361575/1
Veh Reg No: SGV8226P
Make/Model: NISSAN SUNNY
1.6EXA

Tax Invoice-Final Repair Cost to Vehicle No :SGV8226P

Description	Quantity	List Price	PAGE:1
			Amount
		SS	SS
As agreed to proceed repair at Lump Sum Repair			S\$ 4,500.00
Less Excess			S\$ 0.00
Amount Before GST			S\$ 4,500.00
Add GST @ 7%			315.00
Total Amount payable			S\$ 4,815.00

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND EIGHT HUNDRED FIFTEEN ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 24/07/2018

For AH LIM MOTOR COMPANY

E. & O. E.

AUTHORISED SIGNATURE

muihong@ahlimmotor.com.sg

From: "LTA" <LTA-VTL@lta.gov.sg>
Date: Wednesday, 18 July 2018 5:38 PM
To: <muihong@ahlimmotor.com.sg>
Subject: Notification of Successful Vehicle Insurance Search for Receipt No.: ITNET-00000-180718-002005



Notification of Successful Vehicle Insurance Search for Receipt No.: ITNET-00000-180718-002005

Dear Sir/Madam

We wish to inform you that your transaction on "Enquire Vehicle Insurance Particulars" performed on 18 Jul 2018 was successful and the Receipt No. is ITNET-00000-180718-002005.

2. The details of the search results are as follow:

Vehicle No.	Search Date	Search Time	Search Result
SH6434A	17 Jul 2018	18:00:00	INDIA INT'L INS PTE LTD

3. Please contact our customer service officers at tel : 1800-CALL LTA (1800-2255 582) should you require further assistance.
4. Please do not reply to this auto-generated e-mail. If you have any feedback, please go to www.lta.gov.sg/feedback. You can also visit www.cnmotoring.com.sg for more information.
5. Thank you.

If you are not the intended recipient of this communication, please delete it.

As it may contain confidential or official information, do not retain it or disclose the contents to any person as it may be an offence under the Official Secrets Act.



Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 18 Jul 2018 / 17:38:17

Receipt Date/Time : 18 Jul 2018 / 17:38:16

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180718-002005

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$)	GST Amount (\$)	Amount After GST (\$)
Result of Insurance Enquiry - SH6434A As at 17 Jul 2018/18:00:00 Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - SH6434A Enquiry Fee 20180718173712444094	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20180718173725707	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jul 2018 Sendback Est	20 Jul 2018 14:43 S\$11,117.85	23 Jul 2018 08:45 Edit Adj Rpt	S\$4,500.00 Edit Estimates	S\$4,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	COMFORT TRANSPORTATION PTE LTD. Co. Reg. No.: 199303821R								
Main Claimant:	ONG TECK KHIM ID: S1252853A								
Vehicle Reg. No.:	SGV8226P	Date of Loss:	17/07/2018 18:00 - :59 [132 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18070512	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SH6434A	Policy No. (Claimant):	GA361575/1						
		Excess:							
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 01/08/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (14/12/2018): Alert - Adj Mandate Approved (S\$5362.45) - SGV8226P - Claim Handler: Sundari Nag... - III_SG (27/07/2018): Alert - Adj Mandate Approved (S\$10517.39) - SGV8226P - Claim Handler: Sundari Na...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SGV8226P (MCT18070512)
[SH6434A]
TP
ONG TECK KHIM
Jul 17 2018 6:00PM
[COMFORT TRANSPORTATION PTE LTD]
Ah Lim Motor Company

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		☒
No	Finalized On	Ah Lim Motor Company (AMK)						Thumbnail		Print	
1	20/07/18 14:43	Repairer Estimates							Load HTM		
Photos/Images									3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	14/12/18 10:25	General View							Load JPG	☒	
2	14/12/18 10:25	General View							Load JPG	☒	
3	14/12/18 10:25	General View							Load JPG	☒	
4	14/12/18 10:25	General View							Load JPG	☒	
5	14/12/18 10:25	General View							Load JPG	☒	
6	14/12/18 10:25	General View							Load JPG	☒	
7	14/12/18 10:25	General View							Load JPG	☒	
8	14/12/18 10:25	General View							Load JPG	☒	
9	14/12/18 10:25	General View							Load JPG	☒	
10	14/12/18 10:25	General View							Load JPG	☒	
11	14/12/18 10:25	General View							Load JPG	☒	
12	14/12/18 10:25	General View							Load JPG	☒	
13	14/12/18 10:25	General View							Load JPG	☒	
14	14/12/18 10:25	General View							Load JPG	☒	
15	14/12/18 10:25	General View							Load JPG	☒	
16	14/12/18 10:25	General View							Load JPG	☒	
17	14/12/18 10:25	General View							Load JPG	☒	
18	14/12/18 10:25	General View							Load JPG	☒	
19	14/12/18 10:25	General View							Load JPG	☒	
20	14/12/18 10:25	General View							Load JPG	☒	
21	14/12/18 10:25	Reinspection Photo							Load JPG	☒	
22	14/12/18 10:25	Reinspection Photo							Load JPG	☒	
23	14/12/18 10:25	Reinspection Photo							Load JPG	☒	
24	14/12/18 10:25	Reinspection Photo							Load JPG	☒	
25	14/12/18 10:25	Reinspection Photo							Load JPG	☒	
26	14/12/18 10:25	Reinspection Photo							Load JPG	☒	
27	14/12/18 10:25	Reinspection Photo							Load JPG	☒	
28	14/12/18 10:25	Reinspection Photo							Load JPG	☒	
29	14/12/18 10:25	Reinspection Photo							Load JPG	☒	
30	14/12/18 10:25	Reinspection Photo							Load JPG	☒	
31	14/12/18 10:25	Reinspection Photo							Load JPG	☒	
32	14/12/18 10:25	Reinspection Photo							Load JPG	☒	
33	14/12/18 10:25	Reinspection Photo							Load JPG	☒	
34	14/12/18 10:25	Reinspection Photo							Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
				☒
35	14/12/18 10:25	Reinspection Photo	 Load JPG	☒
36	14/12/18 10:25	Reinspection Photo	 Load JPG	☒
37	14/12/18 10:25	Reinspection Photo	 Load JPG	☒
38	14/12/18 10:25	Reinspection Photo	 Load JPG	☒
39	14/12/18 10:25	Reinspection Photo	 Load JPG	☒
40	14/12/18 10:25	Reinspection Photo	 Load JPG	☒
41	14/12/18 10:25	Reinspection Photo	 Load JPG	☒
42	14/12/18 10:25	Reinspection Photo	 Load JPG	☒
43	14/12/18 10:25	Reinspection Photo	 Load JPG	☒
44	14/12/18 10:25	Reinspection Photo	 Load JPG	☒
45	14/12/18 10:25	Reinspection Photo	 Load JPG	☒
46	14/12/18 10:25	Reinspection Photo	 Load JPG	☒
47	14/12/18 10:25	Reinspection Photo	 Load JPG	☒
48	14/12/18 10:25	Reinspection Photo	 Load JPG	☒
49	14/12/18 10:25	Reinspection Photo	 Load JPG	☒
50	14/12/18 10:25	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	23/07/18 08:42	Singapore Accident Statement	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/07/18 10:14	TP ESTIMATE - MARKED	 Load PDF	
2	12/12/18 14:26	WORKSHOP INVOICE	 Load PDF	
3	12/12/18 14:26	LTA SEARCH	 Load PDF	
4	12/12/18 14:26	LOD	 Load PDF	
5	07/01/19 10:41	DISCHARGE VOUCHER	 Load PDF	
6	07/01/19 10:41	AUTHORISATION TO ACT FORM	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	18/07/18 17:11	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	18/07/18 16:56	Accident Photo	 Load JPG	☒
2	18/07/18 16:56	Accident Photo	 Load JPG	☒
3	18/07/18 16:56	Accident Photo	 Load JPG	☒
4	18/07/18 16:56	Accident Photo	 Load JPG	☒
5	18/07/18 16:56	Driving License	 Load JPG	☒
6	18/07/18 16:56	Accident Photo	 Load JPG	☒
7	18/07/18 16:56	Accident Photo	 Load JPG	☒
8	18/07/18 16:56	Accident Photo	 Load JPG	☒
9	18/07/18 16:56	Accident Photo	 Load JPG	☒
10	18/07/18 16:56	Accident Photo	 Load JPG	☒
11	18/07/18 16:56	Accident Photo	 Load JPG	☒
12	18/07/18 16:56	Accident Photo	 Load JPG	☒
13	18/07/18 16:56	Accident Photo	 Load JPG	☒
14	18/07/18 16:56	Accident Photo	 Load JPG	☒
15	18/07/18 16:56	Accident Photo	 Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
				☒
16	18/07/18 16:56	Driving License	Load JPG	☒
17	18/07/18 16:56	Accident Photo	Load JPG	☒
18	18/07/18 16:56	Accident Photo	Load JPG	☒
19	18/07/18 16:56	Accident Photo	Load JPG	☒
20	18/07/18 16:56	Accident Photo	Load JPG	☒
21	18/07/18 16:56	Accident Photo	Load JPG	☒
22	18/07/18 16:56	Accident Photo	Load JPG	☒
23	18/07/18 16:56	Accident Photo	Load JPG	☒
24	18/07/18 16:56	Accident Photo	Load JPG	☒
25	18/07/18 16:56	Accident Photo	Load JPG	☒
26	18/07/18 16:56	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	18/07/18 17:11	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18013339/KWA3Q2

Date: 07/01/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SGV8226P	Insured Vehicle No :	SH6434A
Date of Loss:	17/07/2018	Nature of Claim:	TP
		Claim No:	MCT18070512

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGV8226P	Engine No:	QG16426618
Make & Model:	NISSAN SUNNY, 1.6 EX (A)	Chassis No:	JN1CFAN16Z0110088
Reg. Date:	27/06/2007 (Man. Year: 2007)	Odometer:	178575 km
Colour:	Metallic Silver		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Double Star 8 mm	Rear Left Side:	CST 9 mm
Front Right Side:	Double Star 8 mm	Rear Right Side:	CST 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,187.85	4,281.95	2,905.90	40.43
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	3,920.00	2,730.00	1,190.00	30.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,117.85	7,021.95	4,095.90	36.84
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	11,117.85	4,500.00	6,617.85	59.52
+ GST 7.00/7.00% (S\$)	778.25	315.00	463.25	59.52
Nett Amount (S\$)	11,896.10	4,815.00	7,081.10	59.52
+ Loss of Use (9.0 x S\$60.00/day) (S\$)		540.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,362.45		

INSPECTION

Date of Assignment:	23/07/2018 Present Location:	Ah Lim Motor Company (AMK)
Date Inspected:	24/07/2018 Inspected At:	Ah Lim Motor Company (AMK)
		10 Ang Mo Kio Industrial Park 2A, #01-09

AMK Autopoint
Singapore 568047

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Dec 2018)
Parts:	143	NISSAN SUNNY 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGV8226P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	893.90 FL	*893.90 FL
2	1		*FRONT BONNET INNER LOCK	Repair	78.70 FL	*- FL
3	10		*FRONT BONNET INSULATOR CLIPS	Necessary	44.00 FL	*44.00 FL
4	2		*HEADLAMP LH & RH	Serviceable	973.60 FL	*- FL
5	4		*HEADLAMP CLIPS	Not Necessary	21.20 FL	*- FL
6	1		*FRONT BUMPER	Buckled	387.90 FL	*387.90 FL
7	2		*FRONT BUMPER SIDE RETAINER LH & RH	Serviceable	46.00 FL	*- FL
8	15		*FRONT BUMPER CLIPS	Necessary	66.00 FL	*66.00 FL
9	1		*FRONT BUMPER REINFORCEMENT	Repair	288.20 FL	*- FL
10	1		*FRONT BUMPER TOP BEAM	Bent	162.70 FL	*162.70 FL
11	1		*FRONT BUMPER CHROME MOULDING	Necessary	175.20 FL	*175.20 FL
12	1		*FRONT GRILLE	Scratched	223.00 FL	*223.00 FL
13	1		*FRONT GRILLE EMBLEM	Necessary	50.70 FL	*50.70 FL
14	8		*FRONT GRILLE CLIPS	Necessary	35.20 FL	*35.20 FL
15	1		*REAR BOOT	Buckled	674.60 FL	*674.60 FL
16	2		*REAR BOOT HINGE LH & RH	Repair	175.20 FL	*- FL
17	1		*REAR BOOT EMBLEM	Necessary	58.30 FL	*58.30 FL
18	1		*REAR BOOT SUUNY LOGO	Necessary	95.70 FL	*95.70 FL
19	1		*REAR BOOT EX.SALOON LOGO	Necessary	80.90 FL	*80.90 FL
20	1		*REAR BOOT CIVIC LOGO	Necessary	56.30 FL	*56.30 FL
21	1		*REAR BOOT ETHROTTLE LOGO	Necessary	56.30 FL	*56.30 FL
22	1		*REAR BOOT CHROME MOUDLING TOP	Serviceable	369.10 FL	*- FL
23	1		*REAR BOOT CHROME MOULDING LOWER	Serviceable	288.90 FL	*- FL
24	1		*REAR BOOT INNER LOCK	Jammed	54.50 FL	*54.50 FL
25	1		*REAR BOOT INSULATOR	Repair	163.80 FL	*- FL
26	8		*REAR BOOT INSULATOR CLIPS	Serviceable	35.20 FL	*- FL
27	1		*REAR BOOT RUBBER	Not Necessary	80.30 FL	*- FL
28	1		*TAILAMP LH & RH	O/S Cracked	720.40 FL	*360.20 FL
29	1		*REAR BUMPER	Bent	452.40 FL	*452.40 FL
30	1		*REAR BUMPER SIDE RETAINERS LH & RH	O/S Distorted	61.80 FL	*30.90 FL
31	15		*REAR BUMPER CLIPS	Necessary	66.00 FL	*66.00 FL
32	1		*REAR BUMPER CHROME MOULDING	Distorted	175.20 FL	*175.20 FL
33	1		*REAR BUMPER REINFORCEMENT - CHECK PRICE (NPA)	Not Necessary	0.00 FL	*- FL
34	2		*REAR BUMPER BRACKET LH & RH	Repair	173.20 FL	*- FL
35	1		*REAR END PANEL	Bent	335.60 FL	*335.60 FL
36	1		*REAR END PANEL TOP GARNISH	Serviceable	66.50 FL	*- FL
37	1		*NUMBER PLATE FRONT	Serviceable	35.00 FS	*- FS
38	1		*NUMBER PLATE REAR	Serviceable	35.00 FS	*- FS
39	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part, S=SpcNett, L=ListItemDisc.						
				Sub Total (\$\$)	7,956.50	4,735.50
			- List Item Discount on L Items 10.00/10.00% (\$\$)		768.65	453.55
				Total Parts (\$\$)	7,187.85	4,281.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00	20.00
2	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR FRONT FENDER LH & RH; RADIATOR SUPPORT PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	800.00	500.00
3	TO SPRAY FRONT BONNET;FRONT BUMPER;FRONT FENDER LH & RH;RADIATOR SUPPORT PANEL.	New	800.00	600.00
4	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00	20.00
5	TO REMOVE AND REINSTALL CUSHIONS; SEATS; BACKREST; INNER TRIM; GARNISH; ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	80.00	60.00
6	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	New	80.00	50.00
7	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	New	80.00	80.00
8	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL.TO KNOCK & REPAIR TAILAMP PANEL RH; REAR FENDER RH;SPARE TYRE PANEL & AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.	New	1,000.00	800.00
9	TO SPRAY REAR BOOT;REAR BUMPER;REAR FENDER RH;END PANEL;SPARE TYRE PANEL.	New	1,000.00	600.00
Gross Labour Cost (S\$)			3,920.00	2,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >