

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A
 #01-09 AMK AUTOPOINT Singapore 568047
 Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST Reg No: M9-0009639-E

TP INSURER: India International Insurance Pte Ltd (HQ)

Singapore

Claimant Insurer: AXA Insurance Pte Ltd

*LK12
1pm*
SURVEYOR COPY

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	17/07/2018
Vehicle Reg. No.:	SGV8226P	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	ONG TECK KHIM		
Make/Model:	NISSAN SUNNY, 1.6 EX (A)	Vehicle Reg. Date:	27/06/2007
Vehicle Colour:	SILVER		
Engine No:	QG16426618	Chassis No:	JN1CFAN16Z0110088
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	8 ✓		
Description of Accident/Loss	REFER TO THE SKETCH PLAN BY DRIVER		
Remarks:	CAR NOT IN - TO BE ARRANGE		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

*Not with the
L1 Sy 87
Resurvey After Paint*

COST OF CLAIMS	Amount
Parts	7,187.85
Miscellaneous Items	10.00
Labour	3,920.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	11,117.85
+ GST 7.00% (S\$)	778.25
Nett Amount (S\$)	11,896.10

This claim is handled by: ZILA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 20 Jul 2018)

Parts: 143 **NISSAN SUNNY 1.6 EX (A)** (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ah Lim Motor Company/SGV8226P/20/07/2018 14:43

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*FRONT BONNET	Bu	10.00	0.00	*893.90 FL	✓
2	1		*FRONT BONNET INNER LOCK	R	10.00	0.00	*78.70 FL	X
3	10		*FRONT BONNET INSULATOR CLIPS	me	10.00	0.00	*44.00 FL	✓
4	2		*HEADLAMP LH & RH		10.00	0.00	*973.60 FL	✓
5	4		*HEADLAMP CLIPS		10.00	0.00	*21.20 FL	✓
6	1		*FRONT BUMPER	Bu	10.00	0.00	*387.90 FL	✓
7	2		*FRONT BUMPER SIDE RETAINER LH & RH	Sm	10.00	0.00	*46.00 FL	✓
8	15		*FRONT BUMPER CLIPS	me	10.00	0.00	*66.00 FL	✓
9	1		*FRONT BUMPER REINFORCEMENT		10.00	0.00	*288.20 FL	✓
10	1		*FRONT BUMPER TOP BEAM	By	10.00	0.00	*162.70 FL	✓
11	1		*FRONT BUMPER CHROME MOULDING	me	10.00	0.00	*175.20 FL	✓
12	1		*FRONT GRILLE	Scd	10.00	0.00	*223.00 FL	✓
13	1		*FRONT GRILLE EMBLEM	me	10.00	0.00	*50.70 FL	✓
14	8		*FRONT GRILLE CLIPS	me	10.00	0.00	*35.20 FL	✓
15	1		*REAR BOOT	Bu	10.00	0.00	*674.60 FL	✓
16	2		*REAR BOOT HINGE LH & RH	R	10.00	0.00	*175.20 FL	X
17	1		*REAR BOOT EMBLEM	me	10.00	0.00	*58.30 FL	✓
18	1		*REAR BOOT SUUNY LOGO	me	10.00	0.00	*95.70 FL	✓
19	1		*REAR BOOT EX.SALOON LOGO	me	10.00	0.00	*80.90 FL	✓
20	1		*REAR BOOT CIVIC LOGO	me	10.00	0.00	*56.30 FL	✓
21	1		*REAR BOOT ETHROTTLE LOGO	me	10.00	0.00	*56.30 FL	✓
22	1		*REAR BOOT CHROME MOUDLING TOP		10.00	0.00	*369.10 FL	✓
23	1		*REAR BOOT CHROME MOULDING LOWER		10.00	0.00	*288.90 FL	✓
24	1		*REAR BOOT INNER LOCK	me	10.00	0.00	*54.50 FL	✓
25	1		*REAR BOOT INSULATOR		10.00	0.00	*163.80 FL	✓
26	8		*REAR BOOT INSULATOR CLIPS		10.00	0.00	*35.20 FL	✓
27	1		*REAR BOOT RUBBER		10.00	0.00	*80.30 FL	✓
28	2		*TAILAMP LH & RH	clscm	10.00	0.00	*720.40 FL	✓
29	1		*REAR BUMPER	me	10.00	0.00	*452.40 FL	✓
30	2		*REAR BUMPER SIDE RETAINERS LH & RH	clscm	10.00	0.00	*61.80 FL	✓
31	15		*REAR BUMPER CLIPS	me	10.00	0.00	*66.00 FL	✓
32	1		*REAR BUMPER CHROME MOULDING	diy	10.00	0.00	*175.20 FL	✓
33	1		*REAR BUMPER REINFORCEMENT - CHECK PRICE		10.00	0.00	*- FL	✓
34	2		*REAR BUMPER BRACKET LH & RH		10.00	0.00	*173.20 FL	✓
35	1		*REAR END PANEL		10.00	0.00	*335.60 FL	✓
36	1		*REAR END PANEL TOP GARNISH		10.00	0.00	*66.50 FL	✓
37	1		*NUMBER PLATE FRONT	Sm	0	0.00	*35.00 FS	X
38	1		*NUMBER PLATE REAR	Sm	0	0.00	*35.00 FS	X
39	1		*REVERSE SENSOR		0	0.00	*200.00 FS	✓

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,956.50
- List Item Discount on L Items (S\$)	768.65
Total Parts (S\$)	7,187.85

Ah Lim Motor Company/SGV8226P/20/07/2018 14:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00 201
2	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR FRONT FENDER LH & RH; RADIATOR SUPPORT PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	800.00 501
3	TO SPRAY FRONT BONNET;FRONT BUMPER;FRONT FENDER LH & RH;RADIATOR SUPPORT PANEL.	New	800.00 601
4	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00 201
5	TO REMOVE AND REINSTALL CUSHIONS; SEATS; BACKREST; INNER TRIM; GARNISH; ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	80.00 61
6	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	New	80.00 51
7	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	New	80.00 7
8	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL.TO KNOCK & REPAIR TAILAMP PANEL RH; REAR FENDER RH;SPARE TYRE PANEL & AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.	New	1,000.00 7
9	TO SPRAY REAR BOOT;REAR BUMPER;REAR FENDER RH;END PANEL;SPARE TYRE PANEL.	New	1,000.00 601
Gross Labour Cost (S\$)			3,920.00

Ah Lim Motor Company/SGV8226P/20/07/2018 14:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: