

ASS. REC. BY:

REF: CS/CTI18013342 Avd3<sup>n2</sup> Special Instruction:Surveyor  
Mehmet

Adnan

ASSIGNMENT (Office)

From (Person):

Elcine cheong

of CTI

Date/Time: 23/7/18 @ 9.33am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SCJ 118G

Insured:

SJP 46684

at Workshop m/s

Dynamic Autowork

Tel:

9856 4815

of

8 kalci Bkt Ave 4 #08-09 Premier

Policy No:

DMPCSN 30244 31801

Claim No:

SNM18D03580C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/07/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

11.51am @ 23/7/18

Person Contacted:

Aby

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SCJ 118G - NA/TMI/8013268/24	DOA: 20/07/18
	SJP 46684 - NA/TMI/8013268/24	DOA: 20/07/18
26/7/18	vehicle not in	7/8/18 - VNI yet (Aby)
27/07/18	vehicle still not in yet called Aby.	10/8/18 - Aby said still not in yet.
30/7/18	vehicle still not in yet - Aby	14/8/18 - vehicle not in yet.
31/8/18	VNI (Aby)	17/8/18 - vehicle still not in yet.

REF:

ASS. REC. BY: Adrian Ling

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SCJ 118 G Yr Regn: 2008 AprilType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prado C.C. 2693Colour: Maroon A/C: Insured / Std / NI / NASp. Reading: 159482 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: TRJ1205107211Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 265/65 R17R: 265/65 R17SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 28/08/18Survey held at DynamicDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP China.

COE Expiry: 02/04/28MV: 781K  
PV: 39.2K  
Nett: 38.8K

RECEIVED 16 NOV 2019

16/11/18 Adrian confirmed LS \$5100 (Red 14,034.75, 738)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 5

1)

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2) 16/11 - typist

Add Fee: ☐ : Site Insp (\$)

Transportation:

☐ : Interview (\$)

S + RS. \$

☐ : Tech. Invs (\$)

Photos

☐ : Weekend (\$)

Others

Report Format: merimenLump Sum / L.B.I. (\$) 5100p

220

TOTAL

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18013342/Avd3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 23-07-2018



Code : CTI

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SJP 4668U	Veh. Inspected	SCJ 118G
Policy No.	DMPCSN3024431801	Coverage (\$)	0.00
Claim No.	SNM18D03580C02	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE CHEONG)	Assign Date	23/07/2018

**2. Vehicle Particulars & Condition**

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

**4. Description of Damages**

--

**5. General Information**

Accident Date	20/07/2018	Inspection Date	28/08/2018
Survey held at	DYNAMIC AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4 #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

**5a. Remarks**

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jul 2018		23 Jul 2018 09:33 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by Insurer]

Insured:	
Main Claimant:	<b>YUEN KOK FAI</b>
Vehicle Reg. No.:	<b>SCJ118G</b>
Claim Type:	<b>TP / SNM18D03580C02</b>
Vehicle Reg. No. (Insured):	<b>SJP4668U</b>
Date of Loss:	20/07/2018 00:00 - :59
Policy/Cover Note No.:	DMPCSN3024431801
Policy No. (Claimant):	
Excess:	S\$0.00
Repairer:	<b>Dynamic Autowork Pte. Ltd (HQ)</b> 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel:
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Final Rpt due 01/08/2018]</b>
Adj Asg. Remarks:	NO EST, CASE WITH SJE.


#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## CHEAPEST CAR INSURANCE RENEWAL



Free roadside assistance

Free claims support

GET A CHEAPER QUOTE NOW!

**FOR SALE BY OWNER**

Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

**New 5 Years Coe Renewal Honda Stream 1.8A RSZ**

\$2800 Downpayment Monthly  
From \$738 Onwards. Lowest  
3.68%PA@GV Cars Financing  
GV Credit Pte Ltd - StarAd

**ABWIN ONE-STOP**

MAINTENANCE, REPAIRS, PARTS

VIEW OUR RANGE

Browse by Category Save Search Print Sort by Date Posted 20 results/page

1 vehicles Search Prado Advanced Search Search View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection	Prado	Any	Any	> 10 year(s) old	Any	Any	Any	Available
------------------	-------	-----	-----	------------------	-----	-----	-----	-----------

**Toyota Prado 2.7A TX (COE till 04/2028)** **\$80,000** **\$8,320 /yr** **07-Apr-2008** **2,693 cc** **-** **SUV** **Available**

A True 4x4 SUV With Solid Off Road Performance, Mix With Civilized On Road Manners. Must View! Very Well Kept And Maintained! Reluctant Sale! Superb Excellent Cond! Viewing Strongly Encouraged! Guaran...

Posted: 30-Jun-2018 Tags: 2008 Toyota Prado, Toyota Prado, Toyota, Prado, Used Toyota

Save this search criteria, to get email alerts whenever a match is found. Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads 20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & DPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Prado, Prado Singapore, used Prado Singapore, used Prado, used vehicles Singapore or even buy used Prado Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/07/2018 17:09
Date Of Accident	20/07/2018 14:15
Exact Location Of Accident	SLIP RD TAMPINES AVE 9 TWDS TAMPINES AVE 10
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCJ118G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MR YUEN KOK FAI
NRIC No	S1527667C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97766998
Alternative Phone No	OFFICE-97766998

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRADO 2.7TX A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	18-MT002040-R00
Cover Note Number	

### Driver

Name of Driver	YUEN KOK FAI
NRIC No	S1527667C
Date Of Birth	30/06/1962
Occupation	INDOOR
Date Of Driving Pass	14/04/1980
Driving Experience	38 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97766998
Fax Number	
Contact Number	OFFICE-97766998
Email Address	NOEMAIL

Address	BLK 120 PASIR RIS STREET 11 #01-475
Postcode	510120
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJP4668U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:



Driver's Signature  
(if driver is not the policyholder)  
Date & Time:




Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## Accident Sketch Plan

### SKETCH PLAN



A = SCJ118G

B = SJP4668U

Slip Road of  
Tampines Avenue 9  
towards  
Tampines Avenue 10

### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attach

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:

### Accident Sketch Plan

On 20.07.18 at about 14:15 hours along Slip Road of Tampines Avenue 9 towards Tampines Avenue 10. I was slow moving along the above mentioned slip road and queuing up turning to Tampines Avenue 10. When I came to a complete stop and waiting for the oncoming traffic to clear, suddenly I heard a loud bang from behind. When I alighted I realised it was vehicle (B) had hit onto rear portion of my vehicle (A).

Vehicle (A): SCJ 118G

Vehicle (B): SJP 4668U

A handwritten signature in black ink, enclosed within an oval shape. The signature appears to be 'J. Subramanian'.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7667C
Vehicle Details	
Vehicle No.:	SCJ118G
Vehicle to be Exported:	Yes
Intended De-registration Date:	28 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRADO 2.7TX A
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	2TR0586986
Chassis No.:	TRJ1205107211
Maximum Power Output:	120.0 kW (160 bhp)
Open Market Value:	\$33,642.00
Original Registration Date:	03 Apr 2008
First Registration Date:	03 Apr 2008
Transfer Count:	1
Actual ARF Paid:	\$37,007.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	02 Apr 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$40,881.00
COE Rebate Amount:	\$39,233.00
Total Rebate Amount:	\$39,233.00

The information contained herein is correct as at 28 Aug 2018

OK

**DYNAMIC AUTOWORK PTE. LTD.**

8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, S'PORE 415875

Tel: 6341 6789 Fax: 6341 6778

Co. Reg. No. : 201436361C

Date: 20/07/18

By Fax & Email

To: China Taiping

Attn : Motor Claims Department

Re: Accident involving motor vehicle Nos. SCJ1186 and SJP4668U  
along Slip Road of Tampines Avenue 9 towards Tampines Ave 10 on 20/07/2018

We refer to the above matter.

We are instructed by Yuen Kok Fai to notify you of a road traffic accident on 20/07/2018 at about 14:15 at Slip Road of Tampines Avenue 9 towards Tampines Ave 10 involving our client's/customer's vehicle registration number SCJ1186 and vehicle registration number SJP4668U driven by you at the material time.

As a result of the accident, our client's /customer's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Thank You

Yours faithfully



Abby

Hp : 9856 4815

# Dynamic Autowork Pte.Ltd.

( ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 28.08.18

TO : CHINA TAIPING MOTOR CLAIMS DEPTS

VEHICLE NO : SCJ118G

MODEL : TOYOTA PRADO

DATE OF ACCIDENT : 20.07.18

TIME OF ACCIDENT : 14:15HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,780.00	\$ 1,780.00
2	TAILGATE LOGO	1	\$ 85.00	\$ 85.00
3	TAILGATE EMBLEM 'TX'	1	\$ 75.00	\$ 75.00
4	TAILGATE EMBLEM '5.7L'	1	\$ 80.00	\$ 80.00
5	TAILGATE STICKER 'TOKYO'	1	\$ 120.00	\$ 120.00
6	TAILGATE HINGE <i>new</i>	2	\$ 170.00	\$ 340.00
7	TAILGATE LOCK <i>new</i>	1	\$ 347.00	\$ 347.00
8	TAILGATE LOCK CATCH <i>new</i>	1	\$ 35.00	\$ 35.00
9	TAILGATE INNER BOARD	1	\$ 698.00	\$ 698.00
10	TAILGATE WEATHER STRIP <i>new</i>	1	\$ 360.00	\$ 360.00
11	TAILGATE STOPPER <i>new</i>	2	\$ 40.00	\$ 80.00
12	TAILGATE WINDSCREEN GLASS C/W MOULDING <i>new</i>	1	\$ 1,410.00	\$ 1,410.00
13	SPARE TYRE BRACKET <i>new</i>	1	\$ 580.00	\$ 580.00
14	NUMBER PLATE GARNISH <i>new</i>	1	\$ 230.00	\$ 230.00
15	REAR BUMPER <i>Dented</i>	1	\$ 1,460.00	\$ 1,460.00
16	REAR NUMBER PLATE LAMP GARNISH <i>new</i>	1	\$ 75.00	\$ 75.00
17	REAR NUMBER PLATE TOP GARNISH <i>new</i>	1	\$ 460.00	\$ 460.00
18	REAR BUMPER TOP INNER COVER GARNISH <i>new</i>	1	\$ 475.00	\$ 475.00
19	REAR BUMPER CENTER UPPER BRACKET <i>new</i>	3	\$ 39.00	\$ 117.00
20	REAR BUMPER RETAINER <i>new</i>	2	\$ 60.00	\$ 120.00
21	REAR BUMPER LOWER BRACKET <i>new</i>	1	\$ 295.00	\$ 295.00
22	REAR BUMPER REINFORCEMENT <i>new</i>	1	\$ 540.00	\$ 540.00
23	REAR END PANEL (OUTER) <i>Repair</i>	1	\$ 390.00	\$ 390.00
24	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 198.00	\$ 198.00
25	REAR FLOOR PANEL <i>new</i>	1	\$ 950.00	\$ 950.00
26	REAR FLOOR MAT	1	\$ 693.00	\$ 693.00

TOTAL PRICE \$ 11,993.00  
LESS 25% \$ 2,998.25  
SUB TOTAL PRICE \$ 8,994.75

4185  
3138.75

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	x
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
3	SPARE TYRE OUTER CHROME (SPECIAL TYPE) <i>Beats</i>	1	\$ 2,800.00	\$ 2,800.00	1500
4	TAILGATE SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	x
5	TAILGATE INNER BOARD CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	x
6	TAILGATE WINDSCREEN INNER SEAL <i>new</i>	1	\$ 80.00	\$ 80.00	30
7	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	30
8	TAILGATE WINDSCREEN SOLAR FILM <i>new</i>	1	\$ 550.00	\$ 550.00	x
9	REAR FENDER INNER TRIM CLIP LH (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	x
10	REAR FENDER INNER SHIELD CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	x
11	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	x
12	REAR FLOOR PANEL SEALANT <i>new</i>	1	\$ 350.00	\$ 350.00	x
13	REAR SPARE TYRE RIM <i>new</i>	1	\$ 150.00	\$ 150.00	x
14	REAR SPARE TYRE <i>new</i>	1	\$ 850.00	\$ 850.00	x
15	REAR REVERSE SENSOR (SET) <i>new</i>	1	\$ 220.00	\$ 220.00	200
TOTAL			\$	5,470.00	

#### CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	600
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	600
3	TUFF COAT	\$ 250.00	x
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	40
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
8	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x
9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL

4660

TOTAL PARTS COST : \$ 14,464.75  
TOTAL LABOUR COST : \$ 4,660.00  
TOTAL REPAIR COST : \$ 19,124.75

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

*ABBY*

SERVICE ADVISOR  
ABBY  
HP : 9856 4815

*Adrian King -*

*L/s 28/08/18.*

*05 Aug.*

*total: 6448.75*

*L/s: S.I.R.*

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is carried out "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118013342/AVD3N2

Date: 19/11/2018

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3024431801
Claimant Vehicle No :	SCJ118G	Insured Vehicle No :	SJP4668U
Date of Loss:	20/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03580C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SCJ118G	Engine No:	2TR0586986
Make & Model:	TOYOTA PRADO, 2.7 (A)	Chassis No:	TRJ1205107211
Reg. Date:	03/04/2008 (Man. Year: 2008)	Odometer:	159482 km
Colour:	Maroon		
Engine Capacity:	2693 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	265/65R17	Rear Tyre Size:	265/65R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,464.75	4,928.75	9,536.00	65.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,660.00	1,520.00	3,140.00	67.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>19,124.75</b>	<b>6,448.75</b>	<b>12,676.00</b>	<b>66.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,100.00</b>		
<b>(S\$)</b>	<b>19,124.75</b>	<b>5,100.00</b>	<b>14,024.75</b>	<b>73.33</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,338.73</b>	<b>357.00</b>	<b>981.73</b>	<b>73.33</b>
<b>Nett Amount (S\$)</b>	<b>20,463.48</b>	<b>5,457.00</b>	<b>15,006.48</b>	<b>73.33</b>

## INSPECTION

Date of Assignment:	23/07/2018	
Date Inspected:	28/08/2018	Inspected At:
		Dynamic Autowork Pte. Ltd (HQ)
		8 Kaki Bukit Ave 4, #08-09 Premier @
		Kaki Bukit
		Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 19 Nov 2018)
<b>Parts:</b> M1-SUV	TOYOTA PRADO 2.7 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SCJ118G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Dented	1,780.00 FL	*1,780.00 FL
2	1	*TAILGATE LOGO	Necessary	85.00 FL	*85.00 FL
3	1	*TAILGATE EMBLEM TX	Necessary	75.00 FL	*75.00 FL
4	1	*TAILGATE EMBLEM 5.7L	Necessary	80.00 FL	*80.00 FL
5	1	*TAILGATE STICKER TOKYO	Necessary	120.00 FL	*120.00 FL
6	2	*TAILGATE HINGE	Not Necessary	340.00 FL	*- FL
7	1	*TAILGATE LOCK	Not Necessary	347.00 FL	*- FL
8	1	*TAILGATE LOCK CATCH	Not Necessary	35.00 FL	*- FL
9	1	*TAILGATE INNER BOARD	Not Necessary	698.00 FL	*- FL
10	1	*TAILGATE WEATHERSTRIP	Not Necessary	360.00 FL	*- FL
11	2	*TAILGATE STOPPER	Not Necessary	80.00 FL	*- FL
12	1	*TAILGATE WINDSCREEN GLASS C/W MOULDING	Necessary	1,410.00 FL	*180.00 FL
13	1	*SPARE TYRE BRACKET	Not Necessary	580.00 FL	*- FL
14	1	*NUMBER PLATE GARNISH	Not Necessary	230.00 FL	*- FL
15	1	*REAR BUMPER	Deformed	1,460.00 FL	*1,460.00 FL
16	1	*REAR NUMBER PLATE LAMP GARNISH	Not Necessary	75.00 FL	*- FL
17	1	*REAR NUMBER PLATE TOP GARNISH	Not Necessary	460.00 FL	*- FL
18	1	*REAR BUMPER TOP INNER COVER GARNISH	Cut	475.00 FL	*285.00 FL
19	3	*REAR BUMPER CENTER UPPER BRACKET	Not Necessary	117.00 FL	*- FL
20	2	*REAR BUMPER RETAINER	Necessary	120.00 FL	*120.00 FL
21	1	*REAR BUMPER LOWER BRACKET	Not Necessary	295.00 FL	*- FL
22	1	*REAR BUMPER REINFORCEMENT	Not Necessary	540.00 FL	*- FL
23	1	*REAR END PANEL (OUTER)	Repair	390.00 FL	*- FL
24	1	*REAR END PANEL TOP GARNISH	Not Necessary	198.00 FL	*- FL
25	1	*REAR FLOOR PANEL	Not Necessary	950.00 FL	*- FL
26	1	*REAR FLOOR MAT	Not Necessary	693.00 FL	*- FL
27	1	*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
28	1	*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
29	1	*SPARE TYRE OUTER CHROME (SPECIAL TYPE)	Cracked	2,800.00 FS	*1,500.00 FS
30	1	*TAILGATE SEALANT	Not Necessary	80.00 FS	*- FS
31	1	*SET TAILGATE INNER BOARD CLIP	Not Necessary	60.00 FS	*- FS
32	1	*TAILGATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*30.00 FS
33	1	*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
34	1	*TAILGATE WINDSCREEN SOLAR FILM	Not Necessary	550.00 FS	*- FS
35	1	*SET REAR FENDER INNER TRIM CLIP LH	Not Necessary	60.00 FS	*- FS
36	1	*SET REAR FENDER INNER SHIELD CLIP	Not Necessary	30.00 FS	*- FS
37	1	*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
38	1	*REAR FLOOR PANEL SEALANT	Not Necessary	350.00 FS	*- FS
39	1	*REAR SPARE TYRE RIM	Not Necessary	150.00 FS	*- FS
40	1	*REAR SPARE TYRE	Not Necessary	850.00 FS	*- FS
41	1	*SET REAR REVERSES ENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 17,463.00 5,975.00  
 - List Item Discount on L Items 25.00/25.00% (\$\$) 2,998.25 1,046.25

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	14,464.75
						4,928.75

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEAT,REMOVE AND REPLACE PARTS	New	1,800.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	600.00
3	TUFF COAT	New	250.00	-
4	WIRING AND BULB CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILIATE REPAIR	New	250.00	40.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
8	CONDUCT WATER LEAKAGE TEST	New	120.00	-
9	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	-
Gross Labour Cost (S\$)			4,660.00	1,520.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;