

ASS. REC. BY

REP

CS/MSG/18013346/T1sd3

Serial Instruction

Merimen

Tautilich
Monica chung

ASSIGNMENT (Office)

MSIG

Date/Time

23/7/18 @ 9:56am

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SLT 10255

Insured

SKA 4448E

at Workshop m/s

Vermogen Aze

Tel

6358 3031

of

1 Bkt Bafuk Crescent # 05-23

Policy No

A50451953QMX

Claim No

564959

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A 18/07/2018

CA / REV / REP. / REV 24 HRS

lup

6 Benoi sector @ 24/07/2018 @ Morning

H.O.D. Endorsement

Date/Time

2:42pm @ 23/7/18

Person Contacted

Ezel

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SLT 10255-X

SKA 4448E-NBA/MSG/17000904/Y

DOA: 13/01/2017

26/07/18

@ 17:15 p.m. revised IA to Monica Chung via merimen.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ink Auth'd	Status
Main	19 Jul 2018		23 Jul 2018 09:56 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	PNG WEI LUN NIGEL, ID: 59230478G		
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLL1025S	Date of Loss:	18/07/2018 21:00 - :59 [17 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 564959	Policy/Cover Note No.:	A80451953QMX (Comprehensive) Coverage: 20/12/2017 - 19/12/2018
Vehicle Reg. No. (Insured):	SKA4448E	Policy No. (Claimant):	
		Excess:	
Repairer:	Vermogen Ace Pte Ltd (wcega Plaza) (HQ) 1 Bukit Batok Crescent, #05-23 WCEGA Plaza, 658064 Bukit Batok - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/07/2018]		
Driver/Custodian (Insured):	PNG WEI LUN NIGEL (25 / Male), NRIC: S9230478G		
Adj Asg. Remarks:	SJE Agree Please appoint LKK and contact Janice Chang @ 62686183. The vehicle is CURRENTLY IN workshop. Liability 50%		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18013346/T1sd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 23-07-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKA 4448E	Veh. Inspected	SLL 1025S
Policy No.	A80451953QMX	Coverage (\$)	0.00
Claim No.	564959	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	23/07/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	18/07/2018	Inspection Date	24/07/2018
Survey held at	6 BENOI SECTOR		
Repairer	VERMOGEN ACE PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SLL10255
Vehicle Type:	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA HYBRID 1.5X CVT
Chassis No.:	NHP1707063937
Propellant:	Petrol-Electric
Engine No.:	1NZR450510
Motor No.:	H12606788
Engine Capacity:	1496 cc
Power Rating:	45.0 kW
Maximum Power Output:	73.0 kW (97 bhp)
Maximum Laden Weight:	1765 kg
Unladen Weight:	1380 kg
Year Of Manufacture:	2016
Original Registration Date:	14 Feb 2017
Lifespan Expiry Date:	-
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium:	\$48,000.00
COE Expiry Date:	13 Feb 2027
Road Tax Expiry Date:	13 Aug 2018
PARF Eligibility Expiry Date:	13 Feb 2027
Inspection Due Date:	13 Feb 2020
Intended Transfer Date:	20 Jul 2018
CO2 Emission:	94.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$25,279.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 13 Aug 2018. You may renew the road tax from 14 May 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 13 Aug 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 14 Aug 2018 to 13 Feb 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	341.00	-	341.00
Total Amount Payable:			366.00

Amount Payable (From 14 Aug 2018 to 13 Aug 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	682.00	-	682.00
Total Amount Payable:			707.00

You may print this page for reference.

OK

Print

Shirley Hiew (LKK Auto)

From: ezel.t@vermogen-group.com
Sent: Wednesday, 5 September 2018 10:40 AM
To: 'Shirley Hiew (LKK Auto)'; 'SUR'; 'Taufikh (LKKAuto)'
Cc: 'Baldoz Juan Paulo Bongon'; eric.g@vermogen-group.com; 'Vmg admin'; 'Luis Tan'; 'Pila Ng'; 'Minoko Chan'; 'Paul Tan'; desmond@vermogen-group.com
Subject: RE: FINALISE TP SLL1025S (DOA: 18/07/2018)

Hi Shirley,

We confirmed finalise COR \$3,200.00 (lump sum) in 6 days.

Thanks & Regards,
Ezel Tejano

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, September 5, 2018 10:12 AM
To: ezel.t@vermogen-group.com; 'SUR' <sur@lkkauto.com>; 'Taufikh (LKKAuto)' <Taufikh@lkkauto.com>
Cc: 'Baldoz Juan Paulo Bongon' <paulo.b@vermogen-group.com>; eric.g@vermogen-group.com; 'Vmg admin' <vmg@vermogen-group.com>; 'Luis Tan' <luis@vermogen-group.com>; 'Pila Ng' <pila@vermogen-group.com>; 'Minoko Chan' <minoko@vermogen-group.com>; 'Paul Tan' <paul@vermogen-group.com>; desmond@vermogen-group.com
Subject: RE: FINALISE TP SLL1025S (DOA: 18/07/2018)

Hi Ezel,

Please re-confirm final fig of \$3,200.00 @ 6 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ezel.t@vermogen-group.com [<mailto:ezel.t@vermogen-group.com>]
Sent: Wednesday, 29 August 2018 11:38 AM
To: 'SUR' <sur@lkkauto.com>; 'Taufikh (LKKAuto)' <Taufikh@lkkauto.com>
Cc: 'Baldoz Juan Paulo Bongon' <paulo.b@vermogen-group.com>; eric.g@vermogen-group.com; 'Vmg admin' <vmg@vermogen-group.com>; 'Luis Tan' <luis@vermogen-group.com>; 'Pila Ng' <pila@vermogen-group.com>; 'Minoko Chan' <minoko@vermogen-group.com>; 'Paul Tan' <paul@vermogen-group.com>; desmond@vermogen-group.com
Subject: FINALISE TP SLL1025S (DOA: 18/07/2018)

Dear Taufikh,

Kindly check and confirm finalise COR with \$3,700.00 before 7% gst (lump sum) in 6 working days.

Excluded: PRS, RS, WEEKENDS, PH.

Thank you.

Best Regards,

Ezel Tejano

Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 6358 3031

Fax: 6694 4929

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 26 Jul 2018

Preliminary Advice

Insured Vehicle No	: SKA4448E	Accident Date	: 18/07/2018
TP Vehicle No	: SLL1025S	Assignment Date	: 23/07/2018
Make	: TOYOTA SIENTA	Est. Duration of Repair	: 6 days
Date of Inspection	: 24/07/2018		
Inspection At	: Vermogen Ace Pte Ltd (wcega Plaza) (HQ) 1 Bukit Batok Crescent, #05-23 WCEGA Plaza Singapore 658064		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,585.20
Revised Amount	:S\$	4,633.83
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,633.83

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/07/2018 14:41
Date Of Accident	18/07/2018 21:40
Exact Location Of Accident	PENANG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL1025S
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66944919

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA HYBRID
Exact Purpose for which vehicle was being used at time of accident	HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995010
Cover Note Number	

Driver

Name of Driver	LAU WAI MAN
NRIC No	S7387583H
Date Of Birth	30/10/1973
Occupation	OUTDOOR
Date Of Driving Pass	04/11/2009
Driving Experience	8 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90106639
Fax Number	
Contact Number	
Email Address	NOEMAIL


No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 2

PENANG ROAD

SKETCH PLAN

- (A) SLL10255
- (B) SKA4448E



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report No: 7/20180919/2024

DECLARATION

✓We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: YIRA RAHMAN
NRIC/PPN No.:

Accident Sketch Plan Pg. 2



**SINGAPORE
POLICE FORCE**



T/20180719/2044

2 of 3

Police Station Of Origin:
Bukit Merah West N.P.C
500 Bukit Merah View #01-01 SINGAPORE
159682
Tel No: 1800-3779999

Report No. T/20180719/2044

CONTINUATION OF REPORT

Driver			
Name	LAU WAI MAN		ID No. S7387583H
Related Vehicle	NIL		Contact No.
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL


Brief Details.

On the 18/07/2018 at about 2140hrs, I was travelling in my vehicle, SLL1025S, along Penang road towards Somerset road, on the lane beside the bus lane. As I was on a straight road, a vehicle, SKA4448E, travelling on the lane on my right then came very close to my vehicle and it collided with my vehicle eventually. A sound from the collision could be heard when I was driving and this was when both of us stopped by the road to take pictures. I gave my name card and the other party provided his name and contact number . My vehicle's right side was scratched and there was a dent on my driver's door. The damages also appeared to be marks and scratches cause by the other party's rims. On the other hand, the other party's vehicle suffered some scratches on the left front bumper. I wish to inform that no one was injured during this collision.

IDENTIFICATION CARD, DRIVING LICENCE & VOCATIONAL LICENCE



VMG USE ONLY



VMG USE ONLY



This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to the LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575011.

Type	Description	Issue Date
02	TAXI VL	02/09/2016





SLL1025S

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : MSIG
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 18/7/2018

Vehicle Reg. No. : SLL1025S
Vehicle Reg. Date: 14-Feb-2017
Make / Model : T. SIENTA HYBRID 1.5X CV
Engine No. : 1NZR450510
Chassis No. : NHP1707063937

COST OF CLAIMS

Parts Cost / List Items : \$ 13,113.60
Plus/Less 25% \$ 3,278.40
Total Cost / List : \$ 9,835.20
Special Nett Items : \$ 250.00
Total Parts Amount : \$ 10,085.20
Total Labour Amount : \$ 3,500.00
Gross Total : \$ 13,585.20
GST % : 7% \$ 950.96
Nett Amount : \$ 14,536.16

Surveyor Name and Company :

Tanjik 97495489
Date of survey : 24/7/18 @ 1310
Part by Part / Lump Sum : 6 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : sur@lkkauto.com
Fax No :
HP No :

This claim is handled by : PAULO BALDOZ

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLL1025S**
 Vehicle Reg. Date: **14/2/2017**
 Make / Model : **T. SIENTA HYBRID 1.5X CVT**
 Engine No. : **1NZR450510**
 Chassis No. : **NHP1707063937**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Front door RH	b+ /	\$ 1,344.00	944	
2	1	Front door hinge top	x	\$ 109.00		
3	1	Front door hinge bottom	x } n	\$ 109.00		
4	1	Front door lock RH	x	\$ 855.00		
5	1	Front door catch RH	x	\$ 44.00		
6	1	Front door weatherstrip RH	nk /	\$ 219.00		
7	1	Front door power window motor RH	x	\$ 647.00		
8	1	Front door window moulding RH	x	\$ 184.00		
9	1	Front door window regulator RH	x } x	\$ 430.00		
10	1	Front door trim RH	x } n	\$ 1,500.00		
11	1set	Front door trim clips	x	\$ 40.00		
12	1	Front door stopper RH	x	\$ 30.00		
13	1	Front door outer handle RH	x	\$ 347.00		
14	1	Rear door RH	b+ /	\$ 1,658.00	1232.80	
15	1	Rear door outer handle RH	x } n	\$ 77.00		
16	1	Rear door rubber RH	nk /	\$ 271.40		
17	1	Rear door sticker RH	ne	\$ 79.90		
18	1	Rear door lock RH	x	\$ 219.10		
19	1	Rear door power window motor RH	x	\$ 365.50		
20	1	Rear door window moulding RH	x	\$ 187.00		
21	1	Rear door window regulator RH	x } x	\$ 265.40		
22	1	Rear door trim RH	x	\$ 1,534.50		
23	1set	Rear door trim clips	x	\$ 40.00		
24	1	Rear door stopper RH	x	\$ 30.00		
25	1	Rear door lower garnish RH	nk /	\$ 195.20		
26	1	Rocker panel RH	Rx	\$ 1,100.00		
27	1	Rear fender RH	Rx	\$ 1,075.00		
28	1	Rear fender lower garnish RH	nk /	\$ 157.60		
29	1	Rear rim cover RH	x } n.		\$ 250.00	
30	0	0				
31	0	0				
32	0	0		2099.9		
33	0	0	- 25%	2224.92		
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]



SLL1025S

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : MSIG
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 18/7/2018

Vehicle Reg. No. : SLL1025S
Vehicle Reg. Date: 14-Feb-2017
Make / Model : T. SIENTA HYBRID 1.5X CV
Engine No. : 1NZR450510
Chassis No. : NHP1707063937

COST OF CLAIMS

Parts Cost / List Items : \$ 13,113.60
Plus/Less 25% \$ 3,278.40
Total Cost / List : \$ 9,835.20
Special Nett Items : \$ 250.00
Total Parts Amount : \$ 10,085.20
Total Labour Amount : \$ 3,500.00
Gross Total : \$ 13,585.20
GST % : 7% \$ 950.96
Nett Amount : \$ 14,536.16

Surveyor Name and Company :

Tanjik 97495789
Date of survey : 24/7/18 @ 1310
Part by Part / Lump Sum : 6 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : sur@tuhant.com
Fax No : _____
HP No : _____

This claim is handled by : PAULO BALDOZ

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]

Final - 4638.83

4/2 = ₹ 3700/-

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLL1025S
 Vehicle Reg. Date: 14/2/2017
 Make / Model : T. SIENTA HYBRID 1.5X CVT
 Engine No. : 1NZR450510
 Chassis No. : NHP1707063937

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Front door RH	bt ✓	\$ 1,344.00		
2	1	Front door hinge top	X	\$ 109.00		
3	1	Front door hinge bottom	X	\$ 109.00		
4	1	Front door lock RH	X	\$ 855.00		
5	1	Front door catch RH	X	\$ 44.00		
6	1	Front door weatherstrip RH	bt ✓	\$ 219.00		
7	1	Front door power window motor RH	X	\$ 647.00		
8	1	Front door window moulding RH	X	\$ 184.00		
9	1	Front door window regulator RH	X	\$ 430.00		
10	1	Front door trim RH	X	\$ 1,500.00		
11	1set	Front door trim clips	X	\$ 40.00		
12	1	Front door stopper RH	X	\$ 30.00		
13	1	Front door outer handle RH	X	\$ 347.00		
14	1	Rear door RH	bt ✓	\$ 1,658.00		
15	1	Rear door outer handle RH	X	\$ 77.00		
16	1	Rear door rubber RH	bt ✓	\$ 271.40		
17	1	Rear door sticker RH	bt ✓	\$ 79.90		
18	1	Rear door lock RH	X	\$ 219.10		
19	1	Rear door power window motor RH	X	\$ 365.50		
20	1	Rear door window moulding RH	X	\$ 187.00		
21	1	Rear door window regulator RH	X	\$ 265.40		
22	1	Rear door trim RH	X	\$ 1,534.50		
23	1set	Rear door trim clips	X	\$ 40.00		
24	1	Rear door stopper RH	X	\$ 30.00		
25	1	Rear door lower garnish RH	bt ✓	\$ 195.20		
26	1	Rocker panel RH	X	\$ 1,100.00		
27	1	Rear fender RH	X	\$ 1,075.00		
28	1	Rear fender lower garnish RH	bt ✓	\$ 157.60		
29	1	Rear rim cover RH	X		\$ 250.00	
30	0	0				
31	0	0				
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

3925.10 - 25% = 2943.83

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jul 2018		23 Jul 2018 09:56 Edit Adj Rpt	S\$3,200.00 Edit Estimates	S\$3,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	PNG WEI LUN NIGEL, ID: S9230478G								
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Vehicle Reg. No.:	SLL1025S	Date of Loss:	18/07/2018 21:00 - :59 [17 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 564959	Policy/Cover Note No.:	A80451953QMX (Comprehensive) Coverage: 20/12/2017 - 19/12/2018						
Vehicle Reg. No. (Insured):	SKA4448E	Policy No. (Claimant):							
		Excess:							
Repairer:	Vermogen Ace Pte Ltd (wcega Plaza) (HQ) 1 Bukit Batok Crescent, #05-23 WCEGA Plaza, 658064 Bukit Batok - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 22/08/2018]								
Driver/Custodian (Insured):	PNG WEI LUN NIGEL (25 / Male), NRIC: S9230478G								
Adj Asg. Remarks:	SJE Agree Please appoint LKK and contact Janice Chang @ 62686183. The vehicle is CURRENTLY IN workshop. Liability 50%								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLL1025S (564959)
[SKA4448E]
TP
LCRF PTE LTD
Jul 18 2018 9:00PM
[PNG WEI LUN NIGEL]
Vermogen Ace Pte Ltd (wcega Plaza)

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Letters/Correspondences			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/07/18 16:07	Letter to OI Informing TPD	 Load HTM	
Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/07/18 16:01	Accident Statement From: SC - Reg. No: SKA4448E, Claimant: PNG WEI LUN, NIGEL	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/07/18 17:15	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/07/18 17:16	Odometer Reading	 Load JPG	☒
2	26/07/18 17:16	Chassis Number	 Load JPG	☒
3	26/07/18 17:16	General View	 Load JPG	☒
4	26/07/18 17:16	General View	 Load JPG	☒
5	26/07/18 17:16	General View	 Load JPG	☒
6	26/07/18 17:16	General View	 Load JPG	☒
7	26/07/18 17:16	General View	 Load JPG	☒
8	26/07/18 17:16	General View	 Load JPG	☒
9	26/07/18 17:16	General View	 Load JPG	☒
10	26/07/18 17:16	General View	 Load JPG	☒
11	26/07/18 17:16	General View	 Load JPG	☒
12	26/07/18 17:16	General View	 Load JPG	☒
13	26/07/18 17:16	General View	 Load JPG	☒
14	26/07/18 17:16	General View	 Load JPG	☒
15	26/07/18 17:16	General View	 Load JPG	☒
16	26/07/18 17:16	General View	 Load JPG	☒
17	26/07/18 17:16	General View	 Load JPG	☒
18	26/07/18 17:16	General View	 Load JPG	☒
19	26/07/18 17:16	General View	 Load JPG	☒
20	26/07/18 17:16	General View	 Load JPG	☒
21	26/07/18 17:16	General View	 Load JPG	☒
22	26/07/18 17:16	General View	 Load JPG	☒
23	26/07/18 17:16	General View	 Load JPG	☒
24	05/09/18 11:43	Reinspection Photo	 Load JPG	☒
25	05/09/18 11:43	Reinspection Photo	 Load JPG	☒
26	05/09/18 11:43	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print

Letters/Correspondences			1 per page	☐
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	20/07/18 16:01	Third Party Accident Report From: SC - Reg. No: SKA4448E, Claimant: PNG WEI LUN, NIGEL		Load PDF
2	20/07/18 16:01	SJE AGREE LKK From: SC - Reg. No: SKA4448E, Claimant: PNG WEI LUN, NIGEL		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18013346/T1SD3Q2

Date: 10/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80451953QMX

Claimant Vehicle No: SLL1025S

Insured Vehicle No: SKA4448E

Date of Loss: 18/07/2018

Nature of Claim: TP

Claim No: 564959

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL1025S

Make & Model: TOYOTA SIENTA, 1.5 HYBRID (A)

Engine No: 1NZR450510

Reg. Date: 14/02/2017 (Man. Year: 2016)

Chassis No: NHP1707063937

Colour: Red

Odometer: 115639 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Roadstone 6 mm

Rear Left Side: Roadstone 6 mm

Front Right Side: Roadstone 6 mm

Rear Right Side: Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,085.20	2,324.92	7,760.28	76.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,500.00	1,690.00	1,810.00	51.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,585.20	4,014.92	9,570.28	70.45
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	13,585.20	3,200.00	10,385.20	76.44
+ GST 7.00/7.00% (S\$)	950.96	224.00	726.96	76.44
Nett Amount (S\$)	14,536.16	3,424.00	11,112.16	76.44

INSPECTION

Date of Assignment: 23/07/2018

Date Inspected: 24/07/2018 Inspected At:

6 BENOI SECTOR

Repairer: Vermogen Ace Pte Ltd (wcega Plaza) (HQ)

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2018)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL1025S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Bent	1,344.00 FL	*944.00 FL
2	1		*FRONT DOOR HINGE TOP	Not Necessary	109.00 FL	*- FL
3	1		*FRONT DOOR HINGE BOTTOM	Not Necessary	109.00 FL	*- FL
4	1		*FRONT DOOR LOCK RH	Not Necessary	855.00 FL	*- FL
5	1		*FRONT DOOR CATCH RH	Not Necessary	44.00 FL	*- FL
6	1		*FRONT DOOR WEATHERSTRIP RH	Necessary	219.00 FL	*219.00 FL
7	1		*FRONT DOOR POWER WINDOW MOTO RH	Not Necessary	647.00 FL	*- FL
8	1		*FRONT DOOR WINDOW MOULDING RH	Not Necessary	184.00 FL	*- FL
9	1		*FRONT DOOR WINDOW REGULATOR RH	Not Necessary	430.00 FL	*- FL
10	1		*FRONT DOOR TRIM RH	Not Necessary	1,500.00 FL	*- FL
11	1		*SET FRONT DOOR TRIM CLIPS	Not Necessary	40.00 FL	*- FL
12	1		*FRONT DOOR STOPPER RH	Not Necessary	30.00 FL	*- FL
13	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	347.00 FL	*- FL
14	1		*REAR DOOR RH	Bent	1,658.00 FL	*1,232.80 FL
15	1		*REAR DOOR OUTER HANDLE RH	Not Necessary	77.00 FL	*- FL
16	1		*REAR DOOR RUBBER RH	Necessary	271.40 FL	*271.40 FL
17	1		*REAR DOOR STICKER RH	Necessary	79.90 FL	*79.90 FL
18	1		*REAR DOOR LOCK RH	Not Necessary	219.10 FL	*- FL
19	1		*REAR DOOR POWER WINDOW MOTOR RH	Not Necessary	365.50 FL	*- FL
20	1		*REAR DOOR WINDOW MOULDING RH	Not Necessary	187.00 FL	*- FL
21	1		*REAR DOOR WINDOW REGULATOR RH	Not Necessary	265.40 FL	*- FL
22	1		*REAR DOOR TRIM RH	Not Necessary	1,534.50 FL	*- FL
23	1		*SET REAR DOOR TRIM CLIPS	Not Necessary	40.00 FL	*- FL
24	1		*REAR DOOR STOPPER RH	Not Necessary	30.00 FL	*- FL
25	1		*REAR DOOR LOWER GARNISH RH	Cut	195.20 FL	*195.20 FL
26	1		*ROCKER PANEL RH	Repair	1,100.00 FL	*- FL
27	1		*REAR FENDER RH	Repair	1,075.00 FL	*- FL
28	1		*REAR FENDER LOWER GARNISH RH	Cut	157.60 FL	*157.60 FL
29	1		*REAR RIM COVER RH	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,363.60	3,099.90
- List Item Discount on L Items 25.00/25.00% (S\$)	3,278.40	774.98
Total Parts (S\$)	10,085.20	2,324.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE DAMAGED PARTS AND TO PANEL BEATING ACCIDENT AREA.FRT DOOR RH ,ROCKER PANEL RH ,RR DOOR RH ,RR FENDER RH,RR FENDER RH	New	1,500.00	700.00
2	TO REMOVE & REFIT REAR DOOR COMPONENTS FRONT DOOR RH	New	150.00	60.00
3	TO REMOVE & REFIT REAR DOOR COMPONENTS REAR DOOR RH	New	150.00	60.00
4	TO CHECK AND RECTIFY AFTER DISCONNECT & CONNECT	New	100.00	30.00
5	TO PUTTY AND RESPRAY REPLACED PARTS AND ACCIDENT REPAIR AREA .FRT DOOR RH ,ROCKER PANEL RH ,RR DOOR RH ,RR FENDER RH	New	1,500.00	800.00
6	TO RUST PROOF AFFECTED AREAS	New	100.00	40.00
Gross Labour Cost (\$\$)			3,500.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >