



REF:

LPC

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10

days

Res.: Yes or No

Lum Sum:

P/p

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SUD588511

Yr Regn: 2014 Dec

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz

C180

cc

1595

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

80409

T/Radio:

Insured / Std / NI / NA

Eng/No:

S

C/No:

WDD2050402R009 988

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

275/50R17

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

23/7/18 ELSYS

Survey held at

LPC Panda Loop

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt n/s, u/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

(P/p \$ 24,833.45 / Reo \$ 3,297.34/88%)

Date/Time, File Pass to?

☐

Prel. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS: SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18013369/T1hb3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 23-07-2018		
		Code : LPC2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKZ 4774G	Veh. Inspected	SLD 5585H	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	23/07/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	19/07/2018	Inspection Date	23/07/2018	
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref: To Be Advised  
Our ref: CC4/LPC18013369/T1hb3

Date: 24.07.2018

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SLD5585H**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23.07.2018 at the premises of M/s Cycle & Carriage Industries Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	27,580.25
Revised Estimate Amount	: S\$	16,825.45
"Check" Items Amount	: S\$	8,345.81
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

**Description of Damage:**

The vehicle sustained damages at the  
Front N/S Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 7 days

Yours faithfully,

MOHD. TAUFIKH



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SLD5585H

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555  
62507388

Vehicle & Document Information

WIP No 25413  
Reg No/Reg Date SLD5585H / 16/12/2014  
Date In/Mileage / 0  
Chassis No WDD2050402R009988  
Engine No 27491030216279  
Make/Model MB/MB C 180 SEDAN (W205) "EXCLUSIVE / EX  
Colour/Trim 027 775 Iridium Sil/ 041 101 Learther AR

odo: 80409

Account No	Terms	Date/Time Printed	CSE	Operator				
WL001605	Credit	23/07/2018/ 11:26	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : V0101343 // 19-07-2018 DRIVE IN: 20-07-2018 // TP CAR NO: SKZ4774G (LONPAC INS) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :								
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS. NETT							0.10	380.00
A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT. NETT								96.00
S BPNTOW ACCIDENT TOWING FROM 2 TG PENJURU TO PLSC USING CAR CARRIER WO: 150398								140.00
S BPNSUB SUPPLY & TRANSFER IPC FRONT LEFT RIM PURCHASE ORDER NO:								60.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT. NETT								540.00
A BPILAB REMOVE & REPLACE FRONT BUMPER, FRONT LEFT FENDER, FRONT BONNET & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.								2880.00
A BPIRES RESPRAY FRONT BUMPER, FRONT BONNET & FRONT LEFT FENDER							0.03	2200.00
A BPILAB REMOVE & INSTALL FRONT SUSPENSION & WHEEL BASE								1920.00
M FRT BUMPER					1.00	1375.37	00.00	1375.37
M LH/F BUMPER BRACKET					1.00	11.22	00.00	11.22
M LH/F BOTTOM GRILLE					1.00	63.93	00.00	63.93
M LH/F BASIC MOUNTING FOR BUMPER					1.00	68.53	00.00	68.53
M FRT BASIC MOUNTING FOR BUMPER					1.00	102.80	00.00	102.80
M CT/F IMPACT ABSORBER					1.00	149.56	00.00	149.56
M LH/F OUTER PARKING SENSOR					1.00	172.07	00.00	172.07

Confirmed &amp; accepted by

Authorized signatory and company stamp

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SLD5585H

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555  
62507388

## Vehicle &amp; Document Information

WIP No **25413**  
Reg No/Reg Date **SLD5585H / 16/12/2014**  
Date In/Mileage **/ 0**  
Chassis No **WDD2050402R009988**  
Engine No **27491030216279**  
Make/Model **MB/MB C 180 SEDAN (W205) "EXCLUSIVE / EX**  
Colour/Trim **027 775 Iridium Sil/ 041 101 Learther AR**

Account No	Terms	Date/Time Printed	CSE	Operator	
WL001605	Credit	23/07/2018/ 11:26	AQ	305 / Alan Quek Ai Lun	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	LH/F PARKING SENSOR	2.00	172.07	00.00	un X 344.14
M	LH/F PARKING SENSOR SEAL	3.00	6.42	00.00	un X 19.26
M	CT/F BOTTOM GARNISH	1.00	172.64	00.00	un X 172.64
M	LH/F FENDER	1.00	881.86	00.00	bt 881.86
M	LH/F WHEEL ARCH	1.00	120.19	00.00	de 120.19
M	RADIATOR GRILLE	1.00	1388.66	00.00	ana 1388.66
M	BONNET	1.00	1999.27	00.00	bt 1999.27
M	LH/F BONNET HINGE	1.00	181.73	00.00	bt 181.73
M	RH/F BONNET HINGE	1.00	181.73	00.00	bt 181.73
M	BONNET ACTUATOR	2.00	181.35	00.00	act 362.70
M	BONNET SPRING ELEMENT	2.00	29.91	00.00	un X 59.82
M	BONNET UPPER CATCH	2.00	32.77	00.00	un X 65.54
M	BONNET LOWER CATCH	2.00	62.59	00.00	un X 125.18
M	FRT END SUPPORT TOP MEMBER	1.00	691.68	00.00	bt 691.68
M	FRT CROSS MEMBER	1.00	407.90	00.00	X 407.90
M	LH/F CROSS MEMBER BRACKET	1.00	67.58	00.00	X 67.58
M	LH/F CROSS MEMBER ABSORBER	1.00	88.69	00.00	X 88.69
M	LH/F HEADLAMP	1.00	3126.25	00.00	cn 3126.25
M	LH/F HEADLAMP CONTROL UNIT	1.00	571.36	00.00	dis 571.36
M	FRT UNDER CARRIAGE COVER	1.00	181.26	00.00	? 181.26
M	LH/F DISC WHEEL	1.00	557.10	00.00	unt 557.10
M	LH/F SHOCK-ABSORBER	1.00	822.79	00.00	822.79
M	FRT TORSION BAR	1.00	564.05	00.00	564.05
M	LH/F TORSION BAR ROD	1.00	82.55	00.00	82.55
M	LH/F STEERING KNUCKLE	1.00	1208.64	00.00	1208.64
M	LH/F TRUST ARM	1.00	577.59	00.00	577.59
M	LH/F LOWER CONTROL ARM	1.00	592.02	00.00	592.02
M	LH/F TRUST ARM BUSHING	1.00	182.37	00.00	182.37
M	LH/F UPPER CONTROL ARM	1.00	792.13	00.00	792.13
M	LH/F WHEEL HUB	1.00	524.09	00.00	524.09

Alan Quek

Cycle & Carriage Industries Pte Ltd

Body Care & Repair Center

DID: 6771 1377 HP: 0196 5112 Fax: 0355 1096

28312.00

Alan Quek  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272  
Email: alan.quek@cyclecarriage.com.sg

Confirmed &amp; accepted by

Nett **27,580.25**  
7% GST on **27580.25** **1930.62**

Authorized signatory and company stamp

Total Payable **29,510.87**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## TAX INVOICE

Invoice Name & Address	Owner Name & Vehicle Info
LONPAC INSURANCE BHD	Cust No/Name /Tang Joo Kim
MOTOR CLAIM DEPARTMENT	Reg No/Reg Date SLD5585H / 16/12/2014
300 BEACH ROAD	Date In/Mileage 23/07/2018/ 80409
#17-04/07 THE CONCOURSE	Chassis No WDD2050402R009988
SINGAPORE 199555	Engine No 27491030216279
Contact No 62507388	Make/Model MB/MB C 180 SEDAN (W205) "EXCLUSIVE / EX
	Colour/Trim 027 775 Iridium Sil/ 041 101 Learther AR

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
WL001605	Credit	29/09/2018/ 14:40	AQ	305 / Alan Quek Ai Lun	25413	28146643

Description of Goods / Services	Qty	Unit Price S\$	Amount S\$
X LH/F WHEEL ARCH	1.00	120.19	120.19
X RADIATOR GRILLE	1.00	1388.66	1388.66
X BONNET	1.00	1999.27	1999.27
X LH/F BONNET HINGE	1.00	181.73	181.73
X RH/F BONNET HINGE	1.00	181.73	181.73
X BONNET ACTUATOR	2.00	181.35	362.70
X FRT END SUPPORT TOP MEMBER	1.00	691.68	691.68
X FRT CROSS MEMBER	1.00	407.90	407.90
X LH/F CROSS MEMBER BRACKET	1.00	67.58	67.58
X LH/F HEADLAMP	1.00	3126.25	3126.25
X LH/F HEADLAMP CONTROL UNIT	1.00	571.36	571.36
X LH/F DISC WHEEL	1.00	557.10	557.10
X LH/F SHOCK-ABSORBER	1.00	822.79	822.79
X LH/F STEERING KNUCKLE	1.00	1208.64	1208.64
X LH/F TRUST ARM	1.00	577.59	577.59
X LH/F LOWER CONTROL ARM	1.00	592.02	592.02
X LH/F UPPER CONTROL ARM	1.00	792.13	792.13
X LH/F WHEEL HUB	1.00	524.09	524.09
X BIHEXAGONAL NUT	2.00	10.17	20.34
X NUT	2.00	3.53	7.06
X NUT W FLANGE, BINDING	1.00	6.68	6.68
X SCREW W RND. HEXAL. HEAD	2.00	11.13	22.26
X SCREW W RND. HEXAL. HEAD	2.00	15.64	31.28
X NUT-A-WASHER ASSEMBLY	2.00	10.17	20.34
X HEXAGON NUT	2.00	4.32	8.64
X LH/F STRUT	1.00	42.56	42.56
X CONSOLE	1.00	202.17	202.17
X FRT UNDER CARRIAGE COVER	1.00	181.26	181.26
X SRS ACCELERATION SENSOR	1.00	133.00	133.00
X HEXALOBULAR BOLT	1.00	1.21	1.21
X SCREW	10.00	5.50	55.00

Parts	17,497.45	Nett	24,833.45
Labour	7,136.00	7% GST on	24833.45
Standard Menu	0.00		1738.34
Specialist Job	200.00	Total Payable	26,571.79
Diagnostics Job	0.00	Paid	0.00
Sundry/Others	0.00	Total Due	26,571.79
Total(w/o GST)	24,833.45		

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SLD5585H

## Finalization

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555  
62507388

*Tanfikh*

### Vehicle & Document Information

WIP No 25413  
Reg No/Reg Date SLD5585H / 16/12/2014  
Date In/Mileage 23/07/2018/ 80409  
Chassis No WDD2050402R009988  
Engine No 27491030216279  
Make/Model MB/MB C 180 SEDAN (W205) "EXCLUSIVE / EX  
Colour/Trim 027 775 Iridium Sil/ 041 101 Leather AR

Account No	Terms	Date/Time Printed	CSE	Operator				
WL001605	Credit	29/09/2018/ 14:40	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :V0101343 // 19-07-2018 DRIVE IN:20-07-2018 // TP CAR NO:SKZ4774G (LONPAC INS) DATE IN/DATE SURVEY:23-07-2018 // LKK TAUFIKH BY/AUTHORIZED ON :VIC ALEPH // 06-08-2018								
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT							0.10	380.00
A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT								96.00
S BPNTOW ACCIDENT TOWING FROM 2 TG PENJURU TO PLSC USING CAR CARRIER WO: 150398								140.00
S BPNSUB LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT) WHEEL BALANCE AND INSTALL NEW VALVE HEAD								60.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT								540.00
A BPILAB REMOVE & REPLACE FRONT BUMPER, FRONT LEFT FENDER, FRONT BONNET & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.								2400.00
A BPIRES RESPRAY FRONT BUMPER, FRONT BONNET & FRONT LEFT FENDER								1800.00
A BPILAB REMOVE & INSTALL FRONT SUSPENSION & WHEEL BASE								1920.00
X FRT BUMPER					1.00	1375.37	00.00	1375.37
X LH/F BUMPER BRACKET					1.00	11.22	00.00	11.22
X LH/F BOTTOM GRILLE					1.00	63.93	00.00	63.93
X LH/F BASIC MOUNTING FOR BUMPER					1.00	68.53	00.00	68.53
X LH/F OUTER PARKING SENSOR					1.00	172.07	00.00	172.07
X LH/F PARKING SENSOR SEAL					3.00	6.42	00.00	19.26
X LH/F FENDER					1.00	881.86	00.00	881.86

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## Finalization

## ESTIMATE FOR SLD5585H

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555  
62507388

Vehicle & Document Information  
WIP No 25413  
Reg No/Reg Date SLD5585H / 16/12/2014  
Date In/Mileage 23/07/2018/ 80409  
Chassis No WDD2050402R009988  
Engine No 27491030216279  
Make/Model MB/MB C 180 SEDAN (W205) "EXCLUSIVE / EX  
Colour/Trim 027 775 Iridium Sil/ 041 101 Learther AR

Account No	Terms	Date/Time Printed	CSE	Operator	
WL001605	Credit	29/09/2018/ 14:40	AQ	305 / Alan Quek Ai Lun	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X	LH/F WHEEL ARCH	1.00	120.19	00.00	120.19
X	RADIATOR GRILLE	1.00	1388.66	00.00	1388.66
X	BONNET	1.00	1999.27	00.00	1999.27
X	LH/F BONNET HINGE	1.00	181.73	00.00	181.73
X	RH/F BONNET HINGE	1.00	181.73	00.00	181.73
X	BONNET ACTUATOR	2.00	181.35	00.00	362.70
X	FRT END SUPPORT TOP MEMBER	1.00	691.68	00.00	691.68
X	FRT CROSS MEMBER	1.00	407.90	00.00	407.90
X	LH/F CROSS MEMBER BRACKET	1.00	67.58	00.00	67.58
X	LH/F HEADLAMP	1.00	3126.25	00.00	3126.25
X	LH/F HEADLAMP CONTROL UNIT	1.00	571.36	00.00	571.36
X	LH/F DISC WHEEL	1.00	557.10	00.00	557.10
X	LH/F SHOCK-ABSORBER	1.00	822.79	00.00	822.79
X	LH/F STEERING KNUCKLE	1.00	1208.64	00.00	1208.64
X	LH/F TRUST ARM	1.00	577.59	00.00	577.59
X	LH/F LOWER CONTROL ARM	1.00	592.02	00.00	592.02
X	LH/F UPPER CONTROL ARM	1.00	792.13	00.00	792.13
X	LH/F WHEEL HUB	1.00	524.09	00.00	524.09
X	BIHEXAGONAL NUT	2.00	10.17	00.00	20.34
X	NUT	2.00	3.53	00.00	7.06
X	NUT W FLANGE, BINDING	1.00	6.68	00.00	6.68
X	SCREW W RND. HEXAL. HEAD	2.00	11.13	00.00	22.26
X	SCREW W RND. HEXAL. HEAD	2.00	15.64	00.00	31.28
X	NUT-A-WASHER ASSEMBLY	2.00	10.17	00.00	20.34
X	HEXAGON NUT	2.00	4.32	00.00	8.64
X	LH/F STRUT	1.00	42.56	00.00	42.56
X	CONSOLE	1.00	202.17	00.00	202.17
X	FRT UNDER CARRIAGE COVER	1.00	181.26	00.00	181.26
X	SRS ACCELERATION SENSOR	1.00	133.00	00.00	133.00
X	HEXALOBULAR BOLT	1.00	1.21	00.00	1.21
X	SCREW	10.00	5.50	00.00	55.00

Confirmed &amp; accepted by

7% GST on 24833.45  
Total Payable 26,571.79

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

# ESTIMATE FOR SLD5585H

## SUPPLEMENTARY

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555  
62507388

Taufikh

Vehicle & Document Information  
WIP No 25413  
Reg No/Reg Date SLD5585H / 16/12/2014  
Date In/Mileage 23/07/2018/ 80409  
Chassis No WDD2050402R009988  
Engine No 27491030216279  
Make/Model MB/MB C 180 SEDAN (W205) \*EXCLUSIVE / EX  
Colour/Trim 027 775 Iridium Sil/ 041 101 Learther AR

Account No	Terms	Date/Time Printed	CSE	Operator				
WL001605	Credit	29/09/2018/ 14:39	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN								
POLICY NO/ACC DATE : V0101343 // 19-07-2018								
DRIVE IN: 20-07-2018 // TP CAR NO: SKZ4774G (LONPAC INS)								
DATE IN/DATE SURVEY: 23-07-2018 // LKK TAUFIKH								
BY/AUTHORIZED ON : VIC ALEPH // 06-08-2018								
X BIHEXAGONAL NUT					2.00	10.17	00.00	20.34
X NUT					2.00	3.53	00.00	7.06
X NUT W FLANGE, BINDING					1.00	6.68	00.00	6.68
X SCREW W RND. HEXAL. HEAD					2.00	11.13	00.00	22.26
X SCREW W RND. HEXAL. HEAD					2.00	15.64	00.00	31.28
X NUT-A-WASHER ASSEMBLY					2.00	10.17	00.00	20.34
X HEXAGON NUT					2.00	4.32	00.00	8.64
X LH/F STRUT					1.00	42.56	00.00	42.56
X CONSOLE					1.00	202.17	00.00	202.17
X SRS ACCELERATION SENSOR					1.00	133.00	00.00	133.00
X HEXALOBULAR BOLT					1.00	1.21	00.00	1.21
X SCREW					10.00	5.50	00.00	55.00

## SUPPLEMENTARY

Alan Quek  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272  
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on Nett 550.54 38.54  
Total Payable 589.08

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/07/2018 11:32
Date Of Accident	19/07/2018 16:55
Exact Location Of Accident	TANJONG PENJURU ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD5585H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TANG JOO KIM
NRIC No	S1633132E
Email Address	GIBTANG64@GMAIL.COM
Mobile Phone No	(LOCAL) +65-82885585
Alternative Phone No	OFFICE-82885585
<b>Vehicle Particulars</b>	
Manufacturer	MERCEDES-BENZ
Model	C180 EXCLUSIVE (R17 LED SR)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	V0101343
<b>Driver</b>	
Name of Driver	TANG JOO KIM
NRIC No	S1633132E
Date Of Birth	28/04/1964
Occupation	INDOOR
Date Of Driving Pass	23/01/1987
Driving Experience	31 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82885585
Fax Number	
Contact Number	OFFICE-82885585
EEmail Address	GIBTANG64@GMAIL.COM

Address	168 WOODLANDS STREET 11 #06-141
Postcode	730168
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ4774G
Vehicle Make/Model/Colour	INFINITI / Q50 / WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG MING HUI
NRIC/Passport Number	S8129844J
Contact Number	96630637
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time

20/7/18

1145am


Driver's Signature  
(if driver is not the policyholder)  
Date & Time

IMFORTDELGRU ENGINEERING PTE LTD  
45 PANDAN ROAD  
SINGAPORE 609288  
TEL 6338 8778 FAX 6262 6950  
Reporting Centre Personnel's Signature  
Name: Vo Yung Khay  
NRIC / Fin No.: 62638977T



# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19/7/2018 at about 1655 hrs. while I was travelling along Tanjong Pagar Road. There was a vehicle (SKN 47746) in front of me. ~~He~~ ~~the~~ ~~driver~~ The vehicle filtered into the entrance of the building along the road. while I was just about to pass ~~that~~ through his vehicle on his right, the ~~same~~ driver suddenly turn and his vehicle ~~and~~, I turn and jammed brake to avoid collision but it was too late. His vehicle hit ~~on~~ ~~the~~ ~~front~~ ~~left~~ ~~side~~ ~~of~~ my vehicle and caused damage to my vehicle. The weather is sunny and the road is dry at the point of the accident.

## IMPORTANT NOTE

Under General Condition - Conduct of Claim of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time

20/7/18  
1145am

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

RAFFORTDELGRU ENGINEERING PTE LTD  
45 PANDAN ROAD  
SINGAPORE 609268  
TEL: 6338 8778 FAX: 6262 6955

Reporting Centre Person's Signature  
Name: Vo Yang Khong  
NRIC / Fin No.: 626389977

Page 6

← Cover Note.pdf  
 For Customer Service, contact us at:  
 1 Pickering Street, Great Eastern Centre, Singapore 048659  
 Tel: +65 6248 2888 Fax: +65 6327 3080



Policy No: V0101343

Date of Issue: 25/05/2018 16:00:25

## TEMPORARY CERTIFICATE OF INSURANCE

I/We hereby certify that this Cover Note is issued in accordance with the provisions of Part IV of the Road Transport Act, 1987 (Malaysia) the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189 of the Revised Edition) (Republic of Singapore).

Insured Name: MR TANG JOO KIM

Period of Insurance: From: 16/05/2018 (0000HRS) To: 15/06/2019

Registration No. SLD5585H

Make &amp; Model: MERCEDES BENZ C180 EXCLUSIVE

Type of Cover: Comprehensive any Workshop

This Cover Note is valid for a period of 14 days from Issue Date.

A valid Certificate of Insurance will be issued by Great Eastern General Insurance Limited (GEG) within Three (3) working days covering the same Period of Insurance as indicated above.

Subject to the above Policy's existing terms, conditions and exceptions.

  
 Authorised Signature

Z0000524

Great Eastern General Insurance Limited (Reg. No. 1924 (P) (03/07))  
 1 Pickering Street, #01-01 Great Eastern Centre, Singapore 048659  
 (A wholly owned subsidiary of Great Eastern Life Assurance Co. Limited)

Page 1

## Shu Pei (LKKAUTO)

---


**From:** Alan Quek Ai Lun <alan.quek@cyclecarriage.com.sg>  
**Sent:** Monday, 23 July 2018 11:55 AM  
**To:** GERALD POH WEE BIN  
**Cc:** MT\_Claim\_SG; Admin-D (LKKAUTO); Admin A; Thin Thin (LKKAUTO); Zayyer (LKKAUTO); Vivian Lau (LKKAUTO); SUR  
**Subject:** RE: SLD5585H / SKZ4774G Date of accident:19-07-2018

Dear LKK,

Car is in 188 Pandan Loop Cycle & Carriage, kindly arrange for survey. Thank you.

Your Sincerely

Alan Quek  
Service Advisor  
Mercedes-Benz Body Care & Repair Center  
Cycle & Carriage Industries Pte Ltd  
188 Pandan Loop Service Center  
Tel: 6771 4377 | DID: 9186 5112 | Fax: 6872 1272  
Website: [www.mercedes-benz.com.sg](http://www.mercedes-benz.com.sg)



CYCLE & CARRIAGE

Exceptional Journeys



Care Excellence Respect



Please consider the environment before printing this e-mail.

**From:** GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]  
**Sent:** Monday, 23 July 2018 11:46 AM  
**To:** Alan Quek Ai Lun  
**Cc:** MT\_Claim\_SG; admin-d@lkkauto.com  
**Subject:** RE: SLD5585H / SKZ4774G Date of accident:19-07-2018

WITHOUT PREJUDICE

Our Ref : 18/18/18/ VP05/020770

Dear Alan,

We shall appoint LKK Auto Consultants Pte Ltd to survey the vehicle and revert on direct settlement.

Aside to LKK – Attn: Catherine

Kindly arrange to survey the vehicle.

Best Regards

Gerald Poh

Senior Claims Executive | Lompac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

**From:** Alan Quek Ai Lun [<mailto:alan.quek@cyclecarriage.com.sg>]

**Sent:** Monday, 23 July, 2018 11:32 AM

**To:** MT\_Claim\_SG

**Subject:** SLD5585H / SKZ4774G Date of accident:19-07-2018

**LONPAC INSURANCE BHD**

Attn: Motor Claims Dept

RE: Accident involving motor vehicle nos. **SLD 5585 H & SKZ 4774 G.**

Along **TANJONG PENJURU ROAD.**

We have instructs by our client's of motor vehicle no:**SLD 5585 H**, which was involved in the above accident. Our client's vehicle was damaged and. We now claiming against you for costs of repair and other consequential loss.

In order that you are the insurer of vehicle no:**SKZ 4774 G** are willing to **DIRECT SETTLEMENT** and other incidental claims. We shall be grateful if you could kindly settle the cost of repair directly with us. On this note we will be much appreciated and looking forward to your Confirmation of settlement.

Your Sincerely

Alan Quek

Service Advisor


Mercedes-Benz Body Care & Repair Center

Cycle & Carriage Industries Pte Ltd

188 Pandan Loop Service Center

Tel: 6771 4377 | DID: 9186 5112 | Fax: 6872 1272

Website: [www.mercedes-benz.com.sg](http://www.mercedes-benz.com.sg)



**CYCLE & CARRIAGE**



Please consider the environment before printing this e-mail.

Exceptional Journeys



Care. Excellence. Respect.

**DISCLAIMER:-** This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and

destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.



For Customer Service, contact us at:  
1 Pick Up  
Great Eastern Centre, Singapore 046559  
Tel: +65 6248 2888 Fax: +65 6327 3080



Policy No: V0101343

Date of Issue: 25/05/2018 16:00:25

TEMPORARY CERTIFICATE OF INSURANCE

I/We hereby certify that this Cover Note is issued in accordance with the provisions of Part IV of the Road Transport Act, 1987 (Malaysia) the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189 of the Revised Edition) (Republic of Singapore).

Insured Name: MR TANG JOO KIM

Period of Insurance: From: 16/06/2018 (0000HRS) To: 15/06/2019

Registration No. SLD5585H

Make & Model: MERCEDES BENZ C180 EXCLUSIVE

Type of Cover: Comprehensive any Workshop

This Cover Note is valid for a period of 14 days from Issue Date.

A valid Certificate of Insurance will be issued by Great Eastern General Insurance Limited (GEG) within Three (3) working days covering the same Period of Insurance as indicated above.

Subject to the above Policy's existing terms, conditions and exceptions.

Authorised Signature

Z0000524

Great Eastern General Insurance Limited (Reg No: 19/0/00005W)  
1 Pickering Street, 401-01, Great Eastern Centre, Singapore (48650)  
(A public limited liability company of Great Eastern Insurance Company, Limited)

Page 1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18013369/T1kb3s2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 21-10-2019		
		Code : LPC2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKZ 4774G	Veh. Inspected	SLD 5585H	
Policy No.	Z18VP05017170	Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020770	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	23/07/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ C180	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WDD2050402R009988	Colour	SILVER	
Odometer	80409	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	CONTINENTAL	6 mm	
L/H Front Tyre	225/50 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	19/07/2018	Inspection Date	23/07/2018	
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 5585H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	FRT BUMPER (SN)	DEFORMED	1,375.37	1,375.37
1	LH/F BUMPER BRACKET (SN)	DEFORMED	11.22	11.22
1	LH/F BOTTOM GRILLE (SN)	MISSING	63.93	63.93
1	LH/F BASIC MOUNTING FOR BUMPER (SN)	DEFORMED	68.53	68.53
1	FRT BASIC MOUNTING FOR BUMPER (SN)	NOT NECESSARY	102.80	-
1	CT/F IMPACT ABSORBER (SN)	NOT NECESSARY	149.56	-
1	LH/F OUTER PARKING SENSOR (SN)	DISTORTED	172.07	172.07
2	LH/F PARKING SENSOR (SN)	NOT NECESSARY	344.14	-
3	LH/F PARKING SENSOR SEAL (SN)	NECESSARY	19.26	19.26
1	CT/F BOTTOM GARNISH (SN)	NOT NECESSARY	172.64	-
1	LH/F FENDER (SN)	BENT	881.86	881.86
1	LH/H WHEEL ARCH (SN)	DEFORMED	120.19	120.19
1	RADIATOR GRILLE (SN)	CRACKED	1,388.66	1,388.66
1	BONNET (SN)	BENT	1,999.27	1,999.27
1	LH/F BONNET HINGE (SN)	BENT	181.73	181.73
1	RH/F BONNET HINGE (SN)	BENT	181.73	181.73
2	BONNET ACTUATOR (SN)	ACTIVATED	362.70	362.70
2	BONNET SPRING ELEMENT (SN)	NOT NECESSARY	59.82	-
2	BONNET UPPER CATCH (SN)	NOT NECESSARY	65.54	-
2	BONNET LOWER CATCH (SN)	NOT NECESSARY	125.18	-
1	FRT END SUPPORT TOP MEMBER (SN)	BENT	691.68	691.68
1	FRT CROSS MEMBER (SN)	BENT	407.90	407.90
1	LH/F CROSS MEMBER BRACKET (SN)	BENT	67.58	67.58
1	LH/F CROSS MEMBER ABSORBER (SN)	NOT NECESSARY	88.69	-
1	LH/F HEADLAMP (SN)	CRACKED	3,126.25	3,126.25
1	LH/F HEADLAMP CONTROL UNIT (SN)	DISTORTED	571.36	571.36
1	FRT UNDER CARRIAGE COVER (SN)	NOT NECESSARY	181.26	-
1	LH/F DISC WHEEL (SN)	CUT	557.10	557.10
1	LH/F SHOCK-ABSORBER (SN)	BENT	822.79	822.79
1	FRT TORSION BAR (SN)	NOT NECESSARY	564.05	-
1	LH/F TORSION BAR ROD (SN)	NOT NECESSARY	82.55	-

Report Ref No. CC4/LPC18013369/T1kb3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LH/F STEERING KNUCKLE (SN)	BENT	1,208.64	1,208.64
1	LH/F TRUST ARM (SN)	BENT	577.59	577.59
1	LH/F LOWER CONTROL ARM (SN)	BENT	592.02	592.02
1	LH/F TRUST ARM BUSHING (SN)	NOT NECESSARY	182.37	-
1	LH/F UPPER CONTROL ARM (SN)	BENT	792.13	792.13
1	LH/F WHEEL HUB (SN)	BENT	524.09	524.09
1	FRONT LEFT RIM (SN)	CUT	60.00	60.00
2	BIHEXAGONAL NUT (SN) (ADDITIONAL)	NECESSARY	20.34	20.34
2	NUT (SN) (ADDITIONAL)	NECESSARY	7.06	7.06
1	NUT W FLANGE, BINDING (SN) (ADDITIONAL)	NECESSARY	6.68	6.68
2	SCREW W RND, HEXAL. HEAD (SN) (ADDITIONAL)	NECESSARY	22.26	22.26
2	SCREW W RND, HEXAL. HEAD (SN) (ADDITIONAL)	NECESSARY	31.28	31.28
2	NUT-A-WASHER ASSEMBLY (SN) (ADDITIONAL)	NECESSARY	20.34	20.34
2	HEXAGON NUT (SN) (ADDITIONAL)	NECESSARY	8.64	8.64
1	LH/F STRUT (SN) (ADDITIONAL)	BENT	42.56	42.56
1	CONSOLE (SN) (ADDITIONAL)	DEFORMED	202.17	202.17
1	FRT UNDER CARRIAGE COVER (SN) (ADDITIONAL)	DEFORMED	181.26	181.26
1	SRS ACCELERATION SENSOR (SN) (ADDITIONAL)	NECESSARY	133.00	133.00
1	HEXALOBULAR BOLT (SN) (ADDITIONAL)	NECESSARY	1.21	1.21
10	SCREW (SN) (ADDITIONAL)	NECESSARY	55.00	55.00
			19,676.05	17,557.45
	<b>LABOUR</b>			
	USE XENTRY TO CHECK CONTROL UNIT & RESET MEMORY TO STANDARD SETTINGS.		380.00	380.00
	CHECK HEADLAMP WITH FOCUS ADJUSTMENT.		96.00	96.00
	ACCIDENT TOWING FROM 2 TG PENJURU TO PLSC USING CAR CARRIER.		140.00	140.00
	INSPECT & CONDUCT WHEEL ALIGNMENT.		540.00	540.00
	REMOVE & REPLACE FRONT BUMPER, FRONT LEFT FENDER, FRONT BONNET & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.		2,880.00	2,400.00
	RESPRAY FRONT BUMPER, FRONT BONNET & FRONT LEFT FENDER.		2,200.00	1,800.00

Report Ref No. CC4/LPC18013369/T1kb3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & INSTALL FRONT SUSPENSION & WHEEL BASE.		2,400.00	1,920.00
			8,636.00	7,276.00
	<b>GRAND TOTAL</b>		<b>28,312.05</b>	<b>24,833.45</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>24,833.45</b>

Report Ref No. CC4/LPC18013369/T1kb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever in contract or tort is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.