



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLD5585H

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

25413
SLD5585H / 16/12/2014
0
WDD2050402R009988
27491030216279
MB/MB C 180 SEDAN (W205) "EXCLUSIVE / EX
027 775 Iridium Sil/ 041 101 Learther AR

odo:
80409

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	23/07/2018/ 11:26	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :V0101343 // 19-07-2018 DRIVE IN:20-07-2018 // TP CAR NO:SKZ4774G (LONPAC INS) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT				96.00
S BPNTOW ACCIDENT TOWING FROM 2 TG PENJURU TO PLSC USING CAR CARRIER WO: 150398				140.00
S BPNSUB SUPPLY & TRANSFER 1PC FRONT LEFT RIM PURCHASE ORDER NO:				60.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				540.00
A BPILAB REMOVE & REPLACE FRONT BUMPER, FRONT LEFT FENDER, FRONT BONNET & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.				2880.00
A BPIRES RESPRAY FRONT BUMPER, FRONT BONNET & FRONT LEFT FENDER			0.03	2200.00
A BPILAB REMOVE & INSTALL FRONT SUSPENSION & WHEEL BASE				2400.00
M FRT BUMPER	1.00	1375.37	00.00	1375.37
M LH/F BUMPER BRACKET	1.00	11.22	00.00	11.22
M LH/F BOTTOM GRILLE	1.00	63.93	00.00	63.93
M LH/F BASIC MOUNTING FOR BUMPER	1.00	68.53	00.00	68.53
M FRT BASIC MOUNTING FOR BUMPER	1.00	102.80	00.00	102.80
M CT/F IMPACT ABSORBER	1.00	149.56	00.00	149.56
M LH/F OUTER PARKING SENSOR	1.00	172.07	00.00	172.07

Confirmed & accepted by

Authorized signatory and company stamp

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLD5585H

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information
WIP No **25413**
Reg No/Reg Date **SLD5585H / 16/12/2014**
Date In/Mileage **/ 0**
Chassis No **WDD2050402R009988**
Engine No **27491030216279**
Make/Model **MB/MB C 180 SEDAN (W205) "EXCLUSIVE / EX**
Colour/Trim **027 775 Iridium Sil/ 041 101 Learther AR**

Account No	Terms	Date/Time Printed	CSE	Operator			
WL001605	Credit	23/07/2018/ 11:26	AQ	305 / Alan Quek Ai Lun			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	LH/F PARKING SENSOR			2.00	172.07	00.00	? 344.14
M	LH/F PARKING SENSOR SEAL			3.00	6.42	00.00	all 19.26
M	CT/F BOTTOM GARNISH			1.00	172.64	00.00	X 172.64
M	LH/F FENDER			1.00	881.86	00.00	bt 881.86
M	LH/F WHEEL ARCH			1.00	120.19	00.00	de 120.19
M	RADIATOR GRILLE			1.00	1388.66	00.00	ang 1388.66
M	BONNET			1.00	1999.27	00.00	bt 1999.27
M	LH/F BONNET HINGE			1.00	181.73	00.00	? 181.73
M	RH/F BONNET HINGE			1.00	181.73	00.00	? 181.73
M	BONNET ACTUATOR			2.00	181.35	00.00	net 362.70
M	BONNET SPRING ELEMENT			2.00	29.91	00.00	X 59.82
M	BONNET UPPER CATCH			2.00	32.77	00.00	? 65.54
M	BONNET LOWER CATCH			2.00	62.59	00.00	? 125.18
M	FRT END SUPPORT TOP MEMBER			1.00	691.68	00.00	bt 691.68
M	FRT CROSS MEMBER			1.00	407.90	00.00	X 407.90
M	LH/F CROSS MEMBER BRACKET			1.00	67.58	00.00	X 67.58
M	LH/F CROSS MEMBER ABSORBER			1.00	88.69	00.00	? 88.69
M	LH/F HEADLAMP			1.00	3126.25	00.00	cur 3126.25
M	LH/F HEADLAMP CONTROL UNIT			1.00	571.36	00.00	dis 571.36
M	FRT UNDER CARRIAGE COVER			1.00	181.26	00.00	? 181.26
M	LH/F DISC WHEEL			1.00	557.10	00.00	cut 557.10
M	LH/F SHOCK-ABSORBER			1.00	822.79	00.00	822.79
M	FRT TORSION BAR			1.00	564.05	00.00	564.05
M	LH/F TORSION BAR ROD			1.00	82.55	00.00	82.55
M	LH/F STEERING KNUCKLE			1.00	1208.64	00.00	1208.64
M	LH/F TRUST ARM			1.00	577.59	00.00	? 577.59
M	LH/F LOWER CONTROL ARM			1.00	592.02	00.00	? 592.02
M	LH/F TRUST ARM BUSHING			1.00	182.37	00.00	182.37
M	LH/F UPPER CONTROL ARM			1.00	792.13	00.00	792.13
M	LH/F WHEEL HUB			1.00	524.09	00.00	524.09

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 27,580.25
7% GST on 27580.25 1930.62

Authorized signatory and company stamp

Total Payable 29,510.87

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany