

195210

INS. CASE OWNER:

transferred from

CC ϕ /LPC1801

3376, U *WLB* ^{SZ}

LKK:
IDAC:

Surveyor:

MARUS

DOI:

ASSIGNMENT

27/7/18

Date / Time:

27/7/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SGX 3667K

Name of Insured :

ONG YE UYE

Insured Tel No. :

HP: 96886228

Excess Sec II :SS

D.O.A: 16/6/18

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident :

Claim No. :

15/18/18/UP05/020680

Policy No. :

ZIFVPO5014686

Make / Model :

MITSUBISHI

Place of Accident :

BIK 25A LKAI KEM OPEN UP

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

FBH 3667K



INSRS:
WSP:
Tel:
Liability:
RMKS:

Proton



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
17/7/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
27/7/18	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/> <input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 27/7/18 Sent By: *Dee*

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: SS (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: 7/7/19 Confirm with: *Lee Lee* Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: NIL

Repair Cost: SS 6600.00

Loss of Rental (LOR): SS - (days)

Loss of Use (LOU): SS 160.00 (S 20 x 8 days)

Loss of Income (LOI): SS - (S x days)

LOR only LOU only LOR + LOU LOR + LOU [Tick only one]

GIA/LTA Search SS -

Medical: SS -

Disbursement: SS - (e.g. Tow/ Independent)

Legal Cost SS -

Total: SS 6760.00 Global Sum SS:

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: SS 6760.00 Name 1: *Enrika Motor Trading Pte Ltd*

Payee 2: (Strike if N.A.) SS Name 2:

Payee 3: (Strike if N.A.) SS Name 3:

COPY SENT 15/7/19

27/7/19



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD	Ref : CC4/LPC18013376/Uwb3
300 BEACH ROAD	Date : 23-07-2018
#17-04/07 THE CONCOURSESINGAPORE 199555	Code : LPC2



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGX 3662K	Veh. Inspected	FBH 7267K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	23/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/06/2018	Inspection Date	23/07/2018
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
 B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC18013376/Uwb3

Date: 24.07.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.


FBH7267K

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23.07.2018 at the premises of M/s Erofia Motor Trading Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	19,949.80
Revised Estimate Amount	: S\$	6,297.20
"Check" Items Amount	: S\$	6,429.90
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
N/S Body & Front Portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 6 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

clear
W
compac

No of Authoent
2 bike
2/s #6600/-

Owner : Mohd Anand Bin Ibrahim

Accident Date : 16 Jun 2018

Vehicle No : FBH 7267 K

Vehicle Model : Kawasaki 1300

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ Cnc 285.00
1	Front fender inner bracket	\$ Brl 155.00
1	Fork tube assy -L/H <i>1105</i>	\$ Brl 1,732.00
1	Fork tube assy -R/H	\$ 2 1,732.00
1	Fork under bracket	\$ 17 985.00
1	Front rim shaft	\$ 12 75.00
2	Front brake discs <i>485</i>	<i>ns</i> \$ Brl 1,218.00 <i>ipc</i>
1	Front sport rim	\$ 2 1,950.00
1	Top cowling	\$ Cnc 645.00
1	Windshield	\$ AN 355.00
1	Lampstay <i>288</i>	\$ Brl 509.00
1	Headlamp	\$ Sw 1,205.00
2	Side mirrors <i>265</i>	<i>n/s</i> \$ Sw 530.00 <i>ipc</i>
2	Handle bars	\$ 17 510.00
2	Handle bar ends	\$ 17 120.00
1	Hand grip (1 set)	\$ 17 120.00
1	Clutch lever	\$ 11 155.00
1	Brake lever	\$ 17 155.00
2	Front signals	\$ 11 180.00
2	Side fairings <i>738</i>	<i>n/s cnc</i> \$ 1,476.00 <i>ipc</i>
1	Lower fairing	\$ Cnc 455.00
1	Meter assy	\$ 11 1,478.00
1	Meter panel	\$ AN 247.00
1	Engine cover -L.H	\$ D3 455.00
1	Front footrest	\$ BAO 85.00
1	Front footrest bracket	\$ Brl 135.00
1	Gear pedal	\$ Brl 185.00
1	Rear footrest	\$ Sw 85.00
1	Rear footrest bracket	\$ Brl 135.00
1	Fuel tank cover	\$ AN 455.00
1	Side stand	\$ Brl 95.00
1	Main stand	\$ 2 145.00
1	Rear fairing -L/H	\$ R 515.00
		\$ 18,562.00
Less 10%		\$ 1,856.20
		\$ 16,705.80

6716
6044-4

c/f: \$ 16,705.80

Special Nett Items

1	Number plate (1 set)	\$ 11	28.00	X
2	Fork oils	\$ 2u	40.00	2
2	Fork oil seals	\$ 2u	76.00	7
1	Steering cone (1 set)	\$ 2u	120.00	7
1	Front tyre	\$ 11	200.00	X
1	Side fairing slider (1 set)	\$ 2u1	180.00	—
3	Engine oils	\$ 2u	45.00	50%
1	Engine cover gasket	\$ 2u	45.00	—
1	Side box (1 set)	\$ 2u	1,300.00	1000
		\$	<u>2,034.00</u>	

S/No. Labour

1	To provide towing service.	\$	50.00	35
2	To check wiring and reset headlamp focusing.	\$	11 80.00	X
3	To provide labour.	\$	480.00	400
4	To respray painting.	\$	600.00	400
		\$	<u>1,210.00</u>	

8362.9
6690.

Grand Total \$ 19,949.80

Dollars: Nineteen Thousand Nine Hundred Forty-Nine And Eighty Cents Only.



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

compac

Owner : Mohd Anand Bin Ibrahim

*No of Attachment
2 fork*

Accident Date : 16 Jun 2018

Vehicle No : FBH 7267 K

2/59

Vehicle Model : Kawasaki 1300

Estimated Repair Costs

Qty	Description		Amount S(\$)	
	<u>List Items</u>			
1	Front fender	<i>627.</i>	\$ <i>cm</i> 285.00	<i>23/7/18</i>
1	Front fender inner bracket		\$ 155.00	
1	Fork tube assy -L/H	<i>photo scene.</i>	\$ <i>2</i> 1,732.00	<i>?</i>
1	Fork tube assy -R/H		\$ <i>2</i> 1,732.00	<i>?</i>
1	Fork under bracket		\$ <i>17</i> 985.00	<i>x</i>
1	Front rim shaft		\$ <i>17</i> 75.00	<i>x</i>
2	Front brake discs		\$ 1,218.00	<i>?</i>
1	Front sport rim		\$ <i>2</i> 1,950.00	<i>x</i>
1	Top cowling		\$ <i>cm</i> 645.00	<i>—</i>
1	Windshield		\$ 355.00	<i>?</i>
1	Lampstay		\$ 509.00	<i>?</i>
1	Headlamp		\$ <i>520</i> 1,205.00	<i>—</i>
2	Side mirrors	<i>@7050/s</i>	\$ <i>520</i> 530.00	<i>2c</i>
2	Handle bars		\$ <i>17</i> 510.00	<i>x</i>
2	Handle bar ends		\$ <i>17</i> 120.00	<i>x</i>
1	Hand grip (1 set)		\$ <i>17</i> 120.00	<i>x</i>
1	Clutch lever		\$ <i>17</i> 155.00	<i>x</i>
1	Brake lever		\$ <i>17</i> 155.00	<i>x</i>
2	Front signals		\$ 180.00	<i>?</i>
2	Side fairings	<i>@728 n/s cm</i>	\$ 1,476.00	<i>2c</i>
1	Lower fairing	<i>ntsa</i>	\$ <i>cm</i> 455.00	<i>1c</i>
1	Meter assy		\$ <i>17</i> 1,478.00	<i>x</i>
1	Meter panel		\$ <i>17</i> 247.00	<i>x</i>
1	Engine cover -L.H		\$ <i>20</i> 455.00	<i>—</i>
1	Front footrest		\$ <i>320</i> 85.00	<i>—</i>
1	Front footrest bracket		\$ <i>31</i> 135.00	<i>—</i>
1	Gear pedal		\$ <i>31</i> 185.00	<i>—</i>
1	Rear footrest		\$ <i>52</i> 85.00	<i>x</i>
1	Rear footrest bracket		\$ <i>31</i> 135.00	<i>—</i>
1	Fuel tank cover		\$ 455.00	<i>?</i>
1	Side stand		\$ <i>31</i> 95.00	<i>—</i>
1	Main stand		\$ <i>2</i> 145.00	<i>x</i>
1	Rear fairing -L/H		\$ 515.00	<i>?</i>
			\$ 18,562.00	
	Less 10%		\$ 1,856.20	
			\$ 16,705.80	

Special Nett Items

1	Number plate (1 set)	\$	28.00	?
2	Fork oils	\$	40.00	?
2	Fork oil seals	\$	76.00	?
1	Steering cone (1 set)	\$	120.00	?
1	Front tyre	\$	11 200.00	X
1	Side fairing slider (1 set)	\$	721 180.00	—
3	Engine oils	\$	22.5 45.00	50%
1	Engine cover gasket	\$	45.00	—
1	Side box (1 set)	\$	1,300.00	100%
		\$	<u>2,034.00</u>	

<u>S/No.</u>	<u>Labour</u>			
1	To provide towing service.	\$	50.00	35
2	To check wiring and reset headlamp focusing.	\$	11 80.00	X
3	To provide labour.	\$	480.00	400
4	To respray painting.	\$	600.00	400
		\$	<u>1,210.00</u>	

Grand Total \$ 19,949.80

Dollars: Nineteen Thousand Nine Hundred Forty-Nine And Eighty Cents Only.



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC18013376/Udb3s2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 19-07-2019	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGX 3662K	Veh. Inspected	FBH 7267K
Policy No.	Z17VP05014686	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020680	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	23/07/2018
2. Vehicle Particulars & Condition			
Make & Model	KAWASAKI 1400 GTR M	c.c	1352
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JKBZGT40CCA016000	Colour	ORANG
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/70ZR17	MICHELIN	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	190/50ZR17	MICHELIN	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/06/2018	Inspection Date	23/07/2018
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 7267K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER	CRACKED	285.00	285.00
1	FRONT FENDER INNER BRACKET	BENT	155.00	155.00
1	FORK TUBE ASSY - L/H	DENTED / BENT	1,732.00	1,105.00
1	FORK TUBE ASSY - R/H	TO REPAIR SEE LABOUR	1,732.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	985.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	75.00	-
2	FRONT BRAKE DISCS	N/S BENT	1,218.00	485.00
1	FRONT SPORT RIM	TO REPAIR SEE LABOUR	1,950.00	-
1	TOP COWLING	CRACKED	645.00	645.00
1	WINDSHIELD	NOT NECESSARY	355.00	-
1	LAMPSTAY	BENT	509.00	288.00
1	HEADLAMP	BROKEN	1,205.00	1,205.00
2	SIDE MIRRORS	N/S BROKEN	530.00	265.00
2	HANDLE BARS	NOT NECESSARY	510.00	-
2	HANDLE BAR ENDS	NOT NECESSARY	120.00	-
1	SET HAND GRIP	NOT NECESSARY	120.00	-
1	CLUTCH LEVER	NOT NECESSARY	155.00	-
1	BRAKE LEVER	NOT NECESSARY	155.00	-
2	FRONT SIGNALS	NOT NECESSARY	180.00	-
2	SIDE FAIRINGS	N/S CRACKED	1,476.00	738.00
1	LOWER FAIRING	CRACKED	455.00	455.00
1	METER ASSY	NOT NECESSARY	1,478.00	-
1	METER PANEL	NOT NECESSARY	247.00	-
1	ENGINE COVER - L/H	DENTED	455.00	455.00
1	FRONT FOOTREST	BROKEN	85.00	85.00
1	FRONT FOOTREST BRACKET	BENT	135.00	135.00
1	GEAR PEDAL	BENT	185.00	185.00
1	REAR FOOTREST	SERVICEABLE	85.00	-
1	REAR FOOTREST BRACKET	BENT	135.00	135.00

Report Ref No. CC4/LPC18013376/Udb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FUEL TANK COVER	NOT NECESSARY	455.00	-
1	SIDE STAND	BENT	95.00	95.00
1	MAIN STAND	TO REPAIR SEE LABOUR	145.00	-
1	REAR FAIRING - L/H	TO REPAIR SEE LABOUR	515.00	-
	LESS 10% DISCOUNT		-1,856.20	-671.60
			16,705.80	6,044.40
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN)	NOT NECESSARY	28.00	-
2	FORK OILS (SN)	NECESSARY	40.00	40.00
2	FORK OIL SEALS (SN)	NECESSARY	76.00	76.00
1	SET STEERING CONE (SN)	NECESSARY	120.00	120.00
1	FRONT TYRE (SN)	NOT NECESSARY	200.00	-
1	SET SIDE FAIRING SLIDER (SN)	TWISTED	180.00	180.00
3	ENGINE OILS (50%) (SN)	NECESSARY	45.00	22.50
1	ENGINE COVER GASKET (SN)	NECESSARY	45.00	45.00
1	SET SIDE BOX (SN)	CRACKED	1,300.00	1,000.00
			2,034.00	1,483.50
	<u>LABOUR</u>			
	TO PROVIDE TOWING SERVICE.		50.00	35.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF FORK TUBE ASSY - R/H, FRONT SPORT RIM, MAIN STAND AND REAR FAIRING - L/H.		480.00	400.00
	TO RESPRAY PAINTING.		600.00	400.00
			-	-
			-	-
			-	-
			1,210.00	835.00
	GRAND TOTAL		19,949.80	8,362.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,600.00

Report Ref No. CC4/LPC18013376/Udb3s2



Report Ref No. CC4/LPC18013376/Udb3s2

A handwritten signature in black ink, appearing to read 'Chua'.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.