

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

LOMPAC

*No of Authorized
L/5 3*

Owner : Mohd Anand Bin Ibrahim

Accident Date : 16 Jun 2018

Vehicle No : FBH 7267 K

Vehicle Model : Kawasaki 1300

Estimated Repair Costs

Qty	Description <u>List Items</u>	Amount S(\$)
	<i>6 L/5 23/7/18</i>	
1	Front fender	\$ <i>Cru</i> 285.00
1	Front fender inner bracket	\$ 155.00 ?
1	Fork tube assy -L/H	\$ <i>2</i> 1,732.00 <i>2?</i>
1	Fork tube assy -R/H	\$ <i>2</i> 1,732.00 <i>2?</i>
1	Fork under bracket	\$ <i>17</i> 985.00 <i>x</i>
1	Front rim shaft	\$ <i>17</i> 75.00 <i>x</i>
2	Front brake discs	\$ 1,218.00 ?
1	Front sport rim	\$ <i>1</i> 1,950.00 <i>x</i>
1	Top cowling	\$ <i>Cru</i> 645.00
1	Windshield	\$ 355.00 ?
1	Lampstay	\$ 509.00 ?
1	Headlamp	\$ <i>520</i> 1,205.00
2	Side mirrors	\$ <i>520</i> 530.00 <i>2C</i>
2	Handle bars	\$ <i>17</i> 510.00 <i>x</i>
2	Handle bar ends	\$ <i>17</i> 120.00 <i>x</i>
1	Hand grip (1 set)	\$ <i>17</i> 120.00 <i>x</i>
1	Clutch lever	\$ <i>17</i> 155.00 <i>x</i>
1	Brake lever	\$ <i>17</i> 155.00 <i>x</i>
2	Front signals	\$ 180.00 ?
2	Side fairings	\$ <i>728</i> <i>1/5 Cru</i> 1,476.00 <i>2C</i>
1	Lower fairing	\$ <i>Cru</i> 455.00 <i>1C</i>
1	Meter assy	\$ <i>17</i> 1,478.00 <i>x</i>
1	Meter panel	\$ <i>17</i> 247.00 <i>x</i>
1	Engine cover -L.H	\$ <i>20</i> 455.00
1	Front footrest	\$ <i>320</i> 85.00
1	Front footrest bracket	\$ <i>32</i> 135.00
1	Gear pedal	\$ <i>32</i> 185.00
1	Rear footrest	\$ <i>52</i> 85.00 <i>x</i>
1	Rear footrest bracket	\$ <i>32</i> 135.00
1	Fuel tank cover	\$ 455.00 ?
1	Side stand	\$ <i>32</i> 95.00
1	Main stand	\$ <i>1</i> 145.00 <i>x</i>
1	Rear fairing -L/H	\$ 515.00 ?
		\$ 18,562.00
	Less 10%	\$ 1,856.20
		\$ 16,705.80

Special Nett Items


1	Number plate (1 set)	\$	28.00	?
2	Fork oils	\$	40.00	?
2	Fork oil seals	\$	76.00	?
1	Steering cone (1 set)	\$	120.00	?
1	Front tyre	\$	11 200.00	X
1	Side fairing slider (1 set)	\$	7m 180.00	—
3	Engine oils	\$	22.5 45.00	50%
1	Engine cover gasket	\$	45.00	—
1	Side box (1 set)	\$	cm 1,300.00	100%
		\$	<u>2,034.00</u>	

S/No. Labour

1	To provide towing service.	\$	50.00	35
2	To check wiring and reset headlamp focusing.	\$	17 80.00	X
3	To provide labour.	\$	480.00	40%
4	To respray painting.	\$	600.00	40%
		\$	<u>1,210.00</u>	

Grand Total \$ 19,949.80

Dollars: Nineteen Thousand Nine Hundred Forty-Nine And Eighty Cents Only.



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: