

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

12D/A

Vehicle No : PML 8815

Vehicle Model : Yamaha 125Z

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ 17 55.00 X
2	Fork inner tubes	\$ 17 230.00 X
2	Fork outer tubes	\$ 17 240.00 X
1	Fork under bracket	\$ 17 185.00 X
1	Front brake disc	\$ 17 145.00 X
1	Front sport rim	\$ 17 280.00 X
1	Front rim shaft	\$ 17 45.00 X
1	Front rim bearing	\$ 17 40.00 X
1	Front signal	\$ 17 60.00 X
1	Headlamp	\$ 17 85.00 X
1	Handle bar	\$ 17 80.00 X
1	Handle bar end	\$ 17 28.00 X
1	Hand grip (1 set)	\$ 17 35.00 X
1	Brake lever	\$ 17 28.00 X
1	Side mirror -R/H	\$ 17 50.00 X
1	Side cowling	\$ 17 98.00 X
1	Front footrest	\$ 17 35.00 X
1	Front footrest bracket	\$ 17 48.00 X
1	Brake pedal	\$ 17 42.00 X
1	Rear footrest	\$ 17 35.00 X
1	Rear footrest bracket	\$ 17 50.00 X
1	Rear sport rim	\$ 34 280.00 —
1	Rear tailboard	\$ 17 88.00 X
1	Exhaust pipe	\$ 10 455.00 —
1	Exhaust protector	\$ 11 35.00 X
1	Rear fender	\$ 26 68.00
		\$ 2,820.00
		\$ 282.00
		\$ 2,538.00

Rear swing arm ✓ Less 10% 160 sub/mr —

c/f: \$ 2,538.00

Special Nett Items

1	Number plate (1 set) <i>Ren</i>	\$ <i>one</i>	28.00	<i>10</i>
2	Fork oils	\$ <i>11</i>	30.00	<i>Q</i>
2	Fork oil seals	\$ <i>11</i>	56.00	<i>Q</i>
1	Steering cone (1 set)	\$ <i>11</i>	75.00	<i>Q</i>
1	Front tyre	\$ <i>11</i>	120.00	<i>Q</i>
1	Rear tyre	\$ <i>one</i>	120.00	<i>60</i>
		\$	429.00	

<u>S/No.</u>	<u>Labour</u>			
1	To provide towing service.	\$	50.00	<i>35</i>
2	To provide labour.	\$	380.00	<i>200</i>
3	To repair body frame.	\$ <i>11</i>	350.00	<i>Q</i>
		\$	780.00	

Grand Total \$ 3,747.00

Dollars: Three Thousand Seven Hundred And Forty-Seven Dollars Only.


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: