

006 / CTI 150 13381, A2a302

LKK:
DAG:

DATE CASE OPENED:

ASSIGNMENT

Surveyor:

LWP

DOI:

20/8/18

Date / Time:

20/8/18

Registered in Merimen:

Pre-assign / CCU / FTE

SPR 1180



Insured Vehicle No.:

CHINA BAN XONG

Name of Insured:

Claim No.:

IRM1800262402

Policy No.:

IMPSON 3091780

Insured Tel No.:

HP:

Make / Model:

BMW

Excess Sec II :SS

D.O.A:

20/8/18

Place of Accident:

AMK AVE 37 CTE

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

CHUA YEW AIF

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

94676777

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SLN 2046P



INSRS:

WSP:

Tel:

Liability:

RMKS:

Sm



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

7/8
Am

SLN 2046P - X; SPR1180 - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of: ANSWER 12.9.18

After call ltr to OI:

07.09.18 + 43 CALLED DID NO RESPONSE. LETTER SENT TO OI.

EMAIL WSP LIABILITY CLEAR.

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

08.10.18 FILE PASSED TO TYPIST TO PREPARE REPORT.

RECEIVED 10 OCT 2018

RECEIVED 03 DEC 2018

PRELIMINARY ADVICE Date/Time: 08.10.18

Sent By: LWP

FINALIZATION

Date/Time:

Confirm with:

Confirm by: LWP

Repair Cost:

SS 10,800

(

10 days)

Reduction:

68 %

Email

Call

FINAL SETTLEMENT

Date/Time: 27.11.18

Confirm with:

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

21

If NO or B 28, Ass. Lia:

Repair Cost:

SS 10,800.00

OLD REAR ENDED TP.

Loss of Rental (LOR):

SS -

(

days)

Loss of Use (LOU):

SS 460.00

(S

80

x

12 days)

Loss of Income (LOI):

SS -

(S

x

days)

LOR only

☐

LOU only

☒

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

SS 1.45

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

4400

Total:

SS 11,761.45

Global Sum SS:

FINAL PAYMENT

Date/Time: 27.11.18

Confirm with:

Email

Call

Payee 1:

SS 11,761.45

Name:

SM Automotive

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPIED
5/12/18

Mei Kwan (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Wednesday, 25 July, 2018 9:29 AM
To: Mei Kwan (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SFR118D (OI : CAI - SNM18D03624C02) and SLN2046P (TP : LKK REF - CC6/CTI18013381/Aea3) on 20/07/2018
Attachments: leeSZ_SNM18D03624C01-SFR118D-LKKDirectSettlementAccidentLtr_CLCR95.424.pdf; MSNH18094159-SFR118D.pdf
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Elaine Cheong

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, 24 July, 2018 8:18 PM
To: Claims Dept of CTI
Cc: Lucas Lee; Elaine Cheong; Asher Sng (LKKAUTO); Hsiao Tong (LKKAUTO); Joy Irene (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving SFR118D (OI : CAI - TBA) and SLN2046P (TP : LKK REF - CC6/CTI18013381/Aea3) on 20/07/2018

WITHOUT PREJUDICE



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D03624/C01/8**

Date : **25 JULY 2018**

via Ordinary & Registered Mail

**CHUA BAN YONG
16 BEGONIA DRIVE
HOCK SWEE HILL
SINGAPORE 809874**

Dear Sir / Madam

**ACCIDENT INVOLVING SFR118D AND SLN2046P ON 20 JULY 2018
ALONG ANG MO KIO AVE 3 TOWARDS CTE**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SLN2046P**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,

Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : ASHER
Ref : CC6/CTI18013381/AEA3
Contact No : 68416051
via Email : ASHER@LKKAUTO.COM

CC : Agent - (AN0420A) - INXPRESS INSURANCE AGENCY PTE LTD

F01/LKKDS-2013

➤ **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4201E

Vehicle Details

Vehicle No.: SLN2046P
Vehicle to be Exported: No
Intended De-registration Date: 20 Jul 2018
Vehicle Make: TOYOTA
Vehicle Model: HARRIER ELEGANCE 2.0 CVT
Primary Colour: Silver
Manufacturing Year: 2016
Engine No.: 3ZRB919761
Chassis No.: ZSU600093099
Maximum Power Output: 111.0 kW (148 bhp)
Open Market Value: \$27,953.00
Original Registration Date: 26 Apr 2017
First Registration Date: 26 Apr 2017
Transfer Count: 0
Actual ARF Paid: \$31,135.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Apr 2027
PARF Rebate Amount: \$23,351.00

Intended COE Rebate Details

COE Expiry Date: 25 Apr 2027
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$51,000.00
COE Rebate Amount: \$44,363.00
Total Rebate Amount: \$67,714.00

The information contained herein is correct as at 20 Jul 2018

OK

Adrian LKK C7PI

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

20/07/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Chian

Asher

Accident date: 20/07/2018

Estimated repair cost for vehicle no: SLN2046P TOYOTA HARRIER ELEGANCE 2.0 A '1

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Rear Boot Lid Distorted		\$1,718.45 ✓
2	2	Rear Boot Lid Hinge 3 new	\$182.10	\$364.20 x
3	2	Rear Boot Lid Shock Absorber 1 new	\$374.45	\$748.90 x
4	1	Rear Boot Lid Emblem Logo 3 new		\$61.10 ✓
5	1	Rear Boot Lid Harrier Logo 1 new		\$79.90 ✓
6	1	Rear Boot Lid Number Plate 3 new		\$50.00 x
7	2	Rear Boot Lid Number Plate Lamp 1 new	\$83.10	\$166.20 x
8	1	Rear Boot Lid Centre Moulding 3 new		\$972.85 x
9	1	Rear Boot Lid Top Cover 1 new		\$378.25 x
10	2	Rear Boot Lid Side Reflector Cracked	\$242.20	\$484.40 ✓
11	1	Rear Boot Lid Inner Lock Damaged		\$581.10 ✓ 418.60
12	1	Rear Boot Lid Inner Lock Cover not new		\$377.45 x
13	1	Rear Boot Lid Inner Rubber 1st		\$374.45 ✓
14	1	Rear Boot Lid Inner Trim Board Deformed		\$581.90 ✓
15	1	Rear Boot Lid Inner Side Handle Cover not new		\$278.40 x
16	1	Rear Boot Lid Windscreen Seal new		\$125.00 ✓
17	2	Rear Boot Lid Windscreen Side Moulding not new	\$282.00	\$564.00 x
18	1	Rear Boot Lid Camera Damaged		\$550.00 ✓ 400.50
19	2	Rear Tail Lamp Cracked	\$561.60	\$1,123.20 ✓
20	2	Rear Tail Lamp Panel Repair	\$587.20	\$1,174.40 x
21	2	Rear Tail Lamp Lower Bracket new	\$132.10	\$264.20 x
22	8	Rear Tail Lamp Clip new	\$8.00	\$64.00 20
23	1	Rear Bumper Deformed		\$1,218.45 ✓
24	8	Rear Bumper Clip new	\$6.50	\$52.00 30
25	2	Rear Bumper Side Retainer new	\$131.35	\$262.70 ✓
26	1	Rear Bumper Lower Spoiler Deformed		\$561.30 ✓ 396.50
27	2	Rear Bumper Lower Spoiler Side Reflector not new	\$141.40	\$282.80 x
28	1	Rear Bumper Inner Sponge Cracked		\$182.10 ✓

29	2	Rear Bumper Mud Shield	2 Not new	\$174.45	\$348.90	x
30	8	Rear Bumper Mud Shield Clip	Not new	\$6.50	\$52.00	x
31	1	Rear Bumper Reverse Sensor	Damaged		\$380.00	200(SN) x
32	1	Rear End Panel	Distorted		\$781.90	✓
33	1	Rear End Panel Top Garnish	Deformed		\$347.45	✓
34	1	Rear End Panel Lock Sensor	Not new		\$180.00	x
35	1	Rear Spare Tyre Panel	Buckled		\$972.45	✓
36	1	Rear Spare Tyre Panel L/H Spanner Box	Deformed		\$381.90	✓
37	1	Rear Spare Tyre Panel R/H Spanner Box	Deformed		\$381.90	✓
38	1	Rear Spare Tyre Panel Top Cover Outer	Deformed		\$561.85	✓
39	1	Rear Spare Tyre Panel Top Cover Inner	Deformed		\$379.40	✓
40	1	Rear Spare Tyre Panel Trim	Not new		\$561.10	x
41	1	Rear L/H Fender	Repair		\$970.10	x
42	1	Rear L/H Fender Air Duct	Deformed		\$170.45	✓
43	1	Rear L/H Fender Glass Assy	Not new		\$561.60	x
44	2	Rear Fender Inner Trim Board	Deformed	\$781.90	\$1,563.80	1230.30 x
45	1	Rear Exhaust	Bent		\$731.35	✓
46	1	Rear Centre Exhaust	2		\$1,281.90	x
47	2	Rear Exhaust Mounting	2 Not new	\$69.90	\$139.80	x
48	1	Rear Exhaust Chrome Pipe	✓		\$278.30	x
49	1	Rear Exhaust Aluminium Cover	Not new		\$181.30	x

Subtotal:- \$24,849.15

1307610

S.N: 600

980707

Labour charges

To remove & refit cushion	\$280.00 80
To remove & refit roof lining	\$380.00 X
To remove & refit boot lid camera & windscreen camera	\$380.00 100
To remove & refit reverse sensor	\$100.00 50
To remove & refit L/H fender glass	\$100.00 X
Gum	\$40.00 X
To remove & refit rear windscreen	\$150.00 120
Gum	\$50.00 ✓
To remove & refit petrol tank	\$280.00 X
To remove & refit rear & centre exhaust	\$380.00 80
To check wiring	\$100.00 30 3160
Towing fee	\$100.00 X
Tuff kote	\$150.00 50
Panel beating	\$3,500.00 1400
Spray painting	\$2,800.00 1200

Subtotal:- \$8,790.00

Total:- \$33,639.15

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 13667.07

L/S: 108K

10 Day

108K

10 Day

Assignment

To: SM Automotive (Workshop)

In consideration for your agreement to repair my motor vehicle registration no. SN2046P and to defer demanding for payment of the cost of repair, I/we the undersigned do hereby irrevocably assign absolutely to you all the proceeds of my/our claim(s) including damages, interest, costs and expenses (including legal costs / disbursements payable on a party and party basis which are to be paid to the parties so entitled including solicitors, vehicle appraisers and other experts / consultants).

I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this 20 day of 07 2018.

Signature	:	<u>[Signature]</u>
Name	:	<u>CHONG BOON THONG</u>
ID No.	:	<u>S1354201E</u>
Address	:	<u></u>
Witness Signature	:	<u>[Signature]</u>
Witness Name	:	<u>CHENG YUE YIN</u>
Witness ID	:	<u>S8826618H</u>
Witness Address	:	<u></u>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18013381/Aea3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 05-12-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFR 118D	Veh. Inspected	SLN 2046P
Policy No.	DMPCSN3009171801	Coverage (\$)	0.00
Claim No.	SNM18D03624C02	Excess (\$)	0.00
Assign From		Assign Date	20/07/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZSU600093099	Colour	SILVER
Odometer	33441	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/65 R17	MICHELIN	6 mm
L/H Front Tyre	225/65 R17	MICHELIN	6 mm
R/H Rear Tyre	225/65 R17	MICHELIN	6 mm
L/H Rear Tyre	225/65 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	20/07/2018	Inspection Date	20/07/2018
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 2046P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	DISTORTED	1,718.45	1,718.45
2	REAR BOOT LID HINGE @\$182.10	NOT NECESSARY	364.20	-
2	REAR BOOT LID SHOCK ABSORBER @\$374.45	NOT NECESSARY	748.90	-
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	61.10	61.10
1	REAR BOOT LID HARRIER LOGO	NECESSARY	79.90	79.90
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	-
2	REAR BOOT LID NUMBER PLATE LAMP @\$83.10	NOT NECESSARY	166.20	-
1	REAR BOOT LID CENTRE MOULDING	NOT NECESSARY	972.85	-
1	REAR BOOT LID TOP COVER	NOT NECESSARY	378.25	-
2	REAR BOOT LID SIDE REFLECTOR @\$242.20	CRACKED	484.40	484.40
1	REAR BOOT LID INNER LOCK	DAMAGED	581.10	418.60
1	REAR BOOT LID INNER LOCK COVER	NOT NECESSARY	377.45	-
1	REAR BOOT LID INNER RUBBER	CUT	374.45	374.45
1	REAR BOOT LID INNER TRIM BOARD	DEFORMED	581.90	581.90
1	REAR BOOT LID INNER SIDE HANDLE COVER	NOT NECESSARY	278.40	-
1	REAR BOOT LID WINDSCREEN SEAL	NECESSARY	125.00	125.00
2	REAR BOOT LID WINDSCREEN SIDE MOULDING @\$282.00	NOT NECESSARY	564.00	-
2	REAR TAIL LAMP @\$561.60	CRACKED	1,123.20	1,123.20
2	REAR TAIL LAMP PANEL @\$587.20	TO REPAIR SEE LABOUR	1,174.40	-
2	REAR TAIL LAMP LOWER BRACKET @\$132.10	NOT NECESSARY	264.20	-
8	REAR TAIL LAMP CLIP @\$8.00	NECESSARY	64.00	20.00
1	REAR BUMPER	DEFORMED	1,218.45	1,218.45
8	REAR BUMPER CLIP @\$6.50	NECESSARY	52.00	30.00
2	REAR BUMPER SIDE RETAINER @\$131.35	NECESSARY	262.70	262.70
1	REAR BUMPER LOWER SPOILER	DEFORMED	561.30	396.90
2	REAR BUMPER LOWER SPOILER SIDE REFLECTOR @\$141.40	NOT NECESSARY	282.80	-
1	REAR BUMPER INNER SPONGE	CRACKED	182.10	182.10
2	REAR BUMPER MUD SHIELD @\$174.45	NOT NECESSARY	348.90	-
8	REAR BUMPER MUD SHIELD CLIP @\$6.50	NOT NECESSARY	52.00	-

Report Ref No. CC6/CTI18013381/Aea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL	DISTORTED	781.90	781.90
1	REAR END PANEL TOP GARNISH	DEFORMED	347.45	347.45
1	REAR END PANEL LOCK SENSOR	NOT NECESSARY	180.00	-
1	REAR SPARE TYRE PANEL	BUCKLED	972.45	972.45
1	REAR SPARE TYRE PANEL L/H SPANNER BOX	DEFORMED	381.90	381.90
1	REAR SPARE TYRE PANEL R/H SPANNER BOX	DEFORMED	381.90	381.90
1	REAR SPARE TYRE PANEL TOP COVER OUTER	DEFORMED	561.85	561.85
1	REAR SPARE TYRE PANEL TOP COVER INNER	DEFORMED	379.40	379.40
1	REAR SPARE TYRE PANEL TRIM	NOT NECESSARY	561.10	-
1	REAR L/H FENDER	TO REPAIR SEE LABOUR	970.10	-
1	REAR L/H FENDER AIR DUCT	DEFORMED	170.45	170.45
1	REAR L/H FENDER GLASS ASSY	NOT NECESSARY	561.60	-
2	REAR FENDER INNER TRIM BOARD @\$781.90	DEFORMED	1,563.80	1,230.30
1	REAR EXHAUST	BENT	731.35	731.35
1	REAR CENTRE EXHAUST	NOT NECESSARY	1,281.90	-
2	REAR EXHAUST MOUNTING @\$69.90	NOT NECESSARY	139.80	-
1	REAR EXHAUST CHROME PIPE	NOT NECESSARY	278.30	-
1	REAR EXHAUST ALUMINIUM COVER	NOT NECESSARY	181.30	-
	LESS 25% DISCOUNT		-	-3,254.03
			23,919.15	9,762.07
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BOOT LID CAMERA (SN)	DAMAGED	550.00	400.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	380.00	200.00
1	GUM (SN)	NECESSARY	90.00	50.00
			1,020.00	650.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT CUSHION.		280.00	80.00
	TO REMOVE & REFIT ROOF LINNING.	NOT NECESSARY	380.00	-
	TO REMOVE & REFIT BOOT LID CAMERA & WINDSCREEN CAMERA.		380.00	100.00
	TO REMOVE & REFIT REVERSE SENSOR.		100.00	50.00
	TO REMOVE & REFIT L/H FENDER GLASS.	NOT NECESSARY	100.00	-

Report Ref No. CC6/CTI18013381/Aea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT REAR WINDSCREEN.	NOT NECESSARY	150.00	120.00
	TO REMOVE & REFIT PETROL TANK.		280.00	-
	TO REMOVE & REFIT REAR & CENTRE EXHAUST.		380.00	80.00
	TO CHECK WIRING.		100.00	30.00
	TOWING FEE.	NOT NECESSARY	100.00	-
	TUFF KOTE.		150.00	50.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR TAIL LAMP PANEL AND REAR L/H FENDER.		3,500.00	1,400.00
	SPRAY PAINTING.		2,800.00	1,200.00
			8,700.00	3,110.00
GRAND TOTAL			33,639.15	13,522.07
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,800.00

Report Ref No. CC6/CT118013381/Aea3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.