

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1018M
 Ref. No : TAX/07/18/2078
 Reg. Date : 12/09/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : LIM TECK HENG
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 17/07/2018 12:10:00 PM
 Accident Reported Date / Time : 17/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024097073
 Special Instruction to ARC, if any :
 SGK9091L
 Prepared Date : 17/07/2018 05:00:47 PM



Sathya Sai
 18/7/2018

2 days

- Lamp Sun Repair
 - Photo after paint
 - ? item photo.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damage for airis during resurvey
- Parts prices for confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental survey can be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U205749097

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	0.00
Total Spray Painting Charges	: 558.00	0.00
Total Material Charges	: 798.22	798.22
Other Charges	: 280.00	0.00
TOTAL	: 1,974.22	0.00
Lum Sum Total	: 1,950.00	0.00
No. of Repair Days	: 3.00	0.00 2 days
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 17/07/2018 07:23:33 PM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 17/07/2018 07:20:19 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	0.00 200
Total Labour	338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 ?
Total Spray Painting & Panel Beating	558.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	280.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR <i>R</i>	1	458.60	25.00	343.95	Replace	Replace	No
			PIXEL STICKER <i>✓ NEC</i>	2	60.00	0.00	120.00	Replace	Replace	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR <i>?</i>	1	205.70	25.00	154.27	Replace	Replace	No
			SENSOR REVERSE <i>?</i>	1	180.00	0.00	180.00	Replace	Replace	No
TOTAL MATERIALS								798.23	798.22	
TOTAL MATERIALS(Discounted)								798.22	798.22	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									