

ASS. REC. BY

REF

CS/FCI18013394/Usd3n12

Level of Instruction

Surv. Vey/cf

From (Person)

Manny

Karen fan

ASSIGNMENT (Office)

FCI

Date/Time: 23/7/18 @ 4.46pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 7475B

Insured:

SHC 1076P

at Workshop m/s

Zoom Autowerks

Tel:

94507920

of

Blk 15 Kaki Blk Rd 4 #01-53

Policy No:

Claim No:

D18005574 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A:

20/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

24/7/18 @ 10.18am

Person Contacted:

Elin

Vehicle

IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLN 7475B - X

SHC 1076P - X

27/07/18

@ 10:24 a.m. revert pending estimate from repairer to Karen via email.

(08/11/13) wef

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SN 74753at Workshop n/s room

of: _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLN74753 Yr Regn: 5 17Type: C Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or 1A)Make: mer Benz A180 1595Colour: white/black A/C: Insured / Std / Nil / NASp. Reading: 14566 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WDD1760422J480837Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 205/55-R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mmR/Bal: 6 mm L/Bal: 6 mmD.O.A. 20/7/18 D.O.I. 24/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/8/18 2/5 \$5000 confirmed with Elin.(\$10,913.50 Red - 69%)

RECEIVED 17 AUG 2018

Date/Time, File Pass to?

17/08/181) Typist

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.I. (\$) 5,000/- 215Days Of Repair: 6Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ -- RS \$

Photos: 057Others: 5/18/18

TOTAL

5x15=75170+755050+5070465



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18013394/Usd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 24-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1076P	Veh. Inspected	SLN 7475B
Policy No.		Coverage (\$)	0.00
Claim No.	D18005574MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	24/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/07/2018	Inspection Date	24/07/2018
Survey held at	15 KAKI BUKIT ROAD 4 # 01-53		
Repairer	ZOOM AUTOWERKS PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 27 July 2018 10:24 AM
To: KARENTAN@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: 'Nivitha (LKK Auto)'; sur@lkkauto.com; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18005574MFSH/1

Dear Karen,

Please be informed that we have inspected the vehicle SLN 7475B on 24/07/2018.

We are pending for estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 24 July 2018 10:23 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; sur@lkkauto.com
Subject: RE: SURVEY ASSESSMENT - D18005574MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 23 July 2018 4:46 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005574MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

MOTOR SURVEY ASSIGNMENT

Date	20-07-2018	Our Ref No.	D18005574MFSH
Accident Date	20-07-2018	Claim Type.	Third Party
Insured Vehicle	SHC1076P	Third Party Vehicle.	SLN7475B
Survey Location	LK 15 KAKI BUKIT ROAD 4, BARTLEY BIZ CENTRE, #01-53		
Contact Person.	ELIN CAI		
Contact No.	0/ 94507920	Fax No.	0
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ZOOM AUTOWERKS PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	KARENT		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242596)



PRI Documents



Close



PRI Header Details

Claim No	D18005574MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & ZOOM AU
Workshop Name	ZOOM AUTOWERKS PTE LTD (Contact Person : ELIN CAI)	Survey Location & Contact Details	LK 15 KAKI BUKIT ROAD 4, BARTLEY BIZ CENTRE, #01- Mobile: 94507920 , Phone: 0 , Fax: 0 EmailId: ZOOMAUTOWERKS@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC1076P	TP Vehicle No	SLN7475B
PRI Recieved Date	20-07-2018 06:37:22 PM	Surveyor Appointed Date	23-07-2018 04:45:16 PM	Surveyor Accept Date	24-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	24-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

> **Back to OneMotoring**



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8012B
Vehicle Details	
Vehicle No.:	SLN7475B
Vehicle to be Exported:	No
Intended De-registration Date:	16 Aug 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	A180 SE AUTO
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	27091031001582
Chassis No.:	WDD1760422J480837
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$23,133.00
Original Registration Date:	16 May 2017
First Registration Date:	16 May 2017
Transfer Count:	0
Actual ARF Paid:	\$14,387.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 May 2027
PARF Rebate Amount:	\$10,790.00
Intended COE Rebate Details	
COE Expiry Date:	15 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,106.00
COE Rebate Amount:	\$44,696.00
Total Rebate Amount:	\$55,486.00

The information contained herein is correct as at 16 Aug 2018

OK

4524

[illegible]

1944-2475

[illegible]

44-652

Driving License

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S75280128



DIANNE VERGHESE
GOIN AND LITTLE



NAME
NUTS
EXPIRY DATE
21-09-1978
EXPIRY DATE 14 SEP 1978
EXPIRY DATE 14 SEP 1978

SEX
F

DATE OF BIRTH





ZOOM AUTOWERKS PTE LTD

832 Sims Avenue, Eunosville

#12-884 Singapore 400832

Tel: 9450 7920

* zoomautowerks@gmail.com

D.O.A : 20 JULY 2018
OWNER : DIANNE VERGHESE
REG NO. : SLN 7475 B
MAKE/MODEL : MERCEDES BENZ A180

not Authorised
24/7/18
2/5 5000/-
6 day.

23 JULY 2018

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(S\$)
<u>LIST ITEMS</u>		
1	Rear windscreen moulding	\$ 11 225.00 ✓
1	Rear tailgate	\$ 2 1,945.00 ✓
2	Rear tailgate dampers	\$ 11 230.00 ✓
1	Rear tailgate inner board	\$ 11 485.00 ✓
1	Rear tailgate inner lock	\$ 11 185.00 ✓
1	Rear tailgate rubber	\$ 22 185.00 —
1	Rear tailgate "A180" emblem	\$ 22 78.00 —
2	Rear number plate lamps	\$ 11 164.00 ✓
2	Rear taillamps 485	\$ 1/5cm 970.00 12C
1	Rear end panel	\$ 22 950.00 —
1	Rear end panel inner garnish	\$ 11 185.00 ✓
1	Rear bumper	\$ 22/2cm 1,450.00 —
1	Rear bumper clip (1 set)	\$ 22 80.00 —
1	Rear bumper reinforcement	\$ 22 485.00 —
2	Rear bumper reinforcement stays	\$ 22 440.00 ✓
2	Rear bumper side retainers	\$ 22 190.00 —
1	Rear bumper lower disfusser 445	\$ 22 645.00 —
1	Rear bumper tow hook cover	\$ 11 80.00 ✓
1	Rear bumper PDC sensor	\$ 22 250.00 ✓
1	Rear bumper inner frame pad	\$ 22 238.00 ✓
1	Rear spare tyre board	\$ 11 535.00 ✓
1	Rear spare tyre panel	\$ 11 1,280.00 ✓
1	Rear exhaust silencer	\$ 11 1,850.00 ✓
2	Rear exhaust mountings	\$ 11 90.00 ✓
		\$ 13,215.00
Less 10%		\$ 1,321.50
		\$ 11,893.50

4598
4138.2

c/f:

\$

11,893.50

SPECIAL NETT ITEMS

1

Rear windscreen sealant

\$	17	80.00	X
\$		80.00	

S/NLABOUR CHARGES

- 1 To remove, replaced damaged lamps and check up rear wiring.
- 2 To remove and refit inner garnishes.
- 3 To remove and refit rear reverse sensor.
- 4 To transfer rear tailgate mechanism and wiring assembly.
- 5 To remove and refit rear windscreen glass.
- 6 To remove, refit and replace exhaust silencer and mountings.
- 7 To apply undercoating.
- 8 Panel beating.
- 9 To re-spray painting on the affected areas. *including sticker*

\$		80.00	30
\$		180.00	100
\$		150.00	50
\$	17	120.00	X
\$	17	180.00	X
\$	17	180.00	X
\$		150.00	50
\$		1,500.00	700
\$		1,400.00	1200
\$		3,940.00	

62682

GRAND TOTAL :

\$	15,913.50
----	------------------

LNK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18013394/Usd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 21-08-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1076P	Veh. Inspected	SLN 7475B	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005574MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	23/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ A180 (A)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WDD1760422J480837	Colour	WHITE / BLACK	
Odometer	14566	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	MICHELIN	6 mm	
L/H Front Tyre	205/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/07/2018	Inspection Date	24/07/2018	
Survey held at	15 KAKI BUKIT ROAD 4 # 01-53			
Repairer	ZOOM AUTOWERKS PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 7475B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	225.00	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,945.00	-
2	REAR TAILGATE DAMPERS	NOT NECESSARY	230.00	-
1	REAR TAILGATE INNER BOARD	NOT NECESSARY	485.00	-
1	REAR TAILGATE INNER LOCK	NOT NECESSARY	185.00	-
1	REAR TAILGATE RUBBER	NECESSARY	185.00	185.00
1	REAR TAILGATE "A180" EMBLEM	NECESSARY	78.00	78.00
2	REAR NUMBER PLATE LAMPS	NOT NECESSARY	164.00	-
2	REAR TAILLAMPS	O/S CRACKED	970.00	485.00
1	REAR END PANEL	DENTED	950.00	950.00
1	REAR END PANEL INNER GARNISH	NOT NECESSARY	185.00	-
1	REAR BUMPER	DENTED / TORN	1,450.00	1,450.00
1	SET REAR BUMPER CLIP	NECESSARY	80.00	80.00
1	REAR BUMPER REINFORCEMENT	BENT	485.00	485.00
2	REAR BUMPER REINFORCEMENT STAYS	NO SUCH PARTS	440.00	-
2	REAR BUMPER SIDE RETAINERS	BENT	190.00	190.00
1	REAR BUMPER LOWER DISFUSSE	DEFORMED	645.00	445.00
1	REAR BUMPER TOW HOOK COVER	NOT NECESSARY	80.00	-
1	REAR BUMPER PDC SENSOR	SHORTED	250.00	250.00
1	REAR BUMPER INNER FRAME PAD	NO SUCH PARTS	238.00	-
1	REAR SPARE TYRE BOARD	NOT NECESSARY	535.00	-
1	REAR SPARE TYRE PANEL	NOT NECESSARY	1,280.00	-
1	REAR EXHAUST SILENCER	NOT NECESSARY	1,850.00	-
2	REAR EXHAUST MOUNTINGS	NOT NECESSARY	90.00	-
	LESS 10% DISCOUNT		-1,321.50	-459.80
			11,893.50	4,138.20
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
			80.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING.		80.00	30.00
	TO REMOVE AND REFIT INNER GARNISHES.		180.00	100.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		150.00	50.00
	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	180.00	-
	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS.	NOT NECESSARY	180.00	-
	TO APPLY UNDERCOATING.		150.00	50.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR TAILGATE.		1,500.00	700.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS INCLUDING STICKER.		1,400.00	1,200.00
			3,940.00	2,130.00
	GRAND TOTAL		15,913.50	6,268.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,000.00

Report Ref No. CS/FCI18013394/Usd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.