

INSURANCE

INS. CASE OWNER:

CC 0111801

LKK:

IDAC:

Surveyor:

Tan Fieh

DOI:

ASSIGNMENT

27/7/18

Date / Time:

27/7/18

Registered in Merimen:

27/7/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHD 3073U

Name of Insured:

YD

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

27/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: YEO BOON TIE

Driver Tel No.:

(V/L / YES / NO)

Claim No.:

MY18070628

Policy No.:

ML000015

Make / Model:

MYUNDAI

Place of Accident:

BN TONG SEN ST ENOS
RIVER VALLEY

OI GIA REPORT: YES / NO TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SHD 1877M



INSRS:

WSP:

Tel:

Liability:

RMKS:

prime



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

27/7/18

TH

OI coming out from slip road and
collided with TP making turn at main
road.

RECEIVED 28 OCT 2018

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List:

Notification Itr (if non-pickup):

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandated Reject Instruction:

LOE:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

19/10/18

Confirm with:

Alice

Email

Call

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No. : 11CC

If NO or B 28, Ass. Lia :

Repair Cost:

SS

4066.00

Loss of Rental (LOR):

SS

552.30 (7 days) x 78.90

Loss of Use (LOU):

SS

(5 x days)

Loss of Income (LOI):

SS

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow / Independent)

Legal Cost:

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

4618.30

Global Sum SS:

4600.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

4600.00

Name 1:

PRIME AUTO CLAIMS SERVICE PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT 27/10/18

(08/11/13) wef

ASS. REC. BY: TaufniREF: AKG III

ASSIGNMENT

From: _____ Date: 23/7/2018

Estimated Cost: _____

OP / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 8KM1878Dat Workshop m/s Volkswagenof 244 Alexander Rd

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 4pm @ owner waiting

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS up

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHD 2823M Yr Regn: 2012 actType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 149LColour: Orange A/G: Insured / Std / NI / NASp. Reading: 516457 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NHW203583810Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or GoodrideFront 6 mm Rear 6 mmR/Bal. 6 mm L/Bal. 6 mmL/Bal. 6 mm D.O.I. 23/7/18 @ 5pm

D.O.A. _____

Survey held at Prime AutoDes. of Damages: Frt / Rear / O/S N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LIS - \$3800L (Red. \$3936.01 / 51%).

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18013397/T1ub3		
54 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 24-07-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3033U	Veh. Inspected	SHD 2823M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	24/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/07/2018	Inspection Date	23/07/2018	
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

5 Benoi Place Singapore 629926

Tel: 6861 0908 Fax: 6515 2948

Date: 23.07.2018

India International Insurance Pte Ltd

64 Cecil Street #04/#05

IOB Building

Singapore 049711

RE: ESTIMATE COST TO VEHICLE SHD2823M TOYOTA PRIUS HYBRID 1.5EX (2011)

To supply

1) 1pc	Left front fender	\$	776.00	bt ✓
2) 1pc	Left front fender cowling	\$	185.97	de ✓
3) 1pc	Left front fender cowling clip	\$	30.00	ne ✓
4) 1pc	Left front fender "Hybrid" emblem	\$	132.00	ne ✓
5) 1pc	Left front fender lamp indicator	\$	52.10	ce ✓
6) 1pc	Left front door	\$	1,189.51	bt ✓
7) 1pc	Left front door weatherstrip	\$	183.96	ne ✓
8) 1pc	Left lower rocker panel	\$	562.00	Ry ✓
9) 1pc	Left front door top hinge	\$	79.20	Ry ✓
10) 1pc	Left front door lower hinge	\$	79.20	Ry ✓
11) 1pc	Left front door checker	\$	124.70	Ry ✓
12) 1pc	Left rear door	\$	804.80	Ry ✓
13) 1pc	Left rear door top hinge	\$	79.20	Ry ✓
14) 1pc	Left rear door lower hinge	\$	79.20	Ry ✓
15) 1pc	Left rear door checker	\$	128.50	Ry ✓
16) 1pc	Left rear fender	\$	975.00	Ry ✓
17) 1pc	left rear fender cowling	\$	290.00	Ry ✓
18) 1set	left rear fender cowling clip	\$	30.00	X/M ✓

Sub total parts	\$	5,781.34
Less: 25% discount	\$	1,445.33
	\$	4,336.01

To Supply S.nett parts

1) 1pc	Left front tyre sport rim	\$	180.00	cut ✓
2) 1pc	Left front fender sticker	\$	200.00	ne ✓
3) 1pc	Left front door advertisement sticker	\$	180.00	ne ✓
4) 1pc	Left rear door advertisement sticker	\$	180.00	ne ✓
5) 1pc	Left rear fender advertisement sticker	\$	200.00	ne ✓

Sub total S.Nett Parts	\$	940.00
------------------------	----	--------

L/charges

- | | | |
|---|-------------|------|
| 1) To tuff-kote | \$ 100.00 | 60 |
| 2) To remove left front sport rim, replace tyre sport rim. Balance tyre | \$ 40.00 | 30 |
| 3) To transfer left front door handle, door trim cover and mechanism parts | \$ 60.00 | ✓ |
| 4) To transfer left rear door handle, door trim cover and mechanism parts | \$ 60.00 | x |
| 5) To remove & replace left front fender, left front & rear door. To knock/ repair front door pillar & center door pillar, cut /welding left rear fender. Adjust & align left side doors & fenders | \$ 1,000.00 | 800 |
| 6) To putty, respray painting left front fender & left front door inlet & outlet, left rear door inlet and outer, door pillar & left rear fender. | \$ 1,200.00 | 1000 |

Sub total L/charges	\$ 2,460.00
Estimated Grand Total	\$ 7,736.01

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfer 97445747
 WP
 23/7/18 @ 1700
 LKK
 Resurvey after repair
 7 days
 sure@lkkauto.com



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 31.07.2018

Our Ref: SHD2823M

Your Ref: Please advice

India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Without prejudice

Attn: Ms. Sundari (Motor Claims Dept)

Dear Madam,

ACCIDENT ON 21.07.2018 INVOLVING VEHICLE NO SHD2823M & SHD3033U

We are on behalf of M/s Prime Car Rental & Taxi Services Pte Ltd the owner of vehicle SHD2823M in their third party claim against your insured / driver of SHD3033U negligence caused the accident.

Appended below our client's claim:

1. Cost of repair	\$ 4,066.00
2. Loss of rental @\$78.90 x 7 days	\$ 552.30
Total	<u>\$ 4,618.30</u>

We enclose herewith copy of our invoice no 2264, Letter of authority & Letter of Certification for your retention. Please acknowledge receipt.

For an amicable settlement, please let us have your offer.

Yours faithfully,

Alice Leong

e-mail: aliceleong@primeautoclaims.com

Encl.


LETTER OF AUTHORITY

To: PRIME AUTO CLAIMS SERVICE PTE. LTD.

Re: ACCIDENT ON 21.07.2018 INVOLVING SHD2823M & SHD3033U
ALONG RIVER VALLEY ROAD

I/ We, M/S Prime Car Rental & Taxi Services Pte Ltd hereby authorized you to carry out repairs of the damage caused to my / our vehicle no. SHD2823M in the above accident.

I/ We further also confirm and agree that all sums of money to be recovered by you on my/ our behalf shall be paid to you. I/ We hereby also authorise the third party insurer to release to you such sums of money recovered on my / our behalf.



.....
Signature (Company's stamp if applicable)

Name:

NRIC:

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18070638
 Claimant Ref: SHD 2823M

We/I, Prime Auto Claims Service Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 4,600.00 (global sum) ~~on account of the damage to the vehicle~~
~~on account of the damage to the vehicle~~ vehicle no. SHD 2823M that was damaged pursuant to the accident which occurred on 21/07/2018 (date) at RIVER VALLEY ROAD (location) involving vehicle no. SHD 3033U (insured vehicle). This is pursuant to the inspection conducted on 23/07/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner PRIME CAR RENTAL & TAXI SERVICES PTE LTD ("the third party claimant") of vehicle no. SHD 2823M to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SHD 2823M (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 4,600.00 to Prime Auto Claims Service Pte Ltd

Dated this 17th day of October 2018

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

Signed by "The Workshop" (with chop)

Henry Soh Chey

S781123456

c/o No. 6 Bani Place

S' 689987

PR

Manager, claims

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

Signed by appointed Surveyor

LKK Auto Consultants Pte Ltd

199607198R

Blk 51, Paya Ubi Industrial Park,

Ubi Avenue 1, #02-25 | S(408933)

-

-

TAX INVOICE**No: 2264****Prime Auto Claims Service Pte Ltd**

6 Benoi Place Singapore 629927

Tel: 6861 0908 Fax: 6515 2948

GST Reg. No: 201606560M

Reg No. 201606560M

MESSRS**India International Insurance Pte Ltd**

31/7/2018

Date: _____

64 Cecil Street

#04/05 10B Building

Singapore 049711

Works Order No: 2261Vehicle No: SHD2823M

ITEM	DESCRIPTION	UNIT PRICE	AMOUNT
1.	Make/Model : Toyota Prius Repair Date : 21/7/2018 Terms of Payment: COD <u>Third Party Claims</u> Being lump sum repair to the above vehicle.		\$ 3,800.00

* Compound interests at the rate of 1% per month will be charged on late payment.

SUB TOTAL \$ 3,800.00**GST 7%** \$ 266.00**TOTAL** \$ 4,066.00

Prepared by _____

Prime Auto Claims Service Pte Ltd
Manager



PRIME CAR RENTAL & TAXI SERVICES PTE LTD

Prime Taxi Office
5, Benoi Place
Singapore 629926
Tel : 6898 2000
Fax : 6862 2628
Email : primetaxi@singnet.com.sg
Website : www.primetaxi.com.sg

Co. Cert. No: 199606293Z
Gst Reg. No: 19-9606293-Z

Your Ref : Please advise

Our Ref: SHD2823M

Date : 30.07.2018

To : Whom It May Concern

From : Prime Car Rental & Taxi Services Pte Ltd

RE: LETTER OF CERTIFICATION FOR MR. TAN SONG HUANG

This letter serves to confirm that Mr. Tan Song Huang, Nric Number S1519874E is a Taxi Master for Prime Car Rental & Taxi Services Pte Ltd hiring the Vehicle Registration Number SHD2823M for Singapore Dollar Seventy Nine and Cents Eighty (\$79.80) Only.

Should clarification require I can be contacted at 94524182.

Thank you with Best Regards

Yours Sincerely

.....
Mr Chan Kong Loong
Workshop Manager



CHAN KONG LOONG
S75301061
WORKSHOP MANAGER
NO. 5 BENOI PLACE
SINGAPORE 629926

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jul 2018 Edit Reg		23 Jul 2018 00:00 Edit Adj Rpt	S\$3,800.00 Edit Estimates	S\$3,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -								
Main Claimant:	PRIME CAR RENTAL & TAXI SERVICES PTE LTD, Co. Reg. No.: 199606293Z								
Vehicle Reg. No.:	SHD2823M	Date of Loss:	21/07/2018 19:00 - :59 [69 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18070638	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHD3033U	Policy No. (Claimant):	5068045737-03						
		Excess:							
Repairer:	Prime Auto Claims Service Pte Ltd (HQ) 6 Benoi Place, 629927 Pioneer - Tel: 68610908								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagaraajan - 6347 6071]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 02/08/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (19/10/2018): Alert - Adj Mandate Approved (S\$4618.30) - SHD2823M - Claim Handler: Sundari Nag... - III_SG (30/07/2018): Alert - Adj Mandate Approved (S\$0.00) - SHD2823M - Claim Handler: Sundari Nagara...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHD2823M (MCT18070638)
 [SHD3033U]
 TP
 PRIME CAR RENTAL & TAXI SERVICES PTE LTD
 Jul 21 2018 7:00PM
 [COMFORT TRANSPORTATION PTE LTD]
 Prime Auto Claims Service Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	18/10/18 17:15	General View	 Load JPG	☒	
2	18/10/18 17:15	General View	 Load JPG	☒	
3	18/10/18 17:15	General View	 Load JPG	☒	
4	18/10/18 17:15	General View	 Load JPG	☒	
5	18/10/18 17:15	General View	 Load JPG	☒	
6	18/10/18 17:15	General View	 Load JPG	☒	
7	18/10/18 17:15	General View	 Load JPG	☒	
8	18/10/18 17:15	General View	 Load JPG	☒	
9	18/10/18 17:15	General View	 Load JPG	☒	
10	18/10/18 17:15	General View	 Load JPG	☒	
11	18/10/18 17:15	General View	 Load JPG	☒	
12	18/10/18 17:15	General View	 Load JPG	☒	
13	18/10/18 17:15	General View	 Load JPG	☒	
14	18/10/18 17:15	General View	 Load JPG	☒	
15	18/10/18 17:15	General View	 Load JPG	☒	
16	18/10/18 17:15	General View	 Load JPG	☒	
17	18/10/18 17:15	General View	 Load JPG	☒	
18	18/10/18 17:15	General View	 Load JPG	☒	
19	18/10/18 17:15	General View	 Load JPG	☒	
20	18/10/18 17:15	General View	 Load JPG	☒	
21	18/10/18 17:15	General View	 Load JPG	☒	
22	18/10/18 17:15	General View	 Load JPG	☒	
23	18/10/18 17:15	General View	 Load JPG	☒	
24	18/10/18 17:15	General View	 Load JPG	☒	
25	18/10/18 17:15	General View	 Load JPG	☒	
26	18/10/18 17:15	General View	 Load JPG	☒	
27	18/10/18 17:15	General View	 Load JPG	☒	
28	18/10/18 17:15	General View	 Load JPG	☒	
29	18/10/18 17:15	General View	 Load JPG	☒	
30	18/10/18 17:15	General View	 Load JPG	☒	
31	18/10/18 17:15	General View	 Load JPG	☒	
32	18/10/18 17:15	General View	 Load JPG	☒	
33	18/10/18 17:15	General View	 Load JPG	☒	
34	18/10/18 17:15	General View	 Load JPG	☒	
35	18/10/18 17:15	General View	 Load JPG	☒	
36	18/10/18 17:15	General View	 Load JPG	☒	
37	18/10/18 17:15	General View	 Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	18/10/18 17:15	General View	 Load JPG	☒
39	18/10/18 17:15	General View	 Load JPG	☒
40	18/10/18 17:15	General View	 Load JPG	☒
41	18/10/18 17:15	General View	 Load JPG	☒
42	18/10/18 17:15	General View	 Load JPG	☒
43	18/10/18 17:15	General View	 Load JPG	☒
44	18/10/18 17:15	General View	 Load JPG	☒
45	18/10/18 17:15	General View	 Load JPG	☒
46	18/10/18 17:15	Odometer Reading	 Load JPG	☒
47	18/10/18 17:15	Chassis Number	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/07/18 14:25	EMAIL FROM III DD 23072018	 Load PDF	
2	24/07/18 14:25	TP GIA REPORT	 Load PDF	
3	24/07/18 17:11	TP ESTIMATE- MARKED	 Load PDF	
4	18/10/18 17:12	WORKSHOP INVOICE	 Load PDF	
5	18/10/18 17:12	RENTAL RECEIPT	 Load PDF	
6	18/10/18 17:12	LOD	 Load PDF	
7	01/11/18 08:43	DISCHARGE VOUCHER	 Load PDF	
8	01/11/18 08:43	AUTHORISATION TO ACT FORM	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	25/07/18 09:13	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18013397/T1UB3Q2

Date: 01/11/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No: SHD2823M

Insured Vehicle No: SHD3033U

Date of Loss: 21/07/2018

Nature of Claim: TP

Claim No: MCT18070638

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD2823M

Make & Model: TOYOTA PRIUS, 1.5 HYBRID (A)

Engine No: 1NZ6040171

Reg. Date: 02/10/2012 (Man. Year: 2011)

Chassis No: NHW203583812

Colour: Orange

Odometer: 516457 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Goodride 6 mm

Rear Left Side: Goodride 6 mm

Front Right Side: Goodride 6 mm

Rear Right Side: Goodride 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,276.00	2,852.15	2,423.85	45.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,950.00	510.00	20.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,736.00	4,802.15	2,933.85	37.92
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	7,736.00	3,800.00	3,936.00	50.88
+ GST 7.00/7.00% (S\$)	541.52	266.00	275.52	50.88
Nett Amount (S\$)	8,277.52	4,066.00	4,211.52	50.88
+ Car Rental (7.0 x S\$78.90/day) (S\$)		552.30		
Nett Liability (S\$)		4,618.30		
Global Sum Settlement (S\$)		4,600.00		

INSPECTION

Date of Assignment: 23/07/2018

Date Inspected: 23/07/2018 Inspected At:

Prime Auto Claims Service Pte Ltd -
Pioneer (HQ)

6 BENOI PLACE
Singapore 629927

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Oct 2018)
Parts: 144	TOYOTA PRIUS 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD2823M)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LEFT FRONT FENDER	Bent	776.00 FL	*776.00 FL
2	1		*LEFT FRONT FENDER COWLING	Deformed	185.97 FL	*185.97 FL
3	1		*LEFT FRONT FENDER COWLING CLIP	Necessary	30.00 FL	*30.00 FL
4	1		*LEFT FRONT FENDER HYBRID EMBLEM	Necessary	132.00 FL	*132.00 FL
5	1		*LEFT FRONT FENDER LAMP INDICATOR	Cracked	52.10 FL	*52.10 FL
6	1		*LEFT FRONT DOOR	Bent	1,189.51 FL	*1,189.51 FL
7	1		*LEFT FRONT DOOR WEATHERSTRIP	Necessary	183.96 FL	*183.96 FL
8	1		*LEFT LOWER ROCKER PANEL	Repair	562.00 FL	*- FL
9	1		*LEFT FRONT DOOR TOP HINGE	Repair	79.20 FL	*- FL
10	1		*LEFT FRONT DOOR LOWER HINGE	Repair	79.20 FL	*- FL
11	1		*LEFT FRONT DOOR CHECK	Repair	124.70 FL	*- FL
12	1		*LEFT REAR DOOR	Repair	804.80 FL	*- FL
13	1		*LEFT REAR DOOR TOP HINGE	Repair	79.20 FL	*- FL
14	1		*LEFT REAR DOOR LOWER HINGE	Repair	79.20 FL	*- FL
15	1		*LEFT REAR DOOR CHECKER	Repair	128.50 FL	*- FL
16	1		*LEFT REAR FENDER	Repair	975.00 FL	*- FL
17	1		*LEFT REAR FENDER COWLING	Repair	290.00 FL	*- FL
18	1		*SET LEFT REAR FENDER COWLING CLIP	Not Necessary	30.00 FL	*- FL
19	1		*LEFT FRON TYRE SPORT RIM	Cut	180.00 FS	*180.00 FS
20	1		*LEFT FRONT FENDER STICKER	Necessary	200.00 FS	*200.00 FS
21	1		*LEFT FRONT DOOR ADVERTISEMENT STICKER	Necessary	180.00 FS	*180.00 FS
22	1		*LEFT REAR DOOR ADVERTISEMENT STICKER	Necessary	180.00 FS	*180.00 FS
23	1		*LEFT REAR FENDER ADVERTISEMENT STICKER	Necessary	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **6,721.34** **3,489.54**

- List Item Discount on L Items 25.00/25.00% (\$\$) **1,445.34** **637.39**

Total Parts (\$\$) **5,276.00** **2,852.15**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TUFF-KOTE	New	100.00	60.00
2	TO REMOVE LEFT FRONT SPORT RIM ,REPLACE TYRE SPORT RIM .BALANCE TYRE	New	40.00	30.00
3	TO TRANSFER LEFT FRONT DOOR HANDLE ,DOOR TRIM COVER AND MECHANISM PARTS	New	60.00	60.00
4	TO TRANSFER LEFT REAR DOOR HANDLE ,DOOR TRIM COVER AND MECHANISM PARTS	New	60.00	0.00
5	TO RMEOVE & REPLACE LEFT FRONT FENDER ,LEFT FRONT & REAR DOOR .TO KNOCK /REPAIR FRONT DOOR PILLAR & CENTER DOOR PILLAR ,CUT/WELDING LEFT REAR FENDER .ADJUST & ALIGN LEFT SIDE DOORS & FENDERS	New	1,000.00	800.00
6	TO PUTTY ,RESPRAY PAINTING LEFT FRONT FENDER & LEFT FRONT DOOR INLET & OUTLET ,LEFT REAR DOOR INLET AND OUTER ,DOOR PILLAR & LEFT REAR FENDER	New	1,200.00	1,000.00
Gross Labour Cost (\$\$)			2,460.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >