



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 23.07.2018

India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

RE: ESTIMATE COST TO VEHICLE SHD2823M TOYOTA PRIUS HYBRID 1.5EX (2011)

To supply

1) 1pc	Left front fender	\$	776.00	bt ✓
2) 1pc	Left front fender cowl	\$	185.97	de ✓
3) 1pc	Left front fender cowl clip	\$	30.00	ne ✓
4) 1pc	Left front fender "Hybrid" emblem	\$	132.00	ne ✓
5) 1pc	Left front fender lamp indicator	\$	52.10	ca ✓
6) 1pc	Left front door	\$	1,189.51	bt ✓
7) 1pc	Left front door weatherstrip	\$	183.96	ne ✓
8) 1pc	Left lower rocker panel	\$	562.00	Ry ✓
9) 1pc	Left front door top hinge	\$	79.20	Ry ✓
10) 1pc	Left front door lower hinge	\$	79.20	Ry ✓
11) 1pc	Left front door checker	\$	124.70	Ry ✓
12) 1pc	Left rear door	\$	804.80	Ry ✓
13) 1pc	Left rear door top hinge	\$	79.20	Ry ✓
14) 1pc	Left rear door lower hinge	\$	79.20	Ry ✓
15) 1pc	Left rear door checker	\$	128.50	Ry ✓
16) 1pc	Left rear fender	\$	975.00	Ry ✓
17) 1pc	left rear fender cowl	\$	290.00	Ry ✓
18) 1set	left rear fender cowl clip	\$	30.00	X

Sub total parts	\$	5,781.34
Less: 25% discount	\$	1,445.33
	\$	4,336.01

To Supply S.nett parts

1) 1pc	Left front tyre sport rim	\$	180.00	cut ✓
2) 1pc	Left front fender sticker	\$	200.00	ne ✓
3) 1pc	Left front door advertisement sticker	\$	180.00	ne ✓
4) 1pc	Left rear door advertisement sticker	\$	180.00	ne ✓
5) 1pc	Left rear fender advertisement sticker	\$	200.00	ne ✓

Sub total S.Nett Parts \$ 940.00

L/charges

- | | | |
|---|-------------|------|
| 1) To tuff-kote | \$ 100.00 | 60 |
| 2) To remove left front sport rim, replace tyre sport rim. Balance tyre | \$ 40.00 | 30 |
| 3) To transfer left front door handle, door trim cover and mechanism parts | \$ 60.00 | ✓ |
| 4) To transfer left rear door handle, door trim cover and mechanism parts | \$ 60.00 | x |
| 5) To remove & replace left front fender, left front & rear door. To knock/ repair front door pillar & center door pillar, cut /welding left rear fender. Adjust & align left side doors & fenders | \$ 1,000.00 | 800 |
| 6) To putty, respray painting left front fender & left front door inlet & outlet, left rear door inlet and outer , door pillar & left rear fender. | \$ 1,200.00 | 1000 |

Sub total L/charges	\$ 2,460.00
Estimated Grand Total	\$ 7,736.01

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
 'wp'
 23/7/18 @ 1700
 LKK Auto
 Resurvey after repair.
 7 days
 sum@lkkauto.com