

ASS. REC. BY:

REF: CS/MSG18013402/Asd3⁷²

Special Instruction:

Survivor
merimen

Adrian

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSG

Date/Time: 23/7/18 @ 3:01pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SKD 145P

Insured:

SKU 1067K

at Workshop m/s

Modern Automotive

Tel:

6 748 6720

of

Blk 3023A, Ubi Rd 1 # 01-58

Policy No:

A29071174QMX

Claim No:

565044

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/07/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:36am @ 24/7/18

Person Contacted:

Grace

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKD 145P - X

SKU 1067K - X.

25/07/18

@ 17:05 p.m. revert pending estimate from repairer to Christina Wong via merimen.

REF:

ASS. REC. BY: Adrian King

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKD14SP.Yr Regn: 2007 / July.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda StreamC.C. 1799.Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: Battery flat

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RN61037307Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fireenza.

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A.

D.O.I. 23/07/18.

Survey held at

Modern Motor.Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Attn. MSH

(\$10,915.68 Red - 53%)

MV: 29.5K.

PV: 19.6K

Nett: 9.9K.

COE Expiry: 30/04/22.

RECEIVED 20 AUG 2018

*Parts Prices checked by Adrian

17/02/18 ~~that was~~ Exhaust pass to Simon checked (confirmed)

Date/Time, File Pass to?

20/02/18

1)

Typist

Date/Time, File Return to?

2)

☐

Preli. Report

☒

Final Report

Days Of Repair: 13Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Others

TOTAL

200
10

210

Report Format:

Lump Sum / L.B.I. (\$) 9,800.00 L/S

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth ed	Status
Main	20 Jul 2018		23 Jul 2018 15:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	ONG WEE KIAT, ID: S7800072D		
Main Claimant:	MURNI BINTE MOHAMED, ID: S78109591		
Vehicle Reg. No.:	SKD145P	Date of Loss:	20/07/2018 08:00 - :59 [131 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 565044	Policy/Cover Note No.:	A29071174QMX (Comprehensive) Coverage: 05/02/2018 - 04/02/2019
Vehicle Reg. No. (Insured):	SKU1067K	Policy No. (Claimant):	
		Excess:	
Repairer:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/07/2018]		
Driver/Custodian (Insured):	ONG WEE KIAT (), NRIC: S7800072D		
Adj Asg. Remarks:	Liability 100%, SJE agree - LKK, Contact : Grace Chin at 6748 6720		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18013402/Asd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 24-07-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKU 1067K	Veh. Inspected	SKD 145P	
Policy No.	A29071174QMX	Coverage (\$)	0.00	
Claim No.	565044	Excess (\$)	0.00	
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	24/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/07/2018	Inspection Date	24/07/2018	
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0959I
Vehicle Details	
Vehicle No.:	SKD145P
Vehicle to be Exported:	Yes
Intended De-registration Date:	23 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8 A
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	R18A1742175
Chassis No.:	RN61037307
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$17,775.00
Original Registration Date:	31 Jul 2007
First Registration Date:	31 Jul 2007
Transfer Count:	3
Actual ARF Paid:	\$19,553.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$26,004.00
COE Rebate Amount:	\$19,604.00
Total Rebate Amount:	\$19,604.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 23 Jul 2018

OK



CHEAPEST CAR INSURANCE RENEWAL



Free choice of 1000s of insurance

Options to suit any workshop

GET A CHEAPER QUOTE NOW!



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Lexus GS300 CCE 10 Years COE.



Good Condition.
Direct Owner StarAd



AutoInn
An Inspiration For Car Buyers

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category

Save Search

Print

« Back (1 2 3 4 5) Next »

Sort by Date Posted

20 results/page

85 vehicles

Search

Stream

Advanced Search

Search

View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection Stream Any Any > 10 year(s) old Any Any Any Available



☐ Honda Stream 1.8A RSZ
(COE till 07/2023)

\$37,800

\$7,630 /yr

07-Jul-2008

1,799 cc

-

MPV

Available

\$2800 Down Payment, Lowest Monthly From \$738 Onwards. Low Interest At 3.68% Per Annum By GV Cars Financing. 100% Loan Approval. 2 Years Warranty/servicing By GV In House Workshop. New Full Pure Leather...

\$2800 Downpayment Monthly From \$738 Onwards. Lowest 3.68%P.A@GV Cars Financing
GV Credit Pte Ltd

★ Posted: 23-Jul-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda



☐ Honda Stream 1.8A (COE till
11/2021)

\$28,800

\$8,590 /yr

29-Nov-2006

1,799 cc

-

MPV

Available

1 And Only Unit For 2006 Model! Very Well Maintained And Under Utilised By Owner Who Owns 3 Cars! Hurry, Call Now Before Its Gone! Price Slightly Negotiable For Sincere Buyer!

DIRECT OWNER

★ Posted: 03-Jul-2018 Tags: 2006 Honda Stream, Honda Stream, Honda, Stream, Used Honda



☐ Honda Stream 1.8A RSZ (COE
till 01/2022)

\$27,555

\$7,810 /yr

31-Jan-2007

1,799 cc

140,000 km

MPV

Available

★ Posted: 06-Jun-2018 Tags: 2007 Honda Stream, Honda Stream, Honda, Stream, Used Honda



☐ Honda Stream 1.8A (COE till
02/2022)

\$30,000

\$8,410 /yr

15-Feb-2007

1,799 cc

128,000 km

MPV

Available

Renewed COE Honda Stream 1.8A (Plus 5 Years) Total Mileage 128,000 Pioneer 5850 Rims Changed By Autobacs One Year Ago Schedule A Test Drive Today. Viewing Is Strictly By Appointment Only.

CONSIGNMENT

Carro

★ Posted: 17-Jul-2018 Tags: 2007 Honda Stream, Honda Stream, Honda, Stream, Used Honda

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

TYREPAC

Buy Tyres Online!
Latest Special Offers from Tyrepac!



☐ Honda Stream 1.8A (COE till
03/2022)

\$27,800

\$7,610 /yr

19-Mar-2007

1,799 cc

-

MPV

Available

Selling The Cheapest MPV In The Market, Hassle Free And Accident Free, Flexible Loan Can Be Arranged, Low Interest Rate, Trade In Or Scrap Car Welcome, Hurry Contact Us For More Information Or Drop By ...

★ Posted: 06-Jul-2018 Tags: 2007 Honda Stream, Honda Stream, Honda, Stream, Used Honda



☐ Honda Stream 1.8A (COE till
05/2022)

\$30,800

\$8,110 /yr

10-May-2007

1,799 cc

178,866 km

MPV

Available

Very Reliable MPV With Great Aerodynamics, Combined With Space And Comfort. Regularly Serviced And Maintained. Selling Due To Upgrading. Consignment Unit! Trade In Welcome! Loan And Insurance Availabl...

CONSIGNMENT

Prem Roy Motoring

★ Posted: 04-Jul-2018 Tags: 2007 Honda Stream, Honda Stream, Honda, Stream, Used Honda

SHORTLISTED HISTORY

Compare

☐ Honda Stream 1.8A (COE till
05/2022)

\$29,800

\$7,740 /yr

30-May-2007

1,799 cc

-

MPV

Available



Well Taken Care By The Previous Owner. High Loan With High Trade In. Price Negotiable. Call Now Or Visit Our Showroom Today!

☆ Posted: 26-Jun-2018 Tags: 2007 Honda Stream, Honda Stream, Honda, Stream, Used Honda



☐ Honda Stream 1.8A (COE till 06/2022) \$28,900 \$7,460 /yr 07-Jun-2007 1,799 cc 143,246 km MPV Available

[Drive With Assurance] High Paper + Car Body 1k Free 1 Year Warranty! I Owner Only, Very Low Mileage Done. All Our Pre-Owned Cars Are Selling At The Most Reasonable Price With A Peace Of Mind! STA/VIC...

☆ Posted: 14-Jul-2018 Tags: 2007 Honda Stream, Honda Stream, Honda, Stream, Used Honda



☐ Honda Stream 1.8A (COE till 05/2022) \$32,888 \$8,530 /yr 12-Jun-2007 1,799 cc - MPV Available

Good Fuel Economy Yet Powerful, Pristine Interior. Good Working Condition.

DIRECT OWNER

☆ Posted: 17-Jul-2018 Tags: 2007 Honda Stream, Honda Stream, Honda, Stream, Used Honda



☐ Honda Stream 1.8A X (COE till 07/2022) \$28,500 \$7,180 /yr 12-Jul-2007 1,799 cc 128,566 km MPV Available

The Well Known Stream Is Up For Sale. Genuine And Real Mileage Shown. Hurry, Call Me Now.

☆ Posted: 19-Jul-2018 Tags: 2007 Honda Stream, Honda Stream, Honda, Stream, Used Honda



Save big on petrol at Esso!

Compare and find the card that gets you the most petrol savings at Esso. Save up to 20.88%! Apply for the best Esso petrol discount credit card today.

Find out more!



☐ Honda Stream 1.8A Style Edition (COE till 08/2022) \$30,800 \$7,650 /yr 02-Aug-2007 1,799 cc 203,000 km MPV Available

Owner Has Recently Replaced Aircon, Spring-bumper, Suspension, Break, Spark Plug, Screen Wiper And Many Other Parts. No Repair Needed.

DIRECT OWNER

☆ Posted: 16-Jul-2018 Tags: 2007 Honda Stream, Honda Stream, Honda, Stream, Used Honda



☐ Honda Stream 1.8A (COE till 08/2027) \$52,800 \$5,810 /yr 24-Aug-2007 1,799 cc - MPV Available

Cheapest In Town! Safe Buy At High PARF With Low Depreciation And Low Monthly 7 Seater Most Reliable Sporty MPV! In House Loan Available! High Trade In Are Welcome. Tip Top Condition! 100% Accident Free...

☆ Posted: 22-Jul-2018 Tags: 2007 Honda Stream, Honda Stream, Honda, Stream, Used Honda



☐ Honda Stream 1.8A RSZ (COE till 12/2022) \$37,888 \$8,530 /yr 11-Feb-2008 1,799 cc 130,000 km MPV Available

Very Good Condition RSZ Stream. Full Original Bodykit An Paint. 100% Accident Free. Comes With DVD Entertainment System, Paddle Shift, HID Headlights, All Original! All Wear And Tear Parts Replaced In...

DIRECT OWNER

☆ Posted: 16-Jun-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda



☐ Honda Stream 1.8A (COE till 02/2023) \$32,838 \$7,440 /yr 21-Feb-2008 1,799 cc 129,000 km MPV Available

100% Loan At 2.98% Just Arrived! Silver Honda Stream! New 5 Years COE. Service Every 10K Km Without Fail! No Repair Needed! 2 Years Free Servicing, We Deliver Our Promise! High Trade In Most Welcome! ...

☆ Posted: 29-Jun-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda



☐ Honda Stream 1.8A X (New 5-yr COE) \$39,800 \$7,960 /yr 28-Feb-2008 1,799 cc - MPV Available

Renew COE At \$42,800 (5 Years) Good Condition. DVD Player With Reverse Camera.

PREMIUM AD

☆ Posted: 26-May-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda



☐ Honda Stream 1.8A (New 5-yr COE) \$36,800 \$7,360 /yr 25-Mar-2008 1,799 cc - MPV Available

\$0 Drive Away Possible With Any Scrap Car Trade In. 1 Owner. Low Mileage. Super Well Maintain Unit, No Repairs Needed, Look, Drives And Feel Like New! 6 Months Comprehensive Warranty Provided, 24/7 Fr...

PREMIUM AD

☆ Posted: 20-Jul-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda



☐ Honda Stream 1.8A (COE till 03/2023) \$34,800 \$7,440 /yr 27-Mar-2008 1,799 cc - MPV Available

Call Now.

☆ Posted: 14-Jun-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda

SHORTLISTED HISTORY

Compare

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 #01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747-6720 REG NO 200501102H

MSIG INSURANCE (S) PTE LTD

4 Shenton Way # 21 - 01

SGX Centre 2

Singapore 068807

Hot line : 6827 - 7660

Fax : 6225-7402 (CLAIM)

Quotation

DATE : 23.07.2018

VEH NO : SKD145P

MODEL : Honda Stream

D O A : 20.07.2018

YR REF : SKU1067K

Attn : Motor Claim Dept

(pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKD145P (Honda Stream)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Front Bumper <i>dehnd</i>	1	635.60 ✓
2	Front Bumper Clips <i>m</i>	1 set	30.00 ✓
3	Front Bumper Side Holder - LH & RH <i>m</i>	2	51.00 ✓
4	Front Bumper Reinforcement <i>sent</i>	1	218.80 ✓
5	Front Bumper Lower Grille <i>new</i>	1	123.50 x
6	Front Bumper Fog Lamp - LH & RH <i>new</i>	2	573.40 x
7	Front Grille <i>smashed</i>	1	202.20 ✓
8	Front Grille Chrome Moulding <i>crackd</i>	1	245.70 ✓
9	Front Grille Logo <i>m</i>	1	28.40 ✓
10	Headlamp - LH & RH <i>LH smashed, RH ut</i>	2	1,360.80 ✓
11	Headlamp Lower Bracket - LH & RH <i>ut crackd</i>	2	73.00 36.50
12	Front Support Panel <i>Distorted</i>	1	587.00 ✓
13	Front Support Panel Top Cover <i>dehnd</i>	1	68.90 ✓
14	Front Support Panel Top Cover Clips <i>m</i>	1 set	20.00 ✓
15	Front Fender - LH & RH <i>LH Buckled</i>	2	973.00 486.50
16	Front Fender Top Garnish - LH & RH <i>new</i>	2	73.00 x
17	Front Fender Top Garnish Clips	1 set	20.00 x
18	Bonnet <i>Distorted</i>	1	638.90 ✓
19	Bonnet Lock <i>Damaged</i>	1	68.50 ✓
20	Bonnet Hinge - LH & RH <i>new</i>	2	77.80 x
21	Bonnet Insulation <i>crackd</i>	1	113.80 ✓
22	Bonnet Insulation Clips <i>new</i>	1 set	30.00 ✓
23	Horn <i>Damaged</i>	1	76.30 ✓
24	Air Con Condenser <i>Best</i>	1	826.60 ✓
25	Air Con Fan Blade <i>new</i>	1	65.20 x
26	Air Con Fan Motor	1	356.00 x
27	Air Con Fan Cowling <i>Best</i>	1	85.10 ✓
28	Radiator <i>Distorted</i>	1	1,284.20 ✓
29	Radiator Top Bracket - LH & RH <i>Best</i>	2	48.00 ✓

RE: ESTIMATE FOR ACCIDENT REPAIR SKD145P (Honda Stream)

30	Radiator Fan Blade	at	1	68.40	✓
31	Radiator Fan Motor	new	1	316.00	X
32	Radiator Fan Cowling	crushed	1	98.70	✓
33	Radiator Spare Tank	Defunct.	1	58.40	✓
34	Radiator Top Hose	new	1	29.10	X
35	Rear Bumper	Distorted	1	688.90	✓
36	Rear Bumper Clips	new	1 set	30.00	✓
37	Rear Bumper Side Holder - LH & RH	new	2	42.40	✓
38	Rear Bumper Lower Bracket - LH & RH	But	2	51.00	✓
39	Rear End Panel	Dented	1	398.70	✓
40	Rear End Panel Inner Member	But	1	186.90	✓
41	Rear End Panel Top Garnish	Defunct	1	116.70	✓
42	Taillamp - LH & RH	new	2	677.60	X
43	Tailgate	Distorted	1	903.20	✓
44	Tailgate Lock	Defunct	1	109.60	✓
45	Tailgate Weatherstripe	at	1	116.90	✓
46	Tailgate Inner Trim Board	crushed	1	285.40	✓
47	Tailgate Inner Trim Board Clips	new	1 set	30.00	✓
48	Tailgate Glass Moulding	new	1	60.70	✓
49	Stream Emblem	new	1	31.60	✓
50	Rear Fender Inner Trim - LH & RH	new	2	449.40	X
51	Rear Fender Inner Trim Clips		2 sets	60.00	X
52	Floor Panel	Repair	1	912.30	X
53	Floor Panel Top Board - LH & RH	new	2	238.40	X
54	Rear Exhaust Pipe	new	1	524.20	X
55	Rear Exhaust Mounting	new	1	30.40	X

\$ 15,469.60
 (3,093.92)
 \$ 12,375.68

Less 20%

S/NETT ITEMS

1	Front Number Plate	new	1 set	30.00	X
2	Front Number Plate Holder	new	1	30.00	X
3	Front Bumper Lower Spoiler	Repair	1	880.00	X
4	Rear Number Plate	new	1 set	30.00	X
5	Rear Number Plate Holder		1	30.00	X
6	Rear Bumper Lower Spoiler	Distorted	1	880.00	680
7	Reverse Sensor	Defunct	1 set	280.00	200
8	Rear End Panel Sealant	new	1	60.00	✓
9	Tailgate Glass Sealant	new	1	60.00	✓
10	Floor Panel Insulation Pads	new	1	250.00	X

Total parts

\$ 14,905.68

LABOUR CHARGE

1	To knocking & pull out front & rear portion & renew above parts	\$ 2,400.00	1800
---	---	-------------	------

RE: ESTIMATE FOR ACCIDENT REPAIR SKD145P (Honda Stream)

2	To putty and spray up paint works	\$	2,400.00 2000
3	To check wiring system	\$	100.00 60
4	To remove reverse sensor	\$	100.00 50
5	To remove upholstery	\$	150.00 80
6	To remove tailgate glass	\$	180.00 120
7	To transfer tailgate fittings	\$	150.00 80
8	To remove exhaust pipe	\$	150.00 X
9	To remove radiator, condenser & to re-gas	\$	180.00 120
		\$	5,810.00

4310

GRAND TOTAL

\$ 20,715.68

GST Will be reflected in the final bills

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 13646.24.

L/S: 9.8K (Nett Value)

13 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18013402/ASD3N2

Date: 20/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29071174QMX
Claimant Vehicle No :	SKD145P	Insured Vehicle No :	SKU1067K
Date of Loss:	20/07/2018	Nature of Claim:	TP
		Claim No:	565044

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD145P	Engine No:	R18A1742175
Make & Model:	HONDA STREAM, 1.8 (A)	Chassis No:	RN61037307
Reg. Date:	31/07/2007 (Man. Year: 2007)	Odometer:	0 km
Colour:	White		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,905.68	9,336.24	5,569.44	37.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,810.00	4,310.00	1,500.00	25.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,715.68	13,646.24	7,069.44	34.13
Approved Total (Overridden) (\$\$)		9,800.00		
(\$\$)	20,715.68	9,800.00	10,915.68	52.69
+ GST 7.00/7.00% (\$\$)	1,450.10	686.00	764.10	52.69
Nett Amount (\$\$)	22,165.78	10,486.00	11,679.78	52.69

INSPECTION

Date of Assignment:	23/07/2018	
Date Inspected:	23/07/2018 Inspected At:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717
Estimated Period of Repair:	13.0 days	

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Aug 2018)
Parts:	M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD145P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	635.60 FL	*635.60 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	2		*FRONT BUMPER SIDE HOLDER-LH & RH	Necessary	51.00 FL	*51.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	218.80 FL	*218.80 FL
5	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	123.50 FL	*- FL
6	2		*FRONT BUMPER FOG LAMP-LH & RH	Not Necessary	573.40 FL	*- FL
7	1		*FRONT GRILLE	Smashed	202.20 FL	*202.20 FL
8	1		*FRONT GRILLE CHROME MOULDING	Cracked	245.70 FL	*245.70 FL
9	1		*FRONT GRILLE LOGO	Necessary	28.40 FL	*28.40 FL
10	2		*HEADLAMP-LH & RH	N/s Smashed/O/s Cut	1,360.80 FL	*1,360.80 FL
11	1		*HEADLAMP LOWER BRACKET-LH & RH	N/s Cracked	73.00 FL	*36.50 FL
12	1		*FRONT SUPPORT PANEL	Distorted	587.00 FL	*587.00 FL
13	1		*FRONT SUPPORT PANEL TOP COVER	Deformed	68.90 FL	*68.90 FL
14	1		*SET FRONT SUPPORT PANEL TOP COVER CLIPS	Necessary	20.00 FL	*20.00 FL
15	1		*FRONT FENDER-LH & RH	N/s Buckled	973.00 FL	*486.50 FL
16	2		*FRONT FENDER TOP GARNISH-LH & RH	Not Necessary	73.00 FL	*- FL
17	1		*SET FRONT FENDER TOP GARNISH CLIPS	Not Necessary	20.00 FL	*- FL
18	1		*BONNET	Distorted	638.90 FL	*638.90 FL
19	1		*BONNET LOCK	Damaged	68.50 FL	*68.50 FL
20	2		*BONNET HINGE-LH & RH	Not Necessary	77.80 FL	*- FL
21	1		*BONNET INSULATION	Crumpled	113.80 FL	*113.80 FL
22	1		*SET BONNET INSULATION CLIPS	Necessary	30.00 FL	*30.00 FL
23	1		*HORN	Damaged	76.30 FL	*76.30 FL
24	1		*AIR CON CONDENSER	Bent	826.60 FL	*826.60 FL
25	1		*AIR CON FAN BLADE	Not Necessary	65.20 FL	*- FL
26	1		*AIR CON FAN MOTOR	Not Necessary	356.00 FL	*- FL
27	1		*AIR CON FAN COWLING	Bent	85.10 FL	*85.10 FL
28	1		*RADIATOR	Distorted	1,284.20 FL	*1,284.20 FL
29	2		*RADIATOR TOP BRACKET-LH & RH	Bent	48.00 FL	*48.00 FL
30	1		*RADIATOR FAN BLADE	Cut	68.40 FL	*68.40 FL
31	1		*RADIATOR FAN MOTOR	Not Necessary	316.00 FL	*- FL
32	1		*RADIATOR FAN COWLING	Cracked	98.70 FL	*98.70 FL
33	1		*RADIATOR SPARE TANK	Deformed	58.40 FL	*58.40 FL
34	1		*RADIATOR TOP HOSE	Not Necessary	29.10 FL	*- FL
35	1		*REAR BUMPER	Distorted	688.90 FL	*688.90 FL
36	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
37	2		*REAR BUMPER SIDE HOLDER-LH & RH	Necessary	42.40 FL	*42.40 FL
38	2		*REAR BUMPER LOWER BRACKET-LH & RH	Bent	51.00 FL	*51.00 FL
39	1		*REAR END PANEL	Dented	398.70 FL	*398.70 FL
40	1		*REAR END PANEL INNER MEMBER	Bent	186.90 FL	*186.90 FL
41	1		*REAR END PANEL TOP GARNISH	Deformed	116.70 FL	*116.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	2		*TAILLAMP-LH & RH	Not Necessary	677.60 FL	*- FL
43	1		*TAILGATE	Distorted	903.20 FL	*903.20 FL
44	1		*TAILGATE LOCK	Damaged	109.60 FL	*109.60 FL
45	1		*TAILGATE WEATHERSTRIPE	Cut	116.90 FL	*116.90 FL
46	1		*TAILGATE INNER TRIM BOARD	Cracked	285.40 FL	*285.40 FL
47	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FL	*30.00 FL
48	1		*TAILGATE GLASS MOULDING	Necessary	60.70 FL	*60.70 FL
49	1		*STREAM EMBLEM	Necessary	31.60 FL	*31.60 FL
50	2		*REAR FENDER INNER TRIM-LH & RH	Not Necessary	449.40 FL	*- FL
51	2		*SETS REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 FL	*- FL
52	1		*FLOOR PANEL	Repair	912.30 FL	*- FL
53	2		*FLOOR PANEL TOP BOARD-LH & RH	Not Necessary	238.40 FL	*- FL
54	1		*REAR EXHAUST PIPE	Not Necessary	524.20 FL	*- FL
55	1		*REAR EXHAUST MOUNTING	Not Necessary	30.40 FL	*- FL
56	1		*SET FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
57	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
58	1		*FRONT BUMPER LOWER SPOILER	Repair	880.00 FS	*- FS
59	1		*SET REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
60	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
61	1		*REAR BUMPER LOWER SPOILER	Distorted	880.00 FS	*680.00 FS
62	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
63	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
64	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
65	1		*FOOR PANEL INSULATION PADS	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,999.60	11,420.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,093.92	2,084.06
Total Parts (\$\$)	14,905.68	9,336.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY AND SPRAY UP PAINT WORKS	New	2,400.00	2,000.00
2	TO CHECK WIRING SYSTEM	New	100.00	60.00
3	TO REMOVE REVERSE SENSOR	New	100.00	50.00
4	TO REMOVE UPHOLSTERY	New	150.00	80.00
5	TO REMOVE TAILGATE GLASS	New	180.00	120.00
6	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
7	TO REMOVE EXHAUST PIPE	New	150.00	-
8	TO REMOVE RADIATOR,CONDENSER & TO RE-GAS	New	180.00	120.00
9	TO KNOCKING & PULL OUT FRONT & REAR PORTION & RENEW ABOVE PARTS	New	2,400.00	1,800.00
Gross Labour Cost (\$\$)			5,810.00	4,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >