

VEHICLE NO : SLV 1925 S
 MODEL : KIA NIRO 1.6 A
 WIP : 32569

Material	:	\$	<u>1,104.00</u>
Labour	:	\$	<u>2,910.00</u>
Sub-Total	:	\$	<u>4,014.00</u>
	:		<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>4,014.00</u>
GST 7%	:	\$	<u>280.98</u>
Grand Total	:	\$	<u>4,294.98</u>
Finalise By/Date	:	<u>LOI / 15/01/19</u>	

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 5 WORKING DAYS + 2 Days (1) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 7

☒ TP claim SKN9899K

☒ Claim GIA / LTA fee \$2.00

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR GUC TRANSPORT	Cust No/Name /MR GUC TRANSPORT
C/O AXA INSURANCE PTE LTD	Reg No/Reg Date SLV1925S / 26/12/2017
MOTOR CLAIM DEPARTMENT	Date In/Mileage 04/09/2018/ 76907
8 SHENTON WAY #24-01	Chassis/Package KNACC81CVJ5104700 /KC17RP
SINGAPORE 068811	Engine No G4LEHS233808
Contact No	Make/Model KIA/NIRO 1.6 A G979
04/09/	Colour/Trim C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSK00001	Cash	15/01/2019/ 12:45	TLE	260 / AiTing	32569

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, REPAIR REAR END PANEL, RH REAR FENDER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 1100.00
E PNT98000 RESPRAY ON REAR BUMPER, REAR END PANEL, RH REAR FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 1260.00
E PNT88000 REMOVE & REINSTALL REAR FLOOR BOARD, TRIMS & CARPET TO FACILITATE REPAIR				✓ 120.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				✓ 50.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				✓ 200.00
M SUNDRY APPLT ANTI CORROSION ON AFFECTED AREAS				✓ 80.00
E PNT88000 REMOVE & REINSTALL REVERSE SENSOR TO FACILITATE REPAIR				✓ 80.00
M SUNDRY SUNDRIES				✓ 20.00
X COVER-RR BUMPER,UPR	1.00	✓ 423.00	00.00	423.00
X COVER-RR BUMPER LWR	1.00	✓ 392.00	00.00	392.00
X PIECE-RR BUMPER SIDE,RH	1.00	✓ 16.00	00.00	16.00
X BRACKET ASSY-RR BUMPER SIDE,RH	1.00	✓ 25.00	00.00	25.00
X REFLECTOR/REFLEX ASSY-RR RH	1.00	✓ 104.00	00.00	104.00
X GARNISH ASSY-QTR SIDE,RH	1.00	✓ 144.00	00.00	144.00
Z TEXT TP CLAIM AXA SKN98899K DOA : 20.07.18 SURVEYOR RASUL LKK 04.09.18 5 REPAIR DAYS				

Cycle & Carriage celebrates 120 years.
Visit www.cyclecarriage.com/120 for more info!

Parts	1,104.00	Nett	4,014.00
Labour	2,810.00	7% GST on	280.98
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	4,294.98
Sundry/Others	100.00		
Total(w/o GST)	4,014.00		

This is not an official tax invoice.
This is a computer generated document, no signature is required.