



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR GUC TRANSPORT	Cust No/Name /MR GUC TRANSPORT
BLK 579 WOODLANDS DR 16	Reg No/Reg Date SLV1925S / 26/12/201
#11-596	Date In/Mileage / 0
SINGAPORE 730579	Chassis No KNACC81CVJ5104700
Contact No Mobile: 82786866	Engine No G4LEHS233808
	Make/Model KIA/NIRO 1.6 A G979
	Colour/Trim C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	23/07/2018/ 12:36	QUE	261 / Edwin Caina	32569
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW & RE-ALIGN RR DAMAGED PORTION:				1100 1650.00
	RENEW RR BUMPER				
	REPAIR RR END PNL & RR FENDER RH				
E PNT98000	RESpray RR BUMPER , RR END PNL & RR FENDER RH				1260 1500.00
E PNT88000	REMOVE & REFIT RR FLR BOARD, TRIM & CARPET TO FACILITATE REPAIR				120 200.00
A 54900099	CHECK WIRING & ELECTRICAL SYSTEM				50.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				200.00
	USING HI-SCAN PRO TEST				
M SUNDRY	APPLT ANTI CORROSION ON AFFECTED AREAS				80 120.00
E PNT88000	REMOVE & REFIT REVERSE SENSOR				80 100.00
M SUNDRY	Sundries				20 50.00
M COVER-RR BUMPER, UPR		1.00	423.00	00.00	DE 423.00
M COVER-RR BUMPER LWR		1.00	392.00	00.00	DE 392.00
M PIECE-RR BUMPER SIDE, RH		1.00	16.00	00.00	16.00
M MOULDING ASSY-RR BUMPER SIDE, R		1.00	20.00	00.00	20.00
M BEAM-RR BUMPER		1.00	261.00	00.00	261.00
M STAY-RR BUMPER RH		1.00	67.00	00.00	67.00
M BRACKET ASSY-RR BUMPER SIDE, RH		1.00	25.00	00.00	25.00
M SENSOR ASSY-PARKING ASSIST SYS		1.00	135.00	00.00	135.00
M REFLECTOR/REFLEX ASSY-RR RH		1.00	104.00	00.00	104.00
M COVER-RR BUMPER SIDE UNDER, RH		1.00	27.00	00.00	27.00
M GARNISH ASSY-QTR SIDE, RH		1.00	144.00	00.00	144.00

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Rasul - Hp 90010068SURVEYOR SIGNATURE: [Signature]DATE: 04/08/18 @ 15:00 hrs

Confirm & accepted by

REMARKS: 5 daysRepair by paint

7% GST on

Nett	5,484.00
	383.88
Total Payable	5,867.88

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.