

27/03/2011

ASS. REC. BY:

REF

CS/CTI18013408/Ad3n2

Special Instruction:

Surveyor:
menmen

Adrian

ASSIGNMENT (Office)

From (Person):

Huang Shiang Yi

of

CTI

Date/Time:

24/7/18 @ 10:16am

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD516R

Insured:

XD 1422D

at Workshop n/s:

MCS Garage

Tel:

92700917

of

10 Kaki Bkt Rd 2 #03-25

Policy No:

DMCVSN1756291700

Claim No:

SNM18D0358302

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/07/2018

CA / REV / REP. / REV 24 HRS

up?

H.O.D. Endorsement:

Date/Time:

11am @ 24/7/18

Person Contacted:

Mr. Kendrick

Vehicle ☒ IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLD516R - NA/INC18013293/Z4

DOA: 20/7/2018

XD 1422D - NA/INC18013293/Z4

DOA: 20/7/2018

Lg \$5200, 4 days (Red \$775.00, 60%)

(08/11/13) wef

REF: CTI

ASS. REC. BY:

ASSIGNMENT

From: Date: 24/07/18

Estimated Cost:

OP/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SLD 516R

at Workshop m/s MCS Garage

of 10 Kaki Bkt Rd 2 #03-25

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLD516R Yr Regn: 2016, May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 6 c.c. 2488

Colour: Bronze A/C: Insured / Std / NI / NA

Sp. Reading: 39750 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM6GJ103260238019

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40R19

R: 245/40R19

BS / DON / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 24/07/18

Survey held at MCS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP chm

RECEIVED 21 DEC 2018

Date/Time, File Pass to?

☐ : Preli. Report

11/11/12 MIA

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format: MIA-TP

Lump Sum / I.B.I. (\$) 5200

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jul 2018		24 Jul 2018 10:16 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SRISHTI ENGINEERING PTE LTD, Co. Reg. No.: -		
Main Claimant:	TU KOK CHENG (ZHANG GUOZHENG), ID: S8611642A		
Vehicle Reg. No.:	SLD516R	Date of Loss:	20/07/2018 16:00 - :59
Claim Type:	TP / SNM18D03583C02	Policy/Cover Note No.:	DMCVSN1756291700 (Comprehensive)
Vehicle Reg. No. (Insured):	XD1422D	Policy No. (Claimant):	5090435498-01
		Excess:	S\$0.00
Repairer:	MCS GARAGE (HQ) 10 KAKI BUKIT ROAD 2, #03-25 FIRST EAST CENTRE, 417868 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Hwang Shiang Yi - 63896541]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/08/2018]		
Driver/Custodian (Insured):	THIYAGARAJAN RAMACHANDRAN (47 / Male), NRIC: F8487527U, Tel: +6586787030		
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
ONG BOCK KEE
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
TAN YING XIAN SELWYN

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong-6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.Ins.M89.107405.18 (sj)
Your Ref: **SNM18D03585C02**

24 July 2018

CHINA TAIPING INSURANCE (S'PORE) PTE LTD

3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Attention: Motor Claims Department

BY FAX: 6224 7175

email: claimsdept@sg.cntaiping.com
email: lucas.lee@sg.cntaiping.com

Dear Sirs,

ACCIDENT INVOLVING SLD 516 R & XD 1422 D ON 21 JULY 2018 ALONG JUNCTION OF KRANJI WAY & KRANJI LINK AT ABOUT 1830 HOURS

We refer to your email dated 23 July 2018 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Adrian Ling as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: MCS Garage
10 Kaki Bukit Road 2
#03-25 First East Centre
Singapore 417868
Contact Person: Mr Kendrick (9270 0917) / 8285-7623 (Ah Hock)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

cc: SLD 516 R - By Fax: 6538-4322

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/07/2018 11:11
Date Of Accident	20/07/2018 16:30
Exact Location Of Accident	JUNG KRANJI WAY & KRANJI LINK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD516R
Insured/Policyholder	
Name Of Registered Owner	TU KOK CHENG (ZHANG GUOZHENG)
NRIC No	S8611642A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92333233
Alternative Phone No	OFFICE-92333233

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA6 4-DOOR SEDAN 2.5L SP.6EAT SR LED
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5090435498-01
Cover Note Number	

Driver

Name of Driver	TU KOK CHENG (ZHANG GUOZHENG)
NRIC No	S8611642A
Date Of Birth	03/05/1986
Occupation	INDOOR
Date Of Driving Pass	06/01/2005
Driving Experience	13 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92333233
Fax Number	
Contact Number	OFFICE-92333233
Email Address	NOEMAIL

Address	BLK 312B SUMANG LINK
	#12-165
Postcode	822312
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : -
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, MY VEHICLE WAS STATIONARY STOPPED ALONG KRANJI WAY AS IT WAS CONGESTED. SUDDENLY VEHICLE B REVERSED HIS VEHICLE AND HIT ONTO MY VEHICLE FRONT PORTION

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD1422D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	THIYAGARAJAN RAMACHANDRAN
NRIC/Passport Number	F8487527U
Contact Number	86787030
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to statement

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/FIN No.:

MCS Garage

10 Kaki Bukit Road 2 #03-25, First East Centre Singapore 471868

Tel: 9270 0917 6538 4322

Vehicle No.: SLD 516R

TP China.
Xiao Chen.
Model: MAZDA 6
Jm66J103260238018.

QTY List Price:

Prices \$

1	Front bonnet <i>Buckled</i>	1204.00 ✓
1	Front bonnet w/strip- FRT	68.60 +
1	Front bonnet w/strip- Rear	58.60 +
1	Front bonnet insulator	211.20 +
10	Front bonnet insulator clips @ 5.50 <i>new</i>	55.00 x
1	Front bonnet lock	186.90 +
1	Front bonnet lock bracket	81.50 +
2	Front bonnet hinges- R/L @ 55.00	110.00 +
1	Front bumper <i>Deformed</i>	1154.00 ✓
2	Front bumper chrome mouldings- R/L @ 211.50 <i>new</i>	423.00 +
1	Front bumper top pad <i>Distorted</i>	299.30 ✓
8	Front bumper top pad clips @ 4.50 <i>new</i>	36.00 - 20
1	Front bumper top pad garnish <i>cracked</i>	131.20 ✓
2	Front bumper PDC sensor @ 281.60 <i>new</i>	563.20 +
1	Front bumper inner frame pad <i>cracked</i>	196.20 ✓
1	Front bumper top beam <i>new</i>	155.00 +
1	Front bumper reinforcement <i>new</i>	574.20 +
2	Front bumper side retainers- R/L @ 32.60 <i>new</i>	65.20 ✓
10	Front bumper clips @ 5.50 <i>new</i>	55.00 - 30
1	Front bumper inner sponge <i>cracked</i>	132.80 ✓
1	Front grille <i>cut</i>	481.80 ✓
1	Front grille logo <i>new</i>	62.70 ✓
2	Front headlamps- R/L @ 3209.00 <i>RH cracked</i>	6418.00 3209
1	Front headlamp panel- RH <i>new</i>	145.00 X

Vehicle No.: SLD 516R

1	Front support	} <i>new</i>	6986.20	545.00 +
1	Horn		5588.96	105.60 +
				<hr/>
				13519.00
Less 20%				(2703.80)
				<hr/>
Subtotal				10815.20

Labour Charges:

To checking F/electrical wiring	50.00	30
To remove, refix A/C condenser and refill A/C gas	180.00	+
To respray undercoating	80.00	X
To respray painting and etc	900.00	400
Panel beating, cut, weld, remove and replacing above parts	900.00	500
Subtotal	<hr/> 2110.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 12925.20

total: 6518.96
1/s: 52K.
04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18013408/AQD3N2

Date: 26/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1756291700
Claimant Vehicle No :	SLD516R	Insured Vehicle No :	XD1422D
Date of Loss:	20/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03583C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD516R	Engine No:	PY20765777
Make & Model:	MAZDA 6, 2.5 4-DOOR SEDAN 2.5L SP.6E (A)	Chassis No:	JM6GJ1032G0238019
Reg. Date:	31/05/2016 (Man. Year: 2016)	Odometer:	39750 km
Colour:	Bronze		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40R19	Rear Tyre Size:	245/40R19
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,815.20	5,588.96	5,226.24	48.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,110.00	930.00	1,180.00	55.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,925.20	6,518.96	6,406.24	49.56
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	12,925.20	5,200.00	7,725.20	59.77

INSPECTION

Date of Assignment:	24/07/2018	
Date Inspected:	24/07/2018 Inspected At:	MCS GARAGE (HQ) 10 KAKI BUKIT ROAD 2, #03-25 FIRST EAST CENTRE Singapore 417868
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Dec 2018)
Parts:	143	MAZDA 6 2.5 4-DOOR SEDAN 2.5L SP.6E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD516R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	1,204.00 FL	*1,204.00 FL
2	1		*FRONT BONNET W/STRIP-FRT	Not Necessary	68.60 FL	*- FL
3	1		*FRONT BONNET W/STRIP-REAR	Not Necessary	58.60 FL	*- FL
4	1		*FRONT BONNET INSULATOR	Not Necessary	211.20 FL	*- FL
5	10		*FRONT BONNET INSULATOR CLIPS	Not Necessary	55.00 FL	*- FL
6	1		*FRONT BONNET LOCK	Not Necessary	186.90 FL	*- FL
7	1		*FRONT BONNET LOCK BRACKET	Not Necessary	81.50 FL	*- FL
8	2		*FRONT BONNET HINGES-R/L	Not Necessary	110.00 FL	*- FL
9	1		*FRONT BUMPER	Deformed	1,154.00 FL	*1,154.00 FL
10	2		*FRONT BUMPER CHROME MOULDINGS-R/L	Not Necessary	423.00 FL	*- FL
11	1		*FRONT BUMPER TOP PAD	Distorted	299.30 FL	*299.30 FL
12	8		*FRONT BUMPER TOP PAD CLIPS	Necessary	36.00 FL	*20.00 FL
13	1		*FRONT BUMPER TOP PAD GARNISH	Cracked	131.20 FL	*131.20 FL
14	2		*FRONT BUMPER PDC SENSOR	Not Necessary	563.20 FL	*- FL
15	1		*FRONT BUMPER INNER FRAME PAD	Cracked	196.20 FL	*196.20 FL
16	1		*FRONT BUMPER TOP BEAM	Not Necessary	155.00 FL	*- FL
17	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	574.20 FL	*- FL
18	2		*FRONT BUMPER SIDE RETAINERS-R/L	Necessary	65.20 FL	*65.20 FL
19	10		*FRONT BUMPER CLIPS	Necessary	55.00 FL	*30.00 FL
20	1		*FRONT BUMPER INNER SPONGE	Cracked	132.80 FL	*132.80 FL
21	1		*FRONT GRILLE	Cut	481.80 FL	*481.80 FL
22	1		*FRONT GRILLE LOGO	Necessary	62.70 FL	*62.70 FL
23	1		*FRONT HEADLAMPS-R/L	O/s Cracked	6,418.00 FL	*3,209.00 FL
24	1		*FRONT HEADLAMP PANEL-RH	Not Necessary	145.00 FL	*- FL
25	1		*FRONT SUPPORT	Not Necessary	545.00 FL	*- FL
26	1		*HORN	Not Necessary	105.60 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	13,519.00	6,986.20
- List Item Discount on L Items 20.00/20.00% (S\$)	2,703.80	1,397.24
Total Parts (S\$)	10,815.20	5,588.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECKING F/ELECTRICAL WIRING	New	50.00	30.00
2	TO REMOVE,REFIX A/C CONDENSER AND REFILL A/C GAS	New	180.00	-
3	TO RESPRAY UNDERCOATING	New	80.00	-
4	TO RESPRAY PAINTING AND ETC	New	900.00	400.00
5	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS	New	900.00	500.00
Gross Labour Cost (\$\$)			2,110.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >