

3/23/2018

ASS. REC. BY:

REF: CS/C718013410/T11d3

Special Instruction:

MD/2018

Tauhid
Irene Jay

ASSIGNMENT (Office)

of C71

Date/Time: 24/7/18 @ 8.54am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKX 5610A

Insured:

SKV 86967

at Workshop m/s

Mova Automotive

Tel:

02723842

of

B1k1008 #01-04 Bkt Meruh Lene 3

Policy No:

DMPCSN3072901702

Claim No:

SNM18D03555C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/07/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

11:15am @ 24/7/18

Person Contacted:

Annie

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

7/8/18 - vehicle still not in.

13/8/18 - vehicle not in yet

16/8/18 - vehicle not in (crystal)

19/9/18 - vehicle still not in (nitha)

28/9/18 - VNI

27/7/18

- called Nitha, vehicle still not in

31/7/18

- called Vehicle not in yet (nitha)

31/8/18

- called Nitha vehicle still not in yet.

SKX 5610A - X

SKV 86967 - X.

REFERENCE

Taylor

REF:

CTI

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GiA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SKX 5610A Yr Regn: 2015 Dec.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Odyssey

C.C

2356

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

21235

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMRC18406 (200740)

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUM / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

3/10/18

Survey held at

Move BM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt + N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Lump Sum \$35501- (Red. 2307.28, 39%)

RECEIVED 30 OCT 2018

Date/Time, File Pass to?



: Preli. Report

1) 30/10/18



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS \$

) Photos:

) Others:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

35501-

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jul 2018		24 Jul 2018 08:54 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	IMRAN ABDULLAH TAN @ TAN KIM TECK, ID: S1358323D		
Main Claimant:	RYU SEUNG YOUN, ID: G1753642M		
Vehicle Reg. No.:	SKX5610A	Date of Loss:	18/07/2018 08:00 - :59
Claim Type:	TP / SNM18D03555C02	Policy/Cover Note No.:	DMPCSN3072901702 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	SKV8696T	Policy No. (Claimant):	VPA/P2011180
		Excess:	S\$0.00
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/08/2018]		
Driver/Custodian (Insured):	AZIZ IMRAN TAN (23 / Male), NRIC: S9427218A, Tel: +6591271380		
Adj Asg. Remarks:	EST \$3838.65, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: Tan Yoong Wei <tanyw@movac.com.sg>
Sent: Tuesday, 30 October 2018 10:05 AM
To: Denise Tay (LKKAUTO)
Cc: Taufikh (LKKAUTO)
Subject: RE: FINALISE SKX5610A

Yes we accept the offer for this vehicle lumpsum \$3550 with 4 working days
Thank you.

Best Regards,
Tan Yoong Wei
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Friday, 26 October 2018 11:41 AM
To: Tan Yoong Wei
Subject: RE: FINALISE SKX5610A

Dear Yoong Wei,

I've check with Taufikh

Regarding this vehicle labour

1. To repair front fender lh , and side mirror ,front door lh i have open the side mirror to repair the item can i have the labour total \$500? \$450
2. Tp spray on on front bumper, front fender lh, front side mirror cover lh, front door lh can make it at \$600? \$500

There for offer lump sum \$3550, 4days

Please re-consider on the lump sum amount

Best Regards,
Denise Tay | Case Handler

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/07/2018 11:30
Date Of Accident	18/07/2018 08:40
Exact Location Of Accident	ALONG OUTRAM ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX5610A
Insured/Policyholder	
Name Of Registered Owner	RYU SEUNG YOUN
NRIC No	G1753642M
Email Address	HUHSIK@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93959335
Alternative Phone No	OTHERS-93959335

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY 2.4 EXV-S CVT SR (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P2011180
Cover Note Number	

Driver

Name of Driver	RYU SEUNG YOUN
NRIC No	G1753642M
Date Of Birth	07/04/1978
Occupation	INDOOR
Date Of Driving Pass	14/02/2018
Driving Experience	0 YEAR AND 5 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-93959335
Fax Number	
Contact Number	OTHERS-93959335
Email Address	HUHSIK@GMAIL.COM

Address	331 RIVER VALLEY ROAD #09-04 YONG AN PARK
Postcode	238363
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : HUH YOON GENDER: : MALE
Passenger 2	NAME: : HUH WOONG GENDER: : MALE
Passenger 3	NAME: : HUH YOOL GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STEKCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB7575G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKV8696T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SLZ9317Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature:

Date & Time: 18/7/18

Driver's Signature:

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature:

Name:

NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SKX5610A	ACCIDENT DATE & TIME: 18-07-18, 8:40 AM
CONTACT NUMBER: 9305 9335	E-MAIL ADDRESS:
LOCATION: Along Outram Road	
I was waiting at the traffic light when suddenly SKV8696T hit my vehicle from the side. SKV8696T was pushed by SLB9317Z into my lane and caused damage on my vehicle as well as the taxi in front of me. There was no injury. Please refer to my in car camera footage.	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
Please state:	
☐ Claim Own Policy ☒ Claim Third Party ☐ Claim OD/TP at other workshop ☐ Reporting Only	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 18/7/18

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

20/07/2018

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- SKX5610A

Veh Model :- HONDA ODYSSEY 2.4

Estimate# :- CK417724

Claim # :-

ACC. Date :- 18/07/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT BUMPER	1 PC	986.30	986.30
2.	FRONT BUMPER CLIPS	10 PC	3.80	38.00
3.	FRONT BUMPER LOWER SPOILER LH	1 PC	245.00	245.00
4.	FRONT BUMPER RETAINER LH	1 PC	38.90	38.90
5.	FRONT HEADLAMP LOWER BRACKET LH	1 PC	54.20	54.20
6.	FRONT WHEEL RIM LH	1 PC	54.20	54.20
7.	FRONT HEADLAMP LH - CHECK ON	1 PC	1,297.00	1,297.00
8.	FRONT SIDE MIRROR LH - REPAIR	1 PC		
9.	FRONT FOG LAMP GARNISH LH - CHECK ON	1 PC		
10.	FRONT FOG LAMP LH - CHECK ON	1 PC		

LIST TOTAL S\$

20% DISCOUNT S\$

Parts \$ 5197.40 - 20%

\$14157.92

2,659.40

-531.88

2,127.52

LABOUR :

TO REPAIR FRONT FENDER LH, FRONT SIDE MIRROR LH, FRONT LH DOOR AND REALIGN ACCIDENT AFFECTED AREAS. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS.

TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS

TO TEST WATER LEAKAGE FOR FRONT HEADLAMP

TO CHECK FRONT WHEEL ALIGNMENT

TO REMOVE & REPLACE FRONT TYRE & BALANCING TYRE

TO RUST PROOF AFFECTED AREAS

LABOUR TOTAL S\$

Labour \$ 1250

total \$ 5407.92

total L/s \$ 4300 4 DAYS.

500 400 450

500.00

600 400 500

750.00

20? 40.00

✓ 80.00

30. 50.00

20. 40.00

1,460.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

3,587.52

GST @ 7 %

251.13

AMOUNT DUE S\$

3,838.65

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

SUPPLEMENTARY

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Page : 1
Veh No : SKX5610A
Model : HONDA ODYSSEY
Acc Date : 18-Jul-18
Incharge : AH WEI

No	Description	Qty	U.Price	Amt \$
<u>LIST ITEMS:</u>				
<u>PART WITHOUT PRICE DURING ESTIMATE</u>				
1	FRONT HEADLAMP LH	1	\$ 2,837.20	\$ 2,837.20
	LIST TOTAL S\$			\$ 2,837.20
	20% DISCOUNT			\$ 567.44
				<u>\$ 2,269.76</u>

2237
cut ✓

2237 before 20%

NON-TAX AMOUNTS	\$2,269.76
GST @ 7%	\$158.88
AMOUNT DUE	<u>\$2,428.64</u>

Customer's Signature/Co. Stamp

MOVA AUTOMOTIVE PTE LTD

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314

Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

20/07/2018

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1
 Veh # :- SKX5610A
 Veh Model :- HONDA ODYSSEY 2.4
 Estimate# :- CK417724
 Claim # :-
 ACC. Date :- 18/07/18
 Terms :- C.O.D Days
 Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	FRONT BUMPER	1	PC	986.30	986.30
2.	FRONT BUMPER CLIPS	10	PC	3.80	38.00
3.	FRONT BUMPER LOWER SPOILER LH	1	PC	245.00	245.00
4.	FRONT BUMPER RETAINER LH	1	PC	38.90	38.90
5.	FRONT HEADLAMP LOWER BRACKET LH	1	PC	54.20	54.20
6.	FRONT WHEEL RIM LH	1	PC	* 1,297.00	1,297.00
7.	FRONT HEADLAMP LH - CHECK nn	1	PC		
8.	FRONT SIDE MIRROR LH - REPAIR	1	PC		
9.	FRONT FOG LAMP GARNISH LH - CHECKnn	1	PC		
10.	FRONT FOG LAMP LH - CHECK nn	1	PC		
LIST TOTAL S\$					2,659.40
20% DISCOUNT S\$					-531.88

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LABOUR :

TO REPAIR FRONT FENDER LH, FRONT SIDE MIRROR LH, FRONT LH DOOR AND REALIGN ACCIDENT AFFECTED AREAS. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS.	400	500.00
TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS	400	750.00
TO TEST WATER LEAKAGE FOR FRONT HEADLAMP	20	40.00
TO CHECK FRONT WHEEL ALIGNMENT	✓	80.00
TO REMOVE & REPLACE FRONT TYRE & BALANCING TYRE	30	50.00
TO RUST PROOF AFFECTED AREAS	20	40.00
LABOUR TOTAL S\$		1,460.00

Tanpin 97495749
 WP

3/10/18 1115

To check p/p or L/S

To resurvey before or after paint.

04 days

sur @ lkkauto.com

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 3,587.52

GST @ 7 % 251.13

AMOUNT DUE S\$ 3,838.65

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

3,838.65

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jul 2018		24 Jul 2018 08:54 Edit Adj Rpt	\$3,550.00 Edit Estimates	\$3,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	IMRAN ABDULLAH TAN @ TAN KIM TECK, ID: S1358323D			
Main Claimant:	RYU SEUNG YOUN, ID: G1753642M			
Vehicle Reg. No.:	SKX5610A	Date of Loss:	18/07/2018 08:00 - :59 [31 Months and 1 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM18D03555C03	Policy/Cover Note No.:	DMPCSN3072901702 (TP, Fire & Theft)	
Vehicle Reg. No. (Insured):	SKV8696T	Policy No. (Claimant):	VPA/P2011180	
		Excess:	\$0.00	
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]			
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 02/08/2018]			
Driver/Custodian (Insured):	AZIZ IMRAN TAN (23 / Male), NRIC: S9427218A, Tel: +6591271380			
Adj Asg. Remarks:	EST \$3838.65, CASE WITH SJE.			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKX5610A (SNM18D03555C03)**
[SKV8696T]

TP

RYU SEUNG YOUN

Jul 18 2018 8:00AM

[IMRAN ABDULLAH TAN @ TAN KIM TECK]

Mova Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	18/07/18 13:32	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
2	18/07/18 13:32	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
Assessment Reports			1 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	18/07/18 13:35	Accident Statement	Load HTM	☐
Photos/Images			3 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	18/07/18 13:35	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	18/07/18 13:35	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	18/07/18 13:35	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	18/07/18 13:35	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	18/07/18 13:35	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
6	18/07/18 13:35	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
7	18/07/18 13:35	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
8	18/07/18 13:35	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/10/18 10:25	General View	Load JPG	☒
2	30/10/18 10:25	General View	Load JPG	☒
3	30/10/18 10:25	General View	Load JPG	☒
4	30/10/18 10:25	General View	Load JPG	☒
5	30/10/18 10:25	General View	Load JPG	☒
6	30/10/18 10:25	General View	Load JPG	☒
7	30/10/18 10:25	General View	Load JPG	☒
8	30/10/18 10:25	General View	Load JPG	☒
9	30/10/18 10:25	General View	Load JPG	☒
10	30/10/18 10:25	General View	Load JPG	☒
11	30/10/18 10:25	General View	Load JPG	☒
12	30/10/18 10:25	General View	Load JPG	☒
13	30/10/18 10:25	General View	Load JPG	☒
14	30/10/18 10:25	General View	Load JPG	☒
15	30/10/18 10:25	General View	Load JPG	☒

Video			1 per page	
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
16	30/10/18 10:25	General View	 Load JPG	☒
17	30/10/18 10:25	General View	 Load JPG	☒
18	30/10/18 10:25	General View	 Load JPG	☒
19	30/10/18 10:25	General View	 Load JPG	☒
20	30/10/18 10:25	General View	 Load JPG	☒
21	30/10/18 10:25	General View	 Load JPG	☒
22	30/10/18 10:25	General View	 Load JPG	☒
23	30/10/18 10:25	General View	 Load JPG	☒
24	30/10/18 10:25	General View	 Load JPG	☒
25	30/10/18 10:25	General View	 Load JPG	☒
26	30/10/18 10:25	General View	 Load JPG	☒
27	30/10/18 10:25	General View	 Load JPG	☒
28	30/10/18 10:25	General View	 Load JPG	☒
29	30/10/18 10:25	General View	 Load JPG	☒
30	30/10/18 10:25	General View	 Load JPG	☒
31	30/10/18 10:25	General View	 Load JPG	☒
32	30/10/18 10:25	General View	 Load JPG	☒
33	30/10/18 10:25	General View	 Load JPG	☒
34	30/10/18 10:25	General View	 Load JPG	☒
35	30/10/18 10:25	General View	 Load JPG	☒
36	30/10/18 10:25	General View	 Load JPG	☒
37	30/10/18 10:25	General View	 Load JPG	☒
38	30/10/18 10:25	General View	 Load JPG	☒
39	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
40	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
41	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
42	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
43	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
44	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
45	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
46	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
47	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
48	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
49	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
50	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
51	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
52	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
53	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
54	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
55	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
56	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
57	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
58	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
59	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
60	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
61	30/10/18 10:25	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	

Video			1 per page ▼	✓
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/07/18 08:53	REPAIR EST	Load PDF	
2	24/07/18 08:53	TP GIA	Load PDF	
3	24/07/18 08:54	OI GIA	Load PDF	
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	18/07/18 13:34	Sketch Plan [Linked Accident Report Documents]	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/10/18 10:21	SUPPLEMENTARY	Load PDF	

Linked Accident Report Documents

Video			View View in Browser ▼	1 per page ▼	✓
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print	
1	18/07/18 13:32	Video - Accident	Load MP4		
2	18/07/18 13:32	Video - Accident	Load MP4		
Assessment Reports			1 per page ▼	✓	
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print	
1	18/07/18 13:35	Accident Statement	Load HTM		
Photos/Images			3 per page ▼	✓	
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print	
1	18/07/18 13:35	Accident Photo	Load JPG	✓	
2	18/07/18 13:35	Accident Photo	Load JPG	✓	
3	18/07/18 13:35	Accident Photo	Load JPG	✓	
4	18/07/18 13:35	Accident Photo	Load JPG	✓	
5	18/07/18 13:35	Accident Photo	Load JPG	✓	
6	18/07/18 13:35	Accident Photo	Load JPG	✓	
7	18/07/18 13:35	Accident Photo	Load JPG	✓	
8	18/07/18 13:35	Accident Photo	Load JPG	✓	
Documentation			1 per page ▼	✓	
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print	
1	18/07/18 13:34	Sketch Plan	Load TIF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18013410/T1TD3S2

Date: 31/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN3072901702

Claimant Vehicle No: SKX5610A Insured Vehicle No: SKV8696T

Date of Loss: 18/07/2018 Nature of Claim: TP Claim No: SNM18D03555C03

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX5610A**

Make & Model: HONDA ODYSSEY, 2.4 EXV-S CVT SR (A) Engine No: K24W72010233

Reg. Date: 17/12/2015 (Man. Year: 2015) Chassis No: JHMRC1890GC200740

Colour: Black Odometer: 21235 km

Engine Capacity: 2356 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55R17 Rear Tyre Size: 215/55R17

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,397.28	3,357.76	1,039.52	23.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	1,100.00	360.00	24.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,857.28	4,457.76	1,399.52	23.89
Approved Total (Overridden) (S\$)		3,550.00		
(S\$)	5,857.28	3,550.00	2,307.28	39.39
+ GST 7.00/7.00% (S\$)	410.01	248.50	161.51	39.39
Nett Amount (S\$)	6,267.29	3,798.50	2,468.79	39.39

INSPECTION

Date of Assignment: 24/07/2018

Date Inspected: 03/10/2018 Inspected At: Mova Automotive Pte Ltd (Bukit Merah)
Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3
Singapore 159722

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Oct 2018)
Parts:	M1-SUV	HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX5610A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	986.30 FL	*986.30 FL
2	10		*FRONT BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
3	1		*FRONT BUMPER LOWER SPOILER LH	Repair	245.00 FL	*- FL
4	1		*FRONT BUMPER RETAINER LH	Necessary	38.90 FL	*38.90 FL
5	1		*FRONT HEADLAMP LOWER BRACKET LH	Not Necessary	54.20 FL	*- FL
6	1		*FRONT WHEEL RIM LH	Cut	1,297.00 FL	*897.00 FL
7	1		*FRONT SIDE MIRROR LH (NPA)	Repair	0.00 FL	*- FL
8	1		*FRONT FOG LAMP GARNISH LH (NPA)	Not Necessary	0.00 FL	*- FL
9	1		*FRONT FOG LAMP LH (NPA)	Not Necessary	0.00 FL	*- FL
10	1		*FRONT HEADLAMP LH	Cut	2,837.20 FL	*2,237.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,496.60	4,197.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,099.32	839.44
Total Parts (\$\$)	4,397.28	3,357.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR FRONT FENDER LH,FRONT SIDE MIRROR LH,FRONT LH DOOR AND REALIGN ACCIDENT AFFECTED AREAS.TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS	New	500.00	450.00
2	TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS	New	750.00	500.00
3	TO TEST WATER LEAKAGE FOR FRONT HEADLAMP	New	40.00	20.00
4	TO CHECK FRONT WHEEL ALIGNMENT	New	80.00	80.00
5	TO REMOVE & REPLACE FRONT TYRE & BALANCING TYRE	New	50.00	30.00
6	TO RUST PROOF AFFECTED AREAS	New	40.00	20.00
Gross Labour Cost (S\$)			1,460.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >