

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eliza Ho Teng Boon

Date: 25 Jul 2018

Preliminary Advice

Vehicle No	: SKL7899J	Accident Date	: 18/07/2018
Make	: MERCEDES-BENZ E250	Policy No.	: A28852939QMY
Assignment Date	: 24/07/2018	Excess	: S\$700.00
Date of Inspection	: 25/07/2018	Est. Duration of Repair	: 5.00
Inspection At	: CYCLE & CARRIAGE INDUSTRIES PTE LTD (PANDAN LOOP) 188 PANDAN LOOP SINGAPORE 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,997.77
Revised Amount	:S\$	9,392.95
Check Items (Estimated)	:S\$	5,044.82
Total	:S\$	14,437.77

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	145,000.00
COE / PARF Rebate	:S\$	88,643.00
Salvage Value	:S\$	
Margin for Repair	:S\$	56,357.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.