

ASS. REC. BY:

REF: CS/CTI18013416/R19d3/

Special Instruction:

Surveyor
merimen

Rasul
Elaine Cheong

ASSIGNMENT (Office)

From (Person):

of

CTI

Date/Time:

23/7/18 @ 3:13pm.

Estimated Cost:

Bill to:

OD / (IP) WS / TT RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 5786K

Insured:

GBF 9265M

at Workshop m/s

Kah Motor

Tel:

82886302 / 90721769

of

255 Alexandra Rd

Policy No:

DMEVSN 3022651800

Claim No:

SNM18D03573C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

19/7/18

CA / REV / REP. / REV 24 HRS

kup

H.O.D. Endorsement:

Date/Time:

10:06am @ 24/7/18

Person Contacted:

Ng Sin Hai

Vehicle IN/OUT

OUT

Date/Time	Action/Instruction (✓) Estimate
	SLT 5786K - X
	GBF 9265M - NA/CTI18009530/h4
26/7/18 -	called Mr. Ng - vehicle still not in
15/8/18 @ 10:44am	confirmed with Ng Sin Hai final fig to 8779.05, 8 days. Cred to 5675.75, 39.6%

ASSIGNMENT

From: _____ Date: 30/07/18

Estimated Cost: _____

OP: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLT 5786K

at Workshop m/s

of

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLT 5786K Yr Regn: 2017 / NOV

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA CIVIC 1.6 VTI c.c 1597

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 627504 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MAH FC5650HT 000378

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CONTINENTAL

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 19/07/18 D.O.I. 30/07/18

Survey held at KAH MOTOR

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 15 AUG 2018

Date/Time, File Pass to?

11/5/18 Travis

Date/Time, File Return to?

2)

Report Format: NET TP

Lump Sum / I.B.I. (\$) 8779.05

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee: 150

Transportation:

S + RS \$

Photos

Others

TOTAL

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

E-mail: shng@honda.com.sg

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/07/2018 15:48
Date Of Accident	19/07/2018 06:30
Exact Location Of Accident	WOODLANDS AVE 1 SLIP ROAD TO WOODLANDS AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT5786K
Insured/Policyholder	
Name Of Registered Owner	CHUA LAI GUAN
NRIC No	S1654923A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96224077
Alternative Phone No	OFFICE-96224077

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.6 L (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	CHUA LAI GUAN
NRIC No	S1654923A
Date Of Birth	04/01/1964
Occupation	INDOOR
Date Of Driving Pass	29/03/1986
Driving Experience	32 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96224077
Fax Number	
Contact Number	OFFICE-96224077
Email Address	NOEMAIL

Sketch Plan

Vehicle No. _____

SKETCH PLAN

August 19

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. The Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if needed.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"). The Insurers' lawyers/solicitors, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claim excluding the settlement of the claim and any necessary investigations relating to the claim;

(ii) investigating the accident and/or my claims.

(ii) carrying out and/or doing with my instructions or responding to any enquiries by me;

(iv) administering my claims; (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, funding and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/firm), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Control
Disciplined

Sketch Plan

SLT 5786K

GBF 9245M

Please continue on Answer 2.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE

3 ANSON ROAD #16-00

SPRINGLEAF TOWER

SINGAPORE 079909

Registration No : SLT5786K

Chassis No : MRHFC5650HT000378

Model : CIVIC 1.6 VTI YM2017

Owner's Name : CHUA LAI GUAN

Ins Policy No. :

Date of Accident : 19/7/2018

Document No. : SQT18003019

Date : 20. Jul 2018

Customer No. : WZC008

Svc Advisor :

Engine No : R16B22000748

Date | Time : 20. Jul 2018 3:49:37 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:CHUA LAI GUAN						
	OWNER INSURER:TOKIO MARINE						
	ACC DATE:19/07/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:CHINA TAIPING INSURANCE (S'PORE) PTE LT						
	TP VEH:GBF9265M						
BOSUN	SUNDRIES <i>Nu</i>	1	100.00 <i>30</i>		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES (N)	1	560.00 <i>Xm</i>		560.00	39.20	599.20
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00		560.00	39.20	599.20
BKRP02M	CUT OFF & RENEW RR PANEL	1	5000.00 <i>2800</i>		5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00 <i>2700</i>		3000.00	210.00	3210.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR (N)	1	450.00 <i>Xm</i>		450.00	31.50	481.50
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	380.00		380.00	26.60	406.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	450.00 <i>Xm</i>		450.00	31.50	481.50
	Sum Labor				11420.00	799.40	12,219.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00 <i>XSLC</i>		45.00	3.15	48.15
32131-TEA-R00	SUB CORDRR BUMPER CORNER SENS	1	27.20 <i>7.84</i> <i>25</i>		20.40	1.43	21.83
39670-TEX-Y01	SENSOR UNITPARKING	1	60.70 <i>7.84</i> <i>25</i>		45.52	3.19	48.71
39680-TEX-Y41ZT	SENSOR ASSY,PARKING	4	133.90 <i>7.84</i> <i>25</i>		401.70	28.12	429.82
33500-TEA-T01	TAILLIGHT ASSYR.	1	253.80 <i>XSLC</i> <i>25</i>		190.35	13.32	203.67

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SLT5786K

Chassis No : MRHFC5650HT000378

Model : CIVIC 1.6 VTI YM2017

Owner's Name : CHUA LAI GUAN

Ins Policy No. :

Date of Accident : 19/7/2018

Document No. : SQT18003019

Date : 20. Jul 2018

Customer No. : WZC008

Svc Advisor :

Engine No : R16B22000748

Date | Time : 20. Jul 2018 3:49:37 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
33550-TEA-T01	TAILLIGHT ASSYL	1	273.10	X 25	204.82	14.34	219.16
34150-TEX-Y01	LIGHT ASSYR.LID	1	118.70	X 25	89.02	6.23	95.25
34155-TEX-Y01	LIGHT ASSYL.LID	1	118.70	X 25	89.02	6.23	95.25
68500-TEA-N00ZZ	LID COMP TRUNK	1	472.10	X 25	354.07	24.78	378.85
68610-TEA-T10ZZ	HINGE COMPR.TRUNK	1	43.50	X 25	32.62	2.28	34.90
68660-TEA-T10ZZ	HINGE COMPL.TRUNK	1	43.50	X 25	32.62	2.28	34.90
74851-TEA-003	LOCK ASSYTRUNK	1	72.20	X 25	54.15	3.79	57.94
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	X 25	52.50	3.68	56.18
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	1	97.70	X 25	73.27	5.13	78.40
75722-TBA-A00	EMBLEM SETRR.	1	11.50	X 25	8.62	0.60	9.22
75725-TEA-T01	EMBLEMRR.	1	10.60	X 25	7.95	0.56	8.51
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	X 25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	38.20	X 25	28.65	2.01	30.66
71503-TEA-T00	GARNISHR.RR.BUMPER SIDE	1	7.60	X 25	5.70	0.40	6.10
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	1	2.20	X 25	1.65	0.12	1.77
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE	1	7.60	X 25	5.70	0.40	6.10
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	173.00	X 25	129.75	9.08	138.83
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	1	2.20	X 25	1.65	0.12	1.77
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	X 25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	X 25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	7	2.00	X 25	10.50	0.74	11.24
66100-TEC-307ZZ	PANEL SETRR.	1	236.00	X 25	177.00	12.39	189.39
65550-TEA-T00ZZ	PAN COMPSPARE TIRE	1	210.40	X 25	157.80	11.05	168.85
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1	50.30	X 25	37.72	2.64	40.36
84521-TEA-Q01ZA	LID ASSYSPARE TIRE	1	58.40	X 25	43.80	3.07	46.87
84542-TET-H00	BOX COMPTOOL	1	36.90	X 25	27.67	1.94	29.61
84601-TEA-Q01ZA	LINING ASSYR.TRUNK SIDE	1	47.40	X 25	35.55	2.49	38.04
84651-TEA-Q01ZA	LINING ASSYL.TRUNK SIDE	1	47.40	X 25	35.55	2.49	38.04
72841-SH3-315	OILSHEET	3	39.90	X 25	89.77	6.28	96.05
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	26.00	X 25	19.50	1.37	20.87

Printed on 20/7/2018 4:05:59 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SLT5786K

Chassis No : MRHFC5650HT000378

Model : CIVIC 1.6 VTI YM2017

Owner's Name : CHUA LAI GUAN

Ins Policy No. :

Date of Accident : 19/7/2018

Document No. : SQT18003019 Page 3

Date : 20. Jul 2018

Customer No. : WZC008

Svc Advisor :

Engine No : R16B22000748

Date | Time : 20. Jul 2018 3:49:37 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Sum Item					2989.73	209.30	3,199.03

Survey By : RASH - Hq 90012068

Date & Time : 30/07/18 @ 1210

Excess : 8 days

Status : _____

Signature : [Signature]

Reg by perhit [Signature] 6/8/18

Total Amount 14,409.73 1,008.70 15,418.43

Total (Inclusive of GST) 15,418.43

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 20/7/2018 4:05:59 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	WZC008 / CHINA TAIPING	Document No:	SVO18044406
Chassis No:	MRHFC5650HT000378	Printed By:	SHNG
License No:	SLT5786K	Order Date:	30. July 2018
Mileage:	22112	Order Time:	12:17:23 PM
Engine No:	R16B22000748	Service Advisor:	NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:CHUA LAI GUAN OWNER INSURER:TOKIO MARINE ACC DATE:19/07/2018 SURVEYED BY:RASUL (LKK) DATE:30/07/2018 REF NO: SNM18D03573 (Elaine Cheong) TP INSURER:CHINA TAIPING INSURANCE (S'PORE) PTE LT TP VEH:GBF9265M ADDITIONAL PART						
68500-TEA-N00ZZ	LID COMP TRUNK	1	472.10	25	354.07	24.78	378.85
74851-TEA-003	LOCK ASSYTRUNK	1	72.20	25	54.15	3.79	57.94
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	38.20	25	28.65	2.01	30.66
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	173.00	25	129.75	9.08	138.83
71593-TEA-T01	SPACERR,RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL,RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	7	2.00	25	10.50	0.74	11.24
66100-TEC-307ZZ	PANEL SETRR.	1	236.00	25	177.00	12.39	189.39
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1	50.30	25	37.72	2.64	40.36
66114-TBA-A00ZZ	STIFFENER,R,RR.PANEL SIDE	1	26.00	25	19.50	1.37	20.87
74940-SZW-003	BUZZER ASSYSMART	1	60.10	25	45.07	3.15	48.22
	SUM PARTS:				1,389.05	97.23	1,486.28
BOSUN	0701 SUNDRIES	1	30.00		30.00	2.10	32.10
BA02R	0671 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BML02I	0671 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00		180.00	12.60	192.60
BMI02D	1757 REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)	1	560.00		560.00	39.20	599.20
BKTG02R	0671 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	560.00		560.00	39.20	599.20
BKRP02M	0671 CUT OFF & RENEW RR PANEL. RR FLOOR PAN & RENEW DAMAGE PARTS.	1	2,800.00		2,800.00	196.00	2,996.00
BP06R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) REAR PORTION	1	2,700.00		2,700.00	189.00	2,889.00
BKBU01R	0701	1	380.00		380.00	26.60	406.60



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	WZC008 / CHINA TAIPING	Document No:	SVO18044406
Chassis No:	MRHFC5650HT000378	Printed By:	SHNG
License No:	SLT5786K	Order Date:	30. July 2018
Mileage:	22112	Order Time:	12:17:23 PM
Engine No:	R16B22000748	Service Advisor:	NG SIN HAI

REMOVE, RE-FIX AND ALIGN REAR VIEW
CAMERA

SUM LABOUR:	7,390.00	517.30	7,907.30
TOTAL SGD	8,779.05	614.53	9,393.58

Total Payable (SGD) 9,393.58

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18003303	Page	1
	3 ANSON ROAD #16-00	Date	: 8. Aug 2018		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	:		
Registration No	: SLT5786K	Engine No	: R16B22000748		
Chassis No	: MRHFC5650HT000378	Date Time	: 8. Aug 2018 9:03:01 AM		
Model	: CIVIC 1.6 VTI YM2017	Surveyor Name	:		
Owner's Name	: CHUA LAI GUAN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 19/7/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
	SUPPLEMENTARY						
74940-SZW-003	BUZZER ASSYSMART	1	60.10	25	45.07	3.15	48.22
					Sum Item	45.07	48.22
						3.15	48.22

Survey By	_____						
Date & Time	_____	Total Amount	45.07	3.15	48.22		
Excess	_____	Total (Inclusive of GST)			48.22		
Status	_____						
Signature	_____						

Printed on 8/8/2018 9:04:28 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jul 2018		23 Jul 2018 15:13 Edit Adj Rpt	\$48,779.05 Edit Estimates	\$48,779.05 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	ES AUDIO , Co. Reg. No.: S3185251B								
Main Claimant:	CHUA LAI GUAN , ID: S1654923A								
Vehicle Reg. No.:	SLT5786K	Date of Loss:	19/07/2018 06:00 - :59 [8 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03573C02	Policy/Cover Note No.:	DMCVSN3022651800 (Comprehensive)						
Vehicle Reg. No. (Insured):	G8F9265M	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 01/08/2018]								
Adj Asg. Remarks:	EST \$15,418.43, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT5786K (SNM18D03573C02)
[GBF9265M]
TP
CHUA LAI GUAN
Jul 19 2018 6:00AM
[ES AUDIO]
Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)					Thumbnail	Print		
1	19/07/18 18:06	Accident Statement						Load HTM		
Photos/Images							3 per page		☒	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)					Thumbnail	Print		
1	19/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG		☒
2	19/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG		☒
3	19/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG		☒
4	19/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG		☒
5	19/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG		☒
6	19/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print		
1	15/08/18 11:41	Odometer Reading						Load JPG		☒
2	15/08/18 11:41	Odometer Reading						Load JPG		☒
3	15/08/18 11:41	Chassis Number						Load JPG		☒
4	15/08/18 11:41	General View						Load JPG		☒
5	15/08/18 11:41	General View						Load JPG		☒
6	15/08/18 11:41	General View						Load JPG		☒
7	15/08/18 11:41	General View						Load JPG		☒
8	15/08/18 11:41	General View						Load JPG		☒
9	15/08/18 11:41	General View						Load JPG		☒
10	15/08/18 11:41	General View						Load JPG		☒
11	15/08/18 11:41	General View						Load JPG		☒
12	15/08/18 11:41	General View						Load JPG		☒
13	15/08/18 11:41	General View						Load JPG		☒
14	15/08/18 11:41	General View						Load JPG		☒
15	15/08/18 11:41	General View						Load JPG		☒
16	15/08/18 11:41	General View						Load JPG		☒
17	15/08/18 11:41	General View						Load JPG		☒
18	15/08/18 11:41	General View						Load JPG		☒
19	15/08/18 11:41	General View						Load JPG		☒
20	15/08/18 11:41	General View						Load JPG		☒
21	15/08/18 11:41	General View						Load JPG		☒
22	15/08/18 11:41	General View						Load JPG		☒
23	15/08/18 11:41	General View						Load JPG		☒
24	15/08/18 11:41	General View						Load JPG		☒
25	15/08/18 11:41	General View						Load JPG		☒

Assessment Reports			1 per page	☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
26	15/08/18 11:41	General View	 Load JPG	☒
27	15/08/18 11:41	Reinspection Photo	 Load JPG	☒
28	15/08/18 11:41	Reinspection Photo	 Load JPG	☒
29	15/08/18 11:41	Reinspection Photo	 Load JPG	☒
30	15/08/18 11:41	Reinspection Photo	 Load JPG	☒
31	15/08/18 11:41	Reinspection Photo	 Load JPG	☒
32	15/08/18 11:41	Reinspection Photo	 Load JPG	☒
33	15/08/18 11:41	Reinspection Photo	 Load JPG	☒
34	15/08/18 11:41	Reinspection Photo	 Load JPG	☒
35	15/08/18 11:41	Reinspection Photo	 Load JPG	☒
36	15/08/18 11:41	Reinspection Photo	 Load JPG	☒
37	15/08/18 11:41	Reinspection Photo	 Load JPG	☒
38	15/08/18 11:41	Reinspection Photo	 Load JPG	☒
39	15/08/18 11:41	Reinspection Photo	 Load JPG	☒
40	15/08/18 11:41	Reinspection Photo	 Load JPG	☒
41	15/08/18 11:41	Reinspection Photo	 Load JPG	☒
42	15/08/18 11:41	Reinspection Photo	 Load JPG	☒
43	15/08/18 11:41	Reinspection Photo	 Load JPG	☒
44	15/08/18 11:41	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/07/18 15:12	REPAIR EST WITH TP GIA	 Load PDF	
2	23/07/18 15:12	OI GIA	 Load PDF	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	19/07/18 18:04	Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	19/07/18 18:04	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	☒
3	19/07/18 18:05	DL [Linked Accident Report Documents]	 Load JPG	☒
4	19/07/18 18:05	DL [Linked Accident Report Documents]	 Load JPG	☒
5	19/07/18 18:05	IC [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/09/18 09:12	SUPPLEMENTARY PART	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	19/07/18 18:06	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	19/07/18 18:05	Accident Photo	 Load JPG	☒
2	19/07/18 18:05	Accident Photo	 Load JPG	☒
3	19/07/18 18:05	Accident Photo	 Load JPG	☒
4	19/07/18 18:05	Accident Photo	 Load JPG	☒
5	19/07/18 18:05	Accident Photo	 Load JPG	☒
6	19/07/18 18:05	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒

Assessment Reports			1 per page	☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	19/07/18 18:04	Sketch Plan	 Load JPG	☒
2	19/07/18 18:04	Sketch Plan #2	 Load JPG	☒
3	19/07/18 18:05	DL	 Load JPG	☒
4	19/07/18 18:05	DL	 Load JPG	☒
5	19/07/18 18:05	IC	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18013416/QD3Q2

Date: 06/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3022651800

Claimant Vehicle
No: SLT5786K

Insured Vehicle
No: GBF9265M

Date of Loss: 19/07/2018

Nature of Claim: TP

Claim
No: SNM18D03573C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT5786K**

Make & Model: HONDA CIVIC, 1.6 L (A)

Reg. Date: 01/11/2017 (Man. Year: 2017)

Colour: Grey

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: R16B22000748

Chassis No: MRHFC5650HT000378

Odometer: 627504 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,134.80	1,419.05	1,715.75	54.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,320.00	7,360.00	3,960.00	34.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,454.80	8,779.05	5,675.75	39.27
+ GST 7.00/7.00% (S\$)	1,011.84	614.53	397.31	39.27
Nett Amount (S\$)	15,466.64	9,393.58	6,073.06	39.27

INSPECTION

Date of Assignment: 23/07/2018

Date Inspected: 30/07/2018 Inspected At:

Kah Motor Co Sdn Bhd (ALEXANDRA)
255 ALEXANDRA ROAD
Singapore -

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Sep 2018)
Parts: 143	HONDA CIVIC 1.6 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLT5786K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
2	1		*NUMBER PLATE WITH CASING -L	Serviceable	45.00 FS	*- FS
3	1		*SUB CORDRR.BUMPER CORNER SENS	Serviceable	20.40 FS	*- FS
4	1		*SENSOR UNITPARKING	Serviceable	45.52 FS	*- FS
5	4		*SENSOR ASSY,PARKING	Serviceable	401.70 FS	*- FS
6	1		*TAILLIGHT ASSYR	Serviceable	190.35 FS	*- FS
7	1		*TAILLIGHT ASSYL	Serviceable	204.82 FS	*- FS
8	1		*LIGHT ASSYR.LID	Serviceable	89.02 FS	*- FS
9	1		*LIGHT ASSYL.LID	Serviceable	89.02 FS	*- FS
10	1		*LID COMP TRUNK	Bent	354.07 FS	*354.07 FS
11	1		*HINGE COMPR .TRUNK	Serviceable	32.62 FS	*- FS
12	1		*HINGE COMPL .TRUNK	Serviceable	32.62 FS	*- FS
13	1		*LOCK ASSYTRUNK	Bent	54.15 FS	*54.15 FS
14	1		*WEATHERSTRIPTRUNK LID	Necessary	52.50 FS	*52.50 FS
15	1		*GARNISH ASSYRR.LICENSE	Not Necessary	73.27 FS	*- FS
16	1		*EMBLEM SETRR	Not Necessary	8.62 FS	*- FS
17	1		*EMBLEMRR	Not Necessary	7.95 FS	*- FS
18	1		*FACE ASSY ,RR.BUMPER	Deformed	462.90 FS	*462.90 FS
19	1		*GARNISH ,RR.BUMPER LOWER	Scratched	28.65 FS	*28.65 FS
20	1		*GARNISHR.RR.BUMPER SIDE	Not Necessary	5.70 FS	*- FS
21	1		*BRACKETR.RR.BUMPER SIDE	Not Necessary	1.65 FS	*- FS
22	1		*GARNISHL.RR.BUMPER SIDE	Not Necessary	5.70 FS	*- FS
23	1		*BEAM COMPRR.BUMPER	Bent	129.75 FS	*129.75 FS
24	1		*BRACKETL.RR.BUMPER SIDE	Serviceable	1.65 FS	*- FS
25	1		*SPACERR.RR.BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
26	1		*SPACERL.RR.BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
27	7		*CLIPBUMPER	Necessary	10.50 FS	*10.50 FS
28	1		*PANEL SETRR	Bent	177.00 FS	*177.00 FS
29	1		*PAN COMPSPARE TIRE	Repair	157.80 FS	*- FS
30	1		*LINING ASSYRR.PANEL	Cut	37.72 FS	*37.72 FS
31	1		*LID ASSYSPARE TIRE	Not Necessary	43.80 FS	*- FS
32	1		*BOX COMPTOOL	Not Necessary	27.67 FS	*- FS
33	1		*LINING ASSYR.TRUNK SIDE	Not Necessary	35.55 FS	*- FS
34	1		*LINING ASSYL.TRUNK SIDE	Not Necessary	35.55 FS	*- FS
35	3		*OILSHEET	Not Necessary	89.77 FS	*- FS
36	1		*STIFFENER ,R.RR.PANEL SIDE	Necessary	19.50 FS	*19.50 FS
37	1		*BUZZER ASSYSMART	Cut	45.07 FS	*45.07 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	3,134.80	1,419.05
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & RENEW REVERSE SENSORS	New	180.00	180.00
2	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	180.00	180.00
3	REMOVE & INSTALL FUEL TANK FUEL PIPES	New	560.00	0.00
4	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	New	560.00	560.00
5	REMOVE & TRANSFER ITEMS TO NEW TAILGATE .ADJUST &	New	560.00	560.00
6	CUT OFF & RENEW RR PANEL	New	5,000.00	2,800.00
7	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	3,000.00	2,700.00
8	REMOVE & RENEW RR FLOOR INSULATOR	New	450.00	0.00
9	REMOVE ,RE-FIX AND ALIGN REAR VIEW CAMERA	New	380.00	380.00
10	APPLY BODY UNDERSIDE COATING	New	450.00	0.00
Gross Labour Cost (\$\$)			11,320.00	7,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >