

21/07/2018

ASS. REC. BY:

Surveyor

From (Person)

Estimated Cost

① OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

at Workshop m/s

of B1K 4, 393 M Woodlands Rd Yew Tee Ind. Est

Policy No:

Sum Insured:

Make of Veh:

(Client's Record)

CA / ① REV / REP. / REV 24 HRS

Date/Time:

1:49pm ② 24/7/18

Person Contacted:

Eric

Yong Jian

H.O.D. Endorsement:

Vehicle ① IN OUT

Date/Time Action/Instruction (✓) Estimate

YL 9274H - NA / INC 10013191/

D.O.A: 6/7/2010

26/7/18

Revert from Smart claim.

8/8/18

Amend 1A. market value change to \$15K

Repairer agree to repair within \$5K; L/s basis except Refrigerator (P/P)

14/8/18

Sent authorise to Repairer; Repair cost within \$5K

Circular

Tanglin

REF:

AXA

ASSIGNMENT

2020 Feb.

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


\$1500

(Client's Record)

Make of Veh:

Ponding DL & Company
authorisation letter

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$15K (amend Tanfiah)

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

YL 9274M

Yr Regn: 2005 / Feb

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi FE639

C.C

2908

Colour

Yellow ~~40987~~

A/C: Insured / Std / NI / NA

Sp. Reading

469573

T/Radio: Insured / Std / NI / NA

Eng/No:

G/No:

FE639CA42733

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: ☒ N / S/Rim / STD A/Rim or

Tyre Size:

F: 7.00 R16

R:

1 - (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

D.O.I.

25/7/18

Survey held at

Sin Yew Hyip 393WL Rd

Des. of Damages: Frt / Rear / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

- Depreciation of lorry 41000/mth, ^{CoE} left 16 mths, 2020 Feb therefore MV of lorry is, ^{around} \$15,000 is.

Confirm with Eric LIS \$5K @ 7 days
Pd: \$3776.64, 43%.

RECEIVED 2 JAN 2019

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

7

Resurvey No. of Trip:

1

Survey Fee:

200

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format:

DD

Lump Sum / Pd: (\$ 5K)

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18013418/T1rd3

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 24-07-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	YL 9274H
Policy No.	Coverage (\$)	0.00
Claim No. S8M00PL4	Excess (\$)	1,500.00
Assign From SMARTCLAIM (PETER WANG)	Assign Date	24/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 18/07/2018	Inspection Date 25/07/2018
Survey held at SIN YEW HUP AUTO PTE LTD BLK 4, 393M, WOODLANDS ROAD YEW TEE IND. ESTATE SINGAPORE 677981	

5a. Remarks


A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

◀ Service Request Details

Claim

S8M00PL4

Reference

None 

Loss Date

July 18, 2018

Request Date

July 24, 2018

Due Date

July 31, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

YL9274H

Make

MINISUBISHI FE639C6SRDEA

Model
MITXXX

Service Address

393 M WOODLANDS ROAD YEW, , 677981

Primary Contact/Insured

MONZONE AIR-CONDITIONING PTE LTD
41 SENOKO DRIVE, 758249, Singapore
63651315
monzone@singnet.com.sg ; nicole@monzone-aircon.com

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

Wkshop: Sin Yew Hup Auto Excess: \$1500 Pending DL & company authorization letter To survey WP

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

NIKAM Santosh Pandurang

From: Sin Yew Hup Auto Pte Ltd <sinyewhup@gmail.com>
Sent: Monday, July 23, 2018 6:29 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: Arrangement survey (YL 9274 H)
Attachments: 23072018181416.pdf; 23072018183255-0001.tif; 23072018183255-0002.tif

Categories: Santosh

Hi

Good day

To whom it may concern

Dear Sir/ Madam

Claim Type: OD
OI Vehicle Number: YL 9274 H
Date of Accident: 18-07-2018
Workshop: SIN YEW HUP AUTO (Wdls)

Kindly arrange the surveyor to survey our insured vehicle.

Best Regards,

Yong Jian

SIN YEW HUP AUTO PTE LTD

T : +65 67600819

F : +65 67690221

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Monday, November 12, 2018 3:54 PM
To: 'Sin Yew Hup Auto Pte Ltd'
Cc: Taufikh (LKKAuto)
Subject: RE: YL 9274H AXA OD

Dear Eric,

Confirmed L/S \$5K @ 7 DAYS

*Kindly send the DV and Invoice for early closure

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Lee (LKKAuto)
Sent: Friday, August 17, 2018 10:17 AM
To: 'Sin Yew Hup Auto Pte Ltd' <sinyewhup@gmail.com>
Subject: RE: YL 9274H AXA OD

Hi Yong Jian,

Document received. Thanks

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sin Yew Hup Auto Pte Ltd [<mailto:sinyewhup@gmail.com>]
Sent: Friday, August 17, 2018 10:03 AM
To: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>
Subject: Re: YL 9274H AXA OD

Hi

Good day



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 26.07.2018

Survey Details:

Date of loss	18.07.2018
Date of appointment	24.07.2018
Date of survey	25.04.2018
Location of survey	SIN YEW HUP AUTO PTE LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	YL 9274H
Make and Model	MITSUBISHI FE639C6SRDEA
Date of registration	19-Feb-05
Excess	\$1,500.00
Market Value	\$13,000.00
Parf Rebate	\$9,151.00
Nett Loss	\$3,849.00

Repair details:

Initial Estimate	\$8,776.64
------------------	------------

Proposed/Revised repair cost:

Parts	\$4,636.06
Check items (estimate)	
Labour	\$1,950.00
Total	\$6,586.06
Lump Sum(if applicable)	\$

Number of days for repair	7
---------------------------	---



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Vehicle sustained damages at o/s body. Damages consistent.
Repair cost economical. Pending DL and Authorisation letter.
Pending repair cost from We have not authorize repair.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

New Message

Type *



Message

Subject *

YL 9274H

Message *

Hi Peter, The amend IA has uploaded. We have amend the Market value to \$15,000.00(est) because this is a refrigerator lorry which depreciate \$12,000.00/year(est). Driving license and rental agreement has uploaded. Repairer propose to repair the vehicle within \$5k. Kindly let us have your approval.

Cancel

Send

Depreciation of the refrigerator lorry is around \$12000/year..COE of the lorry left around 16 months..therefore the market value estimated around \$15,000.

13:20



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62863861 FAX : (065) 62864315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 26.07.2018

Survey Details:

Date of loss	18.07.2018
Date of appointment	24.07.2018
Date of survey	25.04.2018
Location of survey	SIN YEW HUP AUTO PTE LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	YL 9274H
Make and Model	MITSUBISHI FE639C6SRDEA
Date of registration	19-Feb-05
Excess	\$1,500.00
Market Value	\$15,000.00
Parf Rebate	\$9,151.00
Nett Loss	\$5,849.00

Repair details:

Initial Estimate	\$8,776.64
------------------	------------

Proposed/Revised repair cost:

Parts	\$4,636.06
Check items (estimate)	
Labour	\$1,950.00
Total	\$6,586.06
Lump Sum(if applicable)	\$

Number of days for repair	7
---------------------------	---



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Vehicle sustained damages at o/s body. Damages consistent. DL and Authorisation letter uploaded. Repair propose to repair the vehicle at repair cost within \$5,000.00. We have not authorize repair.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	



5k limit repair authorized

Type

🔗 Question

Message

In view of the new highest MV of \$15k, please proceed to authorize \$5k limit repair. Please also advise if it is p/p repair or lump-sum repair. If it is lump-sum, pls submit letter of undertaking.

Reply



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 07.08.2018

Survey Details:

Date of loss	18.07.2018
Date of appointment	24.07.2018
Date of survey	25.04.2018
Location of survey	SIN YEW HUP AUTO PTE LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	YL 9274H
Make and Model	MITSUBISHI FE639C6SRDEA
Date of registration	19-Feb-05
Excess	\$1,500.00
Market Value	\$15,000.00
Parf Rebate	\$9,151.00
Nett Loss	\$5,849.00

Repair details:

Initial Estimate	\$8,776.64
------------------	------------

Proposed/Revised repair cost:

Parts	\$4,636.06
Check items (estimate)	
Labour	\$1,950.00
Total	\$6,586.06
Lump Sum(if applicable)	\$

Number of days for repair	7
---------------------------	---



Auto
Consultants
Pte Ltd

81 UBI AVE 1, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Vehicle sustained damages at o/s body. Damages consistent. DL and Authorisation letter uploaded. Please be informed the repairer will repair the vehicle on Lump Sum basis except the refrigerator which the repairer will be repair on new part due to no second hand part. The vehicle repair at repair cost within \$5,000.00.

Mandate:

Liability(TP)	%
Proposed repair cost	\$
Loss of use	\$ no. of days
Loss of rental	\$ no. of days
Loss of income	\$ no. of days
LTA search fees	\$
Others	\$
Proposed Total	#VALUE!



Repair authorized. Pls get Lump-sum repair LOU

Type

🔗 Question

Message

Repair authorized. Based on your IA uploaded on 14 Aug, some parts are to be repaired on lump-sum basis.
Pls still get lump-sum repair LOU.

Reply

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Tuesday, August 14, 2018 2:28 PM
To: Sin Yew Hup Auto Pte Ltd
Cc: SUR
Subject: RE: YL 9274H AXA OD
Attachments: Letter of Undertaking.pdf

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **YL 9274H (excess \$1,5000/-)**. Please note that **the vehicle repair at repair cost not more than \$5,000.00**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



redefining / Insurance

LETTER OF UNDERTAKING/ AUTHORIZATION FOR LUMP SUM REPAIR



1. I, [Name] [NRIC] Monroe Air-conditioning Pte Ltd, the owner/ authorized driver of vehicle [Registration No.] YL 92747 ("Vehicle") do hereby authorize the [Workshop/Insurer] to repair the Vehicle on a lump sum basis instead of part by part.
2. The [Workshop/Insurer] has explained to me the difference between lump sum repair and part by part repair and the consequences of my authorization for lump sum repair for the Vehicle.
3. I understand that with lump sum repair, the Workshop may use a mixture of genuine parts, original equipment manufacturer (OEM) parts, reconditioned and second hand parts to carry out the repair and I note that the [Workshop/Insurer] will not be furnishing a detailed breakdown of parts or price for such lump sum repair.
4. I am aware that AXA Insurance Pte Ltd ("AXA Insurance") does not encourage lump sum repair as AXA Insurance strongly recommends repairs for vehicles on a part by part basis for transparency reasons. I confirm that I will hold AXA Insurance harmless from any claims arising from the lump sum repair of the Vehicle which I have authorized.
5. * To be applicable where person authorizing is the authorized driver.
I confirm that I have the authority from the owner of the Vehicle to authorize the lump sum repairs and that I have duly notified the owner of the Vehicle of the contents of this Letter of Authorization.

Signed and acknowledged by:




Signature of policyholder/ authorized driver* and company stamp (where applicable)

Date:

Name and signature of workshop personnel including workshop stamp

Date:

*authorized driver to either the named drivers as per motor insurance policy or in the case of commercial vehicles, permitted drivers who are permitted to drive the insured Vehicle.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/07/2018 15:56
Date Of Accident	18/07/2018 14:00
Exact Location Of Accident	AT 50 BT BATOK EAST AVE 3 (CALTEX PETROL STATION)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YL9274H
Insured/Policyholder	
Name Of Registered Owner	MONZONE AIR-CONDITIONING PTE LTD
Co Reg No	200102928W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63651315

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FE639C6SRDEA

Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
--	------------

Are you claiming under your own insurance policy for repair to your vehicle?	YES
--	-----

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VFX/1852064
Cover Note Number	

Driver

Name of Driver	SUN SHOUWEN
Passport No/FIN	G5997387N
Date Of Birth	11/12/1976
Occupation	OUTDOOR
Date Of Driving Pass	19/05/2014
Driving Experience	4 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-94672612
Fax Number	
Contact Number	
Email Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Sun Shou Wen
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Yvonne Toh
Reporting Centre Personnel's Signature
Name: Yvonne Toh
NRIC/FIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Police Report J/20180719/2060

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Sun Shou Wen
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Yvonne Toh
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

10/01/2018 10:00 AM

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2928W
Vehicle Details	
Vehicle No.:	YL9274H
Vehicle to be Exported:	No
Intended De-registration Date:	26 Jul 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	FE639C6SRDEA
Primary Colour:	Yellow
Manufacturing Year:	2004
Engine No.:	4D34K15869
Chassis No.:	FE639CA42733
Maximum Power Output:	-
Open Market Value:	\$37,089.00
Original Registration Date:	19 Feb 2005
First Registration Date:	19 Feb 2005
Transfer Count:	2
Actual ARF Paid:	\$1,855.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Feb 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$29,236.00
COE Rebate Amount:	\$9,151.00
Total Rebate Amount:	\$9,151.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 26 Jul 2018

OK



Co./GST Regn. No. 200921075G

新友合汽车私人有限公司 SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg
Specialise in Insurance Claims and General Motor Repair Work

23-Jul-18

OWN DAMAGE CLAIM

Vehicle No: YL 9274 H

Date of Accident : 18/07/2018

MOTOR CLAIM DEPARTMENT**AXA Insurance Singapore Pte Ltd**

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

ESTIMATED COST OF REPAIR TO MITSUBISHI FE639C6SRDEA: YL 9274 H

A) Chassis No : FE639CA42733

B) Date of Registration : 19 FEB 2005

S/No.	Pc/s	Item(s) :-	\$
1	1	Side lamp	141.48 <i>cu</i> ✓
2	1	Front bumper	634.18 <i>de</i> ✓
3	1	Signal lamp RH	237.83 <i>cu</i> ✓
4	1	Door RH	1,800.13 <i>bb</i> ✓
5	1	Door outer garnish RH	206.06 <i>ms</i> ✓
6	6	Door outer garnish clip RH @ \$3.50	21.00 <i>ng</i> ✓
7	1	Door indicator lamp RH	248.74 <i>cu</i> ✓
8	1	Door weatherstrip RH	402.85 <i>de</i> ✓
9	1	Door hinge lower	206.09 <i>Rx</i> ✓
10	1	Door rubber vertical	159.78 <i>de</i> ✓
11	1	Corner panel RH	714.18 <i>dd</i> ✓
12	1	Wheel arch garnish outer RH	182.47 <i>de</i> ✓
13	1	Step garnish RH	165.02 <i>cut</i> ✓
14	1	Step panel RH	379.26 <i>Rx</i> ✓
15	1	Door rear panel RH	1,117.40 <i>Rx</i> ✓
16	1	Door lock RH	290.03 <i>Rx</i> ✓
17	1	Mudflap	199.85 <i>de</i> ✓
18	1	Door outer handle RH	131.84 <i>cut</i> ✓
			7,238.19
Less Discs : 25% -			1,809.55
			5428.64
		<u>Item(s) :-</u>	
19	2	Corner cover @ \$90.00	180.00 <i>nei</i> ✓
20	1	Aluminium profile-2 Meter	480.00 <i>del</i> ✓
21	1	Supply adhesive for assembly box	120.00 <i>nei</i> ✓
			858.00
Mark up : 10% -			858.00
Balance C/F:-			6,286.64



Co./GST Regn. No. 200921075G

新友合汽车私人有限公司 SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg
Specialise in Insurance Claims and General Motor Repair Work

23-Jul-18

OWN DAMAGE CLAIM

Vehicle No: YL 9274 H

Date of Accident : 18/07/2018

MOTOR CLAIM DEPARTMENT

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

ESTIMATED COST OF REPAIR TO MITSUBISHI FE639C6SRDEA: YL 9274 H

A) Chassis No : FE639CA42733

B) Date of Registration : 19 FEB 2005

	Balance B/F:-	\$
		6,286.64
<u>Labour Charges:</u>		
a) To remove and refit all the damaged parts, cut and weld rear door panel RH, panel beat front door pillar		800 1,000.00
b) To putty and spray paint front corner panel RH, front grille garnish RH, front bumper, front door in & out, front door outer garnish RH, step garnish RH, front door pillar RH, front door rear panel RH, wheel arch garnish outer		800 1,000.00
c) To transfer the front door RH mechanism		70.00 50
d) To dismantle and replace with above items, dismantle damage profile and cover, supply new profile and cover, supply paint at damage area		300 420.00
		8,776.64
	GST (7%) :-	614.36
	Total :-	9,391.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:


Date:

Taufik 97495744
Ex 91500
Not Authorise
Resurvey after paint for long parts
Resurvey new parts for fridge body
7 days
sur@lkkauto.com.

31/7/18



I/We Monzone Air-conditioning Pte Ltd.
 Hereby certified that repairs to Vehicle Number YL 9274H have been carried out to
 my/our entire satisfaction and I/we agree that the discharge of the repair account from
Sin Yew Hye Auto Pte Ltd. (company).
 for S\$ 3,745.00. by AXA Insurance Pte Ltd shall be in full discharge of all
 claims under Policy No. VFJC/1852064 in respect of damage to this car resulting
 from an accident which occurred on or about the 18 day of July 2018

Signature: 



SIN YEW HUP AUTO PTE LTD
393M WOODLANDS ROAD,
YEW TEE INDUSTRIAL ESTATE
SINGAPORE 677981
syhapl@singnet.com.sg
GST Registration No. : 200921075G

Tax Invoice 06799

INVOICE TO
AXA INSURANCE PTE LTD
(CS)
8 Shenton Way, #24-01 AXA
Tower, 068811

DATE
13/11/2018

PLEASE PAY
S\$3,745.00

DATE	ACTIVITY	QTY	RATE	AMOUNT
18/07/2018	LUMP SUM COST OF REPAIR FOR YL9274H	1	5,000.00	5,000.00
18/07/2018	BEING LESS EXCESS FOR YL9274H	1	-1,500.00	-1,500.00
SUBTOTAL				3,500.00
GST TOTAL				245.00
TOTAL				3,745.00
TOTAL DUE				S\$3,745.00

THANK YOU.

Please cross your cheque and make it payable to 'SIN YEW HUP AUTO PTE LTD.'




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CS/ASM18013418/T1cd3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: LYNN KHONG		Date : 04-01-2019	
		Code : ASM	
1. Policy Particulars :- OWN DAMAGE			
	Insured Veh.	Veh. Inspected	YL 9274H
	Policy No. VFX/1852064	Coverage (\$)	0.00
	Claim No. S8M00PL4	Excess (\$)	1,500.00
	Assign From LYNN KHONG	Assign Date	24/07/2018
2. Vehicle Particulars & Condition			
	Make & Model MITSUBISHI FE639	c.c	3908
	Engine No. HIDDEN	Year of Reg.	2005
	Chassis No. FE639CA42733	Colour	YELLOW
	Odometer 469573	Steering	IN ORDER
	Brakes IN ORDER	Modification	NIL
	General GOOD		
3. Conditions of Tyres			
		Size	Make
	R/H Front Tyre	7.00 R16	Balance
	L/H Front Tyre	7.00 R16	6 mm
	R/H Rear Tyre	7.00 R16 (D)	6 mm
	L/H Rear Tyre	7.00 R16 (D)	6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.			
DAMAGES SEE DETAILS.			
5. General Information			
	Accident Date 18/07/2018	Inspection Date	25/07/2018
	Survey held at SIN YEW HUP AUTO PTE LTD BLK 4, 393M, WOODLANDS ROAD YEW TEE IND. ESTATE SINGAPORE 677981		
5a. Remarks			
	A)THE MARKET VALUE IS S\$15,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YL 9274H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SIDE LAMP (CONSISTENT)	CRACKED	141.48	141.48
1	FRONT BUMPER (CONSISTENT)	DEFORMED	634.18	634.18
1	SIGNAL LAMP RH (CONSISTENT)	CUT	237.83	237.83
1	DOOR RH (CONSISTENT)	BENT	1,800.13	1,800.13
1	DOOR OUTER GARNISH RH (CONSISTENT)	MISSING	206.06	206.06
6	DOOR OUTER GARNISH CLIP RH @ \$3.50 (CONSISTENT)	NECESSARY	21.00	21.00
1	DOOR INDICATOR LAMP RH (CONSISTENT)	CRACKED	248.74	248.74
1	DOOR WEATHERSTRIP RH (CONSISTENT)	DEFORMED	402.85	402.85
1	DOOR HINGE LOWER (CONSISTENT)	TO REPAIR SEE LABOUR	206.09	-
1	DOOR RUBBER VERTICAL (CONSISTENT)	DEFORMED	159.78	159.78
1	CORNER PANEL RH (CONSISTENT)	DENTED	714.18	714.18
1	WHEEL ARCH GARNISH OUTER RH (CONSISTENT)	DEFORMED	182.47	182.47
1	STEP GARNISH RH (CONSISTENT)	CUT	165.02	165.02
1	STEP PANEL RH (CONSISTENT)	TO REPAIR SEE LABOUR	379.26	-
1	DOOR REAR PANEL RH (CONSISTENT)	TO REPAIR SEE LABOUR	1,117.40	-
1	DOOR LOCK RH (CONSISTENT)	TO REPAIR SEE LABOUR	290.03	-
1	MUDFLAP (CONSISTENT)	DEFORMED	199.85	199.85
1	DOOR OUTER HANDLE RH (CONSISTENT)	CUT	131.84	131.84
	LESS 25% DISCOUNT		-1,809.55	-1,311.35
			5,428.64	3,934.06
NETT ITEMS				
2	CORNER COVER @ \$90.00 (N) (WCP) (CONSISTENT)	NECESSARY	180.00	180.00
1	ALUMINIUM PROFILE - 2 METER (N) (WCP) (CONSISTENT)	DENTED	480.00	480.00
1	ADHESIVE FOR ASSEMBLY BOX (N) (WCP) (CONSISTENT)	NECESSARY	120.00	120.00
	LESS 10% DISCOUNT		-	-78.00

Report Ref No. CS/ASM18013418/T1cd3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	COST PLUS 10%		78.00	-
			858.00	702.00
	LABOUR			
	TO REMOVE AND REFIT ALL THE DAMAGED PARTS, CUT AND WELD REAR DOOR PANEL RH, PANEL BEAT FRONT DOOR PILLAR. INCLUSIVE OF THE REPAIR OF DOOR HINGE LOWER, STEP PANEL RH, DOOR REAR PANEL RH AND DOOR LOCK RH.		1,000.00	800.00
	TO PUTTTY AND SPRAY PAINT FRONT CORNER PANEL RH, FRONT GRILLE GARNISH RH, FRONT BUMPER, FRONT DOOR IN & OUT, FRONT DOOR OUTER GARNISH RH, STEP GARNISH RH, FRONT DOOR PILLAR RH, FRONT DOOR REAR PANEL RH, WHEEL ARCH GARNISH OUTER.		1,000.00	800.00
	TO TRANSFER THE FRONT DOOR RH MECHANISM.		70.00	50.00
	TO DISMANTLE AND REPLACE WITH ABOVE ITEMS, DISMANTLE DAMAGE PROFILE AND COVER, SUPPLY NEW PROFILE AND COVER, SUPPLY PAINT AT DAMAGED AREA.		420.00	300.00
			2,490.00	1,950.00
	GRAND TOTAL		8,776.64	6,586.06
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00
LESS EXCESS				-1,500.00
NETT LIABILITY				3,500.00

Report Ref No. CS/ASM18013418/T1cd3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.